

OWNER: POWDERHORN AVIATION, LLC		OPERATOR: POWDERHORN AVIATION, LLC		OPERATOR: AMERICAN JET CHARTER	
ADDRESS: 5901 PHILIP J RHOADS AVENUE BETHANY OK 73008		ADDRESS: 5901 PHILIP J RHOADS AVENUE BETHANY OK 73008		ADDRESS: 5901 PHILP J RHOADS BETHANY OK 73008	
OFFICE:		OFFICE:		OFFICE:	
FAX:		FAX:		FAX:	
ANALYST: SEAN WELLS		+1-316-928-7895 (DIRECT)		800-787-9749 (EFAX-CARDS)	
EMAIL: SWELLS@CAMPSYSTEMS.COM		+1-631-588-3200 (MAIN)		631-980-4222 (EFAX-CARDS)	
		WWW.CAMPSYSTEMS.COM		PLEASE REACH OUT TO YOUR ANALYST TO RECORD CHANGES TO ADDRESS, LAST ACTUALS (IF ANY).	

FILTER CRITERIA : Spl. Reqs:INCLUDE;Task Type:PACKAGE, COMPONENT, SERVICE;PN/SN-UNKNOWN Components:INCLUDE

AIRCRAFT	SERIAL/REGNO: 45-252/N253SC		MODEL:	LEARJET 45		MANUFACTURER:	BOMBARDIER AVIATION	
	CERTIFICATION DATE: 07-JUL-2004			LAST ACTUALS:				
				5455.2 A/C HRS as of 23-JUL-2026				
				4545 AFL as of 23-JUL-2026				
				1986.7 APH as of 24-JUN-2026				
APU	SERIAL/PART: P-162/3800726-1		MODEL:	RE100 (CIMMS)		MANUFACTURER:	HONEYWELL	
	INSTALLED ON: 09-SEP-2004			LAST ACTUALS:				
	0 APU HRS 16 A/C HRS			1986.7 APU HRS as of 24-JUN-2026				
	0 APUS			4853 APUS as of 24-JUN-2026				
ENGINE NO. 1	SERIAL/PART: P-116538C/3060084-1		MODEL:	TFE731-20BR-1B		MANUFACTURER:	HONEYWELL	
	INSTALLED ON: 07-JUL-2004			LAST ACTUALS:				
	0 ENG. HRS 0 A/C HRS			5455.2 ENG. HRS as of 23-JUL-2026				
	0 ENC			4545 ENC as of 23-JUL-2026				
ENGINE NO. 2	SERIAL/PART: P-116539C/3060084-1		MODEL:	TFE731-20BR-1B		MANUFACTURER:	HONEYWELL	
	INSTALLED ON: 07-JUL-2004			LAST ACTUALS:				
	0 ENG. HRS 0 A/C HRS			5455.2 ENG. HRS as of 23-JUL-2026				
	0 ENC			4545 ENC as of 23-JUL-2026				

Status Report

Model: LEARJET 45
Serial: 45-252
RegNo: N253SC
HRS: 5455.2
AFL: 4545
As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 00 - INFORMATION								
CI45-150721	REVIEW CONCORDE EMERGENCY BATTERY CMM 5-0167 REV E							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF CI45PROC. REF: RCF CI45								
CI45-160527	REVIEW LEARJET AMM REVISION 66							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF CI45PROC. REF: RCF CI45								
CI45-160603	REVIEW LEARJET 45 AMM TR 4-40							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF CI45PROC. REF: RCF CI45								
CI45-160613	REVIEW LEARJET 45 AMM TR 5-110							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF CI45PROC. REF: RCF CI45								
CI45-161207B	REVIEW LEARJET 45 AMM REVISION 67							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF CI45PROC. REF: RCF CI45								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45
Serial: 45-252
RegNo: N253SC
HRS: 5455.2
AFL: 4545
As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 00 - INFORMATION								
CI45-181109B		REVIEW LEARJET 45/45XR AMM REVISION 71						Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF CI45PROC. REF: RCF CI45								
CI45-190429A		REVIEW LEARJET 45/45XR AMM REV 72						Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF CI45PROC. REF: RCF CI45								
CI45-200529		REVIEW AUDIT SUMMARY CHANGE FORM						Service ATA:00
	MOS/MSC	EFF	-					AUDIT SUMMARY CHANGE FORM
	HRS							
	AFL							
PROC. REF: RCF CI45PROC. REF: RCF CI45								
CI45-210120		REVIEW LEARJET 45/45XR AUDIT SUMMARY CHANGE FORM						Service ATA:00
	MOS/MSC	EFF	-					AUDIT SUMMARY CHANGE FORM
	HRS							
	AFL							
PROC. REF: RCF CI45PROC. REF: RCF CI45								
CI45-260206		REVIEW ATTACHED AUDIT SUMMARY CHANGE FORM						Service ATA:00
	MOS/MSC	EFF	-					AUDIT SUMMARY CHANGE FORM
	HRS							
	AFL							
PROC. REF: RCF CI45PROC. REF: RCF CI45								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 00 - INFORMATION								
EC04-180802	NO. 1 ENGINE - REVIEW TFE731-20/-40/-60 (CIMMS) LMM TR 5-17							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
PROC. REF: RCF EC04-180802PROC. REF: RCF EC04-180802								
EC04-180802	NO. 2 ENGINE - REVIEW TFE731-20/-40/-60 (CIMMS) LMM TR 5-17							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
PROC. REF: RCF EC04-180802PROC. REF: RCF EC04-180802								
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
051101	PHASE A1-300 HOUR CHECKS							Package ATA:05
	MOS	31-Jul-25	12 (+14d/-14d)		31-Jul-26	14-Aug-26	8 d (+14)	
	HRS	5307.6	300 (+25/-25)		5607.6	5632.6	152.4 (+25)	
	AFL	4448						
								PKG:1
PROC. REF: AMM 05-10-00, AMM 05-11-01PROC. REF: AMM 05-10-00, AMM 05-11-01								
051102	PHASE A2-300 HOUR CHECKS							Package ATA:05
	MOS	31-Jul-25	12 (+14d/-14d)		31-Jul-26	14-Aug-26	8 d (+14)	
	HRS	5307.6	300 (+25/-25)		5607.6	5632.6	152.4 (+25)	
	AFL	4448						
								PKG:2
PROC. REF: AMM 05-10-00, AMM 05-11-02PROC. REF: AMM 05-10-00, AMM 05-11-02								
051103	PHASE A3-300 HOUR CHECKS							Package ATA:05
	MOS	31-Jul-25	12 (+14d/-14d)		31-Jul-26	14-Aug-26	8 d (+14)	
	HRS	5307.6	300 (+25/-25)		5607.6	5632.6	152.4 (+25)	
	AFL	4448						
								PKG:3
PROC. REF: AMM 05-10-00, AMM 05-11-03PROC. REF: AMM 05-10-00, AMM 05-11-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45
Serial: 45-252
RegNo: N253SC
HRS: 5455.2
AFL: 4545
As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
051104	PHASE A4-300 HOUR CHECKS							Package ATA:05
	MOS	31-Jul-25	12 (+14d/-14d)		31-Jul-26	14-Aug-26	8 d (+14)	
	HRS	5307.6	300 (+25/-25)		5607.6	5632.6	152.4 (+25)	
	AFL	4448						
PROC. REF: AMM 05-10-00, AMM 05-11-04PROC. REF: AMM 05-10-00, AMM 05-11-04								PKG:4
051105	PHASE A5-300 HOUR CHECKS							Package ATA:05
	MOS	31-Jul-25	12 (+14d/-14d)		31-Jul-26	14-Aug-26	8 d (+14)	
	HRS	5307.6	300 (+25/-25)		5607.6	5632.6	152.4 (+25)	
	AFL	4448						
PROC. REF: AMM 05-10-00, AMM 05-11-05PROC. REF: AMM 05-10-00, AMM 05-11-05								PKG:5
051106	PHASE A6-300 HOUR CHECKS							Package ATA:05
	MOS	31-Jul-25	12 (+14d/-14d)		31-Jul-26	14-Aug-26	8 d (+14)	
	HRS	5307.6	300 (+25/-25)		5607.6	5632.6	152.4 (+25)	
	AFL	4448						
PROC. REF: AMM 05-10-00, AMM 05-11-06PROC. REF: AMM 05-10-00, AMM 05-11-06								PKG:6
051201	PHASE B1 600 HOUR CHECKS							Package ATA:05
	MOS	09-Jul-24	24 (+14d/-14d)		31-Jul-26	31-Jul-26	8 d	
	HRS	5131.8	600 (+25/-25)		5731.8	5756.8	276.6 (+25)	
	AFL	4323						
PROC. REF: AMM 05-10-00, AMM 05-12-01PROC. REF: AMM 05-10-00, AMM 05-12-01								PKG:7
051202	PHASE B2 600 HOUR CHECKS							Package ATA:05
	MOS	09-Jul-24	24 (+14d/-14d)		31-Jul-26	31-Jul-26	8 d	
	HRS	5131.8	600 (+25/-25)		5731.8	5756.8	276.6 (+25)	
	AFL	4323						
PROC. REF: AMM 05-10-00, AMM 05-12-02PROC. REF: AMM 05-10-00, AMM 05-12-02								PKG:8

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
051203	PHASE B3 600 HOUR CHECKS							Package ATA:05
	MOS	09-Jul-24	24 (+14d/-14d)		31-Jul-26	31-Jul-26	8 d	
	HRS	5131.8	600 (+25/-25)		5731.8	5756.8	276.6 (+25)	
	AFL	4323						
PROC. REF: AMM 05-10-00, AMM 05-12-03PROC. REF: AMM 05-10-00, AMM 05-12-03								PKG:9
051204	PHASE B4 600 HOUR CHECKS							Package ATA:05
	MOS	09-Jul-24	24 (+14d/-14d)		31-Jul-26	31-Jul-26	8 d	
	HRS	5131.8	600 (+25/-25)		5731.8	5756.8	276.6 (+25)	
	AFL	4323						
PROC. REF: AMM 05-10-00, AMM 05-12-04PROC. REF: AMM 05-10-00, AMM 05-12-04								PKG:10
051205	PHASE B5 600 HOUR CHECKS							Package ATA:05
	MOS	09-Jul-24	24 (+14d/-14d)		31-Jul-26	31-Jul-26	8 d	
	HRS	5131.8	600 (+25/-25)		5731.8	5756.8	276.6 (+25)	
	AFL	4323						
PROC. REF: AMM 05-10-00, AMM 05-12-05PROC. REF: AMM 05-10-00, AMM 05-12-05								PKG:11
051206	PHASE B6 600 HOUR CHECKS							Package ATA:05
	MOS	09-Jul-24	24 (+14d/-14d)		31-Jul-26	31-Jul-26	8 d	
	HRS	5131.8	600 (+25/-25)		5731.8	5756.8	276.6 (+25)	
	AFL	4323						
PROC. REF: AMM 05-10-00, AMM 05-12-06PROC. REF: AMM 05-10-00, AMM 05-12-06								PKG:12
051301	PHASE C1 1200 HOUR CHECKS							Package ATA:05
	MOS	24-Feb-23	48 (+14m/-14m)		28-Feb-27	24-Apr-28	220 d (+421)	
	HRS	5067.1	1200 (+25/-25)		6267.1	6292.1	811.9 (+25)	
	AFL	4262						
PROC. REF: AMM 05-10-00, AMM 05-13-01PROC. REF: AMM 05-10-00, AMM 05-13-01								PKG:13

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45
Serial: 45-252
RegNo: N253SC
HRS: 5455.2
AFL: 4545
As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
051302	PHASE C2 1200 HOUR CHECKS							Package ATA:05
	MOS	24-Feb-23	48 (+14m/-14m)		28-Feb-27	24-Apr-28	220 d (+421)	
	HRS	5067.1	1200 (+25/-25)		6267.1	6292.1	811.9 (+25)	
	AFL	4262						
PROC. REF: AMM 05-10-00, AMM 05-13-02PROC. REF: AMM 05-10-00, AMM 05-13-02								PKG:14
051303	PHASE C3 1200 HOUR CHECKS							Package ATA:05
	MOS	24-Feb-23	48 (+14d/-14d)		28-Feb-27	10-Mar-27	220 d (+10)	
	HRS	5067.1	1200 (+25/-25)		6267.1	6292.1	811.9 (+25)	
	AFL	4262						
PROC. REF: AMM 05-10-00, AMM 05-13-03PROC. REF: AMM 05-10-00, AMM 05-13-03								PKG:15
051304	PHASE C4 1200 HOUR CHECKS							Package ATA:05
	MOS	24-Feb-23	48 (+14m/-14m)		28-Feb-27	24-Apr-28	220 d (+421)	
	HRS	5067.1	1200 (+25/-25)		6267.1	6292.1	811.9 (+25)	
	AFL	4262						
PROC. REF: AMM 05-10-00, AMM 05-13-04PROC. REF: AMM 05-10-00, AMM 05-13-04								PKG:16
051305	PHASE C5 1200 HOUR CHECKS							Package ATA:05
	MOS	24-Feb-23	48 (+14m/-14m)		28-Feb-27	24-Apr-28	220 d (+421)	
	HRS	5067.1	1200 (+25/-25)		6267.1	6292.1	811.9 (+25)	
	AFL	4262						
PROC. REF: AMM 05-10-00, AMM 05-13-05PROC. REF: AMM 05-10-00, AMM 05-13-05								PKG:17
051306	PHASE C6 1200 HOUR CHECKS							Package ATA:05
	MOS	24-Feb-23	48 (+14m/-14m)		28-Feb-27	24-Apr-28	220 d (+421)	
	HRS	5067.1	1200 (+25/-25)		6267.1	6292.1	811.9 (+25)	
	AFL	4262						
PROC. REF: AMM 05-10-00, AMM 05-13-06PROC. REF: AMM 05-10-00, AMM 05-13-06								PKG:18

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
051401	PHASE D1 2400 HOUR CHECKS							Package ATA:05
	MOS	01-Mar-19	96		31-Mar-27		251 d	
	HRS	4123.3	2400		6523.3		1068.1	
	AFL	3499						
PROC. REF: AMM 05-10-00, AMM 05-14-01PROC. REF: AMM 05-10-00, AMM 05-14-01								PKG:19
051402	PHASE D2 2400 HOUR CHECKS							Package ATA:05
	MOS	01-Mar-19	96		31-Mar-27		251 d	
	HRS	4123.3	2400		6523.3		1068.1	
	AFL	3499						
PROC. REF: AMM 05-10-00, AMM 05-14-02PROC. REF: AMM 05-10-00, AMM 05-14-02								PKG:20
051403	PHASE D3 2400 HOUR CHECKS							Package ATA:05
	MOS	01-Mar-19	96 (+14m/-14m)		31-Mar-27	01-May-28	251 d (+397)	
	HRS	4123.3	2400 (+25/-25)		6523.3	6548.3	1068.1 (+25)	
	AFL	3499						
PROC. REF: AMM 05-10-00, AMM 05-14-03PROC. REF: AMM 05-10-00, AMM 05-14-03								PKG:21
051404	PHASE D4 2400 HOUR CHECKS							Package ATA:05
	MOS	01-Mar-19	96 (+14m/-14m)		31-Mar-27	01-May-28	251 d (+397)	
	HRS	4123.3	2400 (+25/-25)		6523.3	6548.3	1068.1 (+25)	
	AFL	3499						
PROC. REF: AMM 05-10-00, AMM 05-14-04PROC. REF: AMM 05-10-00, AMM 05-14-04								PKG:22
051405	PHASE D5 2400 HOUR CHECKS							Package ATA:05
	MOS	01-Mar-19	96 (+14m/-14m)		31-Mar-27	01-May-28	251 d (+397)	
	HRS	4123.3	2400 (+25/-25)		6523.3	6548.3	1068.1 (+25)	
	AFL	3499						
PROC. REF: AMM 05-10-00, AMM 05-14-05PROC. REF: AMM 05-10-00, AMM 05-14-05								PKG:23

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
051406	PHASE D6 2400 HOUR CHECKS							Package ATA:05
	MOS	01-Mar-19	96 (+14m/-14m)		31-Mar-27	01-May-28	251 d (+397)	
	HRS	4123.3	2400 (+25/-25)		6523.3	6548.3	1068.1 (+25)	
	AFL	3499						
PROC. REF: AMM 05-10-00, AMM 05-14-06PROC. REF: AMM 05-10-00, AMM 05-14-06								PKG:24
051500	4800 HOUR CHECKS							Package ATA:05
	MOS	18-Nov-21						
	HRS	4737	4800		9537		4081.8	
	AFL	3987						
PROC. REF: AMM 05-15-00, AMM 05-10-00PROC. REF: AMM 05-15-00, AMM 05-10-00								PKG:25
051600	9600 HOUR CHECKS							Package ATA:05
	MOS	07-Jul-04						
	HRS	0	9600		9600		4144.8	
	AFL	0						
PROC. REF: AMM 05-16-00, AMM 05-10-00PROC. REF: AMM 05-16-00, AMM 05-10-00								PKG:26
051700	MAJOR LANDING GEAR INSPECTION							Package ATA:05
	MOS	07-Jul-04						
	HRS	0						
	AFL	0	10000		10000		5455	
PROC. REF: AMM 05-17-00, AMM 05-10-00PROC. REF: AMM 05-17-00, AMM 05-10-00								PKG:27
057110	NO. 1 ENGINE - 150 TO 250 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS							Package ATA:05
	MOS	31-Jul-25						
	HRS	5307.6	150 (+100)		(5457.6) 5457.6	5557.6	2.4 (+100)	
	ENC	4448						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
057110	NO. 2 ENGINE - 150 TO 250 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS							Package ATA:05
	MOS	31-Jul-25						
	HRS	5307.6	150 (+100)		(5457.6) 5457.6	5557.6	2.4 (+100)	
	ENC	4448						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								
057120	NO. 1 ENGINE - 300 TO 440 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS							Package ATA:05
	MOS/MSC	22-Aug-13	N/A					
	HRS	3014.1						
	ENC	2498						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								
057120	NO. 2 ENGINE - 300 TO 440 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS							Package ATA:05
	MOS/MSC	22-Aug-13	N/A					
	HRS	3014.1						
	ENC	2498						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								
057130	NO. 1 ENGINE - 500 TO 650 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS							Package ATA:05
	MOS	31-Jul-25						
	HRS	5307.6	600		(5907.6) 5907.6		452.4	
	ENC	4448						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								
057130	NO. 2 ENGINE - 500 TO 650 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS							Package ATA:05
	MOS	31-Jul-25						
	HRS	5307.6	600		(5907.6) 5907.6		452.4	
	ENC	4448						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
057140	NO. 1 ENGINE - 500 TO 850 HOUR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS							Package ATA:05
	MOS	26-Oct-22						
	HRS	4984.7	800 (+50/-300)		(5784.7) 5784.7	5834.7	329.5 (+50)	
	ENC	4197						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								
057140	NO. 2 ENGINE - 500 TO 850 HOUR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS							Package ATA:05
	MOS	26-Oct-22						
	HRS	4984.7	800 (+50/-300)		(5784.7) 5784.7	5834.7	329.5 (+50)	
	ENC	4197						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								
057150	NO. 1 ENGINE - 1000 TO 1300 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS							Package ATA:05
	MOS	06-Sep-19						
	HRS	4261.4	1200		(5461.4) 5461.4		6.2	
	ENC	3621						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								
057150	NO. 2 ENGINE - 1000 TO 1300 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS							Package ATA:05
	MOS	06-Sep-19						
	HRS	4261.4	1200		(5461.4) 5461.4		6.2	
	ENC	3621						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								
057160	NO. 1 ENGINE - 1500 TO 1650 HOUR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS							Package ATA:05
	MOS	13-May-21						
	HRS	4665.3	1600 (+50/-100)		(6265.3) 6265.3	6315.3	810.1 (+50)	
	ENC	3922						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
057160	NO. 2 ENGINE - 1500 TO 1650 HOUR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS							Package ATA:05
	MOS	13-May-21						
	HRS	4665.3	1600 (+50/-100)		(6265.3) 6265.3	6315.3	810.1 (+50)	
	ENC	3922						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								
5-50-00-18	PERFORM UNSCHEDULED MAINTENANCE CHECK - FOREIGN OBJECT DAMAGE							Service ATA:05
	MOS/MSC		O/C					
	HRS							
	AFL							
PROC. REF: AMM 05-50-00PROC. REF: AMM 05-50-00								
5-50-00-19	PERFORM UNSCHEDULED MAINTENANCE CHECK - ENGINE VIBRATION INDICATION							Service ATA:05
	MOS/MSC		A/R					
	HRS							
	AFL							
PROC. REF: AMM 05-50-00PROC. REF: AMM 05-50-00								
ATA 08 - LEVELING AND WEIGHING								
082000	WEIGH AIRCRAFT							Service ATA:08
	MOS/MSC	23-Feb-16	A/R					
	HRS	3537						
	AFL	2921						
PROC. REF: AMM 08-10-00, FAR FAR 135.185PROC. REF: AMM 08-10-00, FAR FAR 135.185								
ATA 11 - PLACARDS AND MARKINGS								
G1130000 ^S	CHECK BRIGHTNESS LEVEL OF ALL SELF-LUMINOUS PLACARDS							Service ATA:11
	MOS	24-Feb-23	48 (+14d/-14d)					
	HRS	5067.1	1200 (+25/-25)					
	AFL	4262						
PROC. REF: AMM 11-30-00PROC. REF: AMM 11-30-00								PKG:13

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 12 - SERVICING								
AB1210060 ^S		MAIN LANDING GEAR UPLOCK ACTUATOR - LUBRICATE					Service	ATA:12
	MOS	31-Jul-25	12 (+14d/-14d)					
	HRS	5307.6	300 (+25/-25)					
	AFL	4448						
PROC. REF: AMM 12-21-01PROC. REF: AMM 12-21-01								PKG:5
O1210002 ^S		FLAP ACTUATORS - CHECK OIL LEVEL					Service	ATA:12
	MOS	09-Jul-24	24 (+14d/-14d)					
	HRS	5131.8	600 (+25/-25)					
	AFL	4323						
PROC. REF: AMM 12-21-03PROC. REF: AMM 12-21-03								PKG:10
Q1221064		LEFT INBOARD FLAP ACTUATOR JOINT - APPLY CORROSION PREVENTIVE COMPOUND (CPC)					Service	ATA:12
PN:159174-1	MOS/MSC	19-Feb-14	N/A					
SN:NA	HRS	3107.6						
	AFL	2561						
PROC. REF: AMM 12-21-03PROC. REF: AMM 12-21-03								
Q1221064		LEFT OUTBOARD FLAP ACTUATOR JOINT - APPLY CORROSION PREVENTIVE COMPOUND (CPC)					Service	ATA:12
PN:159174-1	MOS/MSC	19-Feb-14	N/A					
SN:NA	HRS	3107.6						
	AFL	2561						
PROC. REF: AMM 12-21-03PROC. REF: AMM 12-21-03								
Q1221064		RIGHT INBOARD FLAP ACTUATOR JOINT - APPLY CORROSION PREVENTIVE COMPOUND (CPC)					Service	ATA:12
PN:159174-1	MOS/MSC	19-Feb-14	N/A					
SN:NA	HRS	3107.6						
	AFL	2561						
PROC. REF: AMM 12-21-03PROC. REF: AMM 12-21-03								
Q1221064		RIGHT OUTBOARD FLAP ACTUATOR JOINT - APPLY CORROSION PREVENTIVE COMPOUND (CPC)					Service	ATA:12
PN:159174-1	MOS/MSC	19-Feb-14	N/A					
SN:NA	HRS	3107.6						
	AFL	2561						
PROC. REF: AMM 12-21-03PROC. REF: AMM 12-21-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 12 - SERVICING								
T1222004	NO. 1 MAIN BATTERY - LEAD-ACID BATTERIES - PERFORM BATTERY CAPACITY CHECK							Service ATA:12
PN:RG-380E/40L	MOS	12-Dec-25	3 (+1m/-1m)		31-Mar-26	12-Apr-26	OVD	
SN:41195100	HRS	5343						
	AFL	4470						
PROC. REF: AMM 12-22-00, CMM 24-30-71PROC. REF: AMM 12-22-00, CMM 24-30-71								
T1222004	NO. 2 MAIN BATTERY - LEAD-ACID BATTERIES - PERFORM BATTERY CAPACITY CHECK							Service ATA:12
PN:RG-380E/40L	MOS	12-Dec-25	3 (+1m/-1m)		31-Mar-26	12-Apr-26	OVD	
SN:41195098	HRS	5343						
	AFL	4470						
PROC. REF: AMM 12-22-00, CMM 24-30-71PROC. REF: AMM 12-22-00, CMM 24-30-71								
U1210004	FLAP FLEXIBLE TRANSMISSION SHAFTS - HAND LUBRICATE							Service ATA:12
	MOS	21-Feb-22						
	HRS	4819.5	4800 (+25/-25)		9619.5	9644.5	4164.3 (+25)	
	AFL	4049						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
Y1210000 ^S	NOSE LANDING GEAR SHOCK STRUT - CHECK FOR PROPER FLUID LEVEL AND INFLATION PRESSURE							Service ATA:12
	MOS	31-Jul-25	12 (+14d/-14d)					
	HRS	5307.6	300 (+25/-25)					
	AFL	4448						
PROC. REF: AMM 12-10-02PROC. REF: AMM 12-10-02								PKG:5
Y1210001 ^S	MAIN LANDING GEAR SHOCK STRUTS - CHECK FOR PROPER FLUID LEVEL AND INFLATION PRESSURE							Service ATA:12
	MOS	31-Jul-25	12 (+14d/-14d)					
	HRS	5307.6	300 (+25/-25)					
	AFL	4448						
PROC. REF: AMM 12-10-03PROC. REF: AMM 12-10-03								PKG:5

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45
Serial: 45-252
RegNo: N253SC
HRS: 5455.2
AFL: 4545
As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 12 - SERVICING								
Y1210003	^S	FLAP ACTUATOR BALLNUT - LUBRICATE						Service ATA:12
	MOS	31-Jul-25	12 (+14d/-14d)					
	HRS	5307.6	300 (+25/-25)					
	AFL	4448						
PROC. REF: AMM 12-21-03PROC. REF: AMM 12-21-03								PKG:4
Y1210005	^S	NOSE LANDING GEAR TRUNNION PIN - LUBRICATE						Service ATA:12
	MOS	31-Jul-25	12 (+14d/-14d)					
	HRS	5307.6	300 (+25/-25)					
	AFL	4448						
PROC. REF: AMM 12-21-01PROC. REF: AMM 12-21-01								PKG:5
Y1210006	^S	NOSE LANDING GEAR ACTUATOR ATTACH FITTING - LUBRICATE						Service ATA:12
	MOS	31-Jul-25	12 (+14d/-14d)					
	HRS	5307.6	300 (+25/-25)					
	AFL	4448						
PROC. REF: AMM 12-21-01PROC. REF: AMM 12-21-01								PKG:5
Y1210007	^S	NOSE AND MAIN TIRES - CHECK FOR PROPER INFLATION						Service ATA:12
	MOS	31-Jul-25	12 (+14d/-14d)					
	HRS	5307.6	300 (+25/-25)					
	AFL	4448						
PROC. REF: AMM 12-10-04PROC. REF: AMM 12-10-04								PKG:5
Y1210009	^S	NOSE GEAR DOOR HINGE - LUBRICATE						Service ATA:12
	MOS	31-Jul-25	12 (+14d/-14d)					
	HRS	5307.6	300 (+25/-25)					
	AFL	4448						
PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02								PKG:1

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45
Serial: 45-252
RegNo: N253SC
HRS: 5455.2
AFL: 4545
As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 12 - SERVICING								
Y1210011	^S	MAIN LANDING GEAR ACTUATOR JOINTS - LUBRICATE						Service ATA:12
	MOS	31-Jul-25	12 (+14d/-14d)					
	HRS	5307.6	300 (+25/-25)					
	AFL	4448						
PROC. REF: AMM 12-21-01PROC. REF: AMM 12-21-01								PKG:5
Y1210012	^S	MAIN LANDING GEAR AXLE BEAM/PISTON JOINTS - LUBRICATE						Service ATA:12
	MOS	31-Jul-25	12 (+14d/-14d)					
	HRS	5307.6	300 (+25/-25)					
	AFL	4448						
PROC. REF: AMM 12-21-01PROC. REF: AMM 12-21-01								PKG:5
Y1210013	^S	MAIN LANDING GEAR TORQUE LINKS - LUBRICATE						Service ATA:12
	MOS	31-Jul-25	12 (+14d/-14d)					
	HRS	5307.6	300 (+25/-25)					
	AFL	4448						
PROC. REF: AMM 12-21-01PROC. REF: AMM 12-21-01								PKG:5
Y1210014	^S	MAIN LANDING GEAR DOOR HINGE - LUBRICATE						Service ATA:12
	MOS	31-Jul-25	12 (+14d/-14d)					
	HRS	5307.6	300 (+25/-25)					
	AFL	4448						
PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02								PKG:5
Y1210016	^S	PASSENGER/CREW DOOR HINGE - LUBRICATE						Service ATA:12
	MOS	31-Jul-25	12 (+14d/-14d)					
	HRS	5307.6	300 (+25/-25)					
	AFL	4448						
PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02								PKG:6

?-Insufficient Information
S-Suppressed Requirement
*-Estimated Due(New Requirement)
(EFF)-Effective C/W
(M)-Manual Due
U-User Task
Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 12 - SERVICING								
Y1210017	^S	PASSENGER/CREW DOOR PINS - LUBRICATE						Service ATA:12
	MOS	31-Jul-25	12 (+14d/-14d)					
	HRS	5307.6	300 (+25/-25)					
	AFL	4448						
PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02								PKG:6
Y1210018	^S	PASSENGER/CREW DOOR TENSION BOLTS - LUBRICATE						Service ATA:12
	MOS	31-Jul-25	12 (+14d/-14d)					
	HRS	5307.6	300 (+25/-25)					
	AFL	4448						
PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02								PKG:6
Y1210019	^S	EMERGENCY EXIT DOOR LATCHING MECHANISM - LUBRICATE						Service ATA:12
	MOS	31-Jul-25	12 (+14d/-14d)					
	HRS	5307.6	300 (+25/-25)					
	AFL	4448						
PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02								PKG:6
Y1210020	^S	EMERGENCY EXIT DOOR PINS - LUBRICATE						Service ATA:12
	MOS	31-Jul-25	12 (+14d/-14d)					
	HRS	5307.6	300 (+25/-25)					
	AFL	4448						
PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02								PKG:6
Y1210021	^S	BAGGAGE COMPARTMENT DOOR LATCH PINS - LUBRICATE						Service ATA:12
	MOS	31-Jul-25	12 (+14d/-14d)					
	HRS	5307.6	300 (+25/-25)					
	AFL	4448						
PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02								PKG:6

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 12 - SERVICING								
Y1210022 ^S	BAGGAGE COMPARTMENT DOOR HINGE - LUBRICATE							Service ATA:12
	MOS	31-Jul-25	12 (+14d/-14d)					
	HRS	5307.6	300 (+25/-25)					
	AFL	4448						
PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02								PKG:6
Y1210023 ^S	OXYGEN SYSTEM SERVICING DOOR HINGE - LUBRICATE							Service ATA:12
	MOS	31-Jul-25	12 (+14d/-14d)					
	HRS	5307.6	300 (+25/-25)					
	AFL	4448						
PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02								PKG:1
Y1210024 ^S	TOILET SERVICING DOOR HINGE - LUBRICATE							Service ATA:12
	MOS	31-Jul-25	12 (+14d/-14d)					
	HRS	5307.6	300 (+25/-25)					
	AFL	4448						
PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02								PKG:4
Y1210025 ^S	PRESSURE REFUELING STATION DOOR HINGE - LUBRICATE							Service ATA:12
	MOS	31-Jul-25	12 (+14d/-14d)					
	HRS	5307.6	300 (+25/-25)					
	AFL	4448						
PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02								PKG:2
Y1210026 ^S	FUSELAGE FUEL FILLER DOOR HINGE - LUBRICATE							Service ATA:12
	MOS	31-Jul-25	12 (+14d/-14d)					
	HRS	5307.6	300 (+25/-25)					
	AFL	4448						
PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02								PKG:2

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 12 - SERVICING								
Y1210027	^S	TAILCONE ACCESS DOOR PINS - LUBRICATE						Service ATA:12
	MOS	31-Jul-25	12 (+14d/-14d)					
	HRS	5307.6	300 (+25/-25)					
	AFL	4448						
PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02								PKG:6
Y1210028	^S	TAILCONE ACCESS DOOR HINGE - LUBRICATE						Service ATA:12
	MOS	31-Jul-25	12 (+14d/-14d)					
	HRS	5307.6	300 (+25/-25)					
	AFL	4448						
PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02								PKG:6
Y1210029	^S	MAIN LANDING GEAR TRUNNION PIN - LUBRICATE						Service ATA:12
	MOS	31-Jul-25	12 (+14d/-14d)					
	HRS	5307.6	300 (+25/-25)					
	AFL	4448						
PROC. REF: AMM 12-21-01PROC. REF: AMM 12-21-01								PKG:5
Y1221037	^S	FLAPS - LUBRICATE ROLLING SURFACES OF MAIN AND NOSE ROLLER TRACKS						Service ATA:12
	MOS	31-Jul-25	12 (+14d/-14d)					
	HRS	5307.6	300 (+25/-25)					
	AFL	4448						
PROC. REF: AMM 12-21-03PROC. REF: AMM 12-21-03								PKG:4
Y1221042	^S	HORIZONTAL STABILIZER UPPER AND LOWER TORQUE LINKS - LUBRICATE						Service ATA:12
	MOS	09-Jul-24	24 (+14d/-14d)					
	HRS	5131.8	600 (+25/-25)					
	AFL	4323						
PROC. REF: AMM 12-21-03PROC. REF: AMM 12-21-03								PKG:9

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 12 - SERVICING								
Y1227000 ^S	EMERGENCY PARK BRAKE HANDLE SHAFT - LUBRICATE							Service ATA:12
	MOS	31-Jul-25	12 (+14d/-14d)					
	HRS	5307.6	300 (+25/-25)					
	AFL	4448						
PROC. REF: AMM 12-27-00PROC. REF: AMM 12-27-00								PKG:1
ATA 21 - AIR CONDITIONING								
211001	SERVO AIR PRESSURE REGULATING VALVE							Component ATA:21
PN:3213982-2	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:995	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-15-01PROC. REF: AMM 36-15-01								
211011	LEFT PLENUM CHECK VALVE							Component ATA:21
PN:3321000000-043	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:2564	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-20-09PROC. REF: AMM 21-20-09								
211012	RIGHT PLENUM CHECK VALVE							Component ATA:21
PN:3202742-1	MOS/MSC	08-Aug-08	O/C	TSN 0				
SN:3788	HRS	1480.2		TSN 0				
	AFL	1229		TSN 0				
PROC. REF: AMM 21-20-09PROC. REF: AMM 21-20-09								
211017	LEFT EMERGENCY PRESSURIZATION ISOLATION CHECK VALVE							Component ATA:21
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-20-03PROC. REF: AMM 21-20-03								
211018	RIGHT EMERGENCY PRESSURIZATION ISOLATION CHECK VALVE							Component ATA:21
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45
Serial: 45-252
RegNo: N253SC
HRS: 5455.2
AFL: 4545
As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
PROC. REF: AMM 21-20-03PROC. REF: AMM 21-20-03								
212001	COCKPIT AIR CHECK VALVE							Component ATA:21
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-20-01PROC. REF: AMM 21-20-01								
212007	AFT BLOWER MOTOR							Component ATA:21
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-51-09PROC. REF: AMM 21-51-09								
212008	FORWARD BLOWER MOTOR							Component ATA:21
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
212011	LINEAR ELECTRO-MECHANICAL ACTUATOR							Component ATA:21
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
212041	NO. 1 ENGINE OZONE CONVERTER							Component ATA:21
PN:4520000100-801	MOS/MSC	29-Jul-16	O/C	TSN 0				
SN:UNKNOWN	HRS	3589.4		TSN 0				
	AFL	2973		TSN 0				
PROC. REF: AMM 21-20-12PROC. REF: AMM 21-20-12								
212042	NO. 2 ENGINE OZONE CONVERTER							Component ATA:21
PN:4520000100-801	MOS/MSC	29-Jul-16	O/C	TSN 0				
SN:UNKNOWN	HRS	3589.4		TSN 0				
	AFL	2973		TSN 0				

?-Insufficient Information
S-Suppressed Requirement
*-Estimated Due(New Requirement)
(EFF)-Effective C/W
(M)-Manual Due
U-User Task
Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
PROC. REF: AMM 21-20-12PROC. REF: AMM 21-20-12								
212101	NO. 1 THERMAL CONTROL ACTUATOR							Component ATA:21
PN:11-643	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
212102	NO. 2 THERMAL CONTROL ACTUATOR							Component ATA:21
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
212105	LEFT ENVIRONMENTAL CONTROL SYSTEM TRANSITION DUCT							Component ATA:21
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
212106	RIGHT ENVIRONMENTAL CONTROL SYSTEM TRANSITION DUCT							Component ATA:21
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
212201	LEFT GASPER AIR CHECK VALVE							Component ATA:21
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-20-07PROC. REF: AMM 21-20-07								
212202	RIGHT GASPER AIR CHECK VALVE							Component ATA:21
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
PROC. REF: AMM 21-20-07PROC. REF: AMM 21-20-07								
212213	LEFT CABIN AIR CHECK VALVE							Component ATA:21
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-20-02PROC. REF: AMM 21-20-02								
212214	RIGHT CABIN AIR CHECK VALVE							Component ATA:21
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-20-02PROC. REF: AMM 21-20-02								
212801	AVIONICS COOLING FAN MOUNT							Component ATA:21
PN:4521208521-009	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:A00286528-01	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-21-01PROC. REF: AMM 21-21-01								
213000	CABIN PRESSURE CONTROLLER							Component ATA:21
PN:6621300000-027	MOS/MSC	09-Apr-19	O/C	TSR 0				
SN:55-J0083	HRS	4150.9		TSR 0				
	AFL	3538		TSR 0				
PROC. REF: AMM 21-30-03PROC. REF: AMM 21-30-03								
213001	LEFT EMERGENCY PRESSURE SHUTOFF VALVE							Component ATA:21
PN:3291224-1	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:655	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-31-01PROC. REF: AMM 21-31-01								
213002	RIGHT EMERGENCY PRESSURE SHUTOFF VALVE							Component ATA:21
PN:3291224-1	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:657	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
PROC. REF: AMM 21-31-01PROC. REF: AMM 21-31-01								
213021	JET PUMP EJECTOR							Component ATA:21
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-30-06PROC. REF: AMM 21-30-06								
213031	PRIMARY OUTFLOW VALVE							Component ATA:21
PN:103858-1	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:73-A0294	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-30-01PROC. REF: AMM 21-30-01								
213032	SECONDARY OUTFLOW VALVE							Component ATA:21
PN:103858-2	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:12-C0061	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-30-02PROC. REF: AMM 21-30-02								
213055	EMERGENCY PRESSURE ANEROID SWITCH							Component ATA:21
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
213056	ABSOLUTE PRESSURE SWITCH							Component ATA:21
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
213101	TAILCONE CHECK VALVE							Component ATA:21
PN:130158-3-1	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:83-A0563	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45
Serial: 45-252
RegNo: N253SC
HRS: 5455.2
AFL: 4545
As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
213110	CABIN PRESSURIZATION CHECK VALVE							Component ATA:21
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-30-07PROC. REF: AMM 21-30-07								
214301	FOOT WARMER THERMOSTAT (S167)							Component ATA:21
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-41-02PROC. REF: AMM 21-41-02								
214302	PILOT FOOT WARMER HEEL PLATE ASSEMBLY							Component ATA:21
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-41-01PROC. REF: AMM 21-41-01								
214303	CO-PILOT FOOT WARMER HEEL PLATE ASSEMBLY							Component ATA:21
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-41-01PROC. REF: AMM 21-41-01								
215001	WATER SEPARATOR ASSEMBLY							Component ATA:21
PN:2341168-1	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:382	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-50-03PROC. REF: AMM 21-50-03								
215002	WATER SEPARATOR BYPASS VALVE							Component ATA:21
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
215010	AIR CYCLE MACHINE PRECOOLER ASSEMBLY							Component ATA:21
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-50-08PROC. REF: AMM 21-50-08								
215013	PACK BI-LEVEL PRESURE REGULATOR SHUTOFF VALVE							Component ATA:21
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-50-02PROC. REF: AMM 21-50-02								
215015	AIR CYCLE MACHINE BYPASS CHECK VALVE							Component ATA:21
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-50-07PROC. REF: AMM 21-50-07								
215019	CABIN REFRIGERATION CONDENSER							Component ATA:21
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-51-04PROC. REF: AMM 21-51-04								
215030	ENVIRONMENTAL CONTROL UNIT							Component ATA:21
PN:6621000000-086	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:380	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-50-01PROC. REF: AMM 21-50-01								
215033	AIR CYCLE MACHINE							Component ATA:21
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
PROC. REF: AMM 21-50-04PROC. REF: AMM 21-50-04								
215036	PRIMARY, SECONDARY HEAT EXCHANGER							Component ATA:21
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
215039	AIR CYCLE MACHINE TURBINE							Component ATA:21
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-50-04PROC. REF: AMM 21-50-04								
215043	AFT EVAPORATOR							Component ATA:21
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-51-09PROC. REF: AMM 21-51-09								
215044	FORWARD EVAPORATOR							Component ATA:21
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-51-07PROC. REF: AMM 21-51-07								
215100	AIR CONDITIONING COMPRESSOR							Component ATA:21
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-51-01PROC. REF: AMM 21-51-01								
215101	AIR CONDITIONING COMPRESSOR DRIVE MOTOR							Component ATA:21
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
PROC. REF: AMM 21-51-02PROC. REF: AMM 21-51-02								
216001	ENVIRONMENTAL CONTROL SYSTEM - INTEGRATED TEMPERATURE CONTROLLER							Component ATA:21
PN:1151830-3	MOS/MSC	18-Aug-23	O/C					
SN:071C-0578	HRS	5089.1						
	AFL	4280						
PROC. REF: AMM 21-60-10PROC. REF: AMM 21-60-10								
216014	COCKPIT TEMPERATURE CONTROL VALVE							Component ATA:21
PN:6621000000-047	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:681	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-60-04, AMM 21-60-05PROC. REF: AMM 21-60-04, AMM 21-60-05								
216015	CABIN TEMPERATURE CONTROL VALVE							Component ATA:21
PN:6621000000-047	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:680	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-60-04PROC. REF: AMM 21-60-04								
216025	COCKPIT TEMPERATURE CONTROL SELECTOR							Component ATA:21
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-60-01PROC. REF: AMM 21-60-01								
216026	CABIN TEMPERATURE CONTROL SELECTOR							Component ATA:21
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-60-01PROC. REF: AMM 21-60-01								
216036	COCKPIT DUCT OVERHEAT THERMOSTAT							Component ATA:21
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
PROC. REF: AMM 21-60-09PROC. REF: AMM 21-60-09								
216037	CABIN DUCT OVERHEAT THERMOSTAT							Component ATA:21
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-60-08PROC. REF: AMM 21-60-08								
216040	28VDC CABIN TEMPERATURE SENSOR/FAN ASSEMBLY							Component ATA:21
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-60-03PROC. REF: AMM 21-60-03								
216049	CABIN DUCT OVERTEMP LIMITER							Component ATA:21
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-60-06PROC. REF: AMM 21-60-06								
216071	LOW LIMIT TEMPERATURE CONTROL VALVE							Component ATA:21
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
216074	SERVO AIR PRESSURE REGULATING VALVE							Component ATA:21
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-15-01PROC. REF: AMM 36-15-01								
216081	COCKPIT DUCT TEMPERATURE SENSOR							Component ATA:21
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45

Serial: 45-252

RegNo: N253SC

HRS: 5455.2

AFL: 4545

As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
PROC. REF: AMM 21-60-07PROC. REF: AMM 21-60-07								
216083	COCKPIT TEMPERATURE SENSOR							Component ATA:21
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-60-02PROC. REF: AMM 21-60-02								
216084	CABIN LOW LIMIT TEMPERATURE SENSOR							Component ATA:21
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-50-09PROC. REF: AMM 21-50-09								
5-19-00-L2150054	WEAR INSPECTION - AIR CONDITIONING COMPRESSOR DRIVE MOTOR BRUSHES - PERFORM WEAR INSPECTION (RETURN DRIVE MOTOR TO AUTHORIZED SERVICE FACILITY FOR OVERHAUL)							Service ATA:21
	MOS/MSC	07-Jul-04	N/A					NOT INSTALLED
	HRS	0						
	AFL	0						
	ACH	0						
5-19-00-L2150055	OVERHAUL - AIR CONDITIONING COMPRESSOR MOTOR - PERFORM OVERHAUL (RETURN DRIVE MOTOR TO AUTHORIZED SERVICE FACILITY FOR OVERHAUL)							Service ATA:21
	MOS/MSC	07-Jul-04	A/R					INSPECT
	HRS	0						
	AFL	0						
	ACH	0						
J2160007 ^S	TEMPERATURE CONTROL SYSTEM - INSPECT AND CLEAN CABIN AND COCKPIT TEMPERATURE CONTROL VALVE SERVO AIR FILTERS							Service ATA:21
	MOS	09-Jul-24	24 (+14d/-14d)					
	HRS	5131.8	600 (+25/-25)					
	AFL	4323						
PROC. REF: AMM 21-60-11PROC. REF: AMM 21-60-11								
PKG:8								

?-Insufficient Information

S-Suppressed Requirement

*-Estimated Due(New Requirement)

(EFF)-Effective C/W

(M)-Manual Due

U-User Task

Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
L2150054	AIR CONDITIONING COMPRESSOR DRIVE MOTOR BRUSHES - PERFORM WEAR INSPECTION							Service ATA:21
PN:PN	MOS/MSC	07-Jul-04	O/C					
SN:UNKNOWN	HRS	0						
	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
L2150055	AIR CONDITIONING COMPRESSOR DRIVE MOTOR - PERFORM OVERHAUL							Service ATA:21
PN:PN	MOS/MSC	07-Jul-04	O/C					
SN:UNKNOWN	HRS	0						
	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
L2150056 ^S	** AUXILIARY HEAT SYSTEM - PERFORM FUNCTIONAL TEST							Service ATA:21
	MOS	09-Jul-24	24 (+14d/-14d)					AIRWORTHINESS
	HRS	5131.8	600 (+25/-25)					
	AFL	4323						
PROC. REF: AMM 21-51-00PROC. REF: AMM 21-51-00								
L2150057 ^S	** AUXILIARY HEAT SYSTEM - PERFORM AUXILIARY HEATER ELECTRICAL AND TEMPERATURE SWITCH TEST							Service ATA:21
	MOS	24-Feb-23	48 (+14d/-14d)					AIRWORTHINESS
	HRS	5067.1	1200 (+25/-25)					
	AFL	4262						
PROC. REF: AMM 21-51-00PROC. REF: AMM 21-51-00								
O2130000 ^S	PRIMARY AND SECONDARY OUTFLOW VALVES - PERFORM INSPECTION							Service ATA:21
	MOS	24-Feb-23	48 (+14d/-14d)					
	HRS	5067.1	1200 (+25/-25)					
	AFL	4262						
PROC. REF: AMM 21-30-01, AMM 21-30-02PROC. REF: AMM 21-30-01, AMM 21-30-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
O2130001	^S	OUTFLOW VALVE AIR FILTER - REMOVE AND REPLACE						Service ATA:21
	MOS	01-Mar-19	96					
	HRS	4123.3	2400					
	AFL	3499						
PROC. REF: AMM 21-30-04PROC. REF: AMM 21-30-04								PKG:19
O2130002	^S	** PRESSURIZATION CONTROL SYSTEM - PERFORM FUNCTIONAL TEST. (AWL**)						Service ATA:21
	MOS	24-Feb-23	48 (+14d/-14d)					AIRWORTHINESS
	HRS	5067.1	1200 (+25/-25)					
	AFL	4262						
PROC. REF: AMM 21-30-00PROC. REF: AMM 21-30-00								PKG:13
Y2130003	^S	PRESSURIZATION CONTROL SYSTEM - PERFORM OPERATIONAL CHECK						Service ATA:21
	MOS	09-Jul-24	24 (+14d/-14d)					
	HRS	5131.8	600 (+25/-25)					
	AFL	4323						
PROC. REF: AMM 21-30-00PROC. REF: AMM 21-30-00								PKG:7
Y2130065		CABIN PRESSURIZATION SYSTEM - PERFORM CABIN LEAKAGE TEST						Service ATA:21
	MOS	18-Nov-21						
	HRS	4737	1200 (+25/-25)		5937	5962	481.8 (+25)	
	AFL	3987						
PROC. REF: AMM 21-30-00PROC. REF: AMM 21-30-00								
Y2140000	^S	AIR CYCLE MACHINE HEAT EXCHANGER INLET - PERFORM VISUAL INSPECTION						Service ATA:21
	MOS	24-Feb-23	48 (+14d/-14d)					
	HRS	5067.1	1200 (+25/-25)					
	AFL	4262						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								PKG:14

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
Y2140001	NO. 1 ENGINE OZONE CONVERTER - PERFORM CLEANING AND EFFICIENCY TEST							Service ATA:21
PN:4520000100-801	MOS	29-Jul-16						
SN:UNKNOWN	HRS	3589.4	3600 (+25/-25)		7189.4	7214.4	1734.2 (+25)	
	AFL	2973						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
Y2140001	NO. 2 ENGINE OZONE CONVERTER - PERFORM CLEANING AND EFFICIENCY TEST							Service ATA:21
PN:4520000100-801	MOS	29-Jul-16						
SN:UNKNOWN	HRS	3589.4	3600 (+25/-25)		7189.4	7214.4	1734.2 (+25)	
	AFL	2973						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
Y2141000 ^S	ENVIRONMENTAL CONTROL UNIT - PERFORM VISUAL INSPECTION							Service ATA:21
	MOS	24-Feb-23	48 (+14d/-14d)					
	HRS	5067.1	1200 (+25/-25)					
	AFL	4262						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								PKG:14
Y2141001 ^S	WATER SEPARATOR COALESCER BAG - PERFORM VISUAL INSPECTION. CLEAN IF NECESSARY.							Service ATA:21
	MOS	31-Jul-25	12 (+14d/-14d)					
	HRS	5307.6	300 (+25/-25)					
	AFL	4448						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								PKG:2
Y2141002	WATER SEPARATOR COALESCER BAG - REPLACE							Service ATA:21
	MOS/MSC	23-Feb-16	O/C					
	HRS	3537						
	AFL	2921						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45
Serial: 45-252
RegNo: N253SC
HRS: 5455.2
AFL: 4545
As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
Y2142000	^S	BAGGAGE COMPARTMENT HEATING SYSTEM - PERFORM FUNCTIONAL TEST						Service ATA:21
	MOS	01-Mar-19	96 (+14d/-14d)					
	HRS	4123.3	2400 (+25/-25)					
	AFL	3499						
PROC. REF: AMM 21-40-00PROC. REF: AMM 21-40-00								PKG:20
Y2145000	^S	ECS PLENUM ASSEMBLY CHECK VALVES - PERFORM VISUAL INSPECTION. VERIFY FREEDOM OF MOVEMENT OF BUTTERFLY ASSEMBLY.						Service ATA:21
	MOS	24-Feb-23	48 (+14d/-14d)					
	HRS	5067.1	1200 (+25/-25)					
	AFL	4262						
PROC. REF: AMM 21-20-03, AMM 21-20-09PROC. REF: AMM 21-20-03, AMM 21-20-09								PKG:14
Y2150058	^S	PERFORM VISUAL INSPECTION OF AIR CONDITIONING SYSTEM COMPONENTS, INCLUDING COMPRESSOR MOTOR BELT FOR WEAR AND PROPER V-BELT TENSION, CONDENSER COILS FOR CLEANLINESS AND HOSES FOR CHAFING AND WEAR. IF OIL LEAKS ARE VISIBLE AND/OR REFRIGERANT DUMPED, CHECK COMPRESSOR OIL LEVEL. SOME LEAKAGE IS ALLOWABLE AROUND SHAFT.						Service ATA:21
	MOS	24-Feb-23	48 (+14d/-14d)					
	HRS	5067.1	1200 (+25/-25)					
	AFL	4262						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								PKG:14
Y2150059	^S	AIR CONDITIONING SYSTEM - PERFORM LOAD SHED ASSEMBLY CHECK						Service ATA:21
	MOS	24-Feb-23	48 (+14d/-14d)					
	HRS	5067.1	1200 (+25/-25)					
	AFL	4262						
PROC. REF: AMM 21-51-00PROC. REF: AMM 21-51-00								PKG:14
ATA 22 - AUTO FLIGHT								
2210-RVSM		FLIGHT CHECK AUTOMATIC ALTITUDE HOLD FUNCTIONAL. RVSM COMPLIANT AIRCRAFT.						Service ATA:22
	MOS/MSC	07-Jul-04	N/R					
	HRS	0						
	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

? - Insufficient Information
S - Suppressed Requirement
* - Estimated Due(New Requirement)
(EFF) - Effective C/W
(M) - Manual Due
U - User Task
Ex - Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 22 - AUTO FLIGHT								
221001 AUTOPILOT FLIGHT GUIDANCE CONTROLLER								Component ATA:22
PN:7021170-901	MOS/MSC	12-May-15	O/C	TSN 0				
SN:07111847	HRS	3376.2		TSN 0				
	AFL	2786		TSN 0				
PROC. REF: AMM 22-10-01PROC. REF: AMM 22-10-01								
221041 AUTOPILOT ROLL SERVO								Component ATA:22
PN:4006719-948	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:03127748	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 22-10-04PROC. REF: AMM 22-10-04								
221045 AUTOPILOT ROLL SERVO BRACKET								Component ATA:22
PN:4005842	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:00113397	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 22-10-05PROC. REF: AMM 22-10-05								
221051 AUTOPILOT PITCH SERVO								Component ATA:22
PN:4006719-908	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:02037173	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 22-10-02PROC. REF: AMM 22-10-02								
221055 AUTOPILOT PITCH SERVO BRACKET								Component ATA:22
PN:4005842	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:02046086	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 22-10-03PROC. REF: AMM 22-10-03								
221061 AUTOPILOT YAW SERVO								Component ATA:22
PN:7012919-904	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:02060556	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 22-10-06PROC. REF: AMM 22-10-06								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 22 - AUTO FLIGHT								
221065	AUTOPILOT YAW SERVO BRACKET							Component ATA:22
PN:7012098-902	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:02040519	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 22-10-07PROC. REF: AMM 22-10-07								
225001	YAW INTERFACE UNIT							Component ATA:22
PN:4522108501-011	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:MRP721864-01	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 22-50-01PROC. REF: AMM 22-50-01								
225031	PILOT RUDDER BOOST SYSTEM YAW FORCE SENSOR							Component ATA:22
PN:6622500001-005	MOS/MSC	30-Nov-17	O/C	TSN 0				
SN:1625684	HRS	3855.5		TSN 0				
	AFL	3218		TSN 0				
PROC. REF: AMM 22-50-02PROC. REF: AMM 22-50-02								
225032	COPILOT RUDDER BOOST SYSTEM YAW FORCE SENSOR							Component ATA:22
PN:6622500001-005	MOS/MSC	30-Nov-17	O/C	TSN 0				
SN:1622823	HRS	3855.5		TSN 0				
	AFL	3218		TSN 0				
PROC. REF: AMM 22-50-02PROC. REF: AMM 22-50-02								
A2210033 ^S	** AUTOPILOT SYSTEM - PERFORM AUTOPILOT DISCONNECT TONE TEST							Service ATA:22
	MOS	09-Jul-24	24 (+14d/-14d)					AIRWORTHINESS
	HRS	5131.8	600 (+25/-25)					
	AFL	4323						
PROC. REF: AMM 22-10-00PROC. REF: AMM 22-10-00								
G2210030 ^S	PITCH SERVO CABLES - PERFORM CABLE TENSION CHECK							Service ATA:22
	MOS	24-Feb-23	48 (+14d/-14d)					
	HRS	5067.1	1200 (+25/-25)					
	AFL	4262						
PROC. REF: AMM 22-10-03PROC. REF: AMM 22-10-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 22 - AUTO FLIGHT								
G2210031	^S	ROLL SERVO CABLES - PERFORM CABLE TENSION CHECK						Service ATA:22
	MOS	24-Feb-23	48 (+14d/-14d)					
	HRS	5067.1	1200 (+25/-25)					
	AFL	4262						
PROC. REF: AMM 22-10-05PROC. REF: AMM 22-10-05								
G2210032	^S	YAW SERVO CABLES - PERFORM CABLE TENSION CHECK						Service ATA:22
	MOS	24-Feb-23	48 (+14d/-14d)					
	HRS	5067.1	1200 (+25/-25)					
	AFL	4262						
PROC. REF: AMM 22-10-07PROC. REF: AMM 22-10-07								
ATA 23 - COMMUNICATIONS								
230001		UNILINK PROCESSOR						Component ATA:23
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
230002		CONFIGURATION MODULE						Component ATA:23
PN:31990-1	MOS/MSC	09-Sep-04	O/C	TSN 0				
SN:11025	HRS	16		TSN 0				
	AFL	12		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
231011		NO. 1 POWER AMPLIFIER/HF ANTENNA COUPLER						Component ATA:23
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45
Serial: 45-252
RegNo: N253SC
HRS: 5455.2
AFL: 4545
As Of: 23-Jul-2026
23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
231012	NO. 2 POWER AMPLIFIER/HF ANTENNA COUPLER							Component ATA:23
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
231021	NO. 1 VHF COMMUNICATIONS TRANSCEIVER UNIT							Component ATA:23
PN:7510733-666	MOS/MSC	26-Apr-24	O/C					
SN:07038301	HRS	5128.5						
	AFL	4317						
PROC. REF: AMM 23-11-01PROC. REF: AMM 23-11-01								
231021A	TEST/INSPECT ATC TRANSPONDER							Service ATA:23
	MOS	28-Apr-26	24		30-Apr-28		647 d	
	HRS	5406.6						
	AFL	4513						
Calibration Date: : 28-Apr-26								
PROC. REF: AMM 23-11-00, FAR FAR 91.413PROC. REF: AMM 23-11-00, FAR FAR 91.413								
231022	NO. 2 VHF COMMUNICATIONS TRANSCEIVER UNIT							Component ATA:23
PN:7510733-666	MOS/MSC	26-Apr-24	O/C	TSN 235				
SN:04038521	HRS	5128.5		TSN 5125.6				
	AFL	4317		TSN 4319				
PROC. REF: AMM 23-11-01, FAR FAR 91.413PROC. REF: AMM 23-11-01, FAR FAR 91.413								
231022A	TEST/INSPECT ATC TRANSPONDER							Service ATA:23
	MOS	28-Apr-26	24		30-Apr-28		647 d	
	HRS	5406.6						
	AFL	4513						
Calibration Date: : 28-Apr-26								
PROC. REF: AMM 23-11-00, FAR FAR 91.413PROC. REF: AMM 23-11-00, FAR FAR 91.413								
231025	NO. 1 COMMUNICATIONS CIRCUIT CARD							Component ATA:23
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
231026	NO. 2 COMMUNICATIONS CIRCUIT CARD							Component ATA:23
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
231030	NO. 1 HF SELECTIVE CALLING (SELCAL) RECEIVER/EXCITER							Component ATA:23
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
231031	NO. 2 HF SELECTIVE CALLING (SELCAL) RECEIVER/EXCITER							Component ATA:23
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
231032	HF SELECTIVE CALLING (SELCAL) ANTENNA							Component ATA:23
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
231033	UPPER VHF ANTENNA							Component ATA:23
PN:VF10-347	MOS/MSC	11-Mar-09	O/C	TSN 4				
SN:5793	HRS	1684.2		TSN 0				
	AFL	1394		TSN 0				
PROC. REF: AMM 23-11-02PROC. REF: AMM 23-11-02								
231034	LOWER VHF ANTENNA							Component ATA:23
PN:DMC60-17-1	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:13850	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45
Serial: 45-252
RegNo: N253SC
HRS: 5455.2
AFL: 4545
As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
PROC. REF: AMM 23-11-02PROC. REF: AMM 23-11-02								
231045	NO. 1 HF CONTROL (MODEL KCU-951)							Component ATA:23
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
231046	NO. 2 HF CONTROL (MODEL KCU-951)							Component ATA:23
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
231051	NO. 1 HF BRIDGING AMPLIFIER							Component ATA:23
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
231052	NO. 2 HF BRIDGING AMPLIFIER							Component ATA:23
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
231090	PILOT HEADSET							Component ATA:23
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
231091	COPILOT HEADSET							Component ATA:23
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
231200	KHF-1050 HIGH FREQUENCY COMMUNICATION SYSTEM							Component ATA:23
PN:PN	MOS/MSC	07-Jul-04	N/A	TSN 0				N/A EQUIPMENT NOT INSTALLED
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
231200A	GENERAL VISUAL INSPECTION OF THE SYSTEM COMPONENTS AND WIRING							Service ATA:23
PN:PN	MOS/MSC	07-Jul-04	N/A					N/A EQUIPMENT NOT INSTALLED
SN:UNKNOWN	HRS	0						
	AFL	0						
PROC. REF: AMM 23-12-04PROC. REF: AMM 23-12-04								
231200B	CHECK NITROGEN PRESSURE OF THE ANTENNA COUPLER. THE PRESSURE SHOULD BE MEASURED AT THE VALVE ADJACENT TO P10522. WHEN MEASURED AT ROOM TEMPERATURE, IT SHOULD BE BETWEEN 8 AND 10 PSIG (55 TO 69 KPA GAUGE). IF BELOW 8 PSIG, ADD NITROGEN TO BRING THE PRESSURE UP TO 8 TO 10 PSIG.							Service ATA:23
PN:PN	MOS/MSC	07-Jul-04	N/A					N/A EQUIPMENT NOT INSTALLED
SN:UNKNOWN	HRS	0						
	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
231201	RENEWAL OF RADIO STATION LICENCE							Service ATA:23
	MOS/MSC	07-Jul-04	-					
	HRS	0						
	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
231300	MAGNASTAR PHONE TRANSCEIVER							Component ATA:23
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
231305	MAGNASTAR ANTENNA							Component ATA:23
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
231307	COCKPIT PHONE							Component ATA:23
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
231308	CABIN PHONE							Component ATA:23
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
231310	ARTU TRAY							Component ATA:23
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
231313	NO. 1 CABIN DISTRIBUTION BUS REPEATER							Component ATA:23
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
231314	NO. 2 CABIN DISTRIBUTION BUS REPEATER							Component ATA:23
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
231315	CALL ALERTER SWITCH (CAS)							Component ATA:23
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
231320	NO. 1 CABIN IRIDIUM SATCOM HANDSET							Component ATA:23
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
231321	NO. 2 CABIN IRIDIUM SATCOM HANDSET							Component ATA:23
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
231322	CABIN IRIDIUM SATCOM PHONE CRADLE							Component ATA:23
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
231323	IRIDIUM SATCOM TRANSCEIVER							Component ATA:23
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
231325	IRIDIUM SATCOM SONALERT							Component ATA:23
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45
Serial: 45-252
RegNo: N253SC
HRS: 5455.2
AFL: 4545
As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
231327		COCKPIT IRIDIUM SATCOM PHONE CRADLE					Component	ATA:23
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
231328		COCKPIT IRIDIUM SATCOM HANDSET					Component	ATA:23
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
231330		FORWARD IRIDIUM SATCOM ANTENNA					Component	ATA:23
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
231331		AFT IRIDIUM SATCOM ANTENNA					Component	ATA:23
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
231335		COCKPIT IRIDIUM SATCOM BASE UNIT					Component	ATA:23
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
231336		AFT IRIDIUM SATCOM BASE UNIT					Component	ATA:23
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
231351	SATELLITE DATA UNIT (SDU)							Component ATA:23
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
232120	UNILINK ANTENNA							Component ATA:23
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
233001	FORWARD CABIN VIDEO MONITOR							Component ATA:23
PN:AI-LCD104-04-1	MOS/MSC	09-Sep-04	O/C	TSN 0				
SN:0404000753	HRS	16		TSN 0				
	AFL	12		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
233002	AFT CABIN VIDEO MONITOR							Component ATA:23
PN:AI-LCD104-04-1	MOS/MSC	09-Jul-24	O/C					
SN:020500185	HRS	5131						
	AFL	4323						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
233003	AUDIO DISTRIBUTION MODULE							Component ATA:23
PN:AV-4589-01-1	MOS/MSC	19-Jul-09	O/C					
SN:080400253	HRS	1789.5						
	AFL	1483						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
233005	PUBLIC ADDRESS SYSTEM AMPLIFER							Component ATA:23
PN:PA-7501-01-1	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:020400821	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-30-02PROC. REF: AMM 23-30-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
233010	INFRARED REMOTE RECEIVER MODULE							Component ATA:23
PN:IFR-485-05-1	MOS/MSC	09-Sep-04	O/C	TSN 0				
SN:070400234	HRS	16		TSN 0				
	AFL	12		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
233015	AUDIO/VIDEO CONTROLLER							Component ATA:23
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
233053	DVD PLAYER							Component ATA:23
PN:DVD-511-01-1	MOS/MSC	23-Feb-16	O/C					
SN:061500037	HRS	3537						
	AFL	2921						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
233054	CD PLAYER CHANGER							Component ATA:23
PN:MCD-102-RU-3	MOS/MSC	09-Sep-04	O/C	TSN 0				
SN:040400112	HRS	16		TSN 0				
	AFL	12		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
233055	CD PLAYER CONTROL UNIT							Component ATA:23
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
233056	CASSETTE TAPE PLAYER							Component ATA:23
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
233101	LEFT FORWARD CABIN SPEAKER							Component ATA:23
PN:30700011	MOS/MSC	09-Sep-04	O/C	TSN 0				
SN:080400051	HRS	16		TSN 0				
	AFL	12		TSN 0				
PROC. REF: AMM 23-30-01PROC. REF: AMM 23-30-01								
233102	RIGHT FORWARD CABIN SPEAKER							Component ATA:23
PN:30700011	MOS/MSC	09-Sep-04	O/C	TSN 0				
SN:080400050	HRS	16		TSN 0				
	AFL	12		TSN 0				
PROC. REF: AMM 23-30-01PROC. REF: AMM 23-30-01								
233103	LEFT AFT CABIN SPEAKER							Component ATA:23
PN:30700011	MOS/MSC	09-Sep-04	O/C	TSN 0				
SN:080400064	HRS	16		TSN 0				
	AFL	12		TSN 0				
PROC. REF: AMM 23-30-01PROC. REF: AMM 23-30-01								
233104	RIGHT AFT CABIN SPEAKER							Component ATA:23
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-30-01PROC. REF: AMM 23-30-01								
233105	SUBWOOFER SPEAKER							Component ATA:23
PN:EN-646-W	MOS/MSC	09-Sep-04	O/C	TSN 0				
SN:040400508	HRS	16		TSN 0				
	AFL	12		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
233201	PASSENGER INTERFACE UNIT							Component ATA:23
PN:PIU-45-04-1	MOS/MSC	17-Oct-07	O/C	TSN 0				
SN:110400774	HRS	1174.8		TSN 0				
	AFL	963		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

? - Insufficient Information
S - Suppressed Requirement
* - Estimated Due(New Requirement)
(EFF) - Effective C/W
(M) - Manual Due
U - User Task
Ex - Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
234000	INTERPHONE JACK BOX ASSEMBLY							Component ATA:23
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
235001	NO. 1 AUDIO CONTROL UNIT							Component ATA:23
PN:7511001-937	MOS/MSC	05-Jun-15	O/C	TSN 131				
SN:04059348	HRS	3395.9		TSN 3395.9				
	AFL	2798		TSN 2798				
PROC. REF: AMM 23-50-01PROC. REF: AMM 23-50-01								
235002	NO. 2 AUDIO CONTROL UNIT							Component ATA:23
PN:7511001-937	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:04059345	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-50-01PROC. REF: AMM 23-50-01								
235013	LEFT COCKPIT SPEAKER							Component ATA:23
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-50-03PROC. REF: AMM 23-50-03								
235014	RIGHT COCKPIT SPEAKER							Component ATA:23
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-50-03PROC. REF: AMM 23-50-03								
236001	STATIC INVERTER							Component ATA:23
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
236005	XM RADIO WEATHER RECEIVER							Component ATA:23
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
236010	XM RADIO WEATHER DATA PORT							Component ATA:23
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
236012	XM RADIO WEATHER ANTENNA							Component ATA:23
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
236015	XM RADIO ANTENNA							Component ATA:23
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
236020	GDC34 CONVERTER							Component ATA:23
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
236025	AIRSERV TRANSMITTER							Component ATA:23
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information

S-Suppressed Requirement

*-Estimated Due(New Requirement)

(EFF)-Effective C/W

(M)-Manual Due

U-User Task

Ex-Excluded Task

Status Report

Model: LEARJET 45
Serial: 45-252
RegNo: N253SC
HRS: 5455.2
AFL: 4545
As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
236096	NO. 1 NAVIGATION STRAP BOARD							Component ATA:23
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-51-05PROC. REF: AMM 34-51-05								
236097	NO. 2 NAVIGATION STRAP BOARD							Component ATA:23
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-51-05PROC. REF: AMM 34-51-05								
236098	NO. 1 COMMUNICATION STRAP BOARD							Component ATA:23
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-11-03PROC. REF: AMM 23-11-03								
236099	NO. 2 COMMUNICATION STRAP BOARD							Component ATA:23
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-11-03PROC. REF: AMM 23-11-03								
237001	COCKPIT VOICE RECORDER (CVR)							Component ATA:23
PN:980-6020-011	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:CVR30-04043	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-70-01PROC. REF: AMM 23-70-01								
237001A	INTELLIGIBILITY CHECK CVR							Service ATA:23
PN:980-6020-011	MOS/MSC	07-Jul-04	A/R					
SN:CVR30-04043	HRS	0						
	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45
Serial: 45-252
RegNo: N253SC
HRS: 5455.2
AFL: 4545
As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
237005		COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON (CVR ULB)						Component ATA:23
PN:DK120	MOS/MSC	13-Sep-18	O/C					
SN:AT120124	HRS	4046.7						
	AFL	3423						
PROC. REF: AMM 25-61-01PROC. REF: AMM 25-61-01								
237005C ^U		RECERTIFY CVR PER MANUFACTURER'S INSTRUCTIONS						Service ATA:23
PN:DK120	MOS	13-Sep-18	216		30-Sep-36		3722 d	
SN:AT120124	HRS	4046.7						
	AFL	3423						
237018		COCKPIT VOICE RECORDER (CVR) INERTIA SWITCH						Component ATA:23
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-70-05PROC. REF: AMM 23-70-05								
237019		COCKPIT AREA MICROPHONE						Component ATA:23
PN:980-6113-001	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:2569	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
237030		PANEL SWITCH						Component ATA:23
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
237031		COCKPIT VOICE RECORDER PRE-AMPLIFIER						Component ATA:23
PN:980-6118-001	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:CAMP-RAMP-0052	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-70-03PROC. REF: AMM 23-70-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 23 - COMMUNICATIONS									
238001	NO. 1 RADIO MANAGEMENT UNIT (RMU)							Component	ATA:23
PN:7013270-975	MOS/MSC	13-Dec-18	O/C	TSR 134					
SN:01032922	HRS	4087.6	TSR 2912.8						
	AFL	3466	TSR 2503						
PROC. REF: AMM 23-80-01PROC. REF: AMM 23-80-01									
238002	NO. 2 RADIO MANAGEMENT UNIT (RMU)							Component	ATA:23
PN:7013270-975	MOS/MSC	13-Dec-18	O/C	TSN 171					
SN:04064285	HRS	4087.6	TSN 4071.6						
	AFL	3466	TSN 3454						
PROC. REF: AMM 23-80-01PROC. REF: AMM 23-80-01									
238025	CLEARANCE DELIVERY UNIT							Component	ATA:23
PN:7513000-835	MOS/MSC	07-Jul-04	O/C	TSN 0					
SN:0405934	HRS	0	TSN 0						
	AFL	0	TSN 0						
PROC. REF: AMM 23-82-01PROC. REF: AMM 23-82-01									
239004	MASTER CONTROL SWITCH							Component	ATA:23
PN:SP-45-52	MOS/MSC	17-Oct-07	O/C	TSN 0					
SN:120300273	HRS	1174.8	TSN 0						
	AFL	963	TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
239011	LAVATORY MASTER CONTROL SWITCH							Component	ATA:23
PN:SP-45-55	MOS/MSC	23-Jul-09	O/C	TSN 0					
SN:120400660	HRS	1793.6	TSN 0						
	AFL	1488	TSN 0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
A2300000 ^S	** COMMUNICATION SYSTEMS - PERFORM OPERATIONAL CHECK							Service	ATA:23
	MOS	09-Jul-24	24 (+14d/-14d)	AIRWORTHINESS					
	HRS	5131.8	600 (+25/-25)						
	AFL	4323							
PROC. REF: AMM 23-00-00PROC. REF: AMM 23-00-00									
PKG:7									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
V2312003	^S	HF ANTENNA - PERFORM VISUAL INSPECTION. CHECK FOR PROPER TENSION OF HF ANTENNA WIRE.						Service ATA:23
	MOS	24-Feb-23	48 (+14d/-14d)					
	HRS	5067.1	1200 (+25/-25)					
	AFL	4262						
PROC. REF: AMM 23-12-04PROC. REF: AMM 23-12-04								PKG:14
Y2360020	^S	AIRCRAFT STATIC DISCHARGERS - PERFORM FUNCTIONAL TEST						Service ATA:23
	MOS	01-Mar-19	96 (+14d/-14d)					
	HRS	4123.3	2400 (+25/-25)					
	AFL	3499						
PROC. REF: AMM 23-60-00PROC. REF: AMM 23-60-00								PKG:20
Y2360023	^S	AIRCRAFT STATIC DISCHARGERS - PERFORM FUNCTIONAL TEST						Service ATA:23
	MOS	01-Mar-19	96 (+14d/-14d)					
	HRS	4123.3	2400 (+25/-25)					
	AFL	3499						
PROC. REF: AMM 23-60-00PROC. REF: AMM 23-60-00								PKG:22
ATA 24 - ELECTRICAL POWER								
240109		AFT CIRCUIT BREAKER PANEL						Component ATA:24
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-60-04PROC. REF: AMM 24-60-04								
242000		NO. 1 ALTERNATOR						Component ATA:24
PN:90278-2	MOS/MSC	18-Nov-21	O/C	TSO 0				
SN:1230	HRS	4737		TSO 0				
	AFL	3987		TSO 0				
PROC. REF: AMM 24-20-01PROC. REF: AMM 24-20-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
242001	NO. 2 ALTERNATOR							Component ATA:24
PN:90278-2	MOS/MSC	18-Nov-21	O/C	TSO 0				
SN:1526	HRS	4737		TSO 0				
	AFL	3987		TSO 0				
PROC. REF: AMM 24-20-01PROC. REF: AMM 24-20-01								
242008	AC/DC VOLT INDICATOR							Component ATA:24
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
242050	NO. 1 REMOTE CONTROL CIRCUIT BREAKER							Component ATA:24
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-60-01PROC. REF: AMM 24-60-01								
242052	NO. 2 REMOTE CONTROL CIRCUIT BREAKER							Component ATA:24
PN:SM600BA75N1	MOS/MSC	09-Sep-04	O/C	TSN 0				
SN:46452	HRS	16		TSN 0				
	AFL	12		TSN 0				
PROC. REF: AMM 24-60-01PROC. REF: AMM 24-60-01								
242054	NO. 3 REMOTE CONTROL CIRCUIT BREAKER							Component ATA:24
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-60-01PROC. REF: AMM 24-60-01								
242081	CABIN ELECTRICAL INVERTER							Component ATA:24
PN:2D1200-1A-011	MOS/MSC	30-Nov-12	O/C	TSR 4				
SN:GB001441	HRS	2813.5		TSR 0				
	AFL	2326		TSR 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45
Serial: 45-252
RegNo: N253SC
HRS: 5455.2
AFL: 4545
As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
242082	TAILCONE ELECTRICAL INVERTER							Component ATA:24
PN:PN	MOS/MSC	07-Jul-04	A/R	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
242083	ELECTRICAL INVERTER							Component ATA:24
PN:PN	MOS/MSC	07-Jul-04	A/R	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
243001	NO. 1 STARTER/GENERATOR							Component ATA:24
PN:23280-067	MOS/MSC	11-Apr-25	O/C	TSO 0				
SN:991175	HRS	5257.4		TSO 0				
	AFL	4421		TSO 0				
PROC. REF: AMM 24-30-01PROC. REF: AMM 24-30-01								
243002	NO. 2 STARTER/GENERATOR							Component ATA:24
PN:23280-067	MOS/MSC	11-Apr-25	O/C	TSO 0				
SN:Y0514	HRS	5257.4		TSO 0				
	AFL	4421		TSO 0				
PROC. REF: AMM 24-30-01PROC. REF: AMM 24-30-01								
243003	APU STARTER/GENERATOR							Component ATA:24
PN:6608458-010	MOS/MSC	25-Aug-23	O/C	TSO 0				
SN:98231	HRS	5106.9		TSO 0				
	AFL	4299		TSO 0				
PROC. REF: AMM 49-40-01PROC. REF: AMM 49-40-01								
243005	LEFT GENERATOR CONTROL UNIT (GCU)							Component ATA:24
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45
Serial: 45-252
RegNo: N253SC
HRS: 5455.2
AFL: 4545
As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
243006	RIGHT GENERATOR CONTROL UNIT (GCU)							Component ATA:24
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
243019	NO. 1 MAIN BATTERY							Component ATA:24
PN:RG-380E/40L	MOS	09-Jul-24	48 (+1m/-1m)	TSN 29	28-Feb-26	09-Mar-26	OVD	LIFE LIMIT
SN:41195100	HRS	5131		TSN 311.5				
	AFL	4323		TSN 274				
PROC. REF: AMM 24-31-01, AMM 24-31-06, CMM 24-30-71PROC. REF: AMM 24-31-01, AMM 24-31-06, CMM 24-30-71								
243019B	NO. 1 MAIN BATTERY - OVERHAUL							Service ATA:24
PN:RG-380E/40L	MOS/MSC		N/A					
SN:41195100	HRS							
	AFL							
PROC. REF: AMM 24-31-01PROC. REF: AMM 24-31-01								
243019C	NO. 1 VARTA BATTERY TEMPERATURE SWITCH							Component ATA:24
PN:PN	MOS/MSC	07-Jul-04	N/A	TSN 0				N/A EQUIPMENT NOT INSTALLED
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
243020	NO. 2 MAIN BATTERY							Component ATA:24
PN:RG-380E/40L	MOS	09-Jul-24	48 (+1m/-1m)	TSN 29	28-Feb-26	09-Mar-26	OVD	LIFE LIMIT
SN:41195098	HRS	5131		TSN 311.5				
	AFL	4323		TSN 274				
PROC. REF: CMM 24-30-71PROC. REF: CMM 24-30-71								
243020B	NO. 2 MAIN BATTERY - OVERHAUL							Service ATA:24
PN:RG-380E/40L	MOS/MSC		N/A					
SN:41195098	HRS							
	AFL							
PROC. REF: AMM 24-31-01PROC. REF: AMM 24-31-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
243020C	NO. 2 VARTA BATTERY TEMPERATURE SWITCH							Component ATA:24
PN:PN	MOS/MSC	07-Jul-04	N/A	TSN 0				N/A EQUIPMENT NOT INSTALLED
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
243037	EMERGENCY BATTERY							Component ATA:24
PN:RG443	MOS/MSC	15-Oct-25	H/T	TSN 0				
SN:41475043-41475043,44.45	HRS	5343		TSN 0				
	AFL	4470		TSN 0				
PROC. REF: AMM 24-32-01, CMM 24-30-67PROC. REF: AMM 24-32-01, CMM 24-30-67								
246001	LEFT FORWARD POWER DISTRIBUTION PANEL							Component ATA:24
PN:650GC02Y03	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:328	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-60-02PROC. REF: AMM 24-60-02								
246002	RIGHT FORWARD POWER DISTRIBUTION PANEL							Component ATA:24
PN:650GC02Y03	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:333	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-60-02PROC. REF: AMM 24-60-02								
246003	LEFT AFT POWER DISTRIBUTION PANEL							Component ATA:24
PN:660GC02Y07	MOS/MSC	26-Apr-24	O/C	TSR 0				
SN:890	HRS	5128.5		TSR 0				
	AFL	4317		TSR 0				
PROC. REF: AMM 24-60-03PROC. REF: AMM 24-60-03								
246004	RIGHT AFT POWER DISTRIBUTION PANEL							Component ATA:24
PN:700GC02Y07	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:412	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-60-03PROC. REF: AMM 24-60-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
246101	LEFT GENERATOR CONTROL UNIT PRINTED CIRCUIT BOARD							Component ATA:24
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
246102	LEFT LOGIC PRINTED CIRCUIT BOARD							Component ATA:24
PN:790CE01Y04	MOS/MSC	22-Jul-05	O/C					
SN:747	HRS	399.4		TSR 0				
	AFL	324		TSR 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
246104	RIGHT GENERATOR CONTROL UNIT PRINTED CIRCUIT BOARD							Component ATA:24
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
246105	RIGHT LOGIC PRINTED CIRCUIT BOARD							Component ATA:24
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
246106	APU GENERATOR CONTROL UNIT PRINTED CIRCUIT BOARD							Component ATA:24
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
AB2431062	EMERGENCY BATTERY - PERFORM CAPACITY CHECK							Service ATA:24
PN:RG443	MOS		12		?		?	
SN:41475043-41475043,44.45	HRS		1000 (+100/-100)		?			
	AFL							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
AB2431063	EMERGENCY BATTERY - REPLACE							Service ATA:24
PN:RG443	MOS/MSC	15-Oct-25	N/A					
SN:41475043-41475043,44.45	HRS	5343						
	AFL	4470						
AC2460002 ^S	REMOVE ATTACHING PARTS SECURING CIRCUIT BREAKER PANEL TO STRUCTURE. CHECK FOR LOOSE CIRCUIT BREAKER TERMINALS, LOOSE WIRE TERMINALS, CORRODED TERMINALS OR BUS BARS, AND EVIDENCE OF WIRE INSULATION DAMAGE.							Service ATA:24
	MOS	07-Jul-04	96 (+14d/-14d)					
	HRS	0	2400 (+25/-25)					
	AFL	0						
								PKG:19
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
B2450002 ^S	** ELECTRICAL SYSTEM CONTROL - PERFORM OPERATIONAL CHECK							Service ATA:24
	MOS	24-Feb-23	48 (+14d/-14d)					AIRWORTHINESS
	HRS	5067.1	1200 (+25/-25)					
	AFL	4262						
								PKG:13
PROC. REF: AMM 24-00-00PROC. REF: AMM 24-00-00								
F2420000	** NO. 1 ALTERNATOR - PERFORM BEARING REPLACEMENT							Service ATA:24
PN:90278-2	MOS	18-Nov-21						AIRWORTHINESS
SN:1230	HRS	4737	1200 (+25/-25)		5937	5962	481.8 (+25)	
	AFL	3987						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
F2420000	** NO. 2 ALTERNATOR - PERFORM BEARING REPLACEMENT							Service ATA:24
PN:90278-2	MOS	18-Nov-21						AIRWORTHINESS
SN:1526	HRS	4737	1200 (+25/-25)		5937	5962	481.8 (+25)	
	AFL	3987						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
H2450001	S	** AUXILIARY POWER SUPPLIES - PERFORM FUNCTIONAL TEST						Service ATA:24
	MOS	09-Jul-24	24 (+14d/-14d)					AIRWORTHINESS
	HRS	5131.8	600 (+25/-25)					
	AFL	4323						
PROC. REF: AMM 24-00-00PROC. REF: AMM 24-00-00								PKG:7
H2450023	S	** EMER BATT LOW AND GEN AMPS HIGH INDICATION - PERFORM OPERATIONAL CHECK						Service ATA:24
	MOS	09-Jul-24	24 (+14d/-14d)					AIRWORTHINESS
	HRS	5131.8	600 (+25/-25)					
	AFL	4323						
PROC. REF: AMM 24-00-00PROC. REF: AMM 24-00-00								PKG:7
O2431002	EMERGENCY BATTERY - PERFORM CAPACITY CHECK							Service ATA:24
PN:RG443	MOS/MSC	N/A						
SN:41475043-41475043,44.45	HRS							
	AFL							
PROC. REF: CMM 24-30-67PROC. REF: CMM 24-30-67								
P2430003	NO. 1 STARTER/GENERATOR - PERFORM OVERHAUL							Service ATA:24
PN:23280-067	MOS	11-Apr-25						
SN:991175	HRS	5257.4	1200 (+25/-25)		6457.4	6482.4	1002.2 (+25)	
	AFL	4421						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
P2430003	NO. 2 STARTER/GENERATOR - PERFORM OVERHAUL							Service ATA:24
PN:23280-067	MOS	11-Apr-25						
SN:Y0514	HRS	5257.4	1200 (+25/-25)		6457.4	6482.4	1002.2 (+25)	
	AFL	4421						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
P2430007	NO. 1 STARTER/GENERATOR - REPLACE BEARINGS							Service ATA:24
PN:23280-067	MOS/MSC	N/A						
SN:991175	HRS							
	AFL							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
P2430007	NO. 2 STARTER/GENERATOR - REPLACE BEARINGS							Service ATA:24
PN:23280-067	MOS/MSC		N/A					
SN:Y0514	HRS							
	AFL							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
Q2460001 ^S	** POWER DISTRIBUTION SYSTEM - PERFORM SQUAT SWITCH CHECK							Service ATA:24
	MOS	24-Feb-23	48 (+14d/-14d)					AIRWORTHINESS
	HRS	5067.1	1200 (+25/-25)					
	AFL	4262						
PROC. REF: AMM 24-60-00PROC. REF: AMM 24-60-00								PKG:17
R2431003 ^S	** BATTERY WARNING SYSTEM - PERFORM FUNCTIONAL TEST							Service ATA:24
	MOS/MSC	01-Mar-19	N/A					
	HRS	4123.3						
	AFL	3499						
PROC. REF: AMM 24-31-00PROC. REF: AMM 24-31-00								PKG:19
W2450000 ^S	** GENERATOR FAIL INDICATION - PERFORM OPERATIONAL CHECK							Service ATA:24
	MOS	09-Jul-24	24 (+14d/-14d)					AIRWORTHINESS
	HRS	5131.8	600 (+25/-25)					
	AFL	4323						
PROC. REF: AMM 24-00-00PROC. REF: AMM 24-00-00								PKG:7
Y2400001 ^S	SWITCH AND CIRCUIT BREAKER PANELS - PERFORM VISUAL INSPECTION							Service ATA:24
	MOS	24-Feb-23	48 (+14d/-14d)					
	HRS	5067.1	1200 (+25/-25)					
	AFL	4262						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								PKG:13

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
Y2400002	^S	ELECTRICAL WIRING - PERFORM VISUAL INSPECTION FOR ROUTING, SECURITY, CLEARANCES, CHAFING, AND ELECTRICAL COMPONENTS FOR SECURITY AND GENERAL CONDITION.						Service ATA:24
	MOS	09-Jul-24	24 (+14d/-14d)					
	HRS	5131.8	600 (+25/-25)					
	AFL	4323						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								PKG:7
Y2400025	^S	ELECTRICAL WIRING - PERFORM VISUAL INSPECTION FOR ROUTING, SECURITY, CLEARANCES, CHAFING, AND ELECTRICAL COMPONENTS FOR SECURITY AND GENERAL CONDITION.						Service ATA:24
	MOS	09-Jul-24	24 (+14d/-14d)					
	HRS	5131.8	600 (+25/-25)					
	AFL	4323						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								PKG:8
Y2430005	^S	STARTER/GENERATOR - PERFORM GROUNDING LUG BONDING CHECK						Service ATA:24
	MOS	09-Jul-24	24 (+14d/-14d)					
	HRS	5131.8	600 (+25/-25)					
	AFL	4323						
PROC. REF: AMM 24-30-01PROC. REF: AMM 24-30-01								PKG:9
Y2430006	^S	STARTER/GENERATOR - PERFORM VISUAL INSPECTION OF GROUNDING LUGS						Service ATA:24
	MOS	09-Jul-24	24 (+14d/-14d)					
	HRS	5131.8	600 (+25/-25)					
	AFL	4323						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								PKG:9
Y2431000	^S	BATTERY, GENERATOR, AND BUS-TIE CABLES - PERFORM VISUAL INSPECTION						Service ATA:24
	MOS	01-Mar-19	96 (+14d/-14d)					
	HRS	4123.3	2400 (+25/-25)					
	AFL	3499						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								PKG:20

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45
Serial: 45-252
RegNo: N253SC
HRS: 5455.2
AFL: 4545
As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
Y2431001	^S	EMERGENCY BATTERY CABLES - PERFORM VISUAL INSPECTION						Service ATA:24
	MOS	09-Jul-24	24 (+14d/-14d)					
	HRS	5131.8	600 (+25/-25)					
	AFL	4323						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								PKG:7
Y2431005		BATTERY CABLES AND RECEPTACLES - PERFORM BATTERY CONNECTOR TOLERANCE CHECK						Service ATA:24
	MOS	24-Feb-23						
	HRS	5067.1	300 (+25/-25)		5367.1	5392.1	OVD	
	AFL	4262						
PROC. REF: AMM 24-31-00PROC. REF: AMM 24-31-00								
Y2460000	^S	DC BUS ISOLATION - PERFORM OPERATIONAL CHECK						Service ATA:24
	MOS	24-Feb-23	48 (+14d/-14d)					
	HRS	5067.1	1200 (+25/-25)					
	AFL	4262						
PROC. REF: AMM 24-60-00PROC. REF: AMM 24-60-00								PKG:13
ATA 25 - EQUIPMENT/FURNISHINGS								
250010		RELAY MODULE						Component ATA:25
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
252000		JUMP SEAT						Component ATA:25
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-20-45PROC. REF: AMM 25-20-45								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
252000	NO. 1 PASSENGER SEAT							Component ATA:25
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-20-45PROC. REF: AMM 25-20-45								
252000	NO. 2 PASSENGER SEAT							Component ATA:25
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-20-45PROC. REF: AMM 25-20-45								
252000	NO. 3 PASSENGER SEAT							Component ATA:25
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-20-45PROC. REF: AMM 25-20-45								
252000	NO. 4 PASSENGER SEAT							Component ATA:25
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-20-45PROC. REF: AMM 25-20-45								
252000	NO. 5 PASSENGER SEAT							Component ATA:25
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-20-45PROC. REF: AMM 25-20-45								
252000	NO. 6 PASSENGER SEAT							Component ATA:25
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-20-45PROC. REF: AMM 25-20-45								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
252000	NO. 7 PASSENGER SEAT							Component ATA:25
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-20-45PROC. REF: AMM 25-20-45								
252000	NO. 8 PASSENGER SEAT							Component ATA:25
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-20-45PROC. REF: AMM 25-20-45								
252001	LAVATORY PCU							Component ATA:25
PN:PN	MOS/MSC	07-Jul-04	A/R	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-20-45PROC. REF: AMM 25-20-45								
252001	NO. 1 PASSENGER SEAT PCU							Component ATA:25
PN:SP-45-54	MOS/MSC	17-Oct-07	O/C	TSN 0				
SN:060400446	HRS	1174.8		TSN 0				
	AFL	963		TSN 0				
PROC. REF: AMM 25-20-45PROC. REF: AMM 25-20-45								
252001	NO. 2 PASSENGER SEAT PCU							Component ATA:25
PN:SP-45-54	MOS/MSC	17-Oct-07	O/C	TSN 0				
SN:060400873	HRS	1174.8		TSN 0				
	AFL	963		TSN 0				
PROC. REF: AMM 25-20-45PROC. REF: AMM 25-20-45								
252001	NO. 3 PASSENGER SEAT PCU							Component ATA:25
PN:SP-45-54	MOS/MSC	17-Oct-07	O/C	TSN 0				
SN:060400871	HRS	1174.8		TSN 0				
	AFL	963		TSN 0				
PROC. REF: AMM 25-20-45PROC. REF: AMM 25-20-45								

? - Insufficient Information
S - Suppressed Requirement
* - Estimated Due(New Requirement)
(EFF) - Effective C/W
(M) - Manual Due
U - User Task
Ex - Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
252001	NO. 4 PASSENGER SEAT PCU							Component ATA:25
PN:SP-45-54	MOS/MSC	23-Jul-09	O/C	TSN 0				
SN:040300417	HRS	1793.6		TSN 0				
	AFL	1488		TSN 0				
PROC. REF: AMM 25-20-45PROC. REF: AMM 25-20-45								
252001	NO. 5 PASSENGER SEAT PCU							Component ATA:25
PN:SP-45-54	MOS/MSC	17-Oct-07	O/C	TSN 0				
SN:090600455	HRS	1174.8		TSN 0				
	AFL	963		TSN 0				
PROC. REF: AMM 25-20-45PROC. REF: AMM 25-20-45								
252001	NO. 6 PASSENGER SEAT PCU							Component ATA:25
PN:SP-45-54	MOS/MSC	17-Oct-07	O/C	TSN 0				
SN:110600656	HRS	1174.8		TSN 0				
	AFL	963		TSN 0				
PROC. REF: AMM 25-20-45PROC. REF: AMM 25-20-45								
252001	NO. 7 PASSENGER SEAT PCU							Component ATA:25
PN:SP-45-54	MOS/MSC	17-Oct-07	O/C	TSN 0				
SN:060400872	HRS	1174.8		TSN 0				
	AFL	963		TSN 0				
PROC. REF: AMM 25-20-45PROC. REF: AMM 25-20-45								
252001	NO. 8 PASSENGER SEAT PCU							Component ATA:25
PN:SP-45-54	MOS/MSC	17-Oct-07	O/C	TSN 0				
SN:060400868	HRS	1174.8		TSN 0				
	AFL	963		TSN 0				
PROC. REF: AMM 25-20-45PROC. REF: AMM 25-20-45								
252003	NO. 1 STORAGE BOX							Component ATA:25
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-20-32PROC. REF: AMM 25-20-32								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
252003	NO. 2 STORAGE BOX							Component ATA:25
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-20-32PROC. REF: AMM 25-20-32								
252003	NO. 3 STORAGE BOX							Component ATA:25
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-20-32PROC. REF: AMM 25-20-32								
252003	NO. 4 STORAGE BOX							Component ATA:25
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-20-32PROC. REF: AMM 25-20-32								
252003	NO. 5 STORAGE BOX							Component ATA:25
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-20-32PROC. REF: AMM 25-20-32								
252003	NO. 6 STORAGE BOX							Component ATA:25
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-20-32PROC. REF: AMM 25-20-32								
252003	NO. 7 STORAGE BOX							Component ATA:25
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-20-32PROC. REF: AMM 25-20-32								

?-Insufficient Information
 S-Suppressed Requirement
 *-Estimated Due(New Requirement)
 (EFF)-Effective C/W
 (M)-Manual Due
 U-User Task
 Ex-Excluded Task

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
252003	NO. 8 STORAGE BOX							Component ATA:25
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-20-32PROC. REF: AMM 25-20-32								
252010	AIRSHOW COMPUTER							Component ATA:25
PN:920040	MOS/MSC	18-Aug-23	O/C					
SN:495	HRS	5089.1						
	AFL	4280						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
252012	AIRSHOW SWITCH							Component ATA:25
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
252015	INFRARED SENSOR							Component ATA:25
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
252020	CLOSET SWITCH PANEL ASSEMBLY							Component ATA:25
PN:SP-45-21	MOS/MSC	09-Sep-04	O/C	TSN 0				
SN:060401032	HRS	16		TSN 0				
	AFL	12		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
252090	NO. 1 110 VOLT POWER OUTLET							Component ATA:25
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information

S-Suppressed Requirement

*-Estimated Due(New Requirement)

(EFF)-Effective C/W

(M)-Manual Due

U-User Task

Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
252091	NO. 2 110 VOLT POWER OUTLET							Component ATA:25
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
252092	NO. 3 110 VOLT POWER OUTLET							Component ATA:25
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
252095	NO. 4 110 VOLT POWER OUTLET							Component ATA:25
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
252097	NO. 1 AC POWER OUTLET							Component ATA:25
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
252098	NO. 2 AC POWER OUTLET							Component ATA:25
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
252099	NO. 3 AC POWER OUTLET							Component ATA:25
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
253001	MICROWAVE OVEN							Component ATA:25
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
253075	NO. 1 HEATED WATER CONTAINER							Component ATA:25
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
253076	NO. 2 HEATED WATER CONTAINER							Component ATA:25
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
253077	HEATED WATER SWITCH							Component ATA:25
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
253080	GALLEY DRAIN VALVE SOLENOID							Component ATA:25
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
256001	PILOT CREW SEAT							Component ATA:25
PN:4525103038-007	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:590	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-10-50PROC. REF: AMM 25-10-50								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
256002	COPILOT CREW SEAT							Component ATA:25
PN:4525103038-008	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:603	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-10-50PROC. REF: AMM 25-10-50								
256061	PILOTS LIFE VEST							Component ATA:25
PN:P01074-103	MOS/MSC	09-Jul-24	O/C	TSN 0				
SN:23031140005	HRS	5131		TSN 0				
	AFL	4323		TSN 0				
PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01								
256062	COPILOTS LIFE VEST							Component ATA:25
PN:P01074-103	MOS/MSC	09-Jul-24	O/C	TSN 0				
SN:23031140006	HRS	5131		TSN 0				
	AFL	4323		TSN 0				
PROC. REF: CMM 25-60-05PROC. REF: CMM 25-60-05								
256063	NO. 1 PASSENGER LIFE VEST							Component ATA:25
PN:P01074-103	MOS/MSC	09-Jul-24	O/C	TSN 0				
SN:23031140116	HRS	5131		TSN 0				
	AFL	4323		TSN 0				
PROC. REF: CMM 25-60-05PROC. REF: CMM 25-60-05								
256064	NO. 2 PASSENGER LIFE VEST							Component ATA:25
PN:P01074-103	MOS/MSC	09-Jul-24	O/C	TSN 0				
SN:23031140131	HRS	5131		TSN 0				
	AFL	4323		TSN 0				
PROC. REF: CMM 25-60-05PROC. REF: CMM 25-60-05								
256065	NO. 3 PASSENGER LIFE VEST							Component ATA:25
PN:P01074-103	MOS/MSC	09-Jul-24	O/C	TSN 0				
SN:23031140160	HRS	5131		TSN 0				
	AFL	4323		TSN 0				
PROC. REF: CMM 25-60-05PROC. REF: CMM 25-60-05								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
256066	NO. 4 PASSENGER LIFE VEST							Component ATA:25
PN:P01074-103	MOS/MSC	09-Jul-24	O/C	TSN 0				
SN:23031140174	HRS	5131		TSN 0				
	AFL	4323		TSN 0				
PROC. REF: CMM 25-60-05PROC. REF: CMM 25-60-05								
256067	NO. 5 PASSENGER LIFE VEST							Component ATA:25
PN:P01074-103	MOS/MSC	26-Oct-22	O/C					
SN:12061910007	HRS	4984.7						
	AFL	4197						
PROC. REF: CMM 25-60-05PROC. REF: CMM 25-60-05								
256068	NO. 6 PASSENGER LIFE VEST							Component ATA:25
PN:P01074-103	MOS/MSC	26-Oct-22	O/C	TSN 124				
SN:12061910002	HRS	4984.7						
	AFL	4197						
PROC. REF: CMM 25-60-05PROC. REF: CMM 25-60-05								
256069	NO. 7 PASSENGER LIFE VEST							Component ATA:25
PN:P01074-103	MOS/MSC	26-Oct-22	O/C	TSN 124				
SN:12061910006	HRS	4984.7						
	AFL	4197						
PROC. REF: CMM 25-60-05PROC. REF: CMM 25-60-05								
256070	NO. 8 PASSENGER LIFE VEST							Component ATA:25
PN:P01074-103	MOS/MSC	26-Oct-22	O/C					
SN:12061910005	HRS	4984.7						
	AFL	4197						
PROC. REF: CMM 25-60-05PROC. REF: CMM 25-60-05								
256071	LAVATORY LIFE VEST							Component ATA:25
PN:P01074-103	MOS/MSC	26-Oct-22	O/C					
SN:12061910003	HRS	4984.7						
	AFL	4197						
PROC. REF: CMM 25-60-05PROC. REF: CMM 25-60-05								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
256074	LIFE RAFT							Component ATA:25
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
256074A	LIFE RAFT - INSPECT IAW MANUFACTURERS INSTRUCTIONS							Service ATA:25
PN:PN	MOS/MSC	05-Jul-22	-					
SN:UNKNOWN	HRS							
	AFL							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
256074B	LIFE RAFT - PERFORM HYDROSTATIC TEST OF CO2 CYLINDER IAW MANUFACTURERS INSTRUCTIONS							Service ATA:25
PN:PN	MOS/MSC	07-Jul-04	N/A					
SN:UNKNOWN	HRS	0						
	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
256074C	LIFE RAFT - REPLACE DAY/NIGHT FLARES IAW MANUFACTURERS INSTRUCTIONS							Service ATA:25
PN:PN	MOS/MSC	07-Jul-04	N/A					
SN:UNKNOWN	HRS	0						
	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
256076	FIRST AID KIT							Component ATA:25
PN:70002-00	MOS/MSC	29-Aug-23	O/C	TSN 0				
SN:10012026	HRS	5109.4		TSN 0				
	AFL	4301		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
256076A	FIRST AID KIT - VISUALLY INSPECT PER MANUFACTURER INSTRUCTIONS							Service ATA:25
PN:70002-00	MOS	31-Jul-25	12		31-Jul-26		8 d	
SN:10012026	HRS	5307.6						
	AFL	4448						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
256080	INSPECT LIFE VESTS							Service ATA:25
	MOS/MSC	22-Feb-21	A/R					
	HRS	4572.6						
	AFL	3864						
PROC. REF: GENERIC NO REF, CMM 25-60-05PROC. REF: GENERIC NO REF, CMM 25-60-05								
256080A	RECERTIFY LIFE VEST FOR CONTINUED SERVICE PER MANUFACTURER'S INSTRUCTIONS							Service ATA:25
	MOS/MSC	07-Jul-04	A/R					
	HRS	0						
	AFL	0						
PROC. REF: CMM 25-60-05PROC. REF: CMM 25-60-05								
256109	(ELT) EMERGENCY LOCATOR TRANSMITTER							Component ATA:25
PN:453-5000-366	MOS/MSC	24-Jul-23	O/C	TSR 0				
SN:07104	HRS	5076.3		TSR 0				
	AFL	4268		TSR 0				
PROC. REF: AMM 25-62-01PROC. REF: AMM 25-62-01								
256109A	(ELT) EMERGENCY LOCATOR TRANSMITTER - PERFORM NATIONALY REQUIRED FUNCTIONAL TEST							Service ATA:25
PN:453-5000-366	MOS	31-Jul-25	12 (+14d/-14d)		31-Jul-26	14-Aug-26	8 d (+14)	
SN:07104	HRS	5307.6						
	AFL	4448						
PROC. REF: AMM 25-62-00, FAR FAR 91.207PROC. REF: AMM 25-62-00, FAR FAR 91.207								
256109B	(ELT) EMERGENCY LOCATOR TRANSMITTER - INSPECT ELT BATTERIES							Service ATA:25
PN:453-5000-366	MOS	31-Jul-25	12 (+14d/-14d)		31-Jul-26	14-Aug-26	8 d (+14)	
SN:07104	HRS	5307.6						
	AFL	4448						
PROC. REF: AMM 25-62-00, FAR FAR 91.207PROC. REF: AMM 25-62-00, FAR FAR 91.207								
256109C	(ELT) EMERGENCY LOCATOR TRANSMITTER BATTERY - REPLACE							Service ATA:25
PN:453-5000-366	MOS	22-Feb-23	60		29-Feb-28		586 d	LIFE LIMIT
SN:07104	HRS							
	AFL							
PROC. REF: AMM 25-62-01, FAR FAR 91.207PROC. REF: AMM 25-62-01, FAR FAR 91.207								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45
Serial: 45-252
RegNo: N253SC
HRS: 5455.2
AFL: 4545
As Of: 23-Jul-2026
23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
256109D		(ELT) EMERGENCY LOCATOR TRANSMITTER - REPLACE ARTEX 110 REMOTE SWITCH BATTERY						Service ATA:25
PN:453-5000-366	MOS/MSC		N/A					
SN:07104	HRS							
	AFL							
PROC. REF: GENERIC NO REF, FAR FAR 91.207PROC. REF: GENERIC NO REF, FAR FAR 91.207								
256109F		(ELT) EMERGENCY LOCATOR TRANSMITTER - RENEW REGISTRATION						Service ATA:25
	MOS/MSC		A/R					
	HRS							
	AFL							
PROC. REF: MSC ELT REGISTRATIONPROC. REF: MSC ELT REGISTRATION								
256110		EMERGENCY LOCATOR TRANSMITTER (ELT)/NAVIGATION INTERFACE UNIT (C406-2)						Component ATA:25
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
256115		EMERGENCY LOCATOR TRANSMITTER (ELT) ANTENNA						Component ATA:25
PN:110-337	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:4014010	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-62-03PROC. REF: AMM 25-62-03								
256116		EMERGENCY LOCATOR TRANSMITTER (ELT) REMOTE SWITCH						Component ATA:25
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-62-04PROC. REF: AMM 25-62-04								
258001		CABIN AIRSHOW DISPLAY COMPUTER UNIT						Component ATA:25
PN:920040	MOS/MSC	09-Jul-24	O/C					
SN:624	HRS	5131						
	AFL	4323						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

? - Insufficient Information
S - Suppressed Requirement
* - Estimated Due(New Requirement)
(EFF) - Effective C/W
(M) - Manual Due
U - User Task
Ex - Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
259072	AUTOMATIC ELECTRONIC DEFIBRILLATOR (AED)							Component ATA:25
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
259072A	INSPECT AUTOMATIC ELECTRONIC DEFIBRILLATOR IAW MFG RECOMMENDATION.							Service ATA:25
PN:PN	MOS/MSC	07-Jul-04	N/A					
SN:UNKNOWN	HRS	0						
	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
259072B	REPLACE AUTOMATIC ELECTRONIC DEFIBRILLATOR BATTERIES							Service ATA:25
PN:PN	MOS/MSC		N/A					NOT INSTALLED
SN:UNKNOWN	HRS							
	AFL							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
259072C	REPLACE AUTOMATIC ELECTRONIC DEFIBRILLATOR PADS							Service ATA:25
PN:PN	MOS/MSC		O/C					
SN:UNKNOWN	HRS							
	AFL							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
259073	AUTOMATIC ELECTRONIC DEFIBRILLATOR (AED) BATTERIES							Component ATA:25
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
259074	AUTOMATIC ELECTRONIC DEFIBRILLATOR (AED) ELECTRODE PADS							Component ATA:25
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
AA2560000		COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON - CLEAN BEACON SWITCH, PERFORM FUNCTIONAL TEST OF BEACON, AND PERFORM TEST OF ULB BATTERY						Service ATA:25
PN:DK120	MOS	12-Dec-25	24 (+14d/-14d)		31-Dec-27	31-Dec-27	526 d	
SN:AT120124	HRS	5343						
	AFL	4470						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
D2566001		COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON - REPLACE						Service ATA:25
PN:DK120	MOS/MSC	13-Sep-18	DUE		15-Oct-25 (M)		OVD	
SN:AT120124	HRS	4046.7						
	AFL	3423						
Expiry Date: : 15-Oct-25								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
E2561002		COPILOTS LIFE VEST - PERFORM INSPECTION OF LIFE VESTS						Service ATA:25
PN:P01074-103	MOS	09-Jul-24	60 (+14d/-14d)		31-Mar-28 (M)	14-Apr-28	617 d (+14)	
SN:23031140006	HRS	5131						
	AFL	4323						
Inspection Date: : 31-Mar-23								
PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01								
E2561002		LAVATORY LIFE VEST - PERFORM INSPECTION OF LIFE VESTS						Service ATA:25
PN:P01074-103	MOS	15-Oct-22	60 (+14d/-14d)		31-Oct-27	31-Oct-27	465 d	
SN:12061910003	HRS							
	AFL							
Inspection Date: : 15-Oct-22								
PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01								
E2561002		NO. 1 PASSENGER LIFE VEST - PERFORM INSPECTION OF LIFE VESTS						Service ATA:25
PN:P01074-103	MOS	09-Jul-24	60		31-Mar-28 (M)		617 d	
SN:23031140116	HRS	5131						
	AFL	4323						
Inspection Date: : 31-Mar-23								
PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
E2561002	NO. 2 PASSENGER LIFE VEST - PERFORM INSPECTION OF LIFE VESTS							Service ATA:25
PN:P01074-103	MOS	09-Jul-24	60 (+14d/-14d)		31-Mar-28 (M)	14-Apr-28	617 d (+14)	
SN:23031140131	HRS	5131						
	AFL	4323						
Inspection Date: : 31-Mar-23								
PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01								
E2561002	NO. 3 PASSENGER LIFE VEST - PERFORM INSPECTION OF LIFE VESTS							Service ATA:25
PN:P01074-103	MOS	09-Jul-24	60 (+14d/-14d)		31-Mar-28 (M)	14-Apr-28	617 d (+14)	
SN:23031140160	HRS	5131						
	AFL	4323						
Inspection Date: : 31-Mar-23								
PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01								
E2561002	NO. 4 PASSENGER LIFE VEST - PERFORM INSPECTION OF LIFE VESTS							Service ATA:25
PN:P01074-103	MOS	09-Jul-24	60		31-Mar-28 (M)		617 d	
SN:23031140174	HRS	5131						
	AFL	4323						
Inspection Date: : 31-Mar-23								
PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01								
E2561002	NO. 5 PASSENGER LIFE VEST - PERFORM INSPECTION OF LIFE VESTS							Service ATA:25
PN:P01074-103	MOS	15-Oct-22	60 (+14d/-14d)		31-Oct-27	31-Oct-27	465 d	
SN:12061910007	HRS							
	AFL							
Inspection Date: : 15-Oct-22								
PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01								
E2561002	NO. 6 PASSENGER LIFE VEST - PERFORM INSPECTION OF LIFE VESTS							Service ATA:25
PN:P01074-103	MOS	15-Oct-22	60 (+14d/-14d)		31-Oct-27	31-Oct-27	465 d	
SN:12061910002	HRS							
	AFL							
Inspection Date: : 15-Oct-22								
PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT / FURNISHINGS								
E2561002	NO. 7 PASSENGER LIFE VEST - PERFORM INSPECTION OF LIFE VESTS							Service ATA:25
PN:P01074-103	MOS	15-Oct-22	60 (+14d/-14d)		31-Oct-27	31-Oct-27	465 d	
SN:12061910006	HRS							
	AFL							
Inspection Date: : 15-Oct-22								
PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01								
E2561002	NO. 8 PASSENGER LIFE VEST - PERFORM INSPECTION OF LIFE VESTS							Service ATA:25
PN:P01074-103	MOS	15-Oct-22	60 (+14d/-14d)		31-Oct-27	31-Oct-27	465 d	
SN:12061910005	HRS							
	AFL							
Inspection Date: : 15-Oct-22								
PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01								
E2561002	PILOTS LIFE VEST - PERFORM INSPECTION OF LIFE VESTS							Service ATA:25
PN:P01074-103	MOS	09-Jul-24	60		31-Mar-28 (M)		617 d	
SN:23031140005	HRS	5131						
	AFL	4323						
Inspection Date: : 31-Mar-23								
PROC. REF: CMM 25-60-05, AMM 25-60-01PROC. REF: CMM 25-60-05, AMM 25-60-01								
N2561004	(ELT) EMERGENCY LOCATOR TRANSMITTER - REPLACE DORNE AND MARGOLIN REMOTE SWITCH BATTERY							Service ATA:25
PN:453-5000-366	MOS/MSC		N/A					
SN:07104	HRS							
	AFL							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
Y2510000 ^S	GLARESHIELD, HEADLINER, AND TRIM STRIPS - PERFORM VISUAL INSPECTION							Service ATA:25
	MOS	31-Jul-25	12 (+14d/-14d)					
	HRS	5307.6	300 (+25/-25)					
	AFL	4448						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								
PKG:1								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
Y2510001 ^S		CREW SEATS AND SEAT BELTS - PERFORM VISUAL INSPECTION					Service	ATA:25
	MOS	31-Jul-25	12 (+14d/-14d)					
	HRS	5307.6	300 (+25/-25)					
	AFL	4448						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								PKG:1
Y2520000 ^S		CABIN - PERFORM VISUAL INSPECTION OF THE FOLLOWING: A. CABIN SEATS AND SEAT BELTS. ENSURE THAT THE SEATS FUNCTION CORRECTLY AND LOCK IN PLACE. B. STOWAGE CABINETS. C. HEADLINER. D. SIDE PANELS. E. RUG.					Service	ATA:25
	MOS	31-Jul-25	12 (+14d/-14d)					
	HRS	5307.6	300 (+25/-25)					
	AFL	4448						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								PKG:1
Y2540000 ^S		ALL LAVATORY PAPER AND LINEN WASTE RECEPTACLE ACCESS DOORS AND DISPOSAL DOORS FOR PROPER OPERATION, FIT, SEALING, LATCHING, AND LEGIBILITY OF PLACARD.					Service	ATA:25
	MOS	09-Jul-24	24 (+14d/-14d)					
	HRS	5131.8	600 (+25/-25)					
	AFL	4323						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:7
Y2540009 ^S		AVIONICS EQUIPMENT AND WIRING LOCATED IN LAVATORY AREA - PERFORM GENERAL VISUAL INSPECTION					Service	ATA:25
	MOS	18-Nov-21						
	HRS	4737	4800 (+25/-25)					
	AFL	3987						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								PKG:25
ATA 26 - FIRE PROTECTION								
261012		NO. 1 ENGINE FIREWALL FIRE DETECTION ELEMENT					Component	ATA:26
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 26-11-02PROC. REF: AMM 26-11-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
261013	NO. 2 ENGINE FIREWALL FIRE DETECTION ELEMENT							Component ATA:26
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 26-11-02PROC. REF: AMM 26-11-02								
261014	NO. 1 ENGINE ACCESSORY GEARBOX FIRE DETECTION ELEMENT							Component ATA:26
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 26-11-02PROC. REF: AMM 26-11-02								
261015	NO. 2 ENGINE ACCESSORY GEARBOX FIRE DETECTION ELEMENT							Component ATA:26
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 26-11-02PROC. REF: AMM 26-11-02								
261016	NO. 1 ENGINE HOT SECTION FIRE DETECTION ELEMENT							Component ATA:26
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 26-11-02PROC. REF: AMM 26-11-02								
261017	NO. 2 ENGINE HOT SECTION FIRE DETECTION ELEMENT							Component ATA:26
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 26-11-02PROC. REF: AMM 26-11-02								
261057	NO. 1 FIRE DETECT CONTROL UNIT							Component ATA:26
PN:877-01032	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:0403-189	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 26-11-01PROC. REF: AMM 26-11-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
261058	NO. 2 FIRE DETECT CONTROL UNIT							Component ATA:26
PN:877-01032	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:0403-186	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 26-11-01PROC. REF: AMM 26-11-01								
261069	NO. 1 BLEED AIR LEAK DETECTION UNIT							Component ATA:26
PN:6626100000-003	MOS/MSC	11-Jun-08	O/C	TSN 0				
SN:2129	HRS	1443.3		TSN 0				
	AFL	1184		TSN 0				
PROC. REF: AMM 26-12-01PROC. REF: AMM 26-12-01								
261070	NO. 2 BLEED AIR LEAK DETECTION UNIT							Component ATA:26
PN:6626100000-003	MOS/MSC	11-Jun-08	O/C	TSN 0				
SN:2124	HRS	1443.3		TSN 0				
	AFL	1184		TSN 0				
PROC. REF: AMM 26-12-01PROC. REF: AMM 26-12-01								
261071	ANTI-ICE BLEED AIR LEAK DETECTION UNIT							Component ATA:26
PN:6626100000-003	MOS/MSC	11-Jun-08	O/C	TSN 0				
SN:2128	HRS	1443.3		TSN 0				
	AFL	1184		TSN 0				
PROC. REF: AMM 26-12-01PROC. REF: AMM 26-12-01								
261075	APU FIRE/OVERHEAT DETECTOR							Component ATA:26
PN:10-1093	MOS/MSC	09-Sep-04	O/C	TSN 0				
SN:01-0232	HRS	16		TSN 0				
	AFL	12		TSN 0				
PROC. REF: AMM 26-13-01PROC. REF: AMM 26-13-01								
262001	NO. 1/LEFT/LOWER FIRE EXTINGUISHER BOTTLE							Component ATA:26
PN:33100021-1	MOS/MSC	12-Dec-25	O/C	TSO 63				
SN:72373B1	HRS	5343		TSO 870.8				
	AFL	4470		TSO 685				
PROC. REF: AMM 26-21-01PROC. REF: AMM 26-21-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 26 - FIRE PROTECTION									
262002	NO. 2/RIGHT/UPPER FIRE EXTINGUISHER BOTTLE							Component	ATA:26
PN:33100021-1	MOS/MSC	10-Mar-22	O/C	TSN 187, TSO 3					
SN:559005B1	HRS	4830.2	TSO 0						
	AFL	4059	TSO 0						
PROC. REF: AMM 26-21-01PROC. REF: AMM 26-21-01									
262013	NO. 1/LEFT/LOWER FIRE EXTINGUISHER, LEFT SQUIB							Component	ATA:26
PN:30903856	MOS	20-Aug-15	180 (+14d/-14d)	TSN 0	30-Jun-30	14-Jul-30	1438 d (+14)	LIFE LIMIT	
SN:1493TB	HRS	3457.7	TSN 0						
	AFL	2840	TSN 0						
Manufacture Date:: 30-Jun-15									
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
262014	NO. 1/LEFT/LOWER FIRE EXTINGUISHER, RIGHT SQUIB							Component	ATA:26
PN:30903859	MOS	20-Aug-15	180 (+14d/-14d)	TSN 0	30-Jun-30	14-Jul-30	1438 d (+14)	REPLACE	
SN:0247TD	HRS	3457.7	TSN 0						
	AFL	2840	TSN 0						
Manufacture Date:: 30-Jun-15									
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
262015	NO. 2/RIGHT/UPPER FIRE EXTINGUISHER, LEFT SQUIB							Component	ATA:26
PN:30903856	MOS	28-Feb-17	180 (+14d/-14d)	TSN 2	31-Jan-32	31-Jan-32	2018 d		
SN:0707UK	HRS	3694.5							
	AFL	3069							
Manufacture Date:: 01-Jan-17									
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
262016	NO. 2/RIGHT/UPPER FIRE EXTINGUISHER, RIGHT SQUIB							Component	ATA:26
PN:30903859	MOS	28-Feb-17	180 (+14d/-14d)	TSN 2	31-Jan-32	31-Jan-32	2018 d		
SN:0586UJ	HRS	3694.5							
	AFL	3069							
Manufacture Date:: 01-Jan-17									
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
262040		APU FIRE WARNING HORN					Component	ATA:26
PN:430-M1	MOS/MSC	24-Feb-11	O/C	TSN 0				
SN:23931	HRS	2352.3		TSN 0				
	AFL	1915		TSN 0				
PROC. REF: AMM 26-13-02PROC. REF: AMM 26-13-02								
262041		PILOT PORTABLE FIRE EXTINGUISHER					Component	ATA:26
PN:A344	MOS/MSC	21-Jul-23	O/C	TSN 0				
SN:H-29719346	HRS	5076.3		TSN 0				
	AFL	4268		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
262042		COPILOT PORTABLE FIRE EXTINGUISHER					Component	ATA:26
PN:A344	MOS/MSC	21-Jul-23	O/C	TSN 0				
SN:UNKNOWN	HRS	5076.3		TSN 0				
	AFL	4268		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
262051		CABIN PORTABLE FIRE EXTINGUISHER					Component	ATA:26
PN:C352	MOS/MSC	21-Jul-23	O/C	TSN 0				
SN:H-21670215	HRS	5076.3		TSN 0				
	AFL	4268		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
262075		APU FIRE EXTINGUISHER CONTAINER					Component	ATA:26
PN:51600-2	MOS/MSC	26-Apr-24	O/C					
SN:1160	HRS	5128.5						
	AFL	4317						
PROC. REF: AMM 26-22-01PROC. REF: AMM 26-22-01								
262076		APU ENGINE FIRE EXTINGUISHER CONTAINER CARTRIDGE					Component	ATA:26
PN:30600-22	MOS/MSC	26-Apr-24	H/T	TSN 3				
SN:129	HRS	5128.5		TSN 0				
	AFL	4317		TSN 0				
PROC. REF: AMM 26-21-02PROC. REF: AMM 26-21-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
D2620007.S	NO. 1/LEFT/LOWER FIRE EXTINGUISHER, LEFT SQUIB - SERVICE LIFE LIMIT							Service ATA:26
PN:30903856	MOS	12-Dec-25	120	Adj -114d	31-Aug-35		3326 d	SERVICE LIFE LIMIT
SN:1493TB	HRS	5343						
	AFL	4470						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
D2620007.S	NO. 1/LEFT/LOWER FIRE EXTINGUISHER, RIGHT SQUIB - SERVICE LIFE LIMIT							Service ATA:26
PN:30903859	MOS	12-Dec-25	120	Adj -114d	31-Aug-35		3326 d	LIFE LIMIT
SN:0247TD	HRS	5343						
	AFL	4470						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
D2620007.S	NO. 2/RIGHT/UPPER FIRE EXTINGUISHER, LEFT SQUIB - SERVICE LIFE LIMIT							Service ATA:26
PN:30903856	MOS	28-Feb-17	120	TAC 2	31-Dec-26		161 d	LIFE LIMIT
SN:0707UK	HRS	3694.5						
	AFL	3069						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
D2620007.S	NO. 2/RIGHT/UPPER FIRE EXTINGUISHER, RIGHT SQUIB - SERVICE LIFE LIMIT							Service ATA:26
PN:30903859	MOS	28-Feb-17	120	TAC 2	31-Dec-26		161 d	LIFE LIMIT
SN:0586UJ	HRS	3694.5						
	AFL	3069						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
J2620000 ^S	** ENGINE FIRE EXTINGUISHING SYSTEM FIRE SWITCH - PERFORM FUNCTIONAL TEST							Service ATA:26
	MOS	18-Nov-21						AIRWORTHINESS
	HRS	4737	4800 (+25/-25)					
	AFL	3987						
PROC. REF: AMM 26-21-00PROC. REF: AMM 26-21-00								PKG:25
O2610001	NO. 1 ENGINE HOT SECTION FIRE DETECTOR ELEMENT - PERFORM VISUAL INSPECTION							Service ATA:26
	MOS	27-Aug-13						
	HRS	3014.2	3500 (+100/-100)		6514.2	6614.2	1059 (+100)	
	AFL	2498						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
Q2610001	NO. 2 ENGINE HOT SECTION FIRE DETECTOR ELEMENT - PERFORM VISUAL INSPECTION							Service ATA:26
	MOS	27-Aug-13						
	HRS	3014.2	3500 (+100/-100)		6514.2	6614.2	1059 (+100)	
	AFL	2498						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								
Q2510003	CABIN PORTABLE FIRE EXTINGUISHER - PERFORM ICC HYDROSTATIC TEST							Service ATA:26
PN:C352	MOS	21-Jul-23	144 (+14d/-14d)		31-Jul-35	04-Aug-35	3295 d (+4)	
SN:H-21670215	HRS	5076.3						
	AFL	4268						
PROC. REF: AMM 26-23-00PROC. REF: AMM 26-23-00								
Q2510003	COPILOT PORTABLE FIRE EXTINGUISHER - PERFORM ICC HYDROSTATIC TEST							Service ATA:26
PN:A344	MOS	21-Jul-23	144 (+14d/-14d)		31-Jul-35	04-Aug-35	3295 d (+4)	
SN:UNKNOWN	HRS	5076.3						
	AFL	4268						
PROC. REF: AMM 26-23-00PROC. REF: AMM 26-23-00								
Q2510003	PILOT PORTABLE FIRE EXTINGUISHER - PERFORM ICC HYDROSTATIC TEST							Service ATA:26
PN:A344	MOS	21-Jul-23	144 (+14d/-14d)		31-Jul-35	04-Aug-35	3295 d (+4)	
SN:H-29719346	HRS	5076.3						
	AFL	4268						
PROC. REF: AMM 26-23-00PROC. REF: AMM 26-23-00								
Q2620006	NO. 1/LEFT/LOWER FIRE EXTINGUISHER BOTTLE - PERFORM ICC HYDROSTATIC TEST							Service ATA:26
PN:33100021-1	MOS	12-Dec-25	60 (+14d/-14d)	Adj -93d	30-Sep-30	30-Sep-30	1530 d	
SN:72373B1	HRS	5343						
	AFL	4470						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
Q2620006	NO. 2/RIGHT/UPPER FIRE EXTINGUISHER BOTTLE - PERFORM ICC HYDROSTATIC TEST							Service ATA:26
PN:33100021-1	MOS	22-Dec-21	60 (+14d/-14d)		10-Mar-27 (M)	24-Mar-27	230 d (+14)	
SN:559005B1	HRS							
	AFL							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
Q4900014	APU FIRE EXTINGUISHER CONTAINER - PERFORM ICC HYDROSTATIC TEST							Service ATA:26
PN:51600-2	MOS	10-Apr-24	60 (+14d/-14d)		30-Apr-29	30-Apr-29	1012 d	
SN:1160	HRS							
	AFL							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
T2620001 S	** FIREWALL SHUT-OFF VALVES - PERFORM OPERATIONAL CHECK							Service ATA:26
	MOS	24-Feb-23	48 (+14d/-14d)					AIRWORTHINESS
	HRS	5067.1	1200 (+25/-25)					
	AFL	4262						
PROC. REF: AMM 26-21-00PROC. REF: AMM 26-21-00								
Y2610000 S	FIREWALL AND ACCESSORY COMPARTMENT FIRE DETECTOR ELEMENTS - PERFORM VISUAL INSPECTION							Service ATA:26
	MOS	09-Jul-24	24 (+14d/-14d)					
	HRS	5131.8	600 (+25/-25)					
	AFL	4323						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								
Y2620002 S	ENGINE FIRE EXTINGUISHER CONTAINERS - PERFORM VISUAL INSPECTION. CHECK CONTAINERS FOR CONDITION, CARTRIDGES AND CARTRIDGE WIRING FOR SECURITY AND CONDITION, CONTAINER PRESSURE GAUGE FOR PROPER PRESSURES, AND PLUMBING FOR SECURITY AND CONDITION.							Service ATA:26
	MOS	31-Jul-25	12 (+14d/-14d)					
	HRS	5307.6	300 (+25/-25)					
	AFL	4448						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								
Y2620005 S	ENGINE FIRE EXTINGUISHING SYSTEM - PERFORM OPERATIONAL CHECK							Service ATA:26
	MOS	01-Mar-19	96 (+14d/-14d)					
	HRS	4123.3	2400 (+25/-25)					
	AFL	3499						
PROC. REF: AMM 26-21-00PROC. REF: AMM 26-21-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
Y2620009 ^S	CABIN PORTABLE FIRE EXTINGUISHER - INSPECT PORTABLE HAND HELD FIRE EXTINGUISHERS FOR CONDITION AND DATE OF MANUFACTURE. CHECK OPERATING PRESSURE AND WEIGHT PER MAINTENANCE INSTRUCTIONS ON FIRE EXTINGUISHER BOTTLE.						Service	ATA:26
PN:C352	MOS	31-Jul-25	12 (+14d/-14d)					
SN:H-21670215	HRS	5307.6	300 (+25/-25)					
	AFL	4448						
								PKG:1
Y2620009 ^S	COPILOT PORTABLE FIRE EXTINGUISHER - INSPECT PORTABLE HAND HELD FIRE EXTINGUISHERS FOR CONDITION AND DATE OF MANUFACTURE. CHECK OPERATING PRESSURE AND WEIGHT PER MAINTENANCE INSTRUCTIONS ON FIRE EXTINGUISHER BOTTLE.						Service	ATA:26
PN:A344	MOS	31-Jul-25	12 (+14d/-14d)					
SN:UNKNOWN	HRS	5307.6	300 (+25/-25)					
	AFL	4448						
								PKG:1
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
Y2620009 ^S	PILOT PORTABLE FIRE EXTINGUISHER - INSPECT PORTABLE HAND HELD FIRE EXTINGUISHERS FOR CONDITION AND DATE OF MANUFACTURE. CHECK OPERATING PRESSURE AND WEIGHT PER MAINTENANCE INSTRUCTIONS ON FIRE EXTINGUISHER BOTTLE.						Service	ATA:26
PN:A344	MOS	31-Jul-25	12 (+14d/-14d)					
SN:H-29719346	HRS	5307.6	300 (+25/-25)					
	AFL	4448						
								PKG:1
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
Z2620021 ^S	NO. 1 ENGINE FIRE EXTINGUISHER CONTAINER PLUMBING - PERFORM DETAILED INSPECTION						Service	ATA:26
	MOS	31-Jul-25	12					
	HRS	5307.6	300					
	AFL	4448						
								PKG:2
PROC. REF: AMM 26-21-00PROC. REF: AMM 26-21-00								
Z2620021 ^S	NO. 2 ENGINE FIRE EXTINGUISHER CONTAINER PLUMBING - PERFORM DETAILED INSPECTION						Service	ATA:26
	MOS	31-Jul-25	12					
	HRS	5307.6	300					
	AFL	4448						
								PKG:2
PROC. REF: AMM 26-21-00PROC. REF: AMM 26-21-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
270301	TRIM SWITCH PANEL							Component ATA:27
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-00-01PROC. REF: AMM 27-00-01								
271001	LEFT AILERON CONTROL SYSTEM CROSSOVER CABLE							Component ATA:27
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-10-05PROC. REF: AMM 27-10-05								
271002	RIGHT AILERON CONTROL SYSTEM CROSSOVER CABLE							Component ATA:27
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-10-05PROC. REF: AMM 27-10-05								
271003	LEFT AILERON CONTROL SYSTEM CABLE							Component ATA:27
PN:7627102004-005	MOS/MSC	18-Nov-21	O/C	TSN 0				
SN:1450458/1	HRS	4737		TSN 0				
	AFL	3987		TSN 0				
PROC. REF: AMM 27-10-05PROC. REF: AMM 27-10-05								
271004	RIGHT AILERON CONTROL SYSTEM CABLE							Component ATA:27
PN:7627102005-009	MOS/MSC	18-Nov-21	O/C	TSN 0				
SN:890102655706	HRS	4737		TSN 0				
	AFL	3987		TSN 0				
PROC. REF: AMM 27-10-05PROC. REF: AMM 27-10-05								
271005	AFT AILERON CONTROL SYSTEM CABLE							Component ATA:27
PN:7627102001-005	MOS/MSC	18-Nov-21	O/C	TSN 0				
SN:1429552/1	HRS	4737		TSN 0				
	AFL	3987		TSN 0				
PROC. REF: AMM 27-10-05PROC. REF: AMM 27-10-05								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
271045	LEFT INBOARD AILERON CONTROL CABLE							Component ATA:27
PN:4527103077-013	MOS/MSC	26-Oct-22	O/C	TSN 11				
SN:1460019-3	HRS	4984.7		TSN 0				
	AFL	4197		TSN 0				
PROC. REF: AMM 27-10-05PROC. REF: AMM 27-10-05								
271046	RIGHT INBOARD AILERON CONTROL CABLE							Component ATA:27
PN:4527103076-017	MOS/MSC	26-Oct-22	O/C	TSN 10				
SN:1464108-7	HRS	4984.7		TSN 0				
	AFL	4197		TSN 0				
PROC. REF: AMM 27-10-05PROC. REF: AMM 27-10-05								
271051	LEFT FORWARD OUTBOARD AILERON CONTROL CABLE							Component ATA:27
PN:4527103078-011	MOS/MSC	26-Oct-22	O/C	TSN 10				
SN:1461872-5	HRS	4984.7		TSN 0				
	AFL	4197		TSN 0				
PROC. REF: AMM 27-10-05PROC. REF: AMM 27-10-05								
271052	RIGHT FORWARD OUTBOARD AILERON CONTROL CABLE							Component ATA:27
PN:4527103078-011	MOS/MSC	26-Oct-22	O/C	TSN 10				
SN:1461872-4	HRS	4984.7		TSN 0				
	AFL	4197		TSN 0				
PROC. REF: AMM 27-10-05PROC. REF: AMM 27-10-05								
271053	LEFT AFT OUTBOARD AILERON CONTROL CABLE							Component ATA:27
PN:4527103079-011	MOS/MSC	26-Oct-22	O/C	TSN 5				
SN:1472042-24	HRS	4984.7		TSN 0				
	AFL	4197		TSN 0				
PROC. REF: AMM 27-10-05PROC. REF: AMM 27-10-05								
271054	RIGHT AFT OUTBOARD AILERON CONTROL CABLE							Component ATA:27
PN:4527103079-011	MOS/MSC	26-Oct-22	O/C	TSN 5				
SN:1472042-26	HRS	4984.7		TSN 0				
	AFL	4197		TSN 0				
PROC. REF: AMM 27-10-05PROC. REF: AMM 27-10-05								

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
271083	AILERON TRIM TAB ACTUATOR							Component ATA:27
PN:6627108000-001	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:0329	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-10-09PROC. REF: AMM 27-10-09								
271088	AILERON SPINDLE							Component ATA:27
PN:PN	MOS/MSC	07-Jul-04	H/T	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-10-07PROC. REF: AMM 27-10-07								
271095	PILOT ANGLE OF ATTACK INDICATOR (AOA)							Component ATA:27
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
271096	COPILOT ANGLE OF ATTACK INDICATOR (AOA)							Component ATA:27
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
271220	TRIM, TOGGLE, AND PUSH BUTTON SWITCH							Component ATA:27
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-10-06PROC. REF: AMM 27-10-06								
272001	FORWARD UPPER RUDDER CONTROL SYSTEM CABLE							Component ATA:27
PN:7627202001-009	MOS/MSC	18-Nov-21	O/C	TSN 0				
SN:1456177/1	HRS	4737		TSN 0				
	AFL	3987		TSN 0				
PROC. REF: AMM 27-20-08PROC. REF: AMM 27-20-08								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
272002	FORWARD LOWER RUDDER CONTROL SYSTEM CABLE							Component ATA:27
PN:7627202002-009	MOS/MSC	18-Nov-21	O/C	TSN 0				
SN:1456568/1	HRS	4737		TSN 0				
	AFL	3987		TSN 0				
PROC. REF: AMM 27-20-08PROC. REF: AMM 27-20-08								
272003	LEFT AFT UPPER RUDDER CONTROL SYSTEM CABLE							Component ATA:27
PN:7627202003-005	MOS/MSC	18-Nov-21	O/C	TSN 0				
SN:1447888/1	HRS	4737		TSN 0				
	AFL	3987		TSN 0				
PROC. REF: AMM 27-20-08PROC. REF: AMM 27-20-08								
272004	RIGHT AFT UPPER RUDDER CONTROL SYSTEM CABLE							Component ATA:27
PN:7627202004-005	MOS/MSC	18-Nov-21	O/C	TSN 0				
SN:1459983/1	HRS	4737		TSN 0				
	AFL	3987		TSN 0				
PROC. REF: AMM 27-20-08PROC. REF: AMM 27-20-08								
272005	LEFT AFT LOWER RUDDER CONTROL SYSTEM CABLE							Component ATA:27
PN:7627202005-005	MOS/MSC	18-Nov-21	O/C	TSN 0				
SN:1442669-1	HRS	4737		TSN 0				
	AFL	3987		TSN 0				
PROC. REF: AMM 27-20-08PROC. REF: AMM 27-20-08								
272006	RIGHT AFT LOWER RUDDER CONTROL SYSTEM CABLE							Component ATA:27
PN:7627202006-005	MOS/MSC	18-Nov-21	O/C	TSN 0				
SN:1444191-1	HRS	4737		TSN 0				
	AFL	3987		TSN 0				
PROC. REF: AMM 27-20-08PROC. REF: AMM 27-20-08								
272021	RUDDER TRIM TAB ACTUATOR							Component ATA:27
PN:4323322	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:0340	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-20-03PROC. REF: AMM 27-20-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45
Serial: 45-252
RegNo: N253SC
HRS: 5455.2
AFL: 4545
As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
272031	PILOT RUDDER PEDAL ADJUST ACTUATOR							Component ATA:27
PN:6627208001-001	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:730	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-20-05PROC. REF: AMM 27-20-05								
272032	COPILOT RUDDER PEDAL ADJUST ACTUATOR							Component ATA:27
PN:6627208001-001	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:729	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-20-05PROC. REF: AMM 27-20-05								
273001	PILOT FORWARD ELEVATOR CONTROL SYSTEM CABLE							Component ATA:27
PN:7627302021-009	MOS/MSC	18-Nov-21	O/C	TSN 0				
SN:1447886/1	HRS	4737		TSN 0				
	AFL	3987		TSN 0				
PROC. REF: AMM 27-30-05PROC. REF: AMM 27-30-05								
273002	COPILOT FORWARD ELEVATOR CONTROL SYSTEM CABLE							Component ATA:27
PN:7627302022-009	MOS/MSC	18-Nov-21	O/C	TSN 0				
SN:1456178/1	HRS	4737		TSN 0				
	AFL	3987		TSN 0				
PROC. REF: AMM 27-30-05PROC. REF: AMM 27-30-05								
273003	LEFT AFT UPPER ELEVATOR CONTROL SYSTEM CABLE							Component ATA:27
PN:7627302024-005	MOS/MSC	18-Nov-21	O/C	TSN 0				
SN:1449801/1	HRS	4737		TSN 0				
	AFL	3987		TSN 0				
PROC. REF: AMM 27-30-05PROC. REF: AMM 27-30-05								
273004	RIGHT AFT UPPER ELEVATOR CONTROL SYSTEM CABLE							Component ATA:27
PN:7627302023-005	MOS/MSC	18-Nov-21	O/C	TSN 0				
SN:1448778/1	HRS	4737		TSN 0				
	AFL	3987		TSN 0				
PROC. REF: AMM 27-30-05PROC. REF: AMM 27-30-05								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
273005	LEFT AFT LOWER ELEVATOR CONTROL SYSTEM CABLE							Component ATA:27
PN:7627302026-005	MOS/MSC	18-Nov-21	O/C	TSN 0				
SN:1454109-1	HRS	4737		TSN 0				
	AFL	3987		TSN 0				
PROC. REF: AMM 27-30-05PROC. REF: AMM 27-30-05								
273006	RIGHT AFT LOWER ELEVATOR CONTROL SYSTEM CABLE							Component ATA:27
PN:7627302025-005	MOS/MSC	18-Nov-21	O/C	TSN 0				
SN:1450094/1	HRS	4737		TSN 0				
	AFL	3987		TSN 0				
PROC. REF: AMM 27-30-05PROC. REF: AMM 27-30-05								
273015	LEFT ANGLE OF ATTACK VANE (AOA)							Component ATA:27
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-31-04PROC. REF: AMM 27-31-04								
273016	RIGHT ANGLE OF ATTACK VANE (AOA)							Component ATA:27
PN:6627308500-803	MOS/MSC	13-Sep-18	O/C					
SN:7417	HRS	4046.7						
	AFL	3423						
PROC. REF: AMM 27-31-04PROC. REF: AMM 27-31-04								
273020	LEFT ANGLE OF ATTACK SENSOR (AOA)							Component ATA:27
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
273021	RIGHT ANGLE OF ATTACK SENSOR (AOA)							Component ATA:27
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
273022	LEFT ANGLE OF ATTACK TRANSMITTER (AOA)							Component ATA:27
PN:6627308500-001	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:828	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-31-01PROC. REF: AMM 27-31-01								
273023	RIGHT ANGLE OF ATTACK TRANSMITTER (AOA)							Component ATA:27
PN:6627308500-001	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:832	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-31-01PROC. REF: AMM 27-31-01								
273051	ELEVATOR DISCONNECT ACTUATOR							Component ATA:27
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-30-09PROC. REF: AMM 27-30-09								
273063	PILOT STICK SHAKER							Component ATA:27
PN:6627308500-009	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:1371	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-31-03PROC. REF: AMM 27-31-03								
273064	COPILOT STICK SHAKER							Component ATA:27
PN:6627308500-009	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:1362	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-31-03PROC. REF: AMM 27-31-03								
273087	STALL WARNING COMPUTER							Component ATA:27
PN:6627308500-013	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:418	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-31-02PROC. REF: AMM 27-31-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45
 Serial: 45-252
 RegNo: N253SC
 HRS: 5455.2
 AFL: 4545
 As Of: 23-Jul-2026
 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
273201		ELEVATOR DISCONNECT CURRENT LIMITER					Component	ATA:27
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-30-13PROC. REF: AMM 27-30-13								
273220		AFT ELEVATOR DISCONNECT ASSEMBLY					Component	ATA:27
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-30-07PROC. REF: AMM 27-30-07								
273420		ELEVATOR OVERRIDE ACTUATOR					Component	ATA:27
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-30-14PROC. REF: AMM 27-30-14								
274011		HORIZONTAL STABILIZER ACTUATOR					Component	ATA:27
PN:6627401000-009	MOS/MSC	29-Nov-18	O/C	TSO 0				
SN:B0569	HRS	4080.4		TSN 1736.82, TSO 0				
	AFL	3461		TSO 0				
PROC. REF: AMM 27-40-02PROC. REF: AMM 27-40-02								
274031		TRIM-IN-MOTION DETECTOR					Component	ATA:27
PN:1625-1-1	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:0416191	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-41-01PROC. REF: AMM 27-41-01								
274041		FORWARD INTERFACE UNIT					Component	ATA:27
PN:4527408503-027	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:MRP642895	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-40-04PROC. REF: AMM 27-40-04								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
274051	HORIZONTAL STABILIZER ACTUATOR CONTROL BOX							Component ATA:27
PN:6627401000-003	MOS/MSC	13-Jul-20	O/C	TSN 0				
SN:E0870	HRS	4453.4		TSN 0				
	AFL	3769		TSN 0				
PROC. REF: AMM 27-40-02, AMM 27-40-03PROC. REF: AMM 27-40-02, AMM 27-40-03								
274210	WHEEL MASTER DISCONNECT PRINTED CIRCUIT BOARD							Component ATA:27
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
275000	FLAP HYDRAULIC MOTOR							Component ATA:27
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
275020	LEFT OUTBOARD FLAP ACTUATOR							Component ATA:27
PN:6627503000-033	MOS/MSC	13-Jun-14	O/C	TSN 0				
SN:2020	HRS	3187.7		TSN 0				
	AFL	2627		TSN 0				
PROC. REF: AMM 27-50-06PROC. REF: AMM 27-50-06								
275021	LEFT INBOARD FLAP ACTUATOR							Component ATA:27
PN:6627503000-031	MOS/MSC	13-Jun-14	O/C	TSN 0				
SN:2019	HRS	3187.7		TSN 0				
	AFL	2627		TSN 0				
PROC. REF: AMM 27-50-06PROC. REF: AMM 27-50-06								
275022	RIGHT INBOARD FLAP ACTUATOR							Component ATA:27
PN:6627503000-031	MOS/MSC	13-Jun-14	O/C	TSN 0				
SN:2047	HRS	3187.7		TSN 0				
	AFL	2627		TSN 0				
PROC. REF: AMM 27-50-06PROC. REF: AMM 27-50-06								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
275023	RIGHT OUTBOARD FLAP ACTUATOR							Component ATA:27
PN:6627503000-033	MOS/MSC	26-Oct-22	O/C	TSR 13				
SN:2023	HRS	4984.7		TSR 0				
	AFL	4197		TSR 0				
PROC. REF: AMM 27-50-06PROC. REF: AMM 27-50-06								
275030	LEFT INBOARD FLAP ACTUATOR JOINT							Component ATA:27
PN:159174-1	MOS/MSC	19-Feb-14	O/C	TSN 0				
SN:NA	HRS	3107.6		TSN 0				
	AFL	2561		TSN 0				
PROC. REF: AMM 27-50-06PROC. REF: AMM 27-50-06								
275031	LEFT OUTBOARD FLAP ACTUATOR JOINT							Component ATA:27
PN:159174-1	MOS/MSC	19-Feb-14	O/C	TSN 0				
SN:NA	HRS	3107.6		TSN 0				
	AFL	2561		TSN 0				
PROC. REF: AMM 27-50-06PROC. REF: AMM 27-50-06								
275032	RIGHT INBOARD FLAP ACTUATOR JOINT							Component ATA:27
PN:159174-1	MOS/MSC	19-Feb-14	O/C	TSN 0				
SN:NA	HRS	3107.6		TSN 0				
	AFL	2561		TSN 0				
PROC. REF: AMM 27-50-06PROC. REF: AMM 27-50-06								
275033	RIGHT OUTBOARD FLAP ACTUATOR JOINT							Component ATA:27
PN:159174-1	MOS/MSC	19-Feb-14	O/C	TSN 0				
SN:NA	HRS	3107.6		TSN 0				
	AFL	2561		TSN 0				
PROC. REF: AMM 27-50-06PROC. REF: AMM 27-50-06								
275057	FLAP DRIVE POWER UNIT							Component ATA:27
PN:C144483-3	MOS/MSC	01-Mar-19	O/C	TSR 0				
SN:1379X	HRS	4123.3		TSR 0				
	AFL	3499		TSR 0				
PROC. REF: AMM 27-50-08PROC. REF: AMM 27-50-08								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
275058	FLAP CONTROL UNIT							Component ATA:27
PN:6627503000-013	MOS/MSC	10-Feb-21	O/C	TSR 0				
SN:1419	HRS	4568.5		TSR 0				
	AFL	3862		TSR 0				
PROC. REF: AMM 27-50-05PROC. REF: AMM 27-50-05								
275069	FLAP POSITION INDICATOR							Component ATA:27
PN:C145159-1	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:1369	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-50-07PROC. REF: AMM 27-50-07								
275080	FLAP CONTROL MODULE							Component ATA:27
PN:69013-15	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:301	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-50-02PROC. REF: AMM 27-50-02								
275081	LEFT FLAP DRIVE ROTARY VARIABLE DIFFERENTIAL TRANSFORMER							Component ATA:27
PN:6627503000-019	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:A0621	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-50-03PROC. REF: AMM 27-50-03								
275082	RIGHT FLAP DRIVE ROTARY VARIABLE DIFFERENTIAL TRANSFORMER							Component ATA:27
PN:6627503000-019	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:A0620	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-50-03PROC. REF: AMM 27-50-03								
275110	LEFT INBOARD FLAP TRACK							Component ATA:27
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
275112	RIGHT INBOARD FLAP TRACK							Component ATA:27
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
275114	LEFT OUTBOARD FLAP TRACK							Component ATA:27
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
275116	RIGHT OUTBOARD FLAP TRACK							Component ATA:27
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
275120	LEFT CENTER FLAP TRACK							Component ATA:27
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
275122	RIGHT CENTER FLAP TRACK							Component ATA:27
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
275201	LEFT INBOARD FLAP DRIVE SHAFT							Component ATA:27
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-50-04PROC. REF: AMM 27-50-04								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
275202		RIGHT INBOARD FLAP DRIVE SHAFT					Component	ATA:27
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-50-04PROC. REF: AMM 27-50-04								
275203		LEFT OUTBOARD FLAP DRIVE SHAFT					Component	ATA:27
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-50-04PROC. REF: AMM 27-50-04								
275204		RIGHT OUTBOARD FLAP DRIVE SHAFT					Component	ATA:27
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-50-04PROC. REF: AMM 27-50-04								
276001		LEFT SPOILER ACTUATOR					Component	ATA:27
PN:6627602001-005	MOS/MSC	08-May-06	O/C	TSN 1				
SN:DAW735-05	HRS	678.3		TSN 0				
	AFL	577		TSN 0				
PROC. REF: AMM 27-60-04PROC. REF: AMM 27-60-04								
276002		RIGHT SPOILER ACTUATOR					Component	ATA:27
PN:6627602001-005	MOS/MSC	08-May-06	O/C	TSN 1				
SN:DAW808-05	HRS	678.3		TSN 0				
	AFL	577		TSN 0				
PROC. REF: AMM 27-60-04PROC. REF: AMM 27-60-04								
276005		SPOILER CONTROL MODULE					Component	ATA:27
PN:69014-7	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:302	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-60-03PROC. REF: AMM 27-60-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
276010	SPOILERON CONTROLLER RESISTOR BOX							Component ATA:27
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-60-10PROC. REF: AMM 27-60-10								
276013	SPOILER SHUTOFF VALVE							Component ATA:27
PN:6627602002-005	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:0002T	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-60-07PROC. REF: AMM 27-60-07								
276020	SPOILER LOW PRESSURE SWITCH							Component ATA:27
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-60-08PROC. REF: AMM 27-60-08								
276031	LEFT SPOILER ROTARY VARIABLE DIFFERENTIAL TRANSFORMER							Component ATA:27
PN:4527603007-001	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:A0596	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-60-05PROC. REF: AMM 27-60-05								
276032	RIGHT SPOILER ROTARY VARIABLE DIFFERENTIAL TRANSFORMER							Component ATA:27
PN:4527603007-001	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:A0595	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-60-05PROC. REF: AMM 27-60-05								
276073	SPOILERON COMPUTER							Component ATA:27
PN:6627608500-003	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:00534	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-60-02PROC. REF: AMM 27-60-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
276076	CONTROL WHEEL ROTARY VARIABLE DIFFERENTIAL TRANSFORMER							Component ATA:27
PN:3G4-211A	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:0313/0401	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-60-06PROC. REF: AMM 27-60-06								
5-19-01-W2750055	* FLAP ACTUATOR JOINT (P/N 145673-1) (IRN W2750055) REPLACEMENT							Component ATA:27
PN:159174-1	MOS/MSC	19-Feb-14	N/A					NOT APPLICABLE
SN:NSN	HRS	3107.6						
	AFL	2561						
A2711001 ^S	** AILERON TRIM TAB CONTROL SYSTEM - PERFORM OPERATIONAL CHECK							Service ATA:27
	MOS	09-Jul-24	24 (+14d/-14d)					AIRWORTHINESS
	HRS	5131.8	600 (+25/-25)					
	AFL	4323						
PROC. REF: AMM 27-10-04PROC. REF: AMM 27-10-04								
PKG:7								
A2721001 ^S	** RUDDER TRIM SYSTEM - PERFORM OPERATIONAL CHECK							Service ATA:27
	MOS	09-Jul-24	24 (+14d/-14d)					AIRWORTHINESS
	HRS	5131.8	600 (+25/-25)					
	AFL	4323						
PROC. REF: AMM 27-20-00PROC. REF: AMM 27-20-00								
PKG:7								
A2731002 ^S	** ELEVATOR DISCONNECT SYSTEM - PERFORM OPERATIONAL CHECK							Service ATA:27
	MOS	09-Jul-24	24 (+14d/-14d)					AIRWORTHINESS
	HRS	5131.8	600 (+25/-25)					
	AFL	4323						
PROC. REF: AMM 27-30-00PROC. REF: AMM 27-30-00								
PKG:8								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
A2760001 ^S	** SPOILER ACTUATOR CHECK VALVE - PERFORM OPERATIONAL CHECK							Service ATA:27
	MOS	09-Jul-24	24 (+14d/-14d)					AIRWORTHINESS
	HRS	5131.8	600 (+25/-25)					
	AFL	4323						
PROC. REF: AMM 27-60-04PROC. REF: AMM 27-60-04								PKG:10
A2760002 ^S	** SPOILER SYSTEM - PERFORM SPOILER AUTHORITY WITH FLAPS CHECK							Service ATA:27
	MOS	09-Jul-24	24 (+14d/-14d)					AIRWORTHINESS
	HRS	5131.8	600 (+25/-25)					
	AFL	4323						
PROC. REF: AMM 27-60-00PROC. REF: AMM 27-60-00								PKG:10
AA2700000 ^S	AILERON CONTROL CABLE SYSTEM - WITH COCKPIT AND CABIN FLOORBOARDS REMOVED, PERFORM VISUAL INSPECTION OF CABLES							Service ATA:27
	MOS	09-Jul-24	24 (+14d/-14d)					
	HRS	5131.8	600 (+25/-25)					
	AFL	4323						
PROC. REF: AMM 27-00-00PROC. REF: AMM 27-00-00								PKG:7
AA2700001 ^S	RUDDER CONTROL CABLE SYSTEM - WITH COCKPIT AND CABIN FLOORBOARDS REMOVED, PERFORM VISUAL INSPECTION OF CABLES							Service ATA:27
	MOS	09-Jul-24	24 (+14d/-14d)					
	HRS	5131.8	600 (+25/-25)					
	AFL	4323						
PROC. REF: AMM 27-00-00PROC. REF: AMM 27-00-00								PKG:7
AA2700002 ^S	ELEVATOR CONTROL CABLE SYSTEM - WITH COCKPIT AND CABIN FLOORBOARDS REMOVED, PERFORM VISUAL INSPECTION OF CABLES							Service ATA:27
	MOS	09-Jul-24	24 (+14d/-14d)					
	HRS	5131.8	600 (+25/-25)					
	AFL	4323						
PROC. REF: AMM 27-00-00PROC. REF: AMM 27-00-00								PKG:7

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
AA2760021	LEFT SPOILER HYDRAULIC SYSTEM PRESSURE SWIVEL - REPLACE							Service ATA:27
	MOS	01-Mar-19		TSN 0				
	HRS	4123.3	1200 (+25/-25)	TSN 0	5323.3	5348.3	OVD	
	AFL	3499		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
AA2760021	LEFT SPOILER HYDRAULIC SYSTEM RETURN SWIVEL - REPLACE							Service ATA:27
	MOS	01-Mar-19		TSN 0				
	HRS	4123.3	1200 (+25/-25)	TSN 0	5323.3	5348.3	OVD	
	AFL	3499		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
AA2760021	RIGHT SPOILER HYDRAULIC SYSTEM PRESSURE SWIVEL - REPLACE							Service ATA:27
	MOS	01-Mar-19		TSN 0				
	HRS	4123.3	1200 (+25/-25)	TSN 0	5323.3	5348.3	OVD	
	AFL	3499		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
AA2760021	RIGHT SPOILER HYDRAULIC SYSTEM RETURN SWIVEL - REPLACE							Service ATA:27
	MOS	01-Mar-19		TSN 0				
	HRS	4123.3	1200 (+25/-25)	TSN 0	5323.3	5348.3	OVD	
	AFL	3499		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
AD2760085 ^S	SPOILER LEVER ARM - PERFORM DETAILED VISUAL INSPECTION TO ENSURE SPOILER LEVER ARM IS PROPERLY SEATED AND SECURED ON SPOILER RVDT SHAFT							Service ATA:27
	MOS	09-Jul-24	24 (+14d/-14d)					
	HRS	5131.8	600 (+25/-25)					
	AFL	4323						
PROC. REF: AMM 27-60-05PROC. REF: AMM 27-60-05								
AE2710049	* AILERON LEADING EDGE (INTERNAL) - PERFORM BORESCOPE INSPECTION							Service ATA:27
	MOS	EFF	T:6		11-Jun-26 *		OVD	AIRWORTHINESS
	HRS							
	AFL							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45
Serial: 45-252
RegNo: N253SC
HRS: 5455.2
AFL: 4545
As Of: 23-Jul-2026
23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
PROC. REF: AMM 27-10-02PROC. REF: AMM 27-10-02								
AE2730037 ^S		PERFORM DETAILED VISUAL INSPECTION OF THE ELEVATOR UP/DOWN SPRING ASSEMBLY, YOKE ASSEMBLY AND ASSOCIATED PARTS FOR FREE MOVEMENT, LOOSE FASTENERS AND SECURITY OF LOCKING DEVICES						Service ATA:27
	MOS	07-Jul-04	48					
	HRS	0	1200					
	AFL	0						
								PKG:14
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
D2740003		** HORIZONTAL STABILIZER ACTUATOR SECONDARY TRIM - PERFORM FUNCTIONAL TEST						Service ATA:27
PN:6627401000-009	MOS	07-May-25						AIRWORTHINESS
SN:B0569	HRS	5263.7	600 (+25/-25)	Adj 1.6	5865.3	5890.3	410.1 (+25)	
	AFL	4423						
PROC. REF: AMM 27-40-02PROC. REF: AMM 27-40-02								
D2740004		** HORIZONTAL STABILIZER ACTUATOR PRIMARY TRIM - PERFORM FUNCTIONAL TEST						Service ATA:27
PN:6627401000-009	MOS	07-May-25						AIRWORTHINESS
SN:B0569	HRS	5263.7	600 (+25/-25)	Adj 1.6	5865.3	5890.3	410.1 (+25)	
	AFL	4423						
PROC. REF: AMM 27-40-02PROC. REF: AMM 27-40-02								
G2710003 ^S		AILERON CONTROL SYSTEM CABLES (LOCATED IN WING) - PERFORM CABLE TENSION CHECK						Service ATA:27
	MOS	24-Feb-23	48 (+14d/-14d)					
	HRS	5067.1	1200 (+25/-25)					
	AFL	4262						
								PKG:16
PROC. REF: AMM 27-10-00PROC. REF: AMM 27-10-00								
G2710004 ^S		AILERON CONTROL SYSTEM CABLES (LOCATED IN FUSELAGE) - PERFORM CABLE TENSION CHECK						Service ATA:27
	MOS	24-Feb-23	48 (+14d/-14d)					
	HRS	5067.1	1200 (+25/-25)					
	AFL	4262						
								PKG:13
PROC. REF: AMM 27-10-00PROC. REF: AMM 27-10-00								

?-Insufficient Information
S-Suppressed Requirement
*-Estimated Due(New Requirement)
(EFF)-Effective C/W
(M)-Manual Due
U-User Task
Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
G2720003	^S	RUDDER CONTROL CABLES - PERFORM TENSION CHECK						Service ATA:27
	MOS	24-Feb-23	48 (+14d/-14d)					
	HRS	5067.1	1200 (+25/-25)					
	AFL	4262						
PROC. REF: AMM 27-20-00PROC. REF: AMM 27-20-00								PKG:14
G2720004	^S	RUDDER PEDALS, PEDAL PUSHRODS, ADJUSTMENT ACTUATOR, AND SECTORS - PERFORM VISUAL INSPECTION. CHECK DURING FULL TRAVEL OF RUDDER.						Service ATA:27
	MOS	24-Feb-23	48 (+14d/-14d)					
	HRS	5067.1	1200 (+25/-25)					
	AFL	4262						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								PKG:13
G2730003	^S	ELEVATOR CONTROL CABLES - PERFORM TENSION CHECK						Service ATA:27
	MOS	24-Feb-23	48 (+14d/-14d)					
	HRS	5067.1	1200 (+25/-25)					
	AFL	4262						
PROC. REF: AMM 27-30-00PROC. REF: AMM 27-30-00								PKG:14
K2700007		* AILERON CONTROL SYSTEM PRIMARY CABLES - REMOVE FROM AIRCRAFT AND PERFORM DETAILED VISUAL INSPECTION						Service ATA:27
	MOS	18-Nov-21						AIRWORTHINESS
	HRS	4737	4800		9537		4081.8	
	AFL	3987						
PROC. REF: AMM 27-00-00PROC. REF: AMM 27-00-00								
K2700008		* ELEVATOR CONTROL SYSTEM PRIMARY CABLES - REMOVE FROM AIRCRAFT AND PERFORM DETAILED VISUAL INSPECTION						Service ATA:27
	MOS	18-Nov-21						AIRWORTHINESS
	HRS	4737	4800		9537		4081.8	
	AFL	3987						
PROC. REF: AMM 27-00-00PROC. REF: AMM 27-00-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
K2700009	* RUDDER CONTROL SYSTEM PRIMARY CABLES - REMOVE FROM AIRCRAFT AND PERFORM DETAILED VISUAL INSPECTION							Service ATA:27
	MOS	18-Nov-21						AIRWORTHINESS
	HRS	4737	4800		9537		4081.8	
	AFL	3987						
PROC. REF: AMM 27-00-00PROC. REF: AMM 27-00-00								
K2700010	* ELEVATOR CONTROL SYSTEM PRIMARY CABLES - REMOVE FROM AIRCRAFT AND PERFORM DETAILED VISUAL INSPECTION							Service ATA:27
	MOS	18-Nov-21						AIRWORTHINESS
	HRS	4737	4800		9537		4081.8	
	AFL	3987						
PROC. REF: AMM 27-00-00PROC. REF: AMM 27-00-00								
K2700012	* RUDDER CONTROL SYSTEM PRIMARY CABLES - REMOVE FROM AIRCRAFT AND PERFORM DETAILED VISUAL INSPECTION							Service ATA:27
	MOS	18-Nov-21						AIRWORTHINESS
	HRS	4737	4800		9537		4081.8	
	AFL	3987						
PROC. REF: AMM 27-00-00PROC. REF: AMM 27-00-00								
K2700014	* AILERON CONTROL SYSTEM PRIMARY CABLES - REMOVE FROM AIRCRAFT AND PERFORM DETAILED VISUAL INSPECTION							Service ATA:27
	MOS	26-Oct-22						AIRWORTHINESS
	HRS	4984.7	4800		9784.7		4329.5	
	AFL	4197						
PROC. REF: AMM 27-00-00PROC. REF: AMM 27-00-00								
N2720030	RUDDER TORQUE TUBE AND SPINDLE - PERFORM DETAILED VISUAL INSPECTION							Service ATA:27
	MOS	06-Sep-19	72 (+14d/-14d)		30-Sep-25	30-Sep-25	OVD	AIRWORTHINESS
	HRS	4261.4						
	AFL	3621						
PROC. REF: AMM 27-20-01PROC. REF: AMM 27-20-01								
N2740023	* HORIZONTAL STABILIZER ACTUATOR ACME SCREW - REPLACE							Service ATA:27
PN:6627401000-009	MOS/MSC		N/A					
SN:B0569	HRS							
	AFL							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
N2740024	* HORIZONTAL STABILIZER ACTUATOR ACME NUT - REPLACE							Service ATA:27
PN:6627401000-009	MOS/MSC		N/A					
SN:B0569	HRS							
	AFL							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
N2740025	* HORIZONTAL STABILIZER ACTUATOR - PERFORM DETAILED STRUCTURAL INSPECTION							Service ATA:27
PN:6627401000-009	MOS/MSC	29-Nov-18	N/A					
SN:B0569	HRS	4080.4						
	AFL	3461						
P2740032	* HORIZONTAL STABILIZER ACTUATOR - PERFORM INSPECTION							Service ATA:27
PN:6627401000-009	MOS	07-May-25						
SN:B0569	HRS	5263.7	1200		6463.7		1008.5	
	AFL	4423						
P2740033	* HORIZONTAL STABILIZER ACTUATOR - PERFORM DETAILED STRUCTURAL INSPECTION							Service ATA:27
PN:6627401000-009	MOS	29-Nov-18						
SN:B0569	HRS	4080.4	2400	TAC 1143.72	5336.68		OVD	
	AFL	3461						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
R2710041	* AILERON SPINDLE - REPLACE							Service ATA:27
	MOS/MSC	11-Jun-14	N/A					
	HRS	3186.2						
	AFL	2626						
PROC. REF: AMM 27-10-07PROC. REF: AMM 27-10-07								
S2750057	* FLAP ACTUATOR BALLNUT SLEEVE - PERFORM FLUORESCENT PENETRANT INSPECTION							Service ATA:27
	MOS/MSC	09-Jul-14	N/A					NOT APPLICABLE
	HRS	3195.2						
	AFL	2631						
PROC. REF: NDT PART 8/27-50-01, NDT PART 8/27-50-02PROC. REF: NDT PART 8/27-50-01, NDT PART 8/27-50-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
T2740002	* HORIZONTAL STABILIZER ACTUATOR - PERFORM INSPECTION							Service ATA:27
PN:6627401000-009	MOS/MSC	29-Nov-18	N/A					
SN:B0569	HRS	4080.4						
	AFL	3461						
PROC. REF: AMM 27-40-02PROC. REF: AMM 27-40-02								
V2712000 ^S	** ROLL DISCONNECT SWITCHES - PERFORM OPERATIONAL CHECK							Service ATA:27
	MOS	09-Jul-24	24 (+25d/-25d)					AIRWORTHINESS
	HRS	5131.8	600 (+14/-14)					
	AFL	4323						
PROC. REF: AMM 27-60-09PROC. REF: AMM 27-60-09								
W2731001 ^S	** PITCH TRIM - PERFORM OPERATIONAL CHECK OF ELEVATOR OVERRIDE ACTUATOR							Service ATA:27
	MOS	09-Jul-24	24 (+14d/-14d)					AIRWORTHINESS
	HRS	5131.8	600 (+25/-25)					
	AFL	4323						
PROC. REF: AMM 27-30-14PROC. REF: AMM 27-30-14								
W2750055	* LEFT INBOARD FLAP ACTUATOR JOINT - REPLACE							Service ATA:27
PN:159174-1	MOS/MSC	19-Feb-14	N/A					
SN:NA	HRS	3107.6						
	AFL	2561						
W2750055	* LEFT OUTBOARD FLAP ACTUATOR JOINT - REPLACE							Service ATA:27
PN:159174-1	MOS/MSC	19-Feb-14	N/A					
SN:NA	HRS	3107.6						
	AFL	2561						
W2750055	* RIGHT INBOARD FLAP ACTUATOR JOINT - REPLACE							Service ATA:27
PN:159174-1	MOS/MSC	19-Feb-14	N/A					
SN:NA	HRS	3107.6						
	AFL	2561						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
W2750055		* RIGHT OUTBOARD FLAP ACTUATOR JOINT - REPLACE						Service ATA:27
PN:159174-1	MOS/MSC	19-Feb-14	N/A					
SN:NA	HRS	3107.6						
	AFL	2561						
W2750056		* LEFT INBOARD FLAP ACTUATOR JOINT - PERFORM DETAILED VISUAL INSPECTION. APPLY CORROSION PREVENTIVE COMPOUND (CPC) TO JOINT.						Service ATA:27
PN:159174-1	MOS/MSC	19-Feb-14	N/A					
SN:NA	HRS	3107.6						
	AFL	2561						
PROC. REF: AMM 12-21-03, AMM 27-50-06PROC. REF: AMM 12-21-03, AMM 27-50-06								
W2750056		* LEFT OUTBOARD FLAP ACTUATOR JOINT - PERFORM DETAILED VISUAL INSPECTION. APPLY CORROSION PREVENTIVE COMPOUND (CPC) TO JOINT.						Service ATA:27
PN:159174-1	MOS/MSC	19-Feb-14	N/A					
SN:NA	HRS	3107.6						
	AFL	2561						
PROC. REF: AMM 12-21-03, AMM 27-50-06PROC. REF: AMM 12-21-03, AMM 27-50-06								
W2750056		* RIGHT INBOARD FLAP ACTUATOR JOINT - PERFORM DETAILED VISUAL INSPECTION. APPLY CORROSION PREVENTIVE COMPOUND (CPC) TO JOINT.						Service ATA:27
PN:159174-1	MOS/MSC	19-Feb-14	N/A					
SN:NA	HRS	3107.6						
	AFL	2561						
PROC. REF: AMM 12-21-03, AMM 27-50-06PROC. REF: AMM 12-21-03, AMM 27-50-06								
W2750056		* RIGHT OUTBOARD FLAP ACTUATOR JOINT - PERFORM DETAILED VISUAL INSPECTION. APPLY CORROSION PREVENTIVE COMPOUND (CPC) TO JOINT.						Service ATA:27
PN:159174-1	MOS/MSC	19-Feb-14	N/A					
SN:NA	HRS	3107.6						
	AFL	2561						
PROC. REF: AMM 12-21-03, AMM 27-50-06PROC. REF: AMM 12-21-03, AMM 27-50-06								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
Y2700003	^S	AILERON CONTROL CABLE SYSTEM - PERFORM VISUAL INSPECTION OF CABLES WITHIN WING						Service ATA:27
	MOS	09-Jul-24	24 (+14d/-14d)					
	HRS	5131.8	600 (+25/-25)					
	AFL	4323						
PROC. REF: AMM 27-00-00PROC. REF: AMM 27-00-00								PKG:10
Y2700004	^S	RUDDER CONTROL CABLE SYSTEM - PERFORM VISUAL INSPECTION OF ACCESSIBLE UPPER AND LOWER CABLES						Service ATA:27
	MOS	09-Jul-24	24 (+14d/-14d)					
	HRS	5131.8	600 (+25/-25)					
	AFL	4323						
PROC. REF: AMM 27-00-00PROC. REF: AMM 27-00-00								PKG:8
Y2700005	^S	ELEVATOR CONTROL CABLE SYSTEM - PERFORM VISUAL INSPECTION OF ACCESSIBLE UPPER AND LOWER CABLES						Service ATA:27
	MOS	09-Jul-24	24 (+14d/-14d)					
	HRS	5131.8	600 (+25/-25)					
	AFL	4323						
PROC. REF: AMM 27-00-00PROC. REF: AMM 27-00-00								PKG:8
Y2700006	^S	RUDDER AND ELEVATOR CONTROL CABLES AND ASSOCIATED PULLEYS, LOCATED IN AFT PRESSURE BULKHEAD SUPPORT CHANNEL - PERFORM VISUAL INSPECTION						Service ATA:27
	MOS	09-Jul-24	24 (+14d/-14d)					
	HRS	5131.8	600 (+25/-25)					
	AFL	4323						
PROC. REF: AMM 27-00-00PROC. REF: AMM 27-00-00								PKG:9
Y2710000	^S	AILERONS, AILERON TRIM TAB AND VISIBLE PORTION OF RODS - PERFORM VISUAL INSPECTION						Service ATA:27
	MOS	09-Jul-24	24 (+14d/-14d)					
	HRS	5131.8	600 (+25/-25)					
	AFL	4323						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								PKG:10

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
Y2710001	^S	AILERON BALANCE WEIGHT INSTALLATION AND SUPPORTING STRUCTURE - PERFORM VISUAL INSPECTION						Service ATA:27
	MOS	24-Feb-23	48 (+14d/-14d)					
	HRS	5067.1	1200 (+25/-25)					
	AFL	4262						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								PKG:16
Y2710002	^S	AILERON CONTROL SYSTEM - PERFORM OPERATIONAL CHECK						Service ATA:27
	MOS	24-Feb-23	48 (+14d/-14d)					
	HRS	5067.1	1200 (+25/-25)					
	AFL	4262						
PROC. REF: AMM 27-10-00PROC. REF: AMM 27-10-00								PKG:16
Y2710048	^S	AILERON TRIM TAB INSTALLATION - PERFORM FREE PLAY CHECK						Service ATA:27
	MOS	07-Jul-04						
	HRS	0	T:9600 (+25/-25)					
	AFL	0						
PROC. REF: AMM 27-10-04PROC. REF: AMM 27-10-04								PKG:22
Y2720000	^S	RUDDER - PERFORM VISUAL INSPECTION						Service ATA:27
	MOS	31-Jul-25	12 (+14d/-14d)					
	HRS	5307.6	300 (+25/-25)					
	AFL	4448						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								PKG:2
Y2720001	^S	RUDDER BALANCE WEIGHT INSTALLATION AND SUPPORTING STRUCTURE - PERFORM VISUAL INSPECTION						Service ATA:27
	MOS	24-Feb-23	48 (+14d/-14d)					
	HRS	5067.1	1200 (+25/-25)					
	AFL	4262						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								PKG:14

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
Y2720002	^S	RUDDER CONTROL SYSTEM - PERFORM OPERATIONAL CHECK						Service ATA:27
	MOS	24-Feb-23	48 (+14d/-14d)					
	HRS	5067.1	1200 (+25/-25)					
	AFL	4262						
PROC. REF: AMM 27-20-00PROC. REF: AMM 27-20-00								PKG:14
Y2721000	^S	RUDDER TRIM TAB AND VISIBLE RODS - PERFORM VISUAL INSPECTION						Service ATA:27
	MOS	31-Jul-25	12 (+14d/-14d)					
	HRS	5307.6	300 (+25/-25)					
	AFL	4448						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								PKG:2
Y2730000	^S	CONTROL COLUMNS - PERFORM VISUAL INSPECTION. PAY PARTICULAR ATTENTION TO AILERON CONTROL WHEEL CABLE DRUM AND BOTTOM CROSSOVER PULLEYS.						Service ATA:27
	MOS	24-Feb-23	48 (+14d/-14d)					
	HRS	5067.1	1200 (+25/-25)					
	AFL	4262						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								PKG:13
Y2730001	^S	ELEVATORS - PERFORM VISUAL INSPECTION						Service ATA:27
	MOS	31-Jul-25	12 (+14d/-14d)					
	HRS	5307.6	300 (+25/-25)					
	AFL	4448						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								PKG:2
Y2730002	^S	ELEVATOR CONTROL SYSTEM - PERFORM OPERATIONAL CHECK						Service ATA:27
	MOS	24-Feb-23	48 (+14d/-14d)					
	HRS	5067.1	1200 (+25/-25)					
	AFL	4262						
PROC. REF: AMM 27-30-00PROC. REF: AMM 27-30-00								PKG:14

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
Y2730004	^S	CONTROL COLUMNS - PERFORM INSPECTION. INSPECT CABLE, PULLEYS, BEARINGS, AND ELECTRICAL WIRING						Service ATA:27
	MOS	01-Mar-19	96 (+14d/-14d)					
	HRS	4123.3	2400 (+25/-25)					
	AFL	3499						
PROC. REF: AMM 27-00-00PROC. REF: AMM 27-00-00								PKG:19
Y2730007	^S	AFT ELEVATOR DISCONNECT - PERFORM DETAILED VISUAL INSPECTION						Service ATA:27
	MOS	01-Mar-19	96 (+14d/-14d)					
	HRS	4123.3	2400 (+25/-25)					
	AFL	3499						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								PKG:20
Y2740000	^S	PRIMARY PITCH TRIM SYSTEM - PERFORM OPERATIONAL CHECK						Service ATA:27
	MOS	24-Feb-23	48 (+14d/-14d)					
	HRS	5067.1	1200 (+25/-25)					
	AFL	4262						
PROC. REF: AMM 27-40-00PROC. REF: AMM 27-40-00								PKG:14
Y2740001	^S	SECONDARY PITCH TRIM SYSTEM - PERFORM OPERATIONAL CHECK						Service ATA:27
	MOS	24-Feb-23	48 (+14d/-14d)					
	HRS	5067.1	1200 (+25/-25)					
	AFL	4262						
PROC. REF: AMM 27-40-00PROC. REF: AMM 27-40-00								PKG:14
Y2750000	^S	FLAP DRIVE INSTALLATION - PERFORM VISUAL INSPECTION WITH FLAPS LOWERED						Service ATA:27
	MOS	09-Jul-24	24 (+14d/-14d)					
	HRS	5131.8	600 (+25/-25)					
	AFL	4323						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								PKG:10

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
Y2750001	^S	FLAPS - PERFORM VISUAL INSPECTION						Service ATA:27
	MOS	31-Jul-25	12 (+14d/-14d)					
	HRS	5307.6	300 (+25/-25)					
	AFL	4448						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								PKG:4
Y2750053	^S	FLAP DRIVE ACTUATORS - PERFORM A VISUAL INSPECTION OF THE ACTUATOR ATTACHMENT, PAYING PARTICULAR ATTENTION TO THE GIMBAL PIN RETAINING RINGS						Service ATA:27
	MOS	09-Jul-24	24 (+14d/-14d)					
	HRS	5131.8	600 (+25/-25)					
	AFL	4323						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								PKG:10
Y2760000	^S	SPOILER AND SPOILER ACTUATOR - PERFORM VISUAL INSPECTION WITH FLAPS LOWERED AND ACCESS PANELS OPENED						Service ATA:27
	MOS	09-Jul-24	24 (+14d/-14d)					
	HRS	5131.8	600 (+25/-25)					
	AFL	4323						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								PKG:10
ATA 28 - FUEL								
281001		LEFT NO. 1 FUEL EJECTOR SCAVENGE PUMP						Component ATA:28
PN:6628200302-001V0685	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:FR196BL	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-12-01PROC. REF: AMM 28-12-01								
281002		RIGHT NO. 1 FUEL EJECTOR SCAVENGE PUMP						Component ATA:28
PN:6628200302-001V0685	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:FR174BL	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-12-01PROC. REF: AMM 28-12-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
281003	LEFT NO. 2 FUEL EJECTOR SCAVENGE PUMP							Component ATA:28
PN:6628200302-001V0685	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:FR200BL	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-12-01PROC. REF: AMM 28-12-01								
281004	RIGHT NO. 2 FUEL EJECTOR SCAVENGE PUMP							Component ATA:28
PN:6628200302-001V0685	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:FR198BL	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-12-01PROC. REF: AMM 28-12-01								
281005	LEFT NO. 3 FUEL EJECTOR SCAVENGE PUMP							Component ATA:28
PN:6628200302-001V0685	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:FR201BL	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-12-01PROC. REF: AMM 28-12-01								
281006	RIGHT NO. 3 FUEL EJECTOR SCAVENGE PUMP							Component ATA:28
PN:6628200302-001V0685	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:FR199BL	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-12-01PROC. REF: AMM 28-12-01								
281007	LEFT NO. 4 FUEL EJECTOR SCAVENGE PUMP							Component ATA:28
PN:6628200302-001V0685	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:FR195BL	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-12-01PROC. REF: AMM 28-12-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
281008	RIGHT NO. 4 FUEL EJECTOR SCAVENGE PUMP							Component ATA:28
PN:6628200302-001V0685	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:FR008BM	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-12-01PROC. REF: AMM 28-12-01								
281009	LEFT NO. 5 FUEL EJECTOR SCAVENGE PUMP							Component ATA:28
PN:6628200302-001V0685	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:FR025BM	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-12-01PROC. REF: AMM 28-12-01								
281010	RIGHT NO. 5 FUEL EJECTOR SCAVENGE PUMP							Component ATA:28
PN:6628200302-001V0685	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:FR197BL	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-12-01PROC. REF: AMM 28-12-01								
281031	FUSELAGE FUEL CELL							Component ATA:28
PN:6628100103-005	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:293	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-10-02PROC. REF: AMM 28-10-02								
281051	FUEL CROSSFLOW SHUTOFF VALVE							Component ATA:28
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-12-02PROC. REF: AMM 28-12-02								
281401	SURGE TANK FLOAT VALVE							Component ATA:28
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
PROC. REF: AMM 28-11-02PROC. REF: AMM 28-11-02								
281501	LEFT FLEX FUEL HOSE ASSY							Component ATA:28
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
281502	RIGHT FLEX FUEL HOSE ASSY							Component ATA:28
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
281521	LEFT FUEL TRANSFER CHECK VALVE							Component ATA:28
PN:7628200104-001	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:M0163CV0703	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-12-03PROC. REF: AMM 28-12-03								
281522	RIGHT FUEL TRANSFER CHECK VALVE							Component ATA:28
PN:7628200104-001	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:M0132CV1203	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-12-03PROC. REF: AMM 28-12-03								
282001	LEFT FUEL SHUTOFF VALVE							Component ATA:28
PN:6628200102-003	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:FR014BL	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-20-06PROC. REF: AMM 28-20-06								
282003	RIGHT FUEL SHUTOFF VALVE							Component ATA:28
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
PROC. REF: AMM 28-20-06PROC. REF: AMM 28-20-06								
282011	SHUTOFF - REFUEL VALVE							Component ATA:28
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-20-10PROC. REF: AMM 28-20-10								
282031	LEFT NO. 1 FUEL SUPPLY CHECK VALVE							Component ATA:28
PN:7628200101-001	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:M0184CV0304	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-20-03PROC. REF: AMM 28-20-03								
282032	LEFT NO. 2 FUEL SUPPLY CHECK VALVE							Component ATA:28
PN:7628200101-001	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:M018CV0304	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-20-03PROC. REF: AMM 28-20-03								
282033	RIGHT NO. 1 FUEL SUPPLY CHECK VALVE							Component ATA:28
PN:7628200101-001	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:M0182CV0304	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-20-03PROC. REF: AMM 28-20-03								
282034	RIGHT NO. 2 FUEL SUPPLY CHECK VALVE							Component ATA:28
PN:7628200101-001	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:M0149CV0102	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-20-03PROC. REF: AMM 28-20-03								
282037	RIGHT FUEL SUPPLY SHUT-OFF VALVE ASSEMBLY							Component ATA:28
PN:6628200101-003	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:0742	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
PROC. REF: AMM 28-20-06PROC. REF: AMM 28-20-06								
282038	LEFT FUEL SUPPLY SHUT-OFF VALVE ASSEMBLY							Component ATA:28
PN:6628200101-003	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:0619	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-20-06PROC. REF: AMM 28-20-06								
282041	REFUELING CONTROL PANEL							Component ATA:28
PN:4528408000V5-001	MOS/MSC	22-Mar-21	O/C					
SN:00060646AB	HRS	4618.4						
	AFL	3886						
PROC. REF: AMM 28-20-14PROC. REF: AMM 28-20-14								
282051	LEFT MOTIVE FLOW CHECK VALVE							Component ATA:28
PN:6628200106-003	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:FR045BJ	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-20-05PROC. REF: AMM 28-20-05								
282052	RIGHT MOTIVE FLOW CHECK VALVE							Component ATA:28
PN:6628200106-003	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:FR021BL	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-20-05PROC. REF: AMM 28-20-05								
282063	PRE-CHECK SINGLE POINT PRESSURE REFUELING (SPPR) VALVE							Component ATA:28
PN:HTE940032-1	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:5040306	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-20-12PROC. REF: AMM 28-20-12								
282064	PILOT OPERATED SINGLE POINT PRESSURE REFUELING (SPPR) VALVE							Component ATA:28
PN:61087-2	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:292	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
PROC. REF: AMM 28-20-11PROC. REF: AMM 28-20-11								
282075	LEFT MAIN FUEL	EJECTOR PUMP ASSEMBLY						Component ATA:28
PN:6628200301-001	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:FR050BE	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-20-01PROC. REF: AMM 28-20-01								
282076	RIGHT MAIN FUEL	EJECTOR PUMP ASSEMBLY						Component ATA:28
PN:6628200301-001	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:FR014BL	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-20-01PROC. REF: AMM 28-20-01								
282087	LEFT STANDBY FUEL PUMP							Component ATA:28
PN:6628200303-001	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:1AY6	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-20-02PROC. REF: AMM 28-20-02								
282088	RIGHT STANDBY FUEL PUMP							Component ATA:28
PN:6628200303-001	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:A1Y5	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-20-02PROC. REF: AMM 28-20-02								
282601	DEFUEL SHUTOFF VALVE							Component ATA:28
PN:6628200101-003	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:0741	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-20-07PROC. REF: AMM 28-20-07								
282602	REFUEL CHECK VALVE							Component ATA:28
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
PROC. REF: AMM 28-20-09PROC. REF: AMM 28-20-09								
282603	SINGLE POINT PRESSURE REFUELING (SPPR) ADAPTER							Component ATA:28
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
282815	APU FUEL SHUTOFF VALVE							Component ATA:28
PN:7086048-1	MOS/MSC	28-Dec-07	O/C	TSN 0				
SN:072203001251C	HRS	1255.7		TSN 0				
	AFL	1031		TSN 0				
PROC. REF: AMM 28-20-04PROC. REF: AMM 28-20-04								
282829	APU FUEL LINE							Component ATA:28
PN:4549058032-005	MOS/MSC	21-Feb-22	O/C	TSN 0				
SN:UNKNOWN	HRS	4819.5		TSN 0				
	AFL	4049		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
284001	C1 FUEL PROBE							Component ATA:28
PN:6628408000-001	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:0658	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05								
284002	C2 FUEL PROBE							Component ATA:28
PN:6628408000-003	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:0582	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05								
284003	C3 FUEL PROBE							Component ATA:28
PN:6628408000-005	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:0599	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05								
284004	C4 FUEL PROBE							Component ATA:28
PN:6628408000-007	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:0727	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05								
284005	C5 FUEL PROBE							Component ATA:28
PN:6628408000-009	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:0911	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05								
284006	C6 FUEL PROBE							Component ATA:28
PN:6628408000-011	MOS/MSC	11-Jun-13	O/C					
SN:1241	HRS	2964.4						
	AFL	2461						
PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05								
284008	C7 FUEL PROBE							Component ATA:28
PN:6628408000-001	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:0655	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05								
284009	C8 FUEL PROBE							Component ATA:28
PN:6628408000-003	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:0581	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05								
284010	C9 FUEL PROBE							Component ATA:28
PN:6628408000-005	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:0597	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45
Serial: 45-252
RegNo: N253SC
HRS: 5455.2
AFL: 4545
As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05								
284011	C10 FUEL PROBE							Component ATA:28
PN:6628408000-007	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:0726	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05								
284012	C11 FUEL PROBE							Component ATA:28
PN:6628408000-009	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:0942	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05								
284013	C12 FUEL PROBE							Component ATA:28
PN:6628408000-011	MOS/MSC	11-Jun-13	O/C	TSN 107				
SN:1240	HRS	2964.4		TSN 2964.4				
	AFL	2461		TSN 2461				
PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05								
284014	C13 FUEL PROBE							Component ATA:28
PN:6628408000-011	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:1241	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05								
284015	C14 FUEL PROBE							Component ATA:28
PN:6628408000-021	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:0574	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05								
284016	C15 FUEL PROBE							Component ATA:28
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05								
284017	C16 FUEL PROBE							Component ATA:28
PN:6628408000-021	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:0331	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05								
284033	FUSELAGE FUEL PROBE							Component ATA:28
PN:6628408000-019	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:777	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-40-05PROC. REF: AMM 28-40-05								
284035	NO. 1 LOW PRESSURE FUEL SWITCH							Component ATA:28
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-40-01PROC. REF: AMM 28-40-01								
284036	NO. 2 LOW PRESSURE FUEL SWITCH							Component ATA:28
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-40-01PROC. REF: AMM 28-40-01								
284041	LEFT FUEL FLOAT SWITCH							Component ATA:28
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-40-02PROC. REF: AMM 28-40-02								
284042	RIGHT FUEL FLOAT SWITCH							Component ATA:28
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
PROC. REF: AMM 28-40-02PROC. REF: AMM 28-40-02								
284045	FUEL QUANTITY SIGNAL CONDITIONER							Component ATA:28
PN:10551B08Y09	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:0864	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-40-04PROC. REF: AMM 28-40-04								
284047	LEFT LOW LEVEL FUEL SENSOR							Component ATA:28
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-40-03PROC. REF: AMM 28-40-03								
284048	RIGHT LOW LEVEL FUEL SENSOR							Component ATA:28
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-40-03PROC. REF: AMM 28-40-03								
D2820013	PERFORM INITIAL CLEANING AND LEAK CHECK OF LOW-PRESSURE FUEL FILTERS							Service ATA:28
	MOS/MSC	03-Nov-04	A/R					
	HRS	97.2						
	AFL	74						
PROC. REF: AMM 28-20-15PROC. REF: AMM 28-20-15								
F2840003 ^S	** FUEL QUANTITY SIGNAL CONDITIONER - PERFORM FUNCTIONAL TEST TO VERIFY WEIGHT ON WHEELS (WOW) INPUTS							Service ATA:28
	MOS	24-Feb-23	48 (+14d/-14d)					AIRWORTHINESS
	HRS	5067.1	1200 (+25/-25)					
	AFL	4262						
PROC. REF: AMM 28-40-00PROC. REF: AMM 28-40-00								
PKG:14								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
Y2810001	^S	WING TANKS - REMOVE FUEL TANK ACCESS PANELS AND PERFORM VISUAL INSPECTION						Service ATA:28
	MOS	09-Jul-24	24 (+14d/-14d)					
	HRS	5131.8	600 (+25/-25)					
	AFL	4323						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								PKG:10
Y2810002	^S	WING TANKS - REMOVE FUEL TANK ACCESS PANELS AND PERFORM VISUAL INSPECTION						Service ATA:28
	MOS	01-Mar-19	96 (+14d/-14d)					
	HRS	4123.3	2400 (+25/-25)					
	AFL	3499						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								PKG:22
Y2820000	^S	LOW PRESSURE FUEL FILTER - REMOVE AND INSPECT FOR CONTAMINATION. CLEAN IF NECESSARY.						Service ATA:28
	MOS	09-Jul-24	24 (+14d/-14d)					
	HRS	5131.8	600 (+25/-25)					
	AFL	4323						
PROC. REF: AMM 28-20-15PROC. REF: AMM 28-20-15								PKG:10
ATA 29 - HYDRAULIC POWER								
291001		HYDRAULIC RESERVOIR						Component ATA:29
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-10-02PROC. REF: AMM 29-10-02								
291012		L8 HYDRAULIC SHUTOFF VALVE						Component ATA:29
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-10-05PROC. REF: AMM 29-10-05								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 29 - HYDRAULIC POWER								
291013	L9 HYDRAULIC	SHUTOFF VALVE						Component ATA:29
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-10-05PROC. REF: AMM 29-10-05								
291033	RESERVOIR PRESSURIZATION	CONTROL MODULE						Component ATA:29
PN:ZVM11-2	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:3072878	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-10-06PROC. REF: AMM 29-10-06								
291034	RESERVOIR FLUID LEVEL	SENSOR						Component ATA:29
PN:3L14F-17	MOS/MSC	08-May-06	O/C	TSN 0				
SN:554	HRS	678.3		TSN 0				
	AFL	577		TSN 0				
PROC. REF: AMM 29-30-02PROC. REF: AMM 29-30-02								
291045	NO. 1 ENGINE DRIVEN	HYDRAULIC PUMP						Component ATA:29
PN:6629101000-001	MOS/MSC	08-May-06	O/C	TSN 0				
SN:MX696469A	HRS	678.3		TSN 0				
	AFL	577		TSN 0				
PROC. REF: AMM 29-10-01PROC. REF: AMM 29-10-01								
291046	NO. 2 ENGINE DRIVEN	HYDRAULIC PUMP						Component ATA:29
PN:6629101000-001	MOS/MSC	08-May-06	O/C	TSN 1				
SN:MX697472A	HRS	678.3		TSN 0				
	AFL	577		TSN 0				
PROC. REF: AMM 29-10-01PROC. REF: AMM 29-10-01								
291051	NO. 1 MAIN HYDRAULIC	SYSTEM PRESSURE SWITCH						Component ATA:29
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-30-03PROC. REF: AMM 29-30-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 29 - HYDRAULIC POWER								
291052	NO. 2 MAIN HYDRAULIC SYSTEM PRESSURE SWITCH							Component ATA:29
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-30-03PROC. REF: AMM 29-30-03								
291057	MAIN HYDRAULIC SYSTEM ACCUMULATOR							Component ATA:29
PN:88746-1	MOS/MSC	08-May-06	O/C	TSN 0				
SN:305	HRS	678.3		TSN 0				
	AFL	577		TSN 0				
PROC. REF: AMM 29-10-04PROC. REF: AMM 29-10-04								
291059	MAIN HYDRAULIC FILTER MANIFOLD							Component ATA:29
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-10-03PROC. REF: AMM 29-10-03								
291069	THERMAL SHUTOFF VALVE							Component ATA:29
PN:98050	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:0497	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-10-07PROC. REF: AMM 29-10-07								
292001	AUXILIARY FILTER MANIFOLD ASSEMBLY							Component ATA:29
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-20-02PROC. REF: AMM 29-20-02								
292011	AUXILIARY HYDRAULIC PUMP ASSEMBLY							Component ATA:29
PN:93835/66158-02	MOS/MSC	10-Sep-06	O/C	TSR 0				
SN:K0327	HRS	777.1		TSR 0				
	AFL			TSR 0				
PROC. REF: AMM 29-20-01PROC. REF: AMM 29-20-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 29 - HYDRAULIC POWER								
292012		AUXILIARY HYDRAULIC PUMP					Component	ATA:29
PN:66158-02	MOS/MSC	08-Jun-26	O/C	TSO 0				
SN:K0213	HRS	5429.9		TSO 0				
	AFL	4526		TSO 0				
PROC. REF: AMM 29-20-01PROC. REF: AMM 29-20-01								
292013		AUXILIARY HYDRAULIC PUMP ELECTRIC MOTOR					Component	ATA:29
PN:48-16-1	MOS/MSC	12-Apr-26	O/C	TSO 0				
SN:LEO828A	HRS	5373.7		TSO 0				
	AFL	4493		TSO 0				
PROC. REF: AMM 29-20-04PROC. REF: AMM 29-20-04								
292025		AUXILIARY HYDRAULIC SYSTEM PRESSURE SWITCH					Component	ATA:29
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-30-03PROC. REF: AMM 29-30-03								
292401		AUXILIARY HYDRAULIC PRESSURE CHECK VALVE					Component	ATA:29
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
293001		GROUND SERVICE CONTROL BOX					Component	ATA:29
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-30-01PROC. REF: AMM 29-30-01								
293003		LEFT HYDRAULIC LOW PRESSURE SWITCH					Component	ATA:29
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-30-03PROC. REF: AMM 29-30-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 29 - HYDRAULIC POWER								
293004	RIGHT HYDRAULIC LOW PRESSURE SWITCH (S8, S9)							Component ATA:29
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-30-03PROC. REF: AMM 29-30-03								
293011	HYDRAULIC PRESSURE TRANSDUCER							Component ATA:29
PN:7629301001-001	MOS/MSC	08-May-06	O/C					
SN:6677-1-312	HRS	678.3						
	AFL	577						
PROC. REF: AMM 29-30-04PROC. REF: AMM 29-30-04								
D2910017	MAIN HYDRAULIC FILTER MANIFOLD ELEMENTS - REPLACE							Service ATA:29
	MOS/MSC	07-Jul-04	-					
	HRS	0						
	AFL	0						
PROC. REF: AMM 29-10-03PROC. REF: AMM 29-10-03								
D2910018	MAIN HYDRAULIC FILTER MANIFOLD ELEMENTS - REPLACE							Service ATA:29
	MOS	24-Feb-23						
	HRS	5067.1	300 (+25/-25)	5367.1	5392.1	OVD		
	AFL	4262						
PROC. REF: AMM 29-10-03PROC. REF: AMM 29-10-03								
H2920002 ^S	HYDRAULIC SYSTEM GROUND SERVICE LEDS - PERFORM FUNCTIONAL TEST							Service ATA:29
	MOS	24-Feb-23	48 (+14d/-14d)					
	HRS	5067.1	1200 (+25/-25)					
	AFL	4262						
PROC. REF: AMM 29-30-00PROC. REF: AMM 29-30-00								PKG:13
O2910005	AUXILIARY HYDRAULIC FILTER MANIFOLD ELEMENTS - REPLACE							Service ATA:29
	MOS	18-Nov-21					LIFE LIMIT	
	HRS	4737	2400 (+25/-25)	7137	7162	1681.8 (+25)		
	AFL	3987						
PROC. REF: AMM 29-20-02PROC. REF: AMM 29-20-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 29 - HYDRAULIC POWER								
T2910026	^S	RELIEF FUNCTION OF THE PRESSURIZATION CONTROL MODULE - PERFORM FUNCTIONAL TEST						Service ATA:29
	MOS	24-Feb-23	48 (+14d/-14d)					
	HRS	5067.1	1200 (+25/-25)					
	AFL	4262						
PROC. REF: AMM 29-10-06PROC. REF: AMM 29-10-06								PKG:14
Y2910001	^S	HYDRAULIC COMPONENTS AND ASSOCIATED PLUMBING (AFT OF FUSELAGE FUEL CELL, FS 495 TO FS 512) - PERFORM VISUAL INSPECTION						Service ATA:29
	MOS	24-Feb-23	48 (+14d/-14d)					
	HRS	5067.1	1200 (+25/-25)					
	AFL	4262						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								PKG:14
Y2910002	^S	HYDRAULIC COMPONENTS AND ASSOCIATED PLUMBING (WHEEL WELL AND FORWARD AREA OF REAR SPAR) - PERFORM VISUAL INSPECTION						Service ATA:29
	MOS	24-Feb-23	48 (+14d/-14d)					
	HRS	5067.1	1200 (+25/-25)					
	AFL	4262						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								PKG:17
Y2910003	^S	HYDRAULIC COMPONENTS AND ASSOCIATED PLUMBING (AFT AREA OF REAR SPAR) - PERFORM VISUAL INSPECTION						Service ATA:29
	MOS	01-Mar-19	96 (+14d/-14d)					
	HRS	4123.3	2400 (+25/-25)					
	AFL	3499						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								PKG:19
Y2920001	^S	AUXILIARY HYDRAULIC SYSTEM - PERFORM OPERATIONAL CHECK						Service ATA:29
	MOS	24-Feb-23	48 (+14d/-14d)					
	HRS	5067.1	1200 (+25/-25)					
	AFL	4262						
PROC. REF: AMM 29-20-00PROC. REF: AMM 29-20-00								PKG:13

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
301006	ANTI-ICE VERTICAL STABILIZER RELAY PANEL (P40)							Component ATA:30
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-10-06PROC. REF: AMM 30-10-06								
301010	LEFT HORIZONTAL STABILIZER CONTROL SENSOR (MT47)							Component ATA:30
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-10-05PROC. REF: AMM 30-10-05								
301011	RIGHT HORIZONTAL STABILIZER CONTROL SENSOR (MT46)							Component ATA:30
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-10-05PROC. REF: AMM 30-10-05								
301051	LEFT ANTI-ICE 2.0 DIAMETER CHECK VALVE							Component ATA:30
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-10-02PROC. REF: AMM 30-10-02								
301052	RIGHT ANTI-ICE 2.0 DIAMETER CHECK VALVE							Component ATA:30
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-10-02PROC. REF: AMM 30-10-02								
301063	LEFT ANTI-ICE PRESSURE REGULATING SHUTOFF VALVE							Component ATA:30
PN:6621000000-087	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:798	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-10-01PROC. REF: AMM 30-10-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
301064	RIGHT ANTI-ICE PRESSURE REGULATING SHUTOFF VALVE							Component ATA:30
PN:6621000000-087	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:788	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-10-01PROC. REF: AMM 30-10-01								
301065	LEFT ANTI-ICE SHUTTLE VALVE							Component ATA:30
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 49-70-06, AMM 30-10-08PROC. REF: AMM 49-70-06, AMM 30-10-08								
301066	RIGHT ANTI-ICE SHUTTLE VALVE							Component ATA:30
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-10-08PROC. REF: AMM 30-10-08								
301240	ANTI-ICE MANIFOLD ASSEMBLY							Component ATA:30
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-10-07PROC. REF: AMM 30-10-07								
301401	RIGHT OUTBOARD WING ANTI-ICE TUBE							Component ATA:30
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
301601	LEFT INBOARD WING ANTI-ICE TUBE							Component ATA:30
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
301602	RIGHT WING ANTI-ICE TUBE							Component ATA:30
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
301603	LEFT FLEX SLIDE JOINT							Component ATA:30
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
301604	INSULATED ANTI-ICE ELBOW DUCT							Component ATA:30
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
301605	ANTI-ICE DUCT ASSEMBLY							Component ATA:30
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
301606	RIGHT FLEX SLIDE JOINT							Component ATA:30
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
302001	NO. 1 NACELLE INLET ANTI-ICE SHUTOFF VALVE							Component ATA:30
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-20-01PROC. REF: AMM 30-20-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
302002	NO. 2 NACELLE INLET ANTI-ICE SHUTOFF VALVE							Component ATA:30
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-20-01PROC. REF: AMM 30-20-01								
302013	NO. 1 NACELLE ANTI-ICE PRESSURE SWITCH							Component ATA:30
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-20-02PROC. REF: AMM 30-20-02								
302014	NO. 2 NACELLE ANTI-ICE PRESSURE SWITCH							Component ATA:30
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-20-02PROC. REF: AMM 30-20-02								
303501	LEFT NOSE RELAY BOX							Component ATA:30
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-30-01PROC. REF: AMM 30-30-01								
303510	RIGHT NOSE RELAY BOX							Component ATA:30
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-30-01PROC. REF: AMM 30-30-01								
304021	WINDSHIELD ANTI-ICE CONTROLLER							Component ATA:30
PN:90825-7	MOS/MSC	20-Nov-09	O/C					
SN:578	HRS	1920.5						
	AFL	1587						
PROC. REF: AMM 30-40-01PROC. REF: AMM 30-40-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
304060	NO. 1 WING SURFACE TEMPERATURE SENSOR							Component ATA:30
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-10-03PROC. REF: AMM 30-10-03								
304061	NO. 2 WING SURFACE TEMPERATURE SENSOR							Component ATA:30
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-10-03PROC. REF: AMM 30-10-03								
304062	NO. 3 WING SURFACE TEMPERATURE SENSOR							Component ATA:30
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-10-03PROC. REF: AMM 30-10-03								
304063	NO. 4 WING SURFACE TEMPERATURE SENSOR							Component ATA:30
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-10-03PROC. REF: AMM 30-10-03								
308005	ICE DETECTION PROBE							Component ATA:30
PN:0871HN2	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:0280	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-80-01PROC. REF: AMM 30-80-01								
A3020000 ^S	** NACELLE ANTI-ICE SYSTEM - PERFORM FUNCTIONAL TEST							Service ATA:30
	MOS	24-Feb-23	48 (+14d/-14d)					AIRWORTHINESS
	HRS	5067.1	1200 (+25/-25)					
	AFL	4262						
PROC. REF: AMM 30-20-00PROC. REF: AMM 30-20-00								
PKG:15								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
A3030000	^S	** PITOT-STATIC HEAT SYSTEM - PERFORM OPERATIONAL CHECK						Service ATA:30
	MOS	01-Mar-19	96 (+14d/-14d)					AIRWORTHINESS
	HRS	4123.3	2400 (+25/-25)					
	AFL	3499						
PROC. REF: AMM 30-30-00PROC. REF: AMM 30-30-00								PKG:19
AC3010006		** ANTI-ICE MANIFOLD - PERFORM BORESCOPE INSPECTION						Service ATA:30
	MOS	18-Nov-21						
	HRS	4737	600 (+25/-25)		5337	5362	OVD	
	AFL	3987						
PROC. REF: AMM 30-10-07PROC. REF: AMM 30-10-07								
H3010000	^S	** WING/STAB ANTI-ICE SWITCH - PERFORM OPERATIONAL CHECK						Service ATA:30
	MOS	09-Jul-24	24 (+14d/-14d)					AIRWORTHINESS
	HRS	5131.8	600 (+25/-25)					
	AFL	4323						
PROC. REF: AMM 30-10-00PROC. REF: AMM 30-10-00								PKG:7
T3040000	^S	** WINDSHIELD ANTI-ICE - PERFORM FUNCTIONAL TEST OF THE WINDSHIELD ANTI-ICE SYSTEM						Service ATA:30
	MOS	09-Jul-24	24 (+14d/-14d)					AIRWORTHINESS
	HRS	5131.8	600 (+25/-25)					
	AFL	4323						
PROC. REF: AMM 30-40-00PROC. REF: AMM 30-40-00								PKG:7
Y3010007	^S	WING ANTI-ICE PICCOLO TUBE - PERFORM DETAILED VISUAL INSPECTION FOR CRACKS AT W.S. 43 AND W.S. 176.						Service ATA:30
	MOS	09-Jul-24	24 (+14d/-14d)					
	HRS	5131.8	600 (+25/-25)					
	AFL	4323						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:10

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
Y3080000 ^S	ICE DETECTION SYSTEM - PERFORM FUNCTIONAL TEST							Service ATA:30
	MOS	24-Feb-23	48 (+14d/-14d)					
	HRS	5067.1	1200 (+25/-25)					
	AFL	4262						
PROC. REF: AMM 30-80-00PROC. REF: AMM 30-80-00								PKG:13
Z3020005	* NO. 1 ENGINE INLET ANTI-ICE TUBE ASSEMBLY FROM THE AFT INLET BULKHEAD CONNECTION POINT FORWARD TO SPRAY RING CONNECTION, PERFORM DETAILED VISUAL/BORESCOPE INSPECTION OF THE WELDS INSIDE AND OUTSIDE OF THE TUBE AT BOTH FORWARD AND AFT ENDS.							Service ATA:30
	MOS	07-May-25						AIRWORTHINESS
	HRS	5263.7	250		5513.7		58.5	
	AFL	4423						
PROC. REF: AMM 30-20-00PROC. REF: AMM 30-20-00								
Z3020005	* NO. 2 ENGINE INLET ANTI-ICE TUBE ASSEMBLY FROM THE AFT INLET BULKHEAD CONNECTION POINT FORWARD TO SPRAY RING CONNECTION, PERFORM DETAILED VISUAL/BORESCOPE INSPECTION OF THE WELDS INSIDE AND OUTSIDE OF THE TUBE AT BOTH FORWARD AND AFT ENDS.							Service ATA:30
	MOS	07-May-25						AIRWORTHINESS
	HRS	5263.7	250		5513.7		58.5	
	AFL	4423						
PROC. REF: AMM 30-20-00PROC. REF: AMM 30-20-00								
Z3020006	NO. 1 ENGINE INLET ANTI-ICE TUBE ASSEMBLY FROM THE AFT INLET BULKHEAD CONNECTION POINT FORWARD TO SPRAY RING CONNECTION, PERFORM DETAILED VISUAL/BORESCOPE INSPECTION OF THE WELDS INSIDE AND OUTSIDE OF THE TUBE AT BOTH FORWARD AND AFT ENDS							Service ATA:30
	MOS/MSC	07-Jul-04	N/A					
	HRS	0						
	AFL	0						
PROC. REF: AMM 30-20-00PROC. REF: AMM 30-20-00								
Z3020006	NO. 2 ENGINE INLET ANTI-ICE TUBE ASSEMBLY FROM THE AFT INLET BULKHEAD CONNECTION POINT FORWARD TO SPRAY RING CONNECTION, PERFORM DETAILED VISUAL/BORESCOPE INSPECTION OF THE WELDS INSIDE AND OUTSIDE OF THE TUBE AT BOTH FORWARD AND AFT ENDS							Service ATA:30
	MOS/MSC	07-Jul-04	N/A					
	HRS	0						
	AFL	0						
PROC. REF: AMM 30-20-00PROC. REF: AMM 30-20-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 31 - INDICATING/RECORDING SYSTEMS								
311001	PILOT CIRCUIT BREAKER PANEL							Component ATA:31
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-60-01PROC. REF: AMM 24-60-01								
311005	COPILOT CIRCUIT BREAKER PANEL							Component ATA:31
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-60-01PROC. REF: AMM 24-60-01								
311601	GEAR UP/DOWN SWITCH							Component ATA:31
PN:7632608500-009	MOS/MSC	31-Dec-25	O/C	TSN 0				
SN:NA	HRS	5343		TSN 0				
	AFL	4470		TSN 0				
PROC. REF: AMM 32-30-02PROC. REF: AMM 32-30-02								
311606	CENTER SWITCH PANEL							Component ATA:31
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-11-03PROC. REF: AMM 31-11-03								
311805	ENGINE FUEL CONTROL PANEL							Component ATA:31
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-11-05PROC. REF: AMM 31-11-05								
311806	ENGINE/FUEL CONTROL PANEL OVERLAY							Component ATA:31
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 31 - INDICATING/RECORDING SYSTEMS								
311906	FORWARD QUADRANT SWITCH PANEL OVERLAY							Component ATA:31
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-11-04PROC. REF: AMM 31-11-04								
311907	RUDDER BOOST SWITCH (DS48)							Component ATA:31
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
312001	PILOTS DIGITAL CLOCK							Component ATA:31
PN:M850-5V-LA	MOS/MSC	28-Dec-07	O/C					
SN:A2603	HRS	1255.7						
	AFL	1031						
PROC. REF: AMM 31-21-01PROC. REF: AMM 31-21-01								
312002	COPILOTS DIGITAL CLOCK							Component ATA:31
PN:M850-5V-LA	MOS/MSC	12-Sep-14	O/C	TSN 0				
SN:A2848	HRS	3230.5		TSN 0				
	AFL	2666		TSN 0				
PROC. REF: AMM 31-21-01PROC. REF: AMM 31-21-01								
312011	PILOTS DAVTRON M850 DIGITAL CLOCK BATTERY							Component ATA:31
PN:TYPE N	MOS	30-Jan-26	12 (+14d/-14d)	TSN 0	31-Jan-27	13-Feb-27	192 d (+13)	LIFE LIMIT
SN:NA	HRS	5357.2		TSN 0				
	AFL	4482		TSN 0				
PROC. REF: AMM 31-21-02PROC. REF: AMM 31-21-02								
312012	COPILOTS DAVTRON M850 DIGITAL CLOCK BATTERY							Component ATA:31
PN:TYPE N	MOS	30-Jan-26	12 (+14d/-14d)	TSN 0	31-Jan-27	13-Feb-27	192 d (+13)	LIFE LIMIT
SN:NA	HRS	5357.2		TSN 0				
	AFL	4482		TSN 0				
PROC. REF: AMM 31-21-02PROC. REF: AMM 31-21-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45
Serial: 45-252
RegNo: N253SC
HRS: 5455.2
AFL: 4545
As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 31 - INDICATING/RECORDING SYSTEMS								
312101	LEFT INCLINOMETER ASSEMBLY							Component ATA:31
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
312102	RIGHT INCLINOMETER ASSEMBLY							Component ATA:31
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
313001	FLIGHT DATA RECORDER							Component ATA:31
PN:2100-2042-00	MOS/MSC	09-Mar-21	O/C	TSR 0				
SN:000113751	HRS	4594.8		TSR 0				
	AFL	3875		TSR 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
313001A	DOWNLOAD							Service ATA:31
PN:2100-2042-00	MOS	26-Apr-24	12		30-Apr-25		OVD	CUSTOMER CODE
SN:000113751	HRS							
	AFL							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
313003	FLIGHT DATA RECORDER (FDR) ACCELEROMETER							Component ATA:31
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
313005	FLIGHT DATA RECORDER UNDERWATER LOCATOR BEACON (FDR ULB)							Component ATA:31
PN:DK120	MOS/MSC	20-Aug-20	O/C	TSN 0				
SN:NT51812	HRS	4461.9		TSN 0				
	AFL	3775		TSN 0				
PROC. REF: AMM 25-61-01PROC. REF: AMM 25-61-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 31 - INDICATING/RECORDING SYSTEMS								
313010	HOBBS METER							Component ATA:31
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
313018	FLIGHT DATA RECORDER INERTIA SWITCH							Component ATA:31
PN:3LI-871/8	MOS/MSC	20-Aug-20	A/R	TSN 0				
SN:107661	HRS	4461.9		TSN 0				
	AFL	3775		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
314001	SELCAL DECODER							Component ATA:31
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
314011	NO. 1 DATA ACQUISITION (DAU) UNIT							Component ATA:31
PN:7013348-938	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:03125521	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-42-01PROC. REF: AMM 31-42-01								
314012	NO. 2 DATA ACQUISITION (DAU) UNIT							Component ATA:31
PN:7013348-938	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:04055639	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-42-01PROC. REF: AMM 31-42-01								
314023	NO. 1 INTEGRATED AVIONICS COMPUTER (IC-600)							Component ATA:31
PN:7017000-82224	MOS/MSC	21-Jun-10	O/C					
SN:06107773	HRS	2178.1						
	AFL	1788						
PROC. REF: AMM 31-41-01PROC. REF: AMM 31-41-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 31 - INDICATING/RECORDING SYSTEMS								
314024		NO. 2 INTEGRATED AVIONICS COMPUTER (IC-600)					Component	ATA:31
PN:7017000-82221	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:04056491	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-41-01PROC. REF: AMM 31-41-01								
314051		NO. 1 CENTRAL COMPUTING MEMORY MODULE IM-600					Component	ATA:31
PN:7025973-04216	MOS/MSC	20-Aug-20	O/C					
SN:04043013	HRS	4461.9						
	AFL	3775						
PROC. REF: AMM 31-41-02PROC. REF: AMM 31-41-02								
314052		NO. 2 CENTRAL COMPUTING MEMORY MODULE IM-600					Component	ATA:31
PN:7025973-04216	MOS/MSC	20-Aug-20	O/C	TSN 191				
SN:04022881	HRS	4461.9		TSN 4445				
	AFL	3775		TSN 3763				
PROC. REF: AMM 31-41-02PROC. REF: AMM 31-41-02								
315001		CREW WARNING PANEL					Component	ATA:31
PN:90-42801-7	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:278	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-51-01PROC. REF: AMM 31-51-01								
315005		PILOT REVERSION SWITCH					Component	ATA:31
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
316001		NO. 1 DU870 COMPUTER					Component	ATA:31
PN:7014300-901	MOS/MSC	21-Mar-06	O/C	TSR 0				
SN:98043075	HRS	645		TSR 0				
	AFL	562		TSR 0				
PROC. REF: AMM 31-60-01PROC. REF: AMM 31-60-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 31 - INDICATING/RECORDING SYSTEMS								
316002	NO. 2 DU875 COMPUTER							Component ATA:31
PN:7014300-901	MOS/MSC	26-Apr-24	O/C					
SN:01018443	HRS	5128.5						
	AFL	4317						
PROC. REF: AMM 31-60-01PROC. REF: AMM 31-60-01								
316003	NO. 3 DU875 COMPUTER							Component ATA:31
PN:7014300-901	MOS/MSC	26-Apr-24	O/C					
SN:0309C879	HRS	5128.5						
	AFL	4317						
PROC. REF: AMM 31-60-01PROC. REF: AMM 31-60-01								
316004	NO. 4 DU875 COMPUTER							Component ATA:31
PN:7014300-901	MOS/MSC	26-Apr-24	O/C					
SN:0501E310	HRS	5128.5						
	AFL	4317						
PROC. REF: AMM 31-60-01PROC. REF: AMM 31-60-01								
316005	PILOT EFIS DISPLAY CONTROLLER							Component ATA:31
PN:7016986-733	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:04045364	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-60-02PROC. REF: AMM 31-60-02								
316006	COPILOT EFIS DISPLAY CONTROLLER							Component ATA:31
PN:7016986-733	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:04045364	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-60-02PROC. REF: AMM 31-60-02								
316007	PILOT NO. 1 MULTIFUNCTION DISPLAY CONTROLLER BEZEL							Component ATA:31
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-60-01PROC. REF: AMM 31-60-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 31 - INDICATING/RECORDING SYSTEMS								
316008	PILOT NO. 2 MULTIFUNCTION DISPLAY CONTROLLER BEZEL							Component ATA:31
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-60-01PROC. REF: AMM 31-60-01								
316009	COPILOT NO. 1 MULTIFUNCTION DISPLAY CONTROLLER BEZEL							Component ATA:31
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-60-01PROC. REF: AMM 31-60-01								
316010	COPILOT NO. 2 MULTIFUNCTION DISPLAY CONTROLLER BEZEL							Component ATA:31
PN:7014331-715	MOS/MSC	27-Jan-12	O/C					
SN:02014436	HRS	2577.4						
	AFL	2121						
PROC. REF: AMM 31-60-01PROC. REF: AMM 31-60-01								
316091	AFIS DATA TRANSFER UNIT							Component ATA:31
PN:15655-0101	MOS/MSC	09-Sep-04	O/C	TSN 0				
SN:1494	HRS	16		TSN 0				
	AFL	12		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
AA2560000	FLIGHT DATA RECORDER UNDERWATER LOCATOR BEACON - CLEAN BEACON SWITCH, PERFORM FUNCTIONAL TEST OF BEACON, AND PERFORM TEST OF ULB BATTERY							Service ATA:31
PN:DK120	MOS	12-Dec-25	24 (+14d/-14d)	Adj -412d	31-Oct-26	09-Nov-26	100 d (+9)	
SN:NT51812	HRS	5343						
	AFL	4470						
B3100000 ^S	** INDICATING/RECORDING SYSTEM - PERFORM OPERATIONAL CHECK							Service ATA:31
	MOS	09-Jul-24	24 (+14d/-14d)					AIRWORTHINESS
	HRS	5131.8	600 (+25/-25)					
	AFL	4323						
PROC. REF: AMM 31-00-00PROC. REF: AMM 31-00-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 31 - INDICATING/RECORDING SYSTEMS								
D2566001	FLIGHT DATA RECORDER UNDERWATER LOCATOR BEACON - REPLACE							Service ATA:31
PN:DK120	MOS/MSC	20-Aug-20	DUE		15-May-28 (M)		662 d	
SN:NT51812	HRS	4461.9						
	AFL	3775						
Expiry Date: : 15-May-28								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
ATA 32 - LANDING GEAR								
320041	LEFT MAIN LANDING GEAR UPPER LINK PIN							Component ATA:32
PN:200-0214-101	MOS	24-Jul-12						LIFE LIMIT
SN:UNKNOWN	HRS	2714.6						
	AFL	2235	10000	TSN 2235	10000		5455	
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01								
320042	RIGHT MAIN LANDING GEAR UPPER LINK PIN							Component ATA:32
PN:200-0214-101	MOS	24-Jul-12						LIFE LIMIT
SN:UNKNOWN	HRS	2714.6						
	AFL	2235	10000	TSN 2235	10000		5455	
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01								
320043	LEFT MAIN LANDING GEAR LOWER LINK PIN							Component ATA:32
PN:200-0214-101	MOS	24-Jul-12						AIRWORTHINESS
SN:UNKNOWN	HRS	2714.6						
	AFL	2235	10000	TSN 2235	10000		5455	
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01								
320044	RIGHT MAIN LANDING GEAR LOWER LINK PIN							Component ATA:32
PN:200-0214-101	MOS	24-Jul-12						AIRWORTHINESS
SN:UNKNOWN	HRS	2714.6						
	AFL	2235	10000	TSN 2235	10000		5455	
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01								
320051	LEFT MAIN LANDING GEAR PISTON PIN							Component ATA:32
PN:200-0215-101	MOS	19-Jul-12						LIFE LIMIT
SN:H0741	HRS	2714.6						
	AFL	2235	10000	TSN 2235	10000		5455	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01								
320052	RIGHT MAIN LANDING GEAR PISTON PIN							Component ATA:32
PN:200-0215-101	MOS	19-Jul-12						LIFE LIMIT
SN:H0739	HRS	2714.6						
	AFL	2235	10000	TSN 2235	10000		5455	
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01								
320061	LEFT MAIN LANDING GEAR ACTUATOR PISTON							Component ATA:32
PN:PN-UNKNOWN	MOS/MSC	08-May-06	H/T	TSN 0				
SN:UNKNOWN	HRS	678.3		TSN 0				
	AFL	577		TSN 0				
PROC. REF: AMM 32-31-01PROC. REF: AMM 32-31-01								
320062	RIGHT MAIN LANDING GEAR ACTUATOR PISTON							Component ATA:32
PN:PN-UNKNOWN	MOS/MSC	08-May-06	H/T	TSN 0				
SN:UNKNOWN	HRS	678.3		TSN 0				
	AFL	577		TSN 0				
PROC. REF: AMM 32-31-01PROC. REF: AMM 32-31-01								
320071	LEFT MAIN LANDING GEAR ACTUATOR CYLINDER							Component ATA:32
PN:PN-UNKNOWN	MOS/MSC	08-May-06	H/T	TSN 0				
SN:UNKNOWN	HRS	678.3		TSN 0				
	AFL	577		TSN 0				
PROC. REF: AMM 32-31-01PROC. REF: AMM 32-31-01								
320072	RIGHT MAIN LANDING GEAR ACTUATOR CYLINDER							Component ATA:32
PN:PN-UNKNOWN	MOS/MSC	08-May-06	H/T	TSN 0				
SN:UNKNOWN	HRS	678.3		TSN 0				
	AFL	577		TSN 0				
PROC. REF: AMM 32-31-01PROC. REF: AMM 32-31-01								
320081	LEFT MAIN LANDING GEAR ACTUATOR END CAP							Component ATA:32
PN:200-0303-001	MOS/MSC	24-Jul-12	H/T	TSN 0				
SN:H2357	HRS	2714.6		TSN 0				
	AFL	2235		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
PROC. REF: AMM 32-31-01PROC. REF: AMM 32-31-01								
320082	RIGHT MAIN LANDING GEAR ACTUATOR END CAP							Component ATA:32
PN:200-0303-001	MOS/MSC	24-Jul-12	H/T	TSN 0				
SN:H2350	HRS	2714.6		TSN 0				
	AFL	2235		TSN 0				
PROC. REF: AMM 32-31-01PROC. REF: AMM 32-31-01								
320091	LEFT MAIN LANDING GEAR ACTUATOR HOUSING							Component ATA:32
PN:PN-UNKNOWN	MOS/MSC	08-May-06	H/T	TSN 0				
SN:UNKNOWN	HRS	678.3		TSN 0				
	AFL	577		TSN 0				
PROC. REF: AMM 32-31-01PROC. REF: AMM 32-31-01								
320092	RIGHT MAIN LANDING GEAR ACTUATOR HOUSING							Component ATA:32
PN:PN-UNKNOWN	MOS/MSC	08-May-06	H/T	TSN 0				
SN:UNKNOWN	HRS	678.3		TSN 0				
	AFL	577		TSN 0				
PROC. REF: AMM 32-31-01PROC. REF: AMM 32-31-01								
321001	LEFT MAIN LANDING GEAR STRUT							Component ATA:32
PN:200-0200-011	MOS	20-Aug-20						LIFE LIMIT
SN:H0292	HRS	4461.9						
	AFL	3775	10000	TSN 3775	10000		5455	
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01								
321002	RIGHT MAIN LANDING GEAR STRUT							Component ATA:32
PN:200-0200-012	MOS	20-Aug-20						LIFE LIMIT
SN:H1296	HRS	4461.9						
	AFL	3775	10000	TSN 3775	10000		5455	
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01								
321011	LEFT MAIN LANDING GEAR SHOCK STRUT CYLINDER							Component ATA:32
PN:200-0201-109	MOS/MSC	19-Jul-12	H/T					
SN:H0377	HRS	2714.6						
	AFL	2235		TSN 2235				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45
Serial: 45-252
RegNo: N253SC
HRS: 5455.2
AFL: 4545
As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
PROC. REF: NDT PART 4/32-10-01, NDT PART 4/32-10-00, AMM 32-10-01PROC. REF: NDT PART 4/32-10-01, NDT PART 4/32-10-00, AMM 32-10-01								
321012	RIGHT MAIN LANDING GEAR SHOCK STRUT CYLINDER							Component ATA:32
PN:200-0201-110	MOS/MSC	19-Jul-12	H/T					
SN:H0375	HRS	2714.6						
	AFL	2235		TSN 2235				
PROC. REF: NDT PART 4/32-10-01, NDT PART 4/32-10-00PROC. REF: NDT PART 4/32-10-01, NDT PART 4/32-10-00								
321025	LEFT MAIN LANDING GEAR ACTUATOR UPPER PIN							Component ATA:32
PN:200-0325-101	MOS/MSC	26-Apr-24	H/T	TSN 0				
SN:TUR16589	HRS	5128.5		TSN 0				
	AFL	4317		TSN 0				
PROC. REF: AMM 32-31-01PROC. REF: AMM 32-31-01								
321026	RIGHT MAIN LANDING GEAR ACTUATOR UPPER PIN							Component ATA:32
PN:200-0325-101	MOS/MSC	26-Apr-24	H/T	TSN 0				
SN:TUR15179	HRS	5128.5		TSN 0				
	AFL	4317		TSN 0				
321037	LEFT MAIN LANDING GEAR ACTUATOR LOWER PIN							Component ATA:32
PN:200-0217-101	MOS/MSC	26-Apr-24	H/T	TSN 0				
SN:CPS01C-4141	HRS	5128.5		TSN 0				
	AFL	4317		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
321038	RIGHT MAIN LANDING GEAR ACTUATOR LOWER PIN							Component ATA:32
PN:200-0217-101	MOS/MSC	26-Apr-24	H/T	TSN 0				
SN:CPS01C-4140	HRS	5128.5		TSN 0				
	AFL	4317		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
321049	LEFT MAIN LANDING GEAR AXLE BEAM							Component ATA:32
PN:200-0203-101	MOS/MSC	24-Jul-12	H/T					
SN:H0688	HRS	2714.6						
	AFL	2235		TSN 2235				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01								
321050	RIGHT MAIN LANDING GEAR AXLE BEAM							Component ATA:32
PN:200-0203-101	MOS/MSC	24-Jul-12	H/T					
SN:H0706	HRS	2714.6						
	AFL	2235		TSN 2235				
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01								
321061	LEFT MAIN LANDING GEAR SIDE-STAY ACTUATOR PIN							Component ATA:32
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
321062	RIGHT MAIN LANDING GEAR SIDE-STAY ACTUATOR PIN							Component ATA:32
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
321073	LEFT MAIN LANDING GEAR SIDE BRACE ACTUATOR DISPLACEMENT TUBE							Component ATA:32
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
321074	RIGHT MAIN LANDING GEAR SIDE BRACE ACTUATOR DISPLACEMENT TUBE							Component ATA:32
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
321085	LEFT FORWARD TRUNNION ASSEMBLY							Component ATA:32
PN:4532103011-007	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:CM1931	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
321086	RIGHT FORWARD TRUNNION ASSEMBLY							Component ATA:32
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
321087	LEFT AFT TRUNNION ASSEMBLY							Component ATA:32
PN:4532103021-005	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:CM1920	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
321088	RIGHT AFT TRUNNION ASSEMBLY							Component ATA:32
PN:4532103021-006	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:CYC009.	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
321101	LEFT FORWARD MAIN LANDING GEAR TRUNNION PIN							Component ATA:32
PN:200-0212-103	MOS	20-Aug-20						LIFE LIMIT
SN:H0771	HRS	4461.9						
	AFL	3775	10000	TSN 3775	10000		5455	
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01								
321102	RIGHT FORWARD MAIN LANDING GEAR TRUNNION PIN							Component ATA:32
PN:200-0212-103	MOS	20-Aug-20						LIFE LIMIT
SN:H0876	HRS	4461.9						
	AFL	3775	10000	TSN 3775	10000		5455	
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01								
321103	LEFT AFT MAIN LANDING GEAR TRUNNION PIN							Component ATA:32
PN:200-0213-103	MOS	20-Aug-20						LIFE LIMIT
SN:H0580	HRS	4461.9						
	AFL	3775	10000	TSN 3775	10000		5455	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01								
321104	RIGHT AFT MAIN LANDING GEAR TRUNNION PIN							Component ATA:32
PN:200-0213-103	MOS	20-Aug-20						LIFE LIMIT
SN:H0582	HRS	4461.9						
	AFL	3775	10000	TSN 3775	10000		5455	
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01								
32111-2	NO. 1 BRAKE SWIVEL							Component ATA:32
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
321111	LEFT FORWARD LOWER MAIN LANDING GEAR TRUNNION SHEAR PIN							Component ATA:32
PN:4532103201-001	MOS/MSC	10-Jun-10	H/T					
SN:1370	HRS	2168.5						
	AFL	1782		TSN 0				
PROC. REF: AMM 57-10-05PROC. REF: AMM 57-10-05								
321112	RIGHT FORWARD LOWER MAIN LANDING GEAR TRUNNION SHEAR PIN							Component ATA:32
PN:4532103201-001	MOS/MSC	10-Jun-10	H/T					
SN:1222	HRS	2168.5						
	AFL	1782		TSN 0				
PROC. REF: AMM 57-10-05PROC. REF: AMM 57-10-05								
321113	LEFT FORWARD UPPER MAIN LANDING GEAR TRUNNION SHEAR PIN							Component ATA:32
PN:4532103201-001	MOS/MSC	10-Jun-10	H/T					
SN:1380	HRS	2168.5						
	AFL	1782		TSN 0				
PROC. REF: AMM 57-10-05PROC. REF: AMM 57-10-05								
321114	RIGHT FORWARD UPPER MAIN LANDING GEAR TRUNNION SHEAR PIN							Component ATA:32
PN:4532103201-001	MOS/MSC	10-Jun-10	H/T					
SN:1242	HRS	2168.5						
	AFL	1782		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45
Serial: 45-252
RegNo: N253SC
HRS: 5455.2
AFL: 4545
As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
PROC. REF: AMM 57-10-05PROC. REF: AMM 57-10-05								
321117	LEFT AFT UPPER MAIN LANDING GEAR TRUNNION SHEAR PIN							Component ATA:32
PN:4532103202-001	MOS/MSC	10-Jun-10	H/T					
SN:712	HRS	2168.5						
	AFL	1782		TSN 0				
PROC. REF: AMM 57-10-05PROC. REF: AMM 57-10-05								
321118	RIGHT AFT UPPER MAIN LANDING GEAR TRUNNION SHEAR PIN							Component ATA:32
PN:4532103202-001	MOS/MSC	10-Jun-10	H/T					
SN:682	HRS	2168.5						
	AFL	1782		TSN 0				
PROC. REF: AMM 57-10-05PROC. REF: AMM 57-10-05								
321119	LEFT AFT LOWER MAIN LANDING GEAR TRUNNION SHEAR PIN							Component ATA:32
PN:4532103203-001	MOS/MSC	10-Jun-10	H/T					
SN:639	HRS	2168.5						
	AFL	1782		TSN 0				
PROC. REF: AMM 57-10-05PROC. REF: AMM 57-10-05								
321120	RIGHT AFT LOWER MAIN LANDING GEAR TRUNNION SHEAR PIN							Component ATA:32
PN:4532103203-001	MOS/MSC	10-Jun-10	H/T					
SN:564	HRS	2168.5						
	AFL	1782		TSN 0				
PROC. REF: AMM 57-10-05PROC. REF: AMM 57-10-05								
321201	LEFT MAIN LANDING GEAR OLEO ASSEMBLY							Component ATA:32
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
321202	RIGHT MAIN LANDING GEAR OLEO ASSEMBLY							Component ATA:32
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
321215	LEFT MAIN LANDING GEAR SHOCK STRUT PISTON							Component ATA:32
PN:200-0202-101	MOS	19-Jul-12						LIFE LIMIT
SN:H0718	HRS	2714.6						
	AFL	2235	10000	TSN 2235	10000		5455	
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01								
321216	RIGHT MAIN LANDING GEAR SHOCK STRUT PISTON							Component ATA:32
PN:200-0202-101	MOS	19-Jul-12						LIFE LIMIT
SN:H0764	HRS	2714.6						
	AFL	2235	10000	TSN 2235	10000		5455	
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01								
321227	LEFT MAIN LANDING GEAR SHOCK STRUT LINK							Component ATA:32
PN:200-0204-101	MOS	19-Jul-12						LIFE LIMIT
SN:H0540	HRS	2714.6						
	AFL	2235	10000	TSN 2235	10000		5455	
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01								
321228	RIGHT MAIN LANDING GEAR SHOCK STRUT LINK							Component ATA:32
PN:200-0204-101	MOS	19-Jul-12						LIFE LIMIT
SN:H0569	HRS	2714.6						
	AFL	2235	10000	TSN 2235	10000		5455	
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01								
321301	LEFT MAIN LANDING GEAR OUTBOARD DOOR							Component ATA:32
PN:4552803003-003	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:219788300266	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-80-01PROC. REF: AMM 52-80-01								
321302	LEFT MAIN LANDING GEAR INBOARD DOOR							Component ATA:32
PN:4552803004-003	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:365100300266	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
PROC. REF: AMM 52-80-01PROC. REF: AMM 52-80-01								
321303RIGHT MAIN LANDING GEAR INBOARD DOOR								Component ATA:32
PN:4552803004-004	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:223830100266	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-80-01PROC. REF: AMM 52-80-01								
321304RIGHT MAIN LANDING GEAR OUTBOARD DOOR								Component ATA:32
PN:4552803003-004	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:219792000266	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-80-01PROC. REF: AMM 52-80-01								
322001NOSE LANDING GEAR STRUT ASSEMBLY								Component ATA:32
PN:4532201000V12-005	MOS	06-Feb-16		TSR 0				LIFE LIMIT
SN:148	HRS	3536.2		TSR 0				
	AFL	2920	20000	TSN 2920, TSR 0	20000		15455	
PROC. REF: AMM 32-20-01PROC. REF: AMM 32-20-01								
322002NOSE LANDING GEAR CYLINDER								Component ATA:32
PN:2342102-003	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:T302	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-32-01PROC. REF: AMM 32-32-01								
322003NOSE LANDING GEAR PISTON								Component ATA:32
PN:2342104-003	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:N217	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-32-01PROC. REF: AMM 32-32-01								
322004NOSE LANDING GEAR ACTUATOR BRACKET								Component ATA:32
PN:2342111-004	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:R202	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
PROC. REF: AMM 32-32-01PROC. REF: AMM 32-32-01								
322005	NOSE LANDING GEAR FORK							Component ATA:32
PN:2342116-3	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:R319	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-32-01PROC. REF: AMM 32-32-01								
322011	NOSE LANDING GEAR ACTUATOR ASSEMBLY							Component ATA:32
PN:6632201000-005	MOS	10-Sep-06		TSR 3				LIFE LIMIT
SN:EFS-352	HRS	777.1		TSN 678.3, TSR 0				
	AFL	657	20000	TSN 577, TSR 0	20080		15535	
PROC. REF: AMM 32-32-01PROC. REF: AMM 32-32-01								
322061	NOSE LANDING GEAR TRUNNION AXLE							Component ATA:32
PN:2342110-003	MOS	07-Jul-04		TSN 0				LIFE LIMIT
SN:R332	HRS	0		TSN 0				
	AFL	0	20000	TSN 0	20000		15455	
PROC. REF: AMM 32-20-01PROC. REF: AMM 32-20-01								
322071	LEFT NOSE LANDING GEAR TRUNNION PIN							Component ATA:32
PN:2342108-003	MOS	07-Jul-04		TSN 0				LIFE LIMIT
SN:BMC322	HRS	0		TSN 0				
	AFL	0	20000	TSN 0	20000		15455	
PROC. REF: AMM 32-20-01PROC. REF: AMM 32-20-01								
322072	RIGHT NOSE LANDING GEAR TRUNNION PIN							Component ATA:32
PN:2342108-003	MOS	07-Jul-04		TSN 0				LIFE LIMIT
SN:BMC321	HRS	0		TSN 0				
	AFL	0	20000	TSN 0	20000		15455	
PROC. REF: AMM 32-20-01PROC. REF: AMM 32-20-01								
322095	LEFT NOSE LANDING GEAR DOOR							Component ATA:32
PN:4552800001-007	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:0284	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
PROC. REF: AMM 52-81-01PROC. REF: AMM 52-81-01								
322096	RIGHT NOSE LANDING GEAR DOOR							Component ATA:32
PN:4552800002-007	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:0281	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-81-01PROC. REF: AMM 52-81-01								
322098	NOSE LANDING GEAR PISTON AXLE							Component ATA:32
PN:2342117-002	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:R367	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
322111	NOSE LANDING GEAR CHASSIS ASSEMBLY							Component ATA:32
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
322121	NOSE LANDING GEAR UPLOCK MECHANISM							Component ATA:32
PN:2269H000-003	MOS/MSC	10-Sep-06	O/C	TSR 0				
SN:1299	HRS	777.1		TSR 0				
	AFL			TSR 0				
PROC. REF: AMM 32-32-02PROC. REF: AMM 32-32-02								
323001	LEFT MAIN LANDING GEAR SIDE BRACE ACTUATOR ASSEMBLY							Component ATA:32
PN:200-300-003	MOS/MSC	20-Aug-20	H/T	TSR 98				
SN:H0268	HRS	4461.9		TSR 1747.3				
	AFL	3775		TSN 3775, TSR 1540				
323002	RIGHT MAIN LANDING GEAR SIDE BRACE ACTUATOR ASSEMBLY							Component ATA:32
PN:200-300-004	MOS/MSC	20-Aug-20	H/T	TSR 98				
SN:H1318	HRS	4461.9		TSR 1747.3				
	AFL	3775		TSN 3775, TSR 1540				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
323037	LEFT MAIN LANDING GEAR INBOARD DOOR UPLOCK MECHANISM							Component ATA:32
PN:6632303004-005	MOS/MSC	10-Sep-06	O/C	TSR 3				
SN:1667	HRS	777.1		TSR 0				
	AFL			TSR 0				
PROC. REF: AMM 32-31-04PROC. REF: AMM 32-31-04								
323038	RIGHT MAIN LANDING GEAR INBOARD DOOR UPLOCK MECHANISM							Component ATA:32
PN:6632303004-006	MOS/MSC	28-Dec-11	O/C	TSR 0				
SN:1718	HRS	2558.3		TSR 0				
	AFL	2103		TSR 0				
PROC. REF: AMM 32-31-04PROC. REF: AMM 32-31-04								
323110	NOSE LANDING GEAR DOWN-LOCK SWITCH							Component ATA:32
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-60-05PROC. REF: AMM 32-60-05								
323220	LEFT DOWN AND LOCKED SWITCH							Component ATA:32
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-60-02PROC. REF: AMM 32-60-02								
323221	RIGHT DOWN AND LOCKED SWITCH							Component ATA:32
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-60-02PROC. REF: AMM 32-60-02								
323225	LEFT UP LOCKED SWITCH							Component ATA:32
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
323226	RIGHT UP LOCKED SWITCH							Component ATA:32
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
323301	LEFT MAIN LANDING GEAR INBOARD DOOR ACTUATOR CAP SCREWS							Component ATA:32
PN:6632303003-003	MOS	26-Oct-22		TSO 0				LIFE LIMIT
SN:0944	HRS	4984.7	2400	TSN 0	7384.7		1929.5	
	AFL	4197		TSO 0				
PROC. REF: AMM 32-31-02PROC. REF: AMM 32-31-02								
323302	RIGHT MAIN LANDING GEAR INBOARD DOOR ACTUATOR CAP SCREWS							Component ATA:32
PN:6632303003-003	MOS	21-Jul-23						LIFE LIMIT
SN:0318	HRS	5076.3	2400	TSN 0	7476.3		2021.1	
	AFL	4268						
PROC. REF: AMM 32-31-02PROC. REF: AMM 32-31-02								
323304	MAIN LANDING GEAR HYDRAULIC ACTUATOR SWITCH							Component ATA:32
PN:72939	MOS/MSC	26-Sep-10	O/C					
SN:UNKNOWN	HRS	2247.4						
	AFL	1843						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
323305	LEFT MAIN LANDING GEAR ACTUATOR GIMBAL ASSEMBLY							Component ATA:32
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-31-06PROC. REF: AMM 32-31-06								
323306	RIGHT MAIN LANDING GEAR ACTUATOR GIMBAL ASSEMBLY							Component ATA:32
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-31-06PROC. REF: AMM 32-31-06								

?-Insufficient Information

S-Suppressed Requirement

*-Estimated Due(New Requirement)

(EFF)-Effective C/W

(M)-Manual Due

U-User Task

Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
323307	LEFT MAIN LANDING GEAR SHAFT GIMBAL ASSEMBLY							Component ATA:32
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-31-06PROC. REF: AMM 32-31-06								
323308	RIGHT MAIN LANDING GEAR SHAFT GIMBAL ASSEMBLY							Component ATA:32
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-31-06PROC. REF: AMM 32-31-06								
323309	LEFT MAIN LANDING GEAR INBOARD DOOR GIMBAL BRACKET ASSEMBLY							Component ATA:32
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-31-06PROC. REF: AMM 32-31-06								
323310	RIGHT MAIN LANDING GEAR INBOARD DOOR GIMBAL BRACKET ASSEMBLY							Component ATA:32
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-31-06PROC. REF: AMM 32-31-06								
323311	LEFT MAIN GEAR DOOR INBOARD ACTUATOR							Component ATA:32
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-31-02PROC. REF: AMM 32-31-02								
323312	RIGHT MAIN GEAR DOOR INBOARD ACTUATOR							Component ATA:32
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-31-02PROC. REF: AMM 32-31-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
323735	CONTROL VALVE							Component ATA:32
PN:6632302001-003	MOS/MSC	08-May-06	O/C	TSN 0				
SN:1323	HRS	678.3		TSN 0				
	AFL	577		TSN 0				
PROC. REF: AMM 32-30-01PROC. REF: AMM 32-30-01								
324001	NO. 1 MAIN LANDING GEAR WHEEL							Component ATA:32
PN:3-1545-1	MOS/MSC	24-Jun-26	O/C					
SN:1283	HRS	5446						
	AFL	4540						
PROC. REF: AMM 32-40-02PROC. REF: AMM 32-40-02								
324001A	NON DESTRUCTIVE TEST NO. 1 MAIN LANDING GEAR WHEEL							Service ATA:32
PN:3-1545-1	MOS/MSC	24-Jun-26	A/R					
SN:1283	HRS	5446						
	AFL	4540						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
324002	NO. 2 MAIN LANDING GEAR WHEEL							Component ATA:32
PN:3-1545-1	MOS/MSC	24-Jun-26	O/C					
SN:0261	HRS	5446						
	AFL	4540						
PROC. REF: AMM 32-40-02PROC. REF: AMM 32-40-02								
324002A	NON DESTRUCTIVE TEST NO. 2 MAIN LANDING GEAR WHEEL							Service ATA:32
PN:3-1545-1	MOS/MSC	24-Jun-26	A/R					
SN:0261	HRS	5446						
	AFL	4540						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
324003	NO. 3 MAIN LANDING GEAR WHEEL							Component ATA:32
PN:3-1545-1	MOS/MSC	16-Jun-26	O/C					
SN:0425	HRS	5437.4						
	AFL	4530						
PROC. REF: AMM 32-40-02PROC. REF: AMM 32-40-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45

Serial: 45-252

RegNo: N253SC

HRS: 5455.2

AFL: 4545

As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
324003A NON DESTRUCTIVE TEST NO. 3 MAIN LANDING GEAR WHEEL								Service ATA:32
PN:3-1545-1	MOS/MSC	16-Jun-26	A/R					
SN:0425	HRS	5437.4						
	AFL	4530						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
324004 NO. 4 MAIN LANDING GEAR WHEEL								Component ATA:32
PN:3-1545-1	MOS/MSC	16-Jun-26	O/C					
SN:2880	HRS	5437.4						
	AFL	4530						
PROC. REF: AMM 32-40-02PROC. REF: AMM 32-40-02								
324004A NON DESTRUCTIVE TEST NO. 4 MAIN LANDING GEAR WHEEL								Service ATA:32
PN:3-1545-1	MOS/MSC	16-Jun-26	A/R					
SN:2880	HRS	5437.4						
	AFL	4530						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
324005 NOSE GEAR WHEEL ASSEMBLY								Component ATA:32
PN:9544207-47	MOS/MSC	20-May-26	O/C					
SN:MAR04-9865	HRS	5425.8						
	AFL	4522						
PROC. REF: AMM 32-40-01PROC. REF: AMM 32-40-01								
324021 NO. 1 MAIN LANDING GEAR TIRE								Component ATA:32
PN:226K08-4	MOS/MSC	24-Jun-26	O/C	TSN 0				
SN:50030525	HRS	5446		TSN 0				
	AFL	4540		TSN 0				
PROC. REF: AMM 32-40-02PROC. REF: AMM 32-40-02								
324022 NO. 2 MAIN LANDING GEAR TIRE								Component ATA:32
PN:266K08-4	MOS/MSC	24-Jun-26	O/C	TSN 0				
SN:50040404	HRS	5446		TSN 0				
	AFL	4540		TSN 0				
PROC. REF: AMM 32-40-02PROC. REF: AMM 32-40-02								

?-Insufficient Information

S-Suppressed Requirement

*-Estimated Due(New Requirement)

(EFF)-Effective C/W

(M)-Manual Due

U-User Task

Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
324023	NO. 3 MAIN LANDING GEAR TIRE							Component ATA:32
PN:226K08-4	MOS/MSC	16-Jun-26	O/C	TSN 0				
SN:43530765	HRS	5437.4		TSN 0				
	AFL	4530		TSN 0				
PROC. REF: AMM 32-40-02PROC. REF: AMM 32-40-02								
324024	NO. 4 MAIN LANDING GEAR TIRE							Component ATA:32
PN:226K08-4	MOS/MSC	16-Jun-26	O/C	TSN 0				
SN:50030769	HRS	5437.4		TSN 0				
	AFL	4530		TSN 0				
PROC. REF: AMM 32-40-02PROC. REF: AMM 32-40-02								
324025	NOSE LANDING GEAR TIRE							Component ATA:32
PN:031-613-8	MOS/MSC	20-May-26	O/C	TSN 0				
SN:5338T00353	HRS	5425.8		TSN 0				
	AFL	4522		TSN 0				
PROC. REF: AMM 32-40-01PROC. REF: AMM 32-40-01								
324061	LEFT ANTI-SKID CONTROL VALVE							Component ATA:32
PN:6632401001-009	MOS/MSC	31-Dec-25	O/C					
SN:612	HRS	5343						
	AFL	4470						
PROC. REF: AMM 32-41-07PROC. REF: AMM 32-41-07								
324062	RIGHT ANTI-SKID CONTROL VALVE							Component ATA:32
PN:6632401001-009	MOS/MSC	08-May-06	O/C	TSN 15				
SN:357	HRS	678.3		TSN 0				
	AFL	577		TSN 0				
PROC. REF: AMM 32-41-07PROC. REF: AMM 32-41-07								
324066	LEFT ANTI-SKID SHUTOFF VALVE							Component ATA:32
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
324067	RIGHT ANTI-SKID SHUTOFF VALVE							Component ATA:32
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
324097	BRAKE CONTROL UNIT							Component ATA:32
PN:42-933-3	MOS/MSC	07-Oct-11	O/C	TSR 0				
SN:112A	HRS	2499.6		TSR 0				
	AFL	2050		TSR 0				
PROC. REF: AMM 32-41-02PROC. REF: AMM 32-41-02								
324108	EMERGENCY PARKING BRAKE CHECK VALVE							Component ATA:32
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-42-09PROC. REF: AMM 32-42-09								
324109	EMERGENCY/PARK BRAKE VALVE							Component ATA:32
PN:8196-5	MOS/MSC	21-May-08	O/C	TSN 10				
SN:0569	HRS	1422.7		TSN 0				
	AFL	1167		TSN 0				
PROC. REF: AMM 32-42-01PROC. REF: AMM 32-42-01								
324110	EMERGENCY/PARK BRAKE PRESSURE TRANSDUCER							Component ATA:32
PN:7629301001-001	MOS/MSC	08-May-06	O/C	TSN 0				
SN:6475-27	HRS	678.3		TSN 0				
	AFL	577		TSN 0				
PROC. REF: AMM 32-42-03PROC. REF: AMM 32-42-03								
324111	NO. 1 MAIN LANDING GEAR BRAKE ASSEMBLY							Component ATA:32
PN:2-1579-2	MOS/MSC	31-Dec-25	O/C					
SN:0439	HRS	5343						
	AFL	4470						
PROC. REF: AMM 32-41-01PROC. REF: AMM 32-41-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45

Serial: 45-252

RegNo: N253SC

HRS: 5455.2

AFL: 4545

As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
324111-1		INBOARD BRAKE NO. 1 SWIVEL					Component	ATA:32
PN:144890-06	MOS/MSC	06-Feb-16	O/C	TSN 0				
SN:1882	HRS	3536.2		TSN 0				
	AFL	2920		TSN 0				
PROC. REF: AMM 32-41-01PROC. REF: AMM 32-41-01								
324111-2		OUTBOARD BRAKE NO. 1 SWIVEL					Component	ATA:32
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-41-01PROC. REF: AMM 32-41-01								
324112		NO. 2 MAIN LANDING GEAR BRAKE ASSEMBLY					Component	ATA:32
PN:2-1579-2	MOS/MSC	31-Dec-25	O/C					
SN:1414P	HRS	5343						
	AFL	4470						
PROC. REF: AMM 32-41-01PROC. REF: AMM 32-41-01								
324112-1		INBOARD BRAKE NO. 2 SWIVEL					Component	ATA:32
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-41-01PROC. REF: AMM 32-41-01								
324112-2		OUTBOARD BRAKE NO. 2 SWIVEL					Component	ATA:32
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-41-01PROC. REF: AMM 32-41-01								
324113		NO. 3 MAIN LANDING GEAR BRAKE ASSEMBLY					Component	ATA:32
PN:2-1579-2	MOS/MSC	30-Jan-26	O/C					
SN:1894	HRS	5357.2						
	AFL	4482						
PROC. REF: AMM 32-41-01PROC. REF: AMM 32-41-01								

?-Insufficient Information

S-Suppressed Requirement

*-Estimated Due(New Requirement)

(EFF)-Effective C/W

(M)-Manual Due

U-User Task

Ex-Excluded Task

Status Report

Model: LEARJET 45

Serial: 45-252

RegNo: N253SC

HRS: 5455.2

AFL: 4545

As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
324113-1		INBOARD BRAKE NO. 3 SWIVEL					Component	ATA:32
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-41-01PROC. REF: AMM 32-41-01								
324113-2		OUTBOARD BRAKE NO. 3 SWIVEL					Component	ATA:32
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-41-01PROC. REF: AMM 32-41-01								
324114		NO. 4 MAIN LANDING GEAR BRAKE ASSEMBLY					Component	ATA:32
PN:2-1579-2	MOS/MSC	19-Mar-25	O/C	TSO 0				
SN:2250	HRS	5248		TSO 0				
	AFL	4416		TSO 0				
PROC. REF: AMM 32-41-01PROC. REF: AMM 32-41-01								
324114-1		INBOARD BRAKE NO. 4 SWIVEL					Component	ATA:32
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-41-01PROC. REF: AMM 32-41-01								
324114-2		OUTBOARD BRAKE NO. 4 SWIVEL					Component	ATA:32
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-41-01PROC. REF: AMM 32-41-01								
324201		NO. 1 BRAKE SHUTTLE VALVE					Component	ATA:32
PN:7632401002-001	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:1160	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-42-04PROC. REF: AMM 32-42-04								

?-Insufficient Information

S-Suppressed Requirement

*-Estimated Due(New Requirement)

(EFF)-Effective C/W

(M)-Manual Due

U-User Task

Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
324202	NO. 2 BRAKE SHUTTLE VALVE							Component ATA:32
PN:7632401002-001	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:1162	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-42-04PROC. REF: AMM 32-42-04								
324203	NO. 3 BRAKE SHUTTLE VALVE							Component ATA:32
PN:7632401002-003	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:1163	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-42-04PROC. REF: AMM 32-42-04								
324204	NO. 4 BRAKE SHUTTLE VALVE							Component ATA:32
PN:7632401002-003	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:1164	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-42-04PROC. REF: AMM 32-42-04								
324205	BRAKE SHUTTLE MODULE							Component ATA:32
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-41-04PROC. REF: AMM 32-41-04								
324305	LEFT PILOT BRAKE TRANSDUCER							Component ATA:32
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-41-03PROC. REF: AMM 32-41-03								
324306	RIGHT PILOT BRAKE TRANSDUCER							Component ATA:32
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-41-03PROC. REF: AMM 32-41-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
324307		LEFT CO-PILOT BRAKE TRANSDUCER					Component	ATA:32
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
324308		RIGHT CO-PILOT BRAKE TRANSDUCER					Component	ATA:32
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
324601		BRAKE ANTI-SKID SHUTTLE MODULE					Component	ATA:32
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
324610-1		LEFT INBOARD BRAKE SWIVEL					Component	ATA:32
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-41-01PROC. REF: AMM 32-41-01								
324610-2		LEFT OUTBOARD BRAKE SWIVEL					Component	ATA:32
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-41-01PROC. REF: AMM 32-41-01								
324611-1		RIGHT INBOARD BRAKE SWIVEL					Component	ATA:32
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-41-01PROC. REF: AMM 32-41-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
324611-2		RIGHT OUTBOARD BRAKE SWIVEL					Component	ATA:32
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-41-01PROC. REF: AMM 32-41-01								
324701		NO. 1 BRAKE HYDRAULIC FUSE					Component	ATA:32
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-41-09PROC. REF: AMM 32-41-09								
324702		NO. 2 BRAKE HYDRAULIC FUSE					Component	ATA:32
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-41-09PROC. REF: AMM 32-41-09								
324703		NO. 3 BRAKE HYDRAULIC FUSE					Component	ATA:32
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-41-09PROC. REF: AMM 32-41-09								
324704		NO. 4 BRAKE HYDRAULIC FUSE					Component	ATA:32
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-41-09PROC. REF: AMM 32-41-09								
324711		NO. 1 WHEEL SPEED TRANSDUCER					Component	ATA:32
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-41-10PROC. REF: AMM 32-41-10								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
324712	NO. 2 WHEEL SPEED TRANSDUCER							Component ATA:32
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-41-10PROC. REF: AMM 32-41-10								
324713	NO. 3 WHEEL SPEED TRANSDUCER							Component ATA:32
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-41-10PROC. REF: AMM 32-41-10								
324714	NO. 4 WHEEL SPEED TRANSDUCER							Component ATA:32
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-41-10PROC. REF: AMM 32-41-10								
324721	(MT56) BRAKE PRESSURE TRANSDUCER							Component ATA:32
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-41-08PROC. REF: AMM 32-41-08								
324722	(MT57) BRAKE PRESSURE TRANSDUCER							Component ATA:32
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-41-08PROC. REF: AMM 32-41-08								
324723	(MT58) BRAKE PRESSURE TRANSDUCER							Component ATA:32
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-41-08PROC. REF: AMM 32-41-08								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
324724	(MT59) BRAKE PRESSURE TRANSDUCER							Component ATA:32
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-41-08PROC. REF: AMM 32-41-08								
324725	(M69) BRAKE PRESSURE TRANSDUCER							Component ATA:32
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
324726	(M70) BRAKE PRESSURE TRANSDUCER							Component ATA:32
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
324801	EMERGENCY/PARK BRAKE FUSE							Component ATA:32
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-42-07PROC. REF: AMM 32-42-07								
324805	EMERGENCY/PARK BRAKE ACCUMULATOR							Component ATA:32
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-42-02PROC. REF: AMM 32-42-02								
325007	NOSE WHEEL STEERING FILTER BOX (P41)							Component ATA:32
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-50-06PROC. REF: AMM 32-50-06								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
325011	NOSE WHEEL STEERING SERVO ACTUATOR							Component ATA:32
PN:JR5208C	MOS/MSC	24-Sep-25	O/C	TSN 5				
SN:C0904	HRS	5329.2		TSN 0				
	AFL	4461		TSN 0				
PROC. REF: AMM 32-50-02PROC. REF: AMM 32-50-02								
325021	NOSE WHEEL STEERING GEARBOX							Component ATA:32
PN:2W3201D	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:C0317	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-50-03PROC. REF: AMM 32-50-03								
325031	NOSE WHEEL STEERING COMPUTER							Component ATA:32
PN:498000-03	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:00335	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-50-01PROC. REF: AMM 32-50-01								
325035	NOSE WHEEL STEERING POWER SUPPLY							Component ATA:32
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
325041	LEFT NOSE WHEEL STEERING TRANSDUCER							Component ATA:32
PN:3A1-279A	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:0649	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-50-04PROC. REF: AMM 32-50-04								
325042	RIGHT NOSE WHEEL STEERING TRANSDUCER							Component ATA:32
PN:3A1-279A	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:0640	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-50-04PROC. REF: AMM 32-50-04								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45
Serial: 45-252
RegNo: N253SC
HRS: 5455.2
AFL: 4545
As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
325051	NOSE LANDING GEAR ACTUATOR UPPER PIN							Component ATA:32
PN:4532302043-007	MOS	07-Jul-04		TSN 0				LIFE LIMIT
SN:338	HRS	0		TSN 0				
	AFL	0	20000	TSN 0	20000		15455	
PROC. REF: AMM 32-32-01PROC. REF: AMM 32-32-01								
326000	NOSE LANDING GEAR WIRE HARNESS							Component ATA:32
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
326104	NOSE LANDING GEAR SQUAT/WOW SWITCH (S178)							Component ATA:32
PN:622HE1-6	MOS/MSC	19-Mar-25	O/C	TSN 0				
SN:UNKNOWN	HRS	5248		TSN 0				
	AFL	4416		TSN 0				
PROC. REF: AMM 32-50-09PROC. REF: AMM 32-50-09								
326105	NO. 1 MAIN GEAR SQUAT SWITCH							Component ATA:32
PN:444EN2-R	MOS/MSC	31-Dec-25	O/C	TSN 0				
SN:NA	HRS	5343		TSN 0				
	AFL	4470		TSN 0				
PROC. REF: AMM 32-60-09PROC. REF: AMM 32-60-09								
326106	NO. 2 MAIN GEAR SQUAT SWITCH							Component ATA:32
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-60-09PROC. REF: AMM 32-60-09								
326107	NO. 3 MAIN GEAR SQUAT SWITCH							Component ATA:32
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-60-09PROC. REF: AMM 32-60-09								

? - Insufficient Information
S - Suppressed Requirement
* - Estimated Due(New Requirement)
(EFF) - Effective C/W
(M) - Manual Due
U - User Task
Ex - Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
326108	NO. 4 MAIN GEAR SQUAT SWITCH							Component ATA:32
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-60-09PROC. REF: AMM 32-60-09								
326115	SQUAT SWITCH RELAY BOX P21							Component ATA:32
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-60-08PROC. REF: AMM 32-60-08								
A3230001 ^S	** LANDING GEAR - PERFORM EMERGENCY GEAR EXTENSION FUNCTIONAL TEST							Service ATA:32
	MOS	09-Jul-24	24 (+14d/-14d)					AIRWORTHINESS
	HRS	5131.8	600 (+25/-25)					
	AFL	4323						
PROC. REF: AMM 32-33-00PROC. REF: AMM 32-33-00								
A3240005 ^S	** BRAKE HYDRAULIC FUSES - PERFORM FUNCTIONAL TEST							Service ATA:32
	MOS	24-Feb-23	48 (+14d/-14d)					AIRWORTHINESS
	HRS	5067.1	1200 (+25/-25)					
	AFL	4262						
PROC. REF: AMM 32-41-09PROC. REF: AMM 32-41-09								
A3240006 ^S	** BRAKE SHUTTLE MODULE - PERFORM FUNCTIONAL TEST							Service ATA:32
	MOS	24-Feb-23	48 (+14d/-14d)					AIRWORTHINESS
	HRS	5067.1	1200 (+25/-25)					
	AFL	4262						
PROC. REF: AMM 32-41-04PROC. REF: AMM 32-41-04								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
A3240007 ^S	** BRAKE SHUTTLE VALVES - PERFORM FUNCTIONAL TEST							Service ATA:32
	MOS	01-Mar-19	96 (+14d/-14d)					AIRWORTHINESS
	HRS	4123.3	2400 (+25/-25)					
	AFL	3499						
PROC. REF: AMM 32-42-04PROC. REF: AMM 32-42-04								PKG:23
A3240009 ^S	** BRAKE PRESSURE TRANSDUCERS - PERFORM FUNCTIONAL TEST							Service ATA:32
	MOS	18-Nov-21						AIRWORTHINESS
	HRS	4737	4800 (+25/-25)					
	AFL	3987						
PROC. REF: AMM 32-41-08PROC. REF: AMM 32-41-08								PKG:25
AA3220018	LEFT MAIN LANDING GEAR STRUT - PERFORM SPECIAL DETAILED INSPECTION							Service ATA:32
PN:200-0200-011	MOS	20-Aug-20	96 (+14d/-14d)		31-Aug-28	03-Sep-28	770 d (+3)	
SN:H0292	HRS	4461.9						
	AFL	3775	6600 (+25/-25)		10375	10400	5830 (+25)	
PROC. REF: NDT PART 7/32-10-01, NDT PART 7/32-10-03, NDT PART 7/32-10-04, NDT PART 8/32-10-02, NDT PART 7/32-10-05, NDT PART 7/32-10-06, NDT PART 8/32-10-01, NDT PART 8/32-10-03PROC. REF: NDT PART 7/32-10-01, NDT PART 7/32-10-03, NDT PART 7/32-10-04, NDT PART 8/32-10-02, NDT PART 7/32-10-05, NDT PART 7/32-10-06, NDT PART 8/32-10-01, NDT PART 8/32-10-03								
AA3220018	RIGHT MAIN LANDING GEAR STRUT - PERFORM SPECIAL DETAILED INSPECTION							Service ATA:32
PN:200-0200-012	MOS	20-Aug-20	96 (+14d/-14d)		31-Aug-28	03-Sep-28	770 d (+3)	
SN:H1296	HRS	4461.9						
	AFL	3775	6600 (+25/-25)		10375	10400	5830 (+25)	
PROC. REF: NDT PART 7/32-10-01, NDT PART 7/32-10-03, NDT PART 7/32-10-04, NDT PART 8/32-10-02, NDT PART 7/32-10-05, NDT PART 7/32-10-06, NDT PART 8/32-10-01, NDT PART 8/32-10-03PROC. REF: NDT PART 7/32-10-01, NDT PART 7/32-10-03, NDT PART 7/32-10-04, NDT PART 8/32-10-02, NDT PART 7/32-10-05, NDT PART 7/32-10-06, NDT PART 8/32-10-01, NDT PART 8/32-10-03								
AA3220111	LEFT MAIN LANDING GEAR SIDE BRACE ACTUATOR ASSEMBLY - DISASSEMBLE ACTUATOR AND PERFORM DETAILED VISUAL INSPECTION							Service ATA:32
PN:200-300-003	MOS	20-Aug-20	96 (+14d/-14d)		31-Aug-28	03-Sep-28	770 d (+3)	
SN:H0268	HRS	4461.9						
	AFL	3775	10000 (+25/-25)		13775	13800	9230 (+25)	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
AA3220111	RIGHT MAIN LANDING GEAR SIDE BRACE ACTUATOR ASSEMBLY - DISASSEMBLE ACTUATOR AND PERFORM DETAILED VISUAL INSPECTION							Service ATA:32
PN:200-300-004	MOS	20-Aug-20	96 (+14d/-14d)		31-Aug-28	03-Sep-28	770 d (+3)	
SN:H1318	HRS	4461.9						
	AFL	3775	10000 (+25/-25)		13775	13800	9230 (+25)	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
AB3220016 ^S	NOSE LANDING GEAR STRUT ASSEMBLY - PERFORM SPECIAL DETAILED INSPECTION							Service ATA:32
	MOS	07-Jul-04						
	HRS	0						
	AFL	0	10000 (+25/-25)					
PKG:27 PROC. REF: NDT PART 7/32-20-01, NDT PART 7/32-20-02, NDT PART 7/32-20-03, NDT PART 7/32-20-04, NDT PART 8/32-20-01, NDT PART 8/32-20-02, NDT PART 8/32-20-03, NDT PART 8/32-20-04, NDT PART 8/32-20-05PROC. REF: NDT PART 7/32-20-01, NDT PART 7/32-20-02, NDT PART 7/32-20-03, NDT PART 7/32-20-04, NDT PART 8/32-20-01, NDT PART 8/32-20-02, NDT PART 8/32-20-03, NDT PART 8/32-20-04, NDT PART 8/32-20-05								
AE3220151	LEFT - MAIN LANDING GEAR STRUT ASSEMBLY REBOUND RING - REPLACE.							Service ATA:32
	MOS	EFF	96		31-Aug-28 * (M)		770 d	
	HRS							
	AFL							
PROC. REF: AMM 32-31-02PROC. REF: AMM 32-31-02								
AE3220151	RIGHT - MAIN LANDING GEAR STRUT ASSEMBLY REBOUND RING - REPLACE.							Service ATA:32
	MOS	EFF	96		31-Aug-28 * (M)		770 d	
	HRS							
	AFL							
PROC. REF: AMM 32-31-02PROC. REF: AMM 32-31-02								
F3220045	NOSE LANDING GEAR ACTUATOR ATTACHMENT FITTING - REPLACE							Service ATA:32
	MOS/MSC	07-Jul-04	N/A					NOT INSTALLED
	HRS	0						
	AFL	0						
PROC. REF: AMM 32-32-01PROC. REF: AMM 32-32-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45

Serial: 45-252

RegNo: N253SC

HRS: 5455.2

AFL: 4545

As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
H3220017	^S	NOSE LANDING GEAR TRUNNION AXLE - PERFORM VISUAL INSPECTION. IF CORROSION IS FOUND, REMOVE AXLE FROM CYLINDER AND PERFORM FLUORESCENT PENETRANT INSPECTION OF LUG AREA AND MAGNETIC PARTICLE INSPECTION OF AXLE. IF CORROSION IS NOT FOUND, CONDUCT FLUORESCENT PENETRANT INSPECTION OF AXLE PORTION THAT IS EXPOSED FROM CYLINDER.						Service ATA:32
	MOS	07-Jul-04						
	HRS	0						
	AFL	0	10000 (+25/-25)					
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								PKG:27
J3220120		* MAIN LANDING GEAR TRUNNION SHEAR PIN BUSHING - PERFORM DETAILED VISUAL INSPECTION FOR BUSHING MIGRATION						Service ATA:32
	MOS/MSC	07-Jul-04	N/A					
	HRS	0						
	AFL	0						
PROC. REF: AMM 57-10-05PROC. REF: AMM 57-10-05								
L3220019	^S	NOSE LANDING GEAR ACTUATOR ATTACHMENT PIN - REMOVE PIN AND PERFORM MAGNETIC PARTICLE INSPECTION						Service ATA:32
	MOS	07-Jul-04						
	HRS	0						
	AFL	0	10000 (+25/-25)					
PROC. REF: NDT PART 7/32-30-02PROC. REF: NDT PART 7/32-30-02								PKG:27
L3220020		* MAIN LANDING GEAR TRUNNION FITTINGS ON MID AND REAR SPAR - PERFORM EDDY CURRENT INSPECTION						Service ATA:32
	MOS			TAC 0				AIRWORTHINESS
	HRS							
	AFL	0	T:10000		10000		5455	
PROC. REF: NDT PART 6/32-11-00PROC. REF: NDT PART 6/32-11-00								
L3220109	^S	NOSE LANDING GEAR ACTUATOR ASSEMBLY - DISASSEMBLE ACTUATOR AND PERFORM DETAILED VISUAL INSPECTION						Service ATA:32
	MOS	07-Jul-04						
	HRS	0						
	AFL	0	10000 (+25/-25)					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:27

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
L3220118	* LEFT MAIN LANDING GEAR SHOCK STRUT CYLINDER - PERFORM ULTRASONIC INSPECTION OF THE LOWER SERVICE PORT AND FORGING PARTING LINE							Service ATA:32
PN:200-0201-109	MOS/MSC	19-Jul-12	N/A					
SN:H0377	HRS	2714.6						
	AFL	2235						
L3220118	* RIGHT MAIN LANDING GEAR SHOCK STRUT CYLINDER - PERFORM ULTRASONIC INSPECTION OF THE LOWER SERVICE PORT AND FORGING PARTING LINE							Service ATA:32
PN:200-0201-110	MOS/MSC	19-Jul-12	N/A					
SN:H0375	HRS	2714.6						
	AFL	2235						
L3220122	* LEFT MAIN LANDING GEAR SHOCK STRUT CYLINDER - PERFORM ULTRASONIC INSPECTION OF THE LOWER SERVICE PORT AND FORGING PARTING LINE							Service ATA:32
PN:200-0201-109	MOS/MSC	19-Jul-12	N/A					
SN:H0377	HRS	2714.6						
	AFL	2235						
PROC. REF: NDT PART 4/32-10-01, NDT PART 4/32-10-00PROC. REF: NDT PART 4/32-10-01, NDT PART 4/32-10-00								
L3220122	* RIGHT MAIN LANDING GEAR SHOCK STRUT CYLINDER - PERFORM ULTRASONIC INSPECTION OF THE LOWER SERVICE PORT AND FORGING PARTING LINE							Service ATA:32
PN:200-0201-110	MOS/MSC	19-Jul-12	N/A					
SN:H0375	HRS	2714.6						
	AFL	2235						
PROC. REF: NDT PART 4/32-10-01, NDT PART 4/32-10-00PROC. REF: NDT PART 4/32-10-01, NDT PART 4/32-10-00								
M3220136	* LEFT MAIN LANDING GEAR SHOCK STRUT CYLINDER - PERFORM ULTRASONIC INSPECTION OF THE LOWER SERVICE PORT AND FORGING PARTING LINE							Service ATA:32
PN:200-0201-109	MOS/MSC	19-Jul-12	N/A					
SN:H0377	HRS	2714.6						
	AFL	2235						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
M3220136	* RIGHT MAIN LANDING GEAR SHOCK STRUT CYLINDER - PERFORM ULTRASONIC INSPECTION OF THE LOWER SERVICE PORT AND FORGING PARTING LINE							Service ATA:32
PN:200-0201-110	MOS/MSC	19-Jul-12	N/A					
SN:H0375	HRS	2714.6						
	AFL	2235						
N3220036	* LEFT MAIN LANDING GEAR AXLE BEAM - REPLACE							Service ATA:32
PN:200-0203-101	MOS	24-Jul-12						LIFE LIMIT
SN:H0688	HRS	2714.6						
	AFL	2235	10000	TAC 2235	10000		5455	
N3220036	* RIGHT MAIN LANDING GEAR AXLE BEAM - REPLACE							Service ATA:32
PN:200-0203-101	MOS	24-Jul-12						LIFE LIMIT
SN:H0706	HRS	2714.6						
	AFL	2235	10000	TAC 2235	10000		5455	
N3220041	* LEFT FORWARD LOWER MAIN LANDING GEAR TRUNNION SHEAR PIN - REPLACE							Service ATA:32
PN:4532103201-001	MOS/MSC	10-Jun-10	N/A					
SN:1370	HRS	2168.5						
	AFL	1782						
N3220041	* LEFT FORWARD UPPER MAIN LANDING GEAR TRUNNION SHEAR PIN - REPLACE							Service ATA:32
PN:4532103201-001	MOS/MSC	10-Jun-10	N/A					
SN:1380	HRS	2168.5						
	AFL	1782						
N3220041	* RIGHT FORWARD LOWER MAIN LANDING GEAR TRUNNION SHEAR PIN - REPLACE							Service ATA:32
PN:4532103201-001	MOS/MSC	10-Jun-10	N/A					
SN:1222	HRS	2168.5						
	AFL	1782						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
N3220041	* RIGHT FORWARD UPPER MAIN LANDING GEAR TRUNNION SHEAR PIN - REPLACE							Service ATA:32
PN:4532103201-001	MOS/MSC	10-Jun-10	N/A					
SN:1242	HRS	2168.5						
	AFL	1782						
N3220042	* LEFT AFT UPPER MAIN LANDING GEAR TRUNNION SHEAR PIN - REPLACE							Service ATA:32
PN:4532103202-001	MOS/MSC	10-Jun-10	N/A					
SN:712	HRS	2168.5						
	AFL	1782						
N3220042	* RIGHT AFT UPPER MAIN LANDING GEAR TRUNNION SHEAR PIN - REPLACE							Service ATA:32
PN:4532103202-001	MOS/MSC	10-Jun-10	N/A					
SN:682	HRS	2168.5						
	AFL	1782						
N3220043	* LEFT AFT LOWER MAIN LANDING GEAR TRUNNION SHEAR PIN - REPLACE							Service ATA:32
PN:4532103203-001	MOS/MSC	10-Jun-10	N/A					
SN:639	HRS	2168.5						
	AFL	1782						
N3220043	* RIGHT AFT LOWER MAIN LANDING GEAR TRUNNION SHEAR PIN - REPLACE							Service ATA:32
PN:4532103203-001	MOS/MSC	10-Jun-10	N/A					
SN:564	HRS	2168.5						
	AFL	1782						
N3220103	* LEFT MAIN LANDING GEAR ACTUATOR PISTON - REPLACE							Service ATA:32
PN:PN-UNKNOWN	MOS	08-May-06						LIFE LIMIT
SN:UNKNOWN	HRS	678.3						
	AFL	577	17000		17577		13032	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
N3220103	* RIGHT MAIN LANDING GEAR ACTUATOR PISTON - REPLACE							Service ATA:32
PN:PN-UNKNOWN	MOS	08-May-06						LIFE LIMIT
SN:UNKNOWN	HRS	678.3						
	AFL	577	17000		17577		13032	
N3220104	* LEFT MAIN LANDING GEAR ACTUATOR CYLINDER - REPLACE							Service ATA:32
PN:PN-UNKNOWN	MOS	08-May-06						LIFE LIMIT
SN:UNKNOWN	HRS	678.3						
	AFL	577	17000		17577		13032	
N3220104	* RIGHT MAIN LANDING GEAR ACTUATOR CYLINDER - REPLACE							Service ATA:32
PN:PN-UNKNOWN	MOS	08-May-06						LIFE LIMIT
SN:UNKNOWN	HRS	678.3						
	AFL	577	17000		17577		13032	
N3220106	* LEFT MAIN LANDING GEAR ACTUATOR HOUSING - REPLACE							Service ATA:32
PN:PN-UNKNOWN	MOS	08-May-06						LIFE LIMIT
SN:UNKNOWN	HRS	678.3						
	AFL	577	17000		17577		13032	
N3220106	* RIGHT MAIN LANDING GEAR ACTUATOR HOUSING - REPLACE							Service ATA:32
PN:PN-UNKNOWN	MOS	08-May-06						LIFE LIMIT
SN:UNKNOWN	HRS	678.3						
	AFL	577	17000		17577		13032	
N3220116	* LEFT MAIN LANDING GEAR SHOCK STRUT CYLINDER - REPLACE							Service ATA:32
PN:200-0201-109	MOS	19-Jul-12						LIFE LIMIT
SN:H0377	HRS	2714.6						
	AFL	2235	10000	TAC 2235	10000		5455	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
N3220116	* RIGHT MAIN LANDING GEAR SHOCK STRUT CYLINDER - REPLACE							Service ATA:32
PN:200-0201-110	MOS	19-Jul-12						LIFE LIMIT
SN:H0375	HRS	2714.6						
	AFL	2235	10000	TAC 2235	10000		5455	
N3220139	* LEFT FORWARD LOWER MAIN LANDING GEAR TRUNNION SHEAR PIN - REPLACE							Service ATA:32
PN:4532103201-001	MOS	10-Jun-10						LIFE LIMIT
SN:1370	HRS	2168.5						
	AFL	1782	5000		6782		2237	
N3220139	* LEFT FORWARD UPPER MAIN LANDING GEAR TRUNNION SHEAR PIN - REPLACE							Service ATA:32
PN:4532103201-001	MOS	10-Jun-10						LIFE LIMIT
SN:1380	HRS	2168.5						
	AFL	1782	5000		6782		2237	
N3220139	* RIGHT FORWARD LOWER MAIN LANDING GEAR TRUNNION SHEAR PIN - REPLACE							Service ATA:32
PN:4532103201-001	MOS	10-Jun-10						LIFE LIMIT
SN:1222	HRS	2168.5						
	AFL	1782	5000		6782		2237	
N3220139	* RIGHT FORWARD UPPER MAIN LANDING GEAR TRUNNION SHEAR PIN - REPLACE							Service ATA:32
PN:4532103201-001	MOS	10-Jun-10						LIFE LIMIT
SN:1242	HRS	2168.5						
	AFL	1782	5000		6782		2237	
N3220140	* LEFT AFT UPPER MAIN LANDING GEAR TRUNNION SHEAR PIN - REPLACE							Service ATA:32
PN:4532103202-001	MOS	10-Jun-10						LIFE LIMIT
SN:712	HRS	2168.5						
	AFL	1782	5000		6782		2237	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
N3220140	* RIGHT AFT UPPER MAIN LANDING GEAR TRUNNION SHEAR PIN - REPLACE							Service ATA:32
PN:4532103202-001	MOS	10-Jun-10						LIFE LIMIT
SN:682	HRS	2168.5						
	AFL	1782	5000		6782		2237	
N3220141	* LEFT AFT LOWER MAIN LANDING GEAR TRUNNION SHEAR PIN - REPLACE							Service ATA:32
PN:4532103203-001	MOS	10-Jun-10						LIFE LIMIT
SN:639	HRS	2168.5						
	AFL	1782	5000		6782		2237	
N3220141	* RIGHT AFT LOWER MAIN LANDING GEAR TRUNNION SHEAR PIN - REPLACE							Service ATA:32
PN:4532103203-001	MOS	10-Jun-10						LIFE LIMIT
SN:564	HRS	2168.5						
	AFL	1782	5000		6782		2237	
P3220146	* LEFT MAIN LANDING GEAR SHOCK STRUT CYLINDER - PERFORM ULTRASONIC INSPECTION OF THE FORGING PARTING LINE							Service ATA:32
PN:200-0201-109	MOS	19-Jul-12						AIRWORTHINESS
SN:H0377	HRS	2714.6						
	AFL	2235	T:4800		4800 (M)		255	
PROC. REF: NDT PART 4/32-10-01, NDT PART 4/32-10-00PROC. REF: NDT PART 4/32-10-01, NDT PART 4/32-10-00								
P3220146	* RIGHT MAIN LANDING GEAR SHOCK STRUT CYLINDER - PERFORM ULTRASONIC INSPECTION OF THE FORGING PARTING LINE							Service ATA:32
PN:200-0201-110	MOS	19-Jul-12						AIRWORTHINESS
SN:H0375	HRS	2714.6						
	AFL	2235	T:4800		4800 (M)		255	
PROC. REF: NDT PART 4/32-10-01, NDT PART 4/32-10-00PROC. REF: NDT PART 4/32-10-01, NDT PART 4/32-10-00								
P3231020	LEFT MAIN LANDING GEAR DOOR ACTUATOR GIMBAL ASSEMBLY - PERFORM EDDY CURRENT INSPECTION							Service ATA:32
	MOS/MSC	17-Oct-07	N/A					
	HRS	1174.8						
	AFL	963						
PROC. REF: NDT PART 6/32-13-00PROC. REF: NDT PART 6/32-13-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45
Serial: 45-252
RegNo: N253SC
HRS: 5455.2
AFL: 4545
As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
P3231021	LEFT MAIN LANDING GEAR DOOR ACTUATOR GIMBAL SHAFT - PERFORM FLUORESCENT PENETRANT INSPECTION							Service ATA:32
	MOS/MSC	17-Oct-07	N/A					
	HRS	1174.8						
	AFL	963						
PROC. REF: NDT PART 8/32-13-02PROC. REF: NDT PART 8/32-13-02								
Q3220065	* LEFT MAIN LANDING GEAR ACTUATOR PISTON - REPLACE							Service ATA:32
PN:PN-UNKNOWN	MOS/MSC	08-May-06	N/A					
SN:UNKNOWN	HRS	678.3						
	AFL	577						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
Q3220065	* RIGHT MAIN LANDING GEAR ACTUATOR PISTON - REPLACE							Service ATA:32
PN:PN-UNKNOWN	MOS/MSC	08-May-06	N/A					
SN:UNKNOWN	HRS	678.3						
	AFL	577						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
Q3220066	* LEFT MAIN LANDING GEAR ACTUATOR CYLINDER - REPLACE							Service ATA:32
PN:PN-UNKNOWN	MOS/MSC	08-May-06	N/A					
SN:UNKNOWN	HRS	678.3						
	AFL	577						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
Q3220066	* RIGHT MAIN LANDING GEAR ACTUATOR CYLINDER - REPLACE							Service ATA:32
PN:PN-UNKNOWN	MOS/MSC	08-May-06	N/A					
SN:UNKNOWN	HRS	678.3						
	AFL	577						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
Q3220068	* LEFT MAIN LANDING GEAR ACTUATOR HOUSING - REPLACE							Service ATA:32
PN:PN-UNKNOWN	MOS/MSC	08-May-06	N/A					
SN:UNKNOWN	HRS	678.3						
	AFL	577						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45
Serial: 45-252
RegNo: N253SC
HRS: 5455.2
AFL: 4545
As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
Q3220068		* RIGHT MAIN LANDING GEAR ACTUATOR HOUSING - REPLACE						Service ATA:32
PN:PN-UNKNOWN	MOS/MSC	08-May-06	N/A					
SN:UNKNOWN	HRS	678.3						
	AFL	577						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
Q3220128		* LEFT MAIN LANDING GEAR SHOCK STRUT CYLINDER - REPLACE						Service ATA:32
PN:200-0201-109	MOS/MSC	19-Jul-12	N/A					
SN:H0377	HRS	2714.6						
	AFL	2235						
Q3220128		* RIGHT MAIN LANDING GEAR SHOCK STRUT CYLINDER - REPLACE						Service ATA:32
PN:200-0201-110	MOS/MSC	19-Jul-12	N/A					
SN:H0375	HRS	2714.6						
	AFL	2235						
Q3220137		* LEFT MAIN LANDING GEAR SHOCK STRUT CYLINDER - REPLACE						Service ATA:32
PN:200-0201-109	MOS/MSC	19-Jul-12	N/A					
SN:H0377	HRS	2714.6						
	AFL	2235						
Q3220137		* RIGHT MAIN LANDING GEAR SHOCK STRUT CYLINDER - REPLACE						Service ATA:32
PN:200-0201-110	MOS/MSC	19-Jul-12	N/A					
SN:H0375	HRS	2714.6						
	AFL	2235						
Q3220142		* LEFT FORWARD LOWER MAIN LANDING GEAR TRUNNION SHEAR PIN - REPLACE						Service ATA:32
PN:4532103201-001	MOS/MSC	10-Jun-10	N/A					
SN:1370	HRS	2168.5						
	AFL	1782						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
Q3220142	* LEFT FORWARD UPPER MAIN LANDING GEAR TRUNNION SHEAR PIN - REPLACE							Service ATA:32
PN:4532103201-001	MOS/MSC	10-Jun-10	N/A					
SN:1380	HRS	2168.5						
	AFL	1782						
Q3220142	* RIGHT FORWARD LOWER MAIN LANDING GEAR TRUNNION SHEAR PIN - REPLACE							Service ATA:32
PN:4532103201-001	MOS/MSC	10-Jun-10	N/A					
SN:1222	HRS	2168.5						
	AFL	1782						
Q3220142	* RIGHT FORWARD UPPER MAIN LANDING GEAR TRUNNION SHEAR PIN - REPLACE							Service ATA:32
PN:4532103201-001	MOS/MSC	10-Jun-10	N/A					
SN:1242	HRS	2168.5						
	AFL	1782						
Q3220143	* LEFT AFT UPPER MAIN LANDING GEAR TRUNNION SHEAR PIN - REPLACE							Service ATA:32
PN:4532103202-001	MOS/MSC	10-Jun-10	N/A					
SN:712	HRS	2168.5						
	AFL	1782						
Q3220143	* RIGHT AFT UPPER MAIN LANDING GEAR TRUNNION SHEAR PIN - REPLACE							Service ATA:32
PN:4532103202-001	MOS/MSC	10-Jun-10	N/A					
SN:682	HRS	2168.5						
	AFL	1782						
Q3220144	* LEFT AFT LOWER MAIN LANDING GEAR TRUNNION SHEAR PIN - REPLACE							Service ATA:32
PN:4532103203-001	MOS/MSC	10-Jun-10	N/A					
SN:639	HRS	2168.5						
	AFL	1782						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
Q3220144	* RIGHT AFT LOWER MAIN LANDING GEAR TRUNNION SHEAR PIN - REPLACE							Service ATA:32
PN:4532103203-001	MOS/MSC	10-Jun-10	N/A					
SN:564	HRS	2168.5						
	AFL	1782						
T3220007	* LEFT MAIN LANDING GEAR AXLE BEAM - PERFORM MAIN LANDING GEAR AXLE BEAM ASSEMBLY BORESCOPE INSPECTION							Service ATA:32
PN:200-0203-101	MOS	21-Feb-22	48		28-Feb-26		OVD	AIRWORTHINESS
SN:H0688	HRS	4819.5						
	AFL	4049						
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01								
T3220007	* RIGHT MAIN LANDING GEAR AXLE BEAM - PERFORM MAIN LANDING GEAR AXLE BEAM ASSEMBLY BORESCOPE INSPECTION							Service ATA:32
PN:200-0203-101	MOS	21-Feb-22	48		28-Feb-26		OVD	AIRWORTHINESS
SN:H0706	HRS	4819.5						
	AFL	4049						
PROC. REF: AMM 32-10-01PROC. REF: AMM 32-10-01								
T3220013	* LEFT MAIN LANDING GEAR SIDE BRACE ACTUATOR ASSEMBLY - REPLACE							Service ATA:32
PN:200-300-003	MOS	20-Aug-20						LIFE LIMIT
SN:H0268	HRS	4461.9						
	AFL	3775	17000	TAC 3775	17000		12455	
T3220013	* RIGHT MAIN LANDING GEAR SIDE BRACE ACTUATOR ASSEMBLY - REPLACE							Service ATA:32
PN:200-300-004	MOS	20-Aug-20						LIFE LIMIT
SN:H1318	HRS	4461.9						
	AFL	3775	17000	TAC 3775	17000		12455	
T3220014	* LEFT MAIN LANDING GEAR ACTUATOR UPPER PIN - REPLACE							Service ATA:32
PN:200-0325-101	MOS	26-Apr-24	96	TAC 0	26-Apr-32		2104 d	LIFE LIMIT
SN:TUR16589	HRS	5128.5		TAC 0				
	AFL	4317		TAC 0				
PROC. REF: NDT PART 7/32-10-02, NDT PART 7/32-30-01PROC. REF: NDT PART 7/32-10-02, NDT PART 7/32-30-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
T3220014	* RIGHT MAIN LANDING GEAR ACTUATOR UPPER PIN - REPLACE							Service ATA:32
PN:200-0325-101	MOS	26-Apr-24	96	TAC 0	26-Apr-32		2104 d	LIFE LIMIT
SN:TUR15179	HRS	5128.5		TAC 0				
	AFL	4317		TAC 0				
PROC. REF: NDT PART 7/32-10-02, NDT PART 7/32-30-01PROC. REF: NDT PART 7/32-10-02, NDT PART 7/32-30-01								
T3220024	* LEFT MAIN LANDING GEAR ACTUATOR LOWER PIN - PERFORM MAGNETIC PARTICLE INSPECTION							Service ATA:32
PN:200-0217-101	MOS	26-Apr-24	48		30-Apr-28		647 d	AIRWORTHINESS
SN:CPS01C-4141	HRS	5128.5						
	AFL	4317						
PROC. REF: NDT PART 7/32-10-02, NDT PART 7/32-30-01PROC. REF: NDT PART 7/32-10-02, NDT PART 7/32-30-01								
T3220024	* LEFT MAIN LANDING GEAR ACTUATOR UPPER PIN - PERFORM MAGNETIC PARTICLE INSPECTION							Service ATA:32
PN:200-0325-101	MOS	26-Apr-24	48		30-Apr-28		647 d	AIRWORTHINESS
SN:TUR16589	HRS	5128.5						
	AFL	4317						
PROC. REF: NDT PART 7/32-10-02, NDT PART 7/32-30-01PROC. REF: NDT PART 7/32-10-02, NDT PART 7/32-30-01								
T3220024	* RIGHT MAIN LANDING GEAR ACTUATOR LOWER PIN - PERFORM MAGNETIC PARTICLE INSPECTION							Service ATA:32
PN:200-0217-101	MOS	26-Apr-24	48		30-Apr-28		647 d	AIRWORTHINESS
SN:CPS01C-4140	HRS	5128.5						
	AFL	4317						
PROC. REF: NDT PART 7/32-10-02, NDT PART 7/32-30-01PROC. REF: NDT PART 7/32-10-02, NDT PART 7/32-30-01								
T3220024	* RIGHT MAIN LANDING GEAR ACTUATOR UPPER PIN - PERFORM MAGNETIC PARTICLE INSPECTION							Service ATA:32
PN:200-0325-101	MOS	26-Apr-24	48		30-Apr-28		647 d	AIRWORTHINESS
SN:TUR15179	HRS	5128.5						
	AFL	4317						
PROC. REF: NDT PART 7/32-10-02, NDT PART 7/32-30-01PROC. REF: NDT PART 7/32-10-02, NDT PART 7/32-30-01								
T3220038	* LEFT MAIN LANDING GEAR ACTUATOR LOWER PIN - REPLACE							Service ATA:32
PN:200-0217-101	MOS	26-Apr-24	96	TAC 0	26-Apr-32		2104 d	LIFE LIMIT
SN:CPS01C-4141	HRS	5128.5		TAC 0				
	AFL	4317		TAC 0				
PROC. REF: NDT PART 7/32-10-02, NDT PART 7/32-30-01PROC. REF: NDT PART 7/32-10-02, NDT PART 7/32-30-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
T3220038	* RIGHT MAIN LANDING GEAR ACTUATOR LOWER PIN - REPLACE							Service ATA:32
PN:200-0217-101	MOS	26-Apr-24	96	TAC 0	26-Apr-32		2104 d	LIFE LIMIT
SN:CPS01C-4140	HRS	5128.5		TAC 0				
	AFL	4317		TAC 0				
PROC. REF: NDT PART 7/32-10-02, NDT PART 7/32-30-01PROC. REF: NDT PART 7/32-10-02, NDT PART 7/32-30-01								
T3220046	* LEFT MAIN LANDING GEAR SIDE BRACE ACTUATOR ASSEMBLY - REPLACE							Service ATA:32
PN:200-300-003	MOS/MSC	20-Aug-20	N/A					
SN:H0268	HRS	4461.9						
	AFL	3775						
T3220046	* RIGHT MAIN LANDING GEAR SIDE BRACE ACTUATOR ASSEMBLY - REPLACE							Service ATA:32
PN:200-300-004	MOS/MSC	20-Aug-20	N/A					
SN:H1318	HRS	4461.9						
	AFL	3775						
T3220063	* LEFT MAIN LANDING GEAR SIDE BRACE ACTUATOR ASSEMBLY - REPLACE							Service ATA:32
PN:200-300-003	MOS/MSC	20-Aug-20	N/A					
SN:H0268	HRS	4461.9						
	AFL	3775						
T3220063	* RIGHT MAIN LANDING GEAR SIDE BRACE ACTUATOR ASSEMBLY - REPLACE							Service ATA:32
PN:200-300-004	MOS/MSC	20-Aug-20	N/A					
SN:H1318	HRS	4461.9						
	AFL	3775						
T3220064	* LEFT MAIN LANDING GEAR SIDE BRACE ACTUATOR ASSEMBLY - REPLACE							Service ATA:32
PN:200-300-003	MOS/MSC	20-Aug-20	N/A					
SN:H0268	HRS	4461.9						
	AFL	3775						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
T3220064	* RIGHT MAIN LANDING GEAR SIDE BRACE ACTUATOR ASSEMBLY - REPLACE							Service ATA:32
PN:200-300-004	MOS/MSC	20-Aug-20	N/A					
SN:H1318	HRS	4461.9						
	AFL	3775						
T3220067	* LEFT MAIN LANDING GEAR ACTUATOR END CAP - REPLACE							Service ATA:32
PN:200-0303-001	MOS/MSC	24-Jul-12	N/A					
SN:H2357	HRS	2714.6						
	AFL	2235						
T3220067	* RIGHT MAIN LANDING GEAR ACTUATOR END CAP - REPLACE							Service ATA:32
PN:200-0303-001	MOS/MSC	24-Jul-12	N/A					
SN:H2350	HRS	2714.6						
	AFL	2235						
T3220105	* LEFT MAIN LANDING GEAR ACTUATOR END CAP - REPLACE							Service ATA:32
PN:200-0303-001	MOS	24-Jul-12						LIFE LIMIT
SN:H2357	HRS	2714.6						
	AFL	2235	2387		4622		77	
PROC. REF: AMM 32-31-01PROC. REF: AMM 32-31-01								
T3220105	* RIGHT MAIN LANDING GEAR ACTUATOR END CAP - REPLACE							Service ATA:32
PN:200-0303-001	MOS	24-Jul-12						LIFE LIMIT
SN:H2350	HRS	2714.6						
	AFL	2235	2387		4622		77	
PROC. REF: AMM 32-31-01PROC. REF: AMM 32-31-01								
T3220135	* LEFT MAIN LANDING GEAR ACTUATOR LOWER PIN - PERFORM DETAILED VISUAL INSPECTION							Service ATA:32
PN:200-0217-101	MOS	26-Apr-24	48		30-Apr-28		647 d	AIRWORTHINESS
SN:CPS01C-4141	HRS	5128.5						
	AFL	4317						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
T3220135	* LEFT MAIN LANDING GEAR ACTUATOR UPPER PIN - PERFORM DETAILED VISUAL INSPECTION							Service ATA:32
PN:200-0325-101	MOS	26-Apr-24	48		30-Apr-28		647 d	AIRWORTHINESS
SN:TUR16589	HRS	5128.5						
	AFL	4317						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								
T3220135	* RIGHT MAIN LANDING GEAR ACTUATOR LOWER PIN - PERFORM DETAILED VISUAL INSPECTION							Service ATA:32
PN:200-0217-101	MOS	26-Apr-24	48		30-Apr-28		647 d	AIRWORTHINESS
SN:CPS01C-4140	HRS	5128.5						
	AFL	4317						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								
T3220135	* RIGHT MAIN LANDING GEAR ACTUATOR UPPER PIN - PERFORM DETAILED VISUAL INSPECTION							Service ATA:32
PN:200-0325-101	MOS	26-Apr-24	48		30-Apr-28		647 d	AIRWORTHINESS
SN:TUR15179	HRS	5128.5						
	AFL	4317						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								
T3220147	* LEFT AFT LOWER MAIN LANDING GEAR TRUNNION SHEAR PIN - PERFORM VISUAL INSPECTION FOR PIN MIGRATION							Service ATA:32
	MOS/MSC		N/A					
	HRS							
	AFL							
T3220147	* LEFT AFT UPPER MAIN LANDING GEAR TRUNNION SHEAR PIN - PERFORM VISUAL INSPECTION FOR PIN MIGRATION							Service ATA:32
	MOS/MSC		N/A					
	HRS							
	AFL							
T3220147	* LEFT FORWARD LOWER MAIN LANDING GEAR TRUNNION SHEAR PIN - PERFORM VISUAL INSPECTION FOR PIN MIGRATION							Service ATA:32
	MOS/MSC		N/A					
	HRS							
	AFL							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
T3220147	* LEFT FORWARD UPPER MAIN LANDING GEAR TRUNNION SHEAR PIN - PERFORM VISUAL INSPECTION FOR PIN MIGRATION							Service ATA:32
	MOS/MSC		N/A					
	HRS							
	AFL							
T3220147	* RIGHT AFT LOWER MAIN LANDING GEAR TRUNNION SHEAR PIN - PERFORM VISUAL INSPECTION FOR PIN MIGRATION							Service ATA:32
	MOS/MSC		N/A					
	HRS							
	AFL							
T3220147	* RIGHT AFT UPPER MAIN LANDING GEAR TRUNNION SHEAR PIN - PERFORM VISUAL INSPECTION FOR PIN MIGRATION							Service ATA:32
	MOS/MSC		N/A					
	HRS							
	AFL							
T3220147	* RIGHT FORWARD LOWER MAIN LANDING GEAR TRUNNION SHEAR PIN - PERFORM VISUAL INSPECTION FOR PIN MIGRATION							Service ATA:32
	MOS/MSC		N/A					
	HRS							
	AFL							
T3220147	* RIGHT FORWARD UPPER MAIN LANDING GEAR TRUNNION SHEAR PIN - PERFORM VISUAL INSPECTION FOR PIN MIGRATION							Service ATA:32
	MOS/MSC		N/A					
	HRS							
	AFL							
V3220022	LEFT AFT MAIN LANDING GEAR TRUNNION PIN - PERFORM MAGNETIC PARTICLE INSPECTION							Service ATA:32
PN:200-0213-103	MOS	20-Aug-20	96 (+14d/-14d)		31-Aug-28	03-Sep-28	770 d (+3)	
SN:H0580	HRS	4461.9						
	AFL	3775						
PROC. REF: NDT PART 7/32-10-07, NDT PART 7/32-10-08PROC. REF: NDT PART 7/32-10-07, NDT PART 7/32-10-08								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
V3220022	LEFT FORWARD MAIN LANDING GEAR TRUNNION PIN - PERFORM MAGNETIC PARTICLE INSPECTION							Service ATA:32
PN:200-0212-103	MOS	20-Aug-20	96 (+14d/-14d)		31-Aug-28	03-Sep-28	770 d (+3)	
SN:H0771	HRS	4461.9						
	AFL	3775						
PROC. REF: NDT PART 7/32-10-07, NDT PART 7/32-10-08PROC. REF: NDT PART 7/32-10-07, NDT PART 7/32-10-08								
V3220022	RIGHT AFT MAIN LANDING GEAR TRUNNION PIN - PERFORM MAGNETIC PARTICLE INSPECTION							Service ATA:32
PN:200-0213-103	MOS	20-Aug-20	96 (+14d/-14d)		31-Aug-28	03-Sep-28	770 d (+3)	
SN:H0582	HRS	4461.9						
	AFL	3775						
PROC. REF: NDT PART 7/32-10-07, NDT PART 7/32-10-08PROC. REF: NDT PART 7/32-10-07, NDT PART 7/32-10-08								
V3220022	RIGHT FORWARD MAIN LANDING GEAR TRUNNION PIN - PERFORM MAGNETIC PARTICLE INSPECTION							Service ATA:32
PN:200-0212-103	MOS	20-Aug-20	96 (+14d/-14d)		31-Aug-28	03-Sep-28	770 d (+3)	
SN:H0876	HRS	4461.9						
	AFL	3775						
PROC. REF: NDT PART 7/32-10-07, NDT PART 7/32-10-08PROC. REF: NDT PART 7/32-10-07, NDT PART 7/32-10-08								
V3240004 ^S	** EMERGENCY/PARKING BRAKE SWITCH - VERIFY THAT "EMERGENCY/PARKING BRAKE" MESSAGE ILLUMINATES ON EICAS WHEN PARKING BRAKE IS SET AND THROTTLES ARE MOVED ABOVE MCR DETENT.							Service ATA:32
	MOS	09-Jul-24	24 (+14d/-14d)					AIRWORTHINESS
	HRS	5131.8	600 (+25/-25)					
	AFL	4323						
PROC. REF: AMM 32-42-01PROC. REF: AMM 32-42-01								
V3240008 ^S	** EMERGENCY/PARKING BRAKE CONTROL SYSTEM - PERFORM FUNCTIONAL TEST							Service ATA:32
	MOS	09-Jul-24	24 (+14d/-14d)					AIRWORTHINESS
	HRS	5131.8	600 (+25/-25)					
	AFL	4323						
PROC. REF: AMM 32-42-02PROC. REF: AMM 32-42-02								
W3220149	* LEFT MAIN LANDING GEAR SIDE BRACE ACTUATOR ASSEMBLY - REPLACE							Service ATA:32
PN:200-300-003	MOS/MSC	20-Aug-20	N/A					
SN:H0268	HRS	4461.9						
	AFL	3775						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
W3220149	* RIGHT MAIN LANDING GEAR SIDE BRACE ACTUATOR ASSEMBLY - REPLACE							Service ATA:32
PN:200-300-004	MOS/MSC	20-Aug-20	N/A					
SN:H1318	HRS	4461.9						
	AFL	3775						
W3220150	* LEFT MAIN LANDING GEAR SIDE BRACE ACTUATOR ASSEMBLY - REPLACE							Service ATA:32
PN:200-300-003	MOS/MSC	20-Aug-20	N/A					
SN:H0268	HRS	4461.9						
	AFL	3775						
W3220150	* RIGHT MAIN LANDING GEAR SIDE BRACE ACTUATOR ASSEMBLY - REPLACE							Service ATA:32
PN:200-300-004	MOS/MSC	20-Aug-20	N/A					
SN:H1318	HRS	4461.9						
	AFL	3775						
W3231022	LEFT MAIN LANDING GEAR INBOARD DOOR GIMBAL BRACKET - PERFORM EDDY CURRENT INSPECTION							Service ATA:32
	MOS/MSC	17-Oct-07	N/A					
	HRS	1174.8						
	AFL	963						
PROC. REF: NDT PART 6/32-13-01PROC. REF: NDT PART 6/32-13-01								
Y3220000 ^S	NOSE LANDING GEAR ASSEMBLY - PERFORM VISUAL INSPECTION							Service ATA:32
	MOS	09-Jul-24	24 (+14d/-14d)					
	HRS	5131.8	600 (+25/-25)					
	AFL	4323						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
Y3220001	^S	MAIN LANDING GEAR ASSEMBLY - PERFORM VISUAL INSPECTION. INSPECTION TO INCLUDE ACTUATOR, FASTENERS, SUPPORT STRUCTURE, AND SQUAT SWITCHES.					Service	ATA:32
	MOS	09-Jul-24	24 (+14d/-14d)					
	HRS	5131.8	600 (+25/-25)					
	AFL	4323						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								PKG:11
Y3220002	^S	NOSE LANDING GEAR ACTUATOR PRESSURE AND RETURN LINES - PERFORM VISUAL INSPECTION. LOWER ACTUATOR DUST BOOT TO INSPECT LINES.					Service	ATA:32
	MOS	09-Jul-24	24 (+14d/-14d)					
	HRS	5131.8	600 (+25/-25)					
	AFL	4323						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								PKG:11
Y3220003	^S	NOSE GEAR SHOCK STRUT - REMOVE AND REPLACE RETAINER RING LOCKSCREW					Service	ATA:32
	MOS	09-Jul-24	24					
	HRS	5131.8	600					
	AFL	4323						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:11
Y3220004	^S	MAIN LANDING GEAR ACTUATOR AND GEAR INBOARD DOOR ACTUATOR ATTACH POINTS - PERFORM VISUAL INSPECTION					Service	ATA:32
	MOS	09-Jul-24	24 (+14d/-14d)					
	HRS	5131.8	600 (+25/-25)					
	AFL	4323						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								PKG:11
Y3220006	^S	LANDING GEAR ELECTRICAL WIRING - PERFORM VISUAL INSPECTION (THAT PORTION VISIBLE INSIDE WHEEL WELL)					Service	ATA:32
	MOS	09-Jul-24	24 (+14d/-14d)					
	HRS	5131.8	600 (+25/-25)					
	AFL	4323						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								PKG:11

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
Y3220008	^S	NOSE LANDING GEAR AXLE - REMOVE NOSE LANDING GEAR WHEEL AND PERFORM INSPECTION. INSPECT BOTH INSIDE AND OUTSIDE OF AXLE.					Service	ATA:32
	MOS	24-Feb-23	48 (+14d/-14d)					
	HRS	5067.1	1200 (+25/-25)					
	AFL	4262						
PROC. REF: AMM 32-40-01PROC. REF: AMM 32-40-01							PKG:17	
Y3220124	^S	NOSE LANDING GEAR - PERFORM DETAILED VISUAL INSPECTION OF THE NOSE LANDING GEAR UPLOCK ROLLER BRACKET					Service	ATA:32
	MOS	09-Jul-24	24 (+14d/-14d)					
	HRS	5131.8	600 (+25/-25)					
	AFL	4323						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00							PKG:11	
Y3230002	^S	MAIN LANDING GEAR FREE FALL ROLLER - PERFORM VISUAL INSPECTION. PAY PARTICULAR ATTENTION TO BINDING OF ROLLERS.					Service	ATA:32
	MOS	31-Jul-25	12 (+14d/-14d)					
	HRS	5307.6	300 (+25/-25)					
	AFL	4448						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00							PKG:5	
Y3231023	^S	MAIN LANDING GEAR INBOARD DOOR ACTUATOR (PART NUMBER 7469) END CAP SCREWS - PERFORM DETAILED INSPECTION					Service	ATA:32
	MOS	31-Jul-25	12 (+14d/-14d)					
	HRS	5307.6	300 (+25/-25)					
	AFL	4448						
PROC. REF: AMM 32-31-02PROC. REF: AMM 32-31-02							PKG:5	
Y3240000	^S	NOSE AND MAIN TIRES - PERFORM VISUAL INSPECTION					Service	ATA:32
	MOS	31-Jul-25	12 (+14d/-14d)					
	HRS	5307.6	300 (+25/-25)					
	AFL	4448						
PROC. REF: AMM 12-10-04PROC. REF: AMM 12-10-04							PKG:5	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
Y3240001	^S	BRAKE LINES - PERFORM VISUAL INSPECTION. INSPECT ALL BRAKE LINES VISIBLE IN WHEEL WELLS AND ON STRUTS.						Service ATA:32
	MOS	09-Jul-24	24 (+14d/-14d)					
	HRS	5131.8	600 (+25/-25)					
	AFL	4323						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								PKG:11
Y3240002	^S	BRAKE ASSEMBLIES - PERFORM VISUAL INSPECTION WITH PARKING BRAKE SET. WORN BRAKES ARE VISUALLY INDICATED WHEN THE WEAR INDICATOR PINS BECOME EVEN WITH THE OUTER SURFACE OF THE WEAR INDICATOR SLEEVE.						Service ATA:32
	MOS	31-Jul-25	12 (+14d/-14d)					
	HRS	5307.6	300 (+25/-25)					
	AFL	4448						
PROC. REF: AMM 32-41-01PROC. REF: AMM 32-41-01								PKG:5
Y3240003	^S	BRAKE CONTROL SYSTEM LINEAR VARIABLE DIFFERENTIAL TRANSFORMER (LVDT) - PERFORM VISUAL INSPECTION						Service ATA:32
	MOS	24-Feb-23	48 (+14d/-14d)					
	HRS	5067.1	1200 (+25/-25)					
	AFL	4262						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								PKG:13
Y3260005	^S	NOSE LANDING GEAR SQUAT SWITCH ROTATING DISK ASSEMBLY - LUBRICATE						Service ATA:32
	MOS	31-Jul-25	12 (+14d/-14d)					
	HRS	5307.6	300 (+25/-25)					
	AFL	4448						
PROC. REF: AMM 12-21-01PROC. REF: AMM 12-21-01								PKG:5
ATA 33 - LIGHTS								
330000		MODIFIED PULSE CONTROLLER						Component ATA:33
PN:2401S	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:AR00473	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
331001	NO. 1 COCKPIT LIGHTING CONTROL UNIT							Component ATA:33
PN:RDC4-1	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:0584	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-10-06PROC. REF: AMM 33-10-06								
331002	NO. 2 COCKPIT LIGHTING CONTROL UNIT							Component ATA:33
PN:RDC4-1	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:0583	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-10-06PROC. REF: AMM 33-10-06								
331003	PRESSURIZATION PANEL							Component ATA:33
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
331010	PILOT FORWARD SWITCH PANEL OVERLAY							Component ATA:33
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-10-05PROC. REF: AMM 33-10-05								
331011	PILOT SWITCH PANEL							Component ATA:33
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
331012	COPILOT FORWARD SWITCH PANEL OVERLAY							Component ATA:33
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-10-05PROC. REF: AMM 33-10-05								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
331013 COPILOT FORWARD SWITCH PANEL								Component ATA:33
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
331015 CENTER SWITCH PANEL (P5)								Component ATA:33
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
331016 CENTER SWITCH PANEL (P5) OVERLAY								Component ATA:33
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-10-05PROC. REF: AMM 33-10-05								
331017 THROTTLE QUADRANT OVERLAY PANEL								Component ATA:33
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
331018 PILOT AFT CIRCUIT BREAKER PANEL OVERLAY								Component ATA:33
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-10-05PROC. REF: AMM 33-10-05								
331019 COPILOT AFT CIRCUIT BREAKER PANEL OVERLAY								Component ATA:33
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-10-05PROC. REF: AMM 33-10-05								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
331020	DIMMER CONTROL BOX							Component ATA:33
PN:LT-48G	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:1593	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-10-10PROC. REF: AMM 33-10-10								
331021	PILOT FORWARD CIRCUIT BREAKER PANEL OVERLAY							Component ATA:33
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-10-05PROC. REF: AMM 33-10-05								
331022	COPILOT FORWARD CIRCUIT BREAKER PANEL OVERLAY							Component ATA:33
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-10-05PROC. REF: AMM 33-10-05								
331023	GLARESHIELD FLOOR FLOODLIGHTS INVERTER							Component ATA:33
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
331025	COCKPIT MISCELLANEOUS RELAY BOX							Component ATA:33
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-10-07PROC. REF: AMM 33-10-07								
331030	CENTER SWITCH PANEL DIODE BOX (P12)							Component ATA:33
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-10-08PROC. REF: AMM 33-10-08								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
331033	GLARESHIELD FLOODLIGHT POWER SUPPLY							Component ATA:33
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
331040	PILOT REVERSION PANEL OVERLAY (DS55)							Component ATA:33
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
331041	COPILOT OUTBD SWITCH PANEL OVERLAY (DS58)							Component ATA:33
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-10-05PROC. REF: AMM 33-10-05								
331101	P35 FUSE PANEL							Component ATA:33
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-10-09PROC. REF: AMM 33-10-09								
331401-1	NO. 1 LEFT POWER SUPPLY INVERTER (PS5009)							Component ATA:33
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-20-10PROC. REF: AMM 33-20-10								
331401-10	NO. 5 RIGHT POWER SUPPLY INVERTER (PS5006)							Component ATA:33
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-20-10PROC. REF: AMM 33-20-10								

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
331401-11	NO. 6 LEFT POWER SUPPLY INVERTER (LAVATORY) (PS5010)							Component ATA:33
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-20-10PROC. REF: AMM 33-20-10								
331401-2	NO. 1 RIGHT POWER SUPPLY INVERTER (PS5003)							Component ATA:33
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-20-10PROC. REF: AMM 33-20-10								
331401-3	NO. 2 LEFT POWER SUPPLY INVERTER (PS5008)							Component ATA:33
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-20-10PROC. REF: AMM 33-20-10								
331401-4	NO. 2 RIGHT POWER SUPPLY INVERTER (PS5004)							Component ATA:33
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-20-10PROC. REF: AMM 33-20-10								
331401-5	NO. 3 LEFT POWER SUPPLY INVERTER (PS5007)							Component ATA:33
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-20-10PROC. REF: AMM 33-20-10								
331401-6	NO. 3 RIGHT POWER SUPPLY INVERTER (PS5005)							Component ATA:33
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-20-10PROC. REF: AMM 33-20-10								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
331401-7		NO. 4 LEFT POWER SUPPLY INVERTER (PS5006)					Component	ATA:33
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-20-10PROC. REF: AMM 33-20-10								
331401-8		NO. 4 RIGHT POWER SUPPLY INVERTER (LAVATORY) (PS5010)					Component	ATA:33
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-20-10PROC. REF: AMM 33-20-10								
331401-9		NO. 5 LEFT POWER SUPPLY INVERTER (LAVATORY) (PS5011)					Component	ATA:33
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-20-10PROC. REF: AMM 33-20-10								
332001		RIGHT NO. 1 PASSENGER LIGHTING CONTROL UNIT					Component	ATA:33
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-20-05PROC. REF: AMM 33-20-05								
332002		RIGHT NO. 2 PASSENGER LIGHTING CONTROL UNIT					Component	ATA:33
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-20-05PROC. REF: AMM 33-20-05								
332003		RIGHT NO. 3 PASSENGER LIGHTING CONTROL UNIT					Component	ATA:33
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-20-05PROC. REF: AMM 33-20-05								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
332004	RIGHT NO. 4 PASSENGER LIGHTING CONTROL UNIT							Component ATA:33
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-20-05PROC. REF: AMM 33-20-05								
332005	LEFT NO. 1 PASSENGER LIGHTING CONTROL UNIT							Component ATA:33
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-20-05PROC. REF: AMM 33-20-05								
332006	LEFT NO. 2 PASSENGER LIGHTING CONTROL UNIT							Component ATA:33
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-20-05PROC. REF: AMM 33-20-05								
332007	LEFT NO. 3 PASSENGER LIGHTING CONTROL UNIT							Component ATA:33
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-20-05PROC. REF: AMM 33-20-05								
332008	LEFT NO. 4 PASSENGER LIGHTING CONTROL UNIT							Component ATA:33
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-20-05PROC. REF: AMM 33-20-05								
332030	LAVATORY NO SMOKING / RETURN TO SEAT SIGN CONTROL UNIT (DS138)							Component ATA:33
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-20-11PROC. REF: AMM 33-20-11								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
332068	COPILOT LIGHTING CONTROL MODULE							Component ATA:33
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-20-02PROC. REF: AMM 33-20-02								
332404	ENTRYWAY CONTROL LIGHT PANEL							Component ATA:33
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-20-01PROC. REF: AMM 33-20-01								
333004	TAIL CONE MAINTENANCE LIGHT CHANGE							Component ATA:33
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-30-01PROC. REF: AMM 33-30-01								
334011	LEFT LANDING AND TAXI LIGHT							Component ATA:33
PN:Q5587	MOS/MSC	02-Jul-13	O/C					
SN:UNKNOWN	HRS	2991.1						
	AFL	2482						
PROC. REF: AMM 33-40-04PROC. REF: AMM 33-40-04								
334012	RIGHT LANDING AND TAXI LIGHT							Component ATA:33
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-40-04PROC. REF: AMM 33-40-04								
334020	EMPENNAGE LIGHT ASSEMBLY							Component ATA:33
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-40-02PROC. REF: AMM 33-40-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45
Serial: 45-252
RegNo: N253SC
HRS: 5455.2
AFL: 4545
As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
334021	LEFT NAVIGATION LIGHT (DS37)							Component ATA:33
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-40-02PROC. REF: AMM 33-40-02								
334022	RIGHT NAVIGATION LIGHT (DS38)							Component ATA:33
PN:628	MOS/MSC	06-Feb-12	O/C					
SN:UNKNOWN	HRS	2584.5						
	AFL	2127						
PROC. REF: AMM 33-40-02PROC. REF: AMM 33-40-02								
334023	TAIL NAVIGATION LIGHT (DS39)							Component ATA:33
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-40-02PROC. REF: AMM 33-40-02								
334041	COPILOT REVERSION PANEL OVERLAY (DS56)							Component ATA:33
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
334175	RELAY OPTIONS PANEL							Component ATA:33
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
334332	UPPER ANTI-COLLISION LIGHT							Component ATA:33
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-40-01PROC. REF: AMM 33-40-01								

? - Insufficient Information
S - Suppressed Requirement
* - Estimated Due(New Requirement)
(EFF) - Effective C/W
(M) - Manual Due
U - User Task
Ex - Excluded Task

Status Report

Model: LEARJET 45

Serial: 45-252

RegNo: N253SC

HRS: 5455.2

AFL: 4545

As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
334333	LOWER ANTI-COLLISION LIGHT							Component ATA:33
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-40-01PROC. REF: AMM 33-40-01								
335005	FORWARD ELS ACTIVATION MODULE (A81)							Component ATA:33
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-50-01PROC. REF: AMM 33-50-01								
335006	AFT ELS ACTIVATION MODULE (A82)							Component ATA:33
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-50-01PROC. REF: AMM 33-50-01								
336001	PILOT CHART HOLDER							Component ATA:33
PN:10-62-01	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:4153	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
336002	COPILOT CHART HOLDER							Component ATA:33
PN:10-62-01	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:4156	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
336003	PILOT MAP LIGHT							Component ATA:33
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-10-01PROC. REF: AMM 33-10-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
336004	COPILOT MAP LIGHT							Component ATA:33
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-10-01PROC. REF: AMM 33-10-01								
Y3310000 ^S	FLIGHT COMPARTMENT LIGHTING - PERFORM OPERATIONAL CHECK OF THE FOLLOWING: A. MAP LIGHTS. B. INSTRUMENT PANEL FLUORESCENT LIGHTS. C. INSTRUMENT/INDICATOR LIGHTS. D. LIGHT DIMMING SWITCHES. E. CREW WARNING PANEL. F. PANEL OVERLAYS.							Service ATA:33
	MOS	31-Jul-25	12 (+14d/-14d)					
	HRS	5307.6	300 (+25/-25)					
	AFL	4448						
								PKG:1
PROC. REF: AMM 33-10-00PROC. REF: AMM 33-10-00								
Y3340000 ^S	EXTERIOR LIGHTING SYSTEMS - PERFORM OPERATION CHECK OF THE FOLLOWING: A. TAXI LIGHTS. B. ANTI-COLLISION BEACONS. C. NAVIGATION LIGHTS. D. STROBE LIGHTS. E. LANDING/RECOGNITION LIGHTS. F. WING ICE INSPECTION LIGHTS. G. EMERGENCY DOOR EGRESS LIGHTS.							Service ATA:33
	MOS	31-Jul-25	12 (+14d/-14d)					
	HRS	5307.6	300 (+25/-25)					
	AFL	4448						
								PKG:2
PROC. REF: AMM 33-40-00, AMM 33-41-00PROC. REF: AMM 33-40-00, AMM 33-41-00								
Y3350003 ^S	EMERGENCY LIGHTING SYSTEM - PERFORM OPERATIONAL CHECK							Service ATA:33
	MOS	24-Feb-23	48 (+14d/-14d)					
	HRS	5067.1	1200 (+25/-25)					
	AFL	4262						
								PKG:14
PROC. REF: AMM 33-50-00PROC. REF: AMM 33-50-00								
ATA 34 - NAVIGATION								
14CFR PART 47 ^U	PERFORM RECURRENT AIRCRAFT REGISTRATION							Service ATA:34
	MOS/MSC	07-Jul-04	-					
	HRS	0						
	AFL	0						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34-00-FAR-91.171	CHECK VOR EQUIPMENT FOR IFR OPERATIONS FAR 91.171							Service ATA:34
	MOS/MSC	26-Oct-22	O/C					
	HRS	4984.7						
	AFL	4197						
PROC. REF: GENERIC NO REF, FAR FAR 91.171PROC. REF: GENERIC NO REF, FAR FAR 91.171								
341001	NO. 1 AIR DATA COMPUTER							Component ATA:34
PN:7014700-606	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:03087013	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-17-01PROC. REF: AMM 34-17-01								
341001A	TEST/INSPECT NO. 1 AIR DATA COMPUTER							Service ATA:34
PN:7014700-606	MOS	28-Apr-26	24		30-Apr-28		647 d	
SN:03087013	HRS	5406.6						
	AFL	4513						
PROC. REF: FAR FAR 91.411, AMM 34-17-00, CFR 14 CFR PART 43 APP EPROC. REF: FAR FAR 91.411, AMM 34-17-00, CFR 14 CFR PART 43 APP E								
341002	NO. 2 AIR DATA COMPUTER							Component ATA:34
PN:7014700-606	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:03087012	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-17-01PROC. REF: AMM 34-17-01								
341002A	TEST/INSPECT NO. 2 AIR DATA COMPUTER							Service ATA:34
PN:7014700-606	MOS	28-Apr-26	24		30-Apr-28		647 d	
SN:03087012	HRS	5406.6						
	AFL	4513						
PROC. REF: FAR FAR 91.411, AMM 34-17-00, CFR 14 CFR PART 43 APP EPROC. REF: FAR FAR 91.411, AMM 34-17-00, CFR 14 CFR PART 43 APP E								
341013	STANDBY AIRSPEED INDICATOR							Component ATA:34
PN:6634208002-003	MOS/MSC	01-Aug-14	O/C	TSN 0				
SN:284359	HRS	3206.6		TSN 0				
	AFL	2642		TSN 0				
PROC. REF: AMM 34-18-01PROC. REF: AMM 34-18-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
341025	STANDBY ALTIMETER							Component ATA:34
PN:16650-1150	MOS/MSC	21-Nov-24	O/C					
SN:171353	HRS	5163.2						
	AFL	4351						
PROC. REF: AMM 34-15-01PROC. REF: AMM 34-15-01								
341025A	TEST/INSPECT STANDBY ALTIMETER							Service ATA:34
PN:16650-1150	MOS	28-Apr-26	24		30-Apr-28		647 d	
SN:171353	HRS	5406.6						
	AFL	4513						
PROC. REF: FAR FAR 91.411, AMM 34-15-01, CFR 14 CFR PART 43 APP EPROC. REF: FAR FAR 91.411, AMM 34-15-01, CFR 14 CFR PART 43 APP E								
341037	LEFT PRIMARY PITOT/STATIC PROBE							Component ATA:34
PN:6634100000-001	MOS	07-Jul-04		TSN 0				LIFE LIMIT
SN:223882	HRS	0	15000 (+25/-25)	TSN 0	15000	15025	9544.8 (+25)	
	AFL	0		TSN 0				
PROC. REF: AMM 34-11-01PROC. REF: AMM 34-11-01								
341037A	LEFT PRIMARY PITOT/STATIC PROBE - PERFORM NATIONALLY REQUIRED EQUIPMENT TESTS AND INSPECTIONS							Service ATA:34
PN:6634100000-001	MOS	28-Apr-26	24		30-Apr-28		647 d	
SN:223882	HRS	5406.6						
	AFL	4513						
Test Date: : 28-Apr-26								
PROC. REF: GENERIC NO REF, FAR FAR 91.411, CFR 14 CFR PART 43 APP EPROC. REF: GENERIC NO REF, FAR FAR 91.411, CFR 14 CFR PART 43 APP E								
341038	RIGHT PRIMARY PITOT/STATIC PROBE							Component ATA:34
PN:6634100000-003	MOS	07-Jul-04		TSN 0				LIFE LIMIT
SN:223861	HRS	0	15000 (+25/-25)	TSN 0	15000	15025	9544.8 (+25)	
	AFL	0		TSN 0				
PROC. REF: AMM 34-11-01PROC. REF: AMM 34-11-01								
341038A	RIGHT PRIMARY PITOT/STATIC PROBE - PERFORM NATIONALLY REQUIRED EQUIPMENT TESTS AND INSPECTIONS							Service ATA:34
PN:6634100000-003	MOS	28-Apr-26	24		30-Apr-28		647 d	
SN:223861	HRS	5406.6						
	AFL	4513						
Test Date: : 28-Apr-26								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
PROC. REF: FAR FAR 91.411, AMM 34-11-00, CFR 14 CFR PART 43 APP EPROC. REF: FAR FAR 91.411, AMM 34-11-00, CFR 14 CFR PART 43 APP E								
341049	STANDBY PITOT/STATIC PROBE							Component ATA:34
PN:6634100000-005	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:221970	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-11-01PROC. REF: AMM 34-11-01								
341049A	TEST/INSPECT STANDBY PITOT/STATIC PROBE							Service ATA:34
	MOS	28-Apr-26	24		30-Apr-28		647 d	
	HRS	5406.6						
	AFL	4513						
PROC. REF: FAR FAR 91.411, AMM 34-11-00, CFR 14 CFR PART 43 APP EPROC. REF: FAR FAR 91.411, AMM 34-11-00, CFR 14 CFR PART 43 APP E								
341061	RADAR ALTIMETER RECEIVER							Component ATA:34
PN:7001840-936	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:0405B297	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-14-01PROC. REF: AMM 34-14-01								
341073	FORWARD RADAR ALTIMETER ANTENNA							Component ATA:34
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-14-02PROC. REF: AMM 34-14-02								
341074	AFT RADAR ALTIMETER ANTENNA							Component ATA:34
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-14-02PROC. REF: AMM 34-14-02								
3413-RVSM	FLIGHT CHECK ALTITUDE ALERTER FUNCTION. RVSM COMPLIANT AIRCRAFT.							Service ATA:34
	MOS/MSC	07-Jul-04	N/R					
	HRS	0						
	AFL	0						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
341901	TOTAL AIR TEMPERATURE PROBE (TAT)							Component ATA:34
PN:102AU1AG	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:A36560	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-17-02PROC. REF: AMM 34-17-02								
342001	NO. 1 ATTITUDE HEADING REFERENCE COMPUTER (AHRS)							Component ATA:34
PN:142185-1102	MOS/MSC	19-Aug-15	O/C	TSN 0				
SN:1444	HRS	3455		TSN 0				
	AFL	2839		TSN 0				
PROC. REF: AMM 34-26-01PROC. REF: AMM 34-26-01								
342002	NO. 2 ATTITUDE HEADING REFERENCE COMPUTER (AHRS)							Component ATA:34
PN:142185-1102	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:1207	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-26-01PROC. REF: AMM 34-26-01								
342003	NO. 1 ATTITUDE HEADING REFERENCE COMPUTER FAN (AHRS)							Component ATA:34
PN:011809	MOS/MSC	09-Sep-04	O/C	TSN 0				
SN:I99138590	HRS	16		TSN 0				
	AFL	12		TSN 0				
PROC. REF: AMM 34-26-03PROC. REF: AMM 34-26-03								
342004	NO. 2 ATTITUDE HEADING REFERENCE COMPUTER FAN (AHRS)							Component ATA:34
PN:011809	MOS/MSC	09-Sep-04	O/C	TSN 0				
SN:I00318557	HRS	16		TSN 0				
	AFL	12		TSN 0				
PROC. REF: AMM 34-26-03PROC. REF: AMM 34-26-03								
342037	LEFT FLUX VALVE							Component ATA:34
PN:7010133	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:02126418	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45
Serial: 45-252
RegNo: N253SC
HRS: 5455.2
AFL: 4545
As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
PROC. REF: AMM 34-26-02PROC. REF: AMM 34-26-02								
342038	RIGHT FLUX VALVE							Component ATA:34
PN:7010133	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:02126419	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-26-02PROC. REF: AMM 34-26-02								
342101	DUAL ANGLE OF ATTACK INDICATOR							Component ATA:34
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
342103	STANDBY COMPASS							Component ATA:34
PN:PAI-700	MOS/MSC	07-Feb-25	O/C					
SN:32776	HRS	5215.4						
	AFL	4401						
PROC. REF: AMM 34-21-01PROC. REF: AMM 34-21-01								
342103A	CALIBRATION CHECK STANDBY COMPASS							Service ATA:34
PN:PAI-700	MOS/MSC		A/R					
SN:32776	HRS							
	AFL							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
342701	LEFT ATTITUDE HEADING REFERENCE SYSTEM MEMORY MODULE (AHRS)							Component ATA:34
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-26-01PROC. REF: AMM 34-26-01								
342702	RIGHT ATTITUDE HEADING REFERENCE SYSTEM MEMORY MODULE (AHRS)							Component ATA:34
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45
 Serial: 45-252
 RegNo: N253SC
 HRS: 5455.2
 AFL: 4545
 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
PROC. REF: AMM 34-26-01PROC. REF: AMM 34-26-01								
342801	STANDBY ATTITUDE INDICATOR							Component ATA:34
PN:501-1648-02	MOS/MSC	06-Sep-12	O/C					
SN:1109	HRS	2737						
	AFL	2256						
PROC. REF: AMM 34-23-01PROC. REF: AMM 34-23-01								
343005	MARKER BEACON ANTENNA							Component ATA:34
PN:DMN27-3	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:14540	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-30-01PROC. REF: AMM 34-30-01								
343008	UPPER GLIDESCOPE ANTENNA (E11)							Component ATA:34
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-30-02PROC. REF: AMM 34-30-02								
343009	LOWER GLIDESCOPE ANTENNA (E12)							Component ATA:34
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-30-02PROC. REF: AMM 34-30-02								
343030	MARKER BEACON ANTENNA SPLITTER							Component ATA:34
PN:DMH21-1	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:29613	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-30-03PROC. REF: AMM 34-30-03								
344101	AIRSERVE COMPUTER CHANGE							Component ATA:34
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
344102	RS-232 CONVERTER CHANGE							Component ATA:34
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
344111	UPPER TCAS ANTENNA							Component ATA:34
PN:7514081-913	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:ANE20142	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-43-02PROC. REF: AMM 34-43-02								
344112	LOWER TCAS ANTENNA							Component ATA:34
PN:7514081-913	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:ANE20150	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-43-02PROC. REF: AMM 34-43-02								
344143	TCAS PROCESSOR							Component ATA:34
PN:7517900-55020	MOS/MSC	18-Nov-21	O/C					
SN:20011189	HRS	4737						
	AFL	3987						
PROC. REF: AMM 34-43-01PROC. REF: AMM 34-43-01								
344155	TCAS RELAY BOX ASSEMBLY							Component ATA:34
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-43-03PROC. REF: AMM 34-43-03								
344167	TCAS CONFIGURATION MODULE							Component ATA:34
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
344171	NO. 1 TCAS UPPER ANTENNA CABLE							Component ATA:34
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
344172	NO. 2 TCAS UPPER ANTENNA CABLE							Component ATA:34
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
344173	NO. 3 TCAS UPPER ANTENNA CABLE							Component ATA:34
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
344174	NO. 4 TCAS UPPER ANTENNA CABLE							Component ATA:34
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
344176	UPPER TCAS ADAPTER ASSEMBLY							Component ATA:34
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
344177	LOWER TCAS ADAPTER ASSEMBLY							Component ATA:34
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
344181	NO. 1 TCAS LOWER ANTENNA CABLE							Component ATA:34
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
344182	NO. 2 TCAS LOWER ANTENNA CABLE							Component ATA:34
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
344183	NO. 3 TCAS LOWER ANTENNA CABLE							Component ATA:34
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
344184	NO. 4 TCAS LOWER ANTENNA CABLE							Component ATA:34
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
344201	GPS / XM WEATHER ANTENNA							Component ATA:34
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-53-01PROC. REF: AMM 34-53-01								
344205	WEATHER RADAR RECEIVER/TRANSMITTER/ANTENNA							Component ATA:34
PN:7021450-801	MOS/MSC	18-Aug-09	O/C					
SN:01063251	HRS	1827						
	AFL	1512						

?-Insufficient Information

S-Suppressed Requirement

*-Estimated Due(New Requirement)

(EFF)-Effective C/W

(M)-Manual Due

U-User Task

Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
PROC. REF: AMM 34-42-01PROC. REF: AMM 34-42-01								
344207	WEATHER RADAR TRANSCEIVER							Component ATA:34
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-42-01PROC. REF: AMM 34-42-01								
344209	WEATHER RADAR LIGHTNING SENSOR ANTENNA							Component ATA:34
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
344221	WEATHER RADAR CONTROLLER							Component ATA:34
PN:7008471-667	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:01035913	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-42-02PROC. REF: AMM 34-42-02								
344223	LIGHTNING DETECTION PROCESSOR							Component ATA:34
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
344513	TERRAIN AWARENESS WARNING (TAWS) COMPUTER							Component ATA:34
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
344514	TERRAIN AWARENESS WARNING (TAWS) CONFIGURATION MODULE							Component ATA:34
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45
Serial: 45-252
RegNo: N253SC
HRS: 5455.2
AFL: 4545
As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
344515	TAWS RELAY BOX							Component ATA:34
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
345001	NO. 1 INTEGRATED NAVIGATION UNIT							Component ATA:34
PN:7510100-631	MOS/MSC	17-Oct-07	O/C					
SN:04057425	HRS	1174.8						
	AFL	963						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
345002	NO. 2 INTEGRATED NAVIGATION UNIT							Component ATA:34
PN:7510100-633	MOS/MSC	08-Aug-08	O/C	TSN 0				
SN:0706B243	HRS	1480.2		TSN 0				
	AFL	1229		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
345011	NO. 1 NAVIGATION RECEIVER MODULE							Component ATA:34
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
345012	NO. 2 NAVIGATION RECEIVER MODULE							Component ATA:34
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
345013	NO. 1 ADF ANTENNA							Component ATA:34
PN:7510300-901	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:04038091	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
PROC. REF: AMM 34-57-01PROC. REF: AMM 34-57-01								
345014	NO. 2 ADF ANTENNA							Component ATA:34
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-57-01PROC. REF: AMM 34-57-01								
345024	GPWS CONTROL PANEL							Component ATA:34
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
345025	ENHANCED GROUND PROXIMITY WARNING (EGPWS) COMPUTER							Component ATA:34
PN:965-0976-040-218-218	MOS/MSC	18-Aug-23	O/C					
SN:20608	HRS	5089.1						
	AFL	4280						
PROC. REF: AMM 34-45-01PROC. REF: AMM 34-45-01								
345037	FORWARD ATC ANTENNA							Component ATA:34
PN:DMN150-2-2	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:88838	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
345038	AFT ATC ANTENNA							Component ATA:34
PN:DMN150-2-2	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:89483	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45
Serial: 45-252
RegNo: N253SC
HRS: 5455.2
AFL: 4545
As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
345049	AFT (NO. 1) DME ANTENNA							Component ATA:34
PN:DMN150-2-2	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:89446	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-55-01PROC. REF: AMM 34-55-01								
345050	FORWARD (NO. 2) DME ANTENNA							Component ATA:34
PN:DMN150-2-2	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:88793	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-55-01PROC. REF: AMM 34-55-01								
345083	LEFT VOR/LOCALIZER ANTENNA							Component ATA:34
PN:DMN4-17-1/N	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:16833	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-51-02PROC. REF: AMM 34-51-02								
345084	RIGHT VOR/LOCALIZER ANTENNA							Component ATA:34
PN:DMN4-17-1/N	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:16263	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-51-02PROC. REF: AMM 34-51-02								
345201	NAV VHF (A42) DUPLEXER							Component ATA:34
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-51-04PROC. REF: AMM 34-51-04								
345260	PHASING COUPLER							Component ATA:34
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-51-03PROC. REF: AMM 34-51-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
345501	DME INDICATOR							Component ATA:34
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
345605	LEFT UPPER MODE S ATC ANTENNA							Component ATA:34
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
345606	RIGHT UPPER MODE S ATC ANTENNA							Component ATA:34
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
346001	PILOT FLIGHT MANAGEMENT CONTROL DISPLAY CDU							Component ATA:34
PN:3017-41-221	MOS/MSC	08-Jan-15	O/C	TSN 0				
SN:1672	HRS	3288.6		TSN 0				
	AFL	2723		TSN 0				
PROC. REF: AMM 34-60-01PROC. REF: AMM 34-60-01								
346001A	NO.1 FMS BATTERY REPLACE							Component ATA:34
PN:PN	MOS/MSC	08-Jan-15	A/R	TSN 0				
SN:UNKNOWN	HRS	3288.6		TSN 0				
	AFL	2723		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
346002	COPILOT FLIGHT MANAGEMENT CONTROL DISPLAY CDU							Component ATA:34
PN:3017-41-221	MOS/MSC	08-Jan-15	O/C	TSN 0				
SN:1673	HRS	3288.6		TSN 0				
	AFL	2723		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
346002A		NO.2 FMS BATTERY REPLACE					Component	ATA:34
PN:PN	MOS/MSC	08-Jan-15	A/R	TSN 0				
SN:UNKNOWN	HRS	3288.6		TSN 0				
	AFL	2723		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
346021		FMS DATA (DTU) TRANSFER UNIT					Component	ATA:34
PN:1408-00-1	MOS/MSC	08-Jan-15	O/C	TSN 0				
SN:2844	HRS	3288.6		TSN 0				
	AFL	2723		TSN 0				
PROC. REF: AMM 34-60-02PROC. REF: AMM 34-60-02								
346025		NO. 1 FLIGHT MANAGEMENT CONFIGURATION MODULE					Component	ATA:34
PN:30171	MOS/MSC	08-Jan-15	O/C	TSN 0				
SN:1755	HRS	3288.6		TSN 0				
	AFL	2723		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
346026		NO. 2 FLIGHT MANAGEMENT CONFIGURATION MODULE					Component	ATA:34
PN:30171	MOS/MSC	08-Jan-15	O/C	TSN 0				
SN:1756	HRS	3288.6		TSN 0				
	AFL	2723		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
346031		NO. 1 FMS ANTENNA					Component	ATA:34
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
346032		NO. 2 FMS ANTENNA					Component	ATA:34
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
346090	AFIS DATA MANAGEMENT UNIT							Component ATA:34
PN:PN	MOS/MSC	20-Aug-20	O/C					
SN:NOT INSTALLED	HRS	4461.9						
	AFL	3775						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
346092	AFIS (FLIGHT INFORMATION SYSTEM) ANTENNA REPLACE							Component ATA:34
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
347510	NO. 1 GPS ANTENNA							Component ATA:34
PN:10708	MOS/MSC	08-Jan-15	O/C	TSN 0				
SN:8840	HRS	3288.6		TSN 0				
	AFL	2723		TSN 0				
PROC. REF: AMM 34-53-01PROC. REF: AMM 34-53-01								
347511	NO. 2 GPS ANTENNA							Component ATA:34
PN:10708	MOS/MSC	08-Jan-15	O/C	TSN 0				
SN:8839	HRS	3288.6		TSN 0				
	AFL	2723		TSN 0				
PROC. REF: AMM 34-53-01PROC. REF: AMM 34-53-01								
A3400000 ^S	** NAVIGATION SYSTEMS - PERFORM OPERATIONAL CHECK							Service ATA:34
	MOS	09-Jul-24	24 (+14d/-14d)					AIRWORTHINESS
	HRS	5131.8	600 (+25/-25)					
	AFL	4323						
PROC. REF: AMM 34-00-00PROC. REF: AMM 34-00-00								
L3411062	LEFT PRIMARY PITOT/STATIC PROBE - PERFORM DETAILED VISUAL INSPECTION							Service ATA:34
PN:6634100000-001	MOS	28-Apr-26	24 (+14d/-14d)	Adj -2d	30-Apr-28	10-May-28	647 d (+10)	
SN:223882	HRS	5406.6						
	AFL	4513						
PROC. REF: AMM 34-11-01PROC. REF: AMM 34-11-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
M3411052	LEFT PRIMARY PITOT/STATIC PROBE - VERIFY PITCH, ROLL, AND YAW ALIGNMENT							Service ATA:34
PN:6634100000-001	MOS	28-Apr-26	24 (+14d/-14d)	Adj -2d	30-Apr-28	10-May-28	647 d (+10)	
SN:223882	HRS	5406.6						
	AFL	4513						
PROC. REF: AMM 34-11-01PROC. REF: AMM 34-11-01								
U3411060	AIR DATA SYSTEM - PERFORM FUNCTIONAL TEST							Service ATA:34
	MOS	28-Apr-26	24 (+14d/-14d)	Adj -2d	30-Apr-28	10-May-28	647 d (+10)	
	HRS	5406.6						
	AFL	4513						
PROC. REF: AMM 34-17-00PROC. REF: AMM 34-17-00								
V3420000 ^S	ATTITUDE HEADING REFERENCE UNIT (AHRU) MOUNTING TRAY FAN FILTER - PERFORM VISUAL INSPECTION. ENSURE FILTER IS FREE OF OBSTRUCTIONS.							Service ATA:34
	MOS	09-Jul-24	24 (+14d/-14d)					
	HRS	5131.8	600 (+25/-25)					
	AFL	4323						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								
PKG:7								
Y3411000 ^S	PITOT-STATIC PROBES - PERFORM VISUAL INSPECTION. ENSURE DRAIN HOLES ARE CLEAR OF OBSTRUCTIONS							Service ATA:34
	MOS	09-Jul-24	24 (+14d/-14d)					
	HRS	5131.8	600 (+25/-25)					
	AFL	4323						
PROC. REF: AMM 34-11-01PROC. REF: AMM 34-11-01								
PKG:7								
Y3440000 ^S	RADOME STRUCTURE AND ANTENNA INSTALLATION - PERFORM VISUAL INSPECTION							Service ATA:34
	MOS	24-Feb-23	48 (+14d/-14d)					
	HRS	5067.1	1200 (+25/-25)					
	AFL	4262						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								
PKG:13								
ATA 35 - OXYGEN								
256030	PILOTS PROTECTIVE BREATHING EQUIPMENT							Component ATA:35
PN:PN	MOS/MSC		N/A					NOT INSTALLED

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 35 - OXYGEN									
SN:UNKNOWN	HRS								
	AFL								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
256032	COPILOTS PROTECTIVE BREATHING EQUIPMENT							Component	ATA:35
PN:PN	MOS/MSC		N/A					NOT INSTALLED	
SN:UNKNOWN	HRS								
	AFL								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
350001	OXYGEN CYLINDER							Component	ATA:35
PN:6635000000-119	MOS/MSC	17-Nov-22	H/T		TSN 92, TSO 0				
SN:C15050999	HRS	5002			TSO 0				
	AFL	4210			TSO 0				
PROC. REF: AMM 35-00-01PROC. REF: AMM 35-00-01									
350013	OXYGEN CYLINDER LOW PRESSURE RELIEF VALVE							Component	ATA:35
PN:PN	MOS/MSC	07-Jul-04	O/C		TSN 0				
SN:UNKNOWN	HRS	0			TSN 0				
	AFL	0			TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
350201	TEMP/PRESSURE TRANSDUCER							Component	ATA:35
PN:PN	MOS/MSC	07-Jul-04	O/C		TSN 0				
SN:UNKNOWN	HRS	0			TSN 0				
	AFL	0			TSN 0				
PROC. REF: AMM 35-00-03PROC. REF: AMM 35-00-03									
350225	OXYGEN FILL VALVE (POST SB 45-12-1)							Component	ATA:35
PN:PN	MOS/MSC	07-Jul-04	O/C		TSN 0				
SN:UNKNOWN	HRS	0			TSN 0				
	AFL	0			TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45
Serial: 45-252
RegNo: N253SC
HRS: 5455.2
AFL: 4545
As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
350230	REMOTE OXYGEN PRESSURE INDICATOR							Component ATA:35
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 35-00-05PROC. REF: AMM 35-00-05								
351001	PILOTS OXYGEN MASK							Component ATA:35
PN:MC10-15-166	MOS/MSC	18-Nov-21	O/C	TSO 0				
SN:76977	HRS	4737		TSO 0				
	AFL	3987		TSO 0				
PROC. REF: AMM 35-10-01PROC. REF: AMM 35-10-01								
351002	COPILOTS OXYGEN MASK							Component ATA:35
PN:MC10-15-166	MOS/MSC	18-Nov-21	O/C	TSO 0				
SN:91697	HRS	4737		TSO 0				
	AFL	3987		TSO 0				
PROC. REF: AMM 35-10-01PROC. REF: AMM 35-10-01								
351003	PASSENGER OXYGEN MASK (OVHL/SCRAP) - 289 SERIES PAX OXYGEN MASK (REFER ZODIAC / AVOX MANUAL 833-35-01) REPLACE							Component ATA:35
PN:PN	MOS/MSC	07-Jul-04	N/A	TSN 0				NOT INSTALLED
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: SI 833-35-01, AMM 35-20-03PROC. REF: SI 833-35-01, AMM 35-20-03								
351003A	INSPECTION PASSENGER OXYGEN MASK (INSPECTION) - PERFORM VISUAL INSPECTION OF 289 SERIES PAX OXYGEN MASK (REFER ZODIAC / AVOX MANUAL 833-35-01).							Service ATA:35
	MOS	07-Feb-25	36 (+14d/-14d)	Adj 14d	29-Feb-28	06-Mar-28	586 d (+6)	VENDOR RECOMMENDATION
	HRS	5215.4						
	AFL	4401						
PROC. REF: GENERIC NO REF, SI 833-35-01PROC. REF: GENERIC NO REF, SI 833-35-01								
351005	PILOT CREW OXYGEN OUTLET							Component ATA:35
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 35-10-01PROC. REF: AMM 35-10-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
351006	COPILOT CREW-OXYGEN OUTLET							Component ATA:35
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 35-10-01PROC. REF: AMM 35-10-01								
352002	ALTITUDE COMPENSATING REGULATOR							Component ATA:35
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 35-20-06PROC. REF: AMM 35-20-06								
352011	OXYGEN CONTROL VALVE							Component ATA:35
PN:P21081	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:0316	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 35-20-01PROC. REF: AMM 35-20-01								
352025	OXYGEN CYLINDER REGULATOR							Component ATA:35
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
353001	PORTABLE OXYGEN CYLINDER							Component ATA:35
PN:PN	MOS/MSC		-					NOT INSTALLED
SN:UNKNOWN	HRS							
	AFL							
PROC. REF: AMM 35-00-01PROC. REF: AMM 35-00-01								
353001B	VISUALLY INSPECT PER MANUFACTURER'S INSTRUCTIONS							Service ATA:35
PN:PN	MOS/MSC		N/A					NOT INSTALLED
SN:UNKNOWN	HRS							
	AFL							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
355111	OXYGEN PRESSURE INDICATOR							Component ATA:35
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 35-00-05PROC. REF: AMM 35-00-05								
K3500021	** OXYGEN SYSTEM LOW PRESSURE SUPPLY HOSES - PERFORM OPERATIONAL CHECK. ENSURE THAT HOSES ARE FREE OF OBSTRUCTIONS							Service ATA:35
	MOS/MSC	07-Jul-04	N/A					
	HRS	0						
	AFL	0						
PROC. REF: AMM 35-00-00PROC. REF: AMM 35-00-00								
N3510013	** OXYGEN CYLINDER AND REMOTE OXYGEN FILL VALVES - PERFORM PERIODIC CHECK							Service ATA:35
	MOS	06-Sep-19						AIRWORTHINESS
	HRS	4261.4	1500 (+25/-25)		5761.4	5786.4	306.2 (+25)	
	AFL	3621						
PROC. REF: AMM 35-00-01PROC. REF: AMM 35-00-01								
N3510019	** OXYGEN CYLINDER AND REMOTE OXYGEN FILL VALVES - PERFORM PERIODIC CHECK							Service ATA:35
	MOS/MSC		N/A					
	HRS							
	AFL							
PROC. REF: AMM 35-00-01PROC. REF: AMM 35-00-01								
O3510003 ^S	** CABIN LOW PRESSURE OXYGEN DISTRIBUTION FLEX HOSES - PERFORM FUNCTIONAL TEST							Service ATA:35
	MOS	09-Jul-24	24 (+14d/-14d)					AIRWORTHINESS
	HRS	5131.8	600 (+25/-25)					
	AFL	4323						
PROC. REF: AMM 35-20-00PROC. REF: AMM 35-20-00								
PKG:7								
O3510006	COPILOTS OXYGEN MASK - E.R.O.S. CREW OXYGEN MASKS - COMPLY WITH FACTORY OVERHAUL							Service ATA:35
PN:MC10-15-166	MOS	01-Jul-21	72 (+14d/-14d)		31-Jul-27	31-Jul-27	373 d	
SN:91697	HRS							
	AFL							
OverHaul Date:: 01-Jul-21								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
O3510006		PILOTS OXYGEN MASK - E.R.O.S. CREW OXYGEN MASKS - COMPLY WITH FACTORY OVERHAUL						Service ATA:35
PN:MC10-15-166	MOS	01-Mar-21	72 (+14d/-14d)		31-Mar-27	31-Mar-27	251 d	
SN:76977	HRS							
	AFL							
OverHaul Date:: 01-Mar-21								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
O3510007		OXYGEN CYLINDER (COMPOSITE) - SCRAP						Service ATA:35
	MOS	07-Jul-04	180 (+14d/-14d)		31-Mar-30 (M)	14-Apr-30	1347 d (+14)	LIFE LIMIT
	HRS	0						
	AFL	0						
Q3500024		PORTABLE OXYGEN CYLINDER - PERFORM ICC HYDROSTATIC TEST ON PORTABLE OXYGEN CYLINDER (STEEL, DOT3AA1800)						Service ATA:35
PN:PN	MOS/MSC		N/A					NOT INSTALLED
SN:UNKNOWN	HRS							
	AFL							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
Q3510005		** OXYGEN CYLINDER (COMPOSITE) AND LOW PRESSURE RELIEF VALVE - PERFORM ICC HYDROSTATIC TEST ON CYLINDER (PER DOT EXEMPTION E8162) AND FUNCTIONALLY TEST OXYGEN CYLINDER LOW PRESSURE RELIEF VALVE.						Service ATA:35
PN:6635000000-119	MOS	01-Sep-22	60 (+14d/-14d)		30-Sep-27	30-Sep-27	434 d	
SN:C15050999	HRS	5002	5000 (+25/-25)		10002	10027	4546.8 (+25)	
	AFL							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
Q3510018		** OXYGEN CYLINDER (COMPOSITE) AND LOW PRESSURE RELIEF VALVE - PERFORM ICC HYDROSTATIC TEST ON CYLINDER (PER DOT EXEMPTION E8162) AND FUNCTIONALLY TEST OXYGEN CYLINDER LOW PRESSURE RELIEF VALVE						Service ATA:35
PN:6635000000-119	MOS	17-Nov-22	60 (+14d/-14d)		01-Oct-27 (M)	15-Oct-27	435 d (+14)	
SN:C15050999	HRS	5002	5000 (+25/-25)		10002	10027	4546.8 (+25)	
	AFL	4210						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
Q3510022	OXYGEN CYLINDER REGULATOR - PERFORM OVERHAUL							Service ATA:35
	MOS	17-Nov-22	60 (+14d/-14d)		30-Nov-27	01-Dec-27	495 d (+1)	
	HRS	5002	5000 (+25/-25)		10002	10027	4546.8 (+25)	
	AFL	4210						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
Q3510023	OXYGEN CYLINDER REGULATOR - PERFORM OVERHAUL							Service ATA:35
	MOS/MSC		N/A					
	HRS							
	AFL							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
S3510014 ^S	** OXYGEN SYSTEM ALTITUDE COMPENSATING REGULATOR - PERFORM FUNCTIONAL TEST							Service ATA:35
	MOS	09-Jul-24	24 (+14d/-14d)					AIRWORTHINESS
	HRS	5131.8	600 (+25/-25)					
	AFL	4323						
PROC. REF: AMM 35-20-00PROC. REF: AMM 35-20-00								
W3510002 ^S	** OXYGEN SYSTEM - PERFORM OPERATIONAL CHECK							Service ATA:35
	MOS	09-Jul-24	24 (+14d/-14d)					AIRWORTHINESS
	HRS	5131.8	600 (+25/-25)					
	AFL	4323						
PROC. REF: AMM 35-00-00PROC. REF: AMM 35-00-00								
Y3510000 ^S	OXYGEN CYLINDER INSTALLATION - PERFORM VISUAL INSPECTION. CHECK PLUMBING FOR ROUTING, SECURITY, AND CONDITION.							Service ATA:35
	MOS	24-Feb-23	48 (+14d/-14d)					
	HRS	5067.1	1200 (+25/-25)					
	AFL	4262						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
Y3510001	^S	CREW SEAT OXYGEN HOSES - PERFORM VISUAL INSPECTION. PAY PARTICULAR ATTENTION TO AREA WHERE OXYGEN HOSES ENTER CREW SEATS ABOVE COCKPIT FLOOR.						Service ATA:35
	MOS	31-Jul-25	12 (+14d/-14d)					
	HRS	5307.6	300 (+25/-25)					
	AFL	4448						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								PKG:1
Y3510017	^S	OXYGEN CYLINDER INSTALLATION - PERFORM VISUAL INSPECTION. CHECK PLUMBING FOR ROUTING, SECURITY, AND CONDITION						Service ATA:35
	MOS	09-Jul-24	24 (+14d/-14d)					
	HRS	5131.8	600 (+25/-25)					
	AFL	4323						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								PKG:7
ATA 36 - PNEUMATIC								
361001		LEFT OUTBOARD HIGH PRESSURE TAILCONE MANIFOLD						Component ATA:36
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
361002		LEFT OUTBOARD ANTI-ICE MANIFOLD						Component ATA:36
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-10-07PROC. REF: AMM 30-10-07								
361004		LEFT INBOARD HIGH-PRESSURE BLEED AIR MANIFOLD						Component ATA:36
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-10-07PROC. REF: AMM 36-10-07								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 36 - PNEUMATIC								
361005	RIGHT INBOARD HIGH-PRESSURE BLEED AIR MANIFOLD							Component ATA:36
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-10-07PROC. REF: AMM 36-10-07								
361015	CENTER MANIFOLD							Component ATA:36
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
361016	RIGHT OUTBOARD ANTI-ICE MANIFOLD							Component ATA:36
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-10-07PROC. REF: AMM 30-10-07								
361017	RIGHT OUTBOARD HIGH PRESSURE TAILCONE MANIFOLD							Component ATA:36
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
361020	LEFT HIGH PRESSURE OVER-TEMP SWITCH							Component ATA:36
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-20-03PROC. REF: AMM 36-20-03								
361021	RIGHT HIGH PRESSURE OVER-TEMP SWITCH							Component ATA:36
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-20-03PROC. REF: AMM 36-20-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 36 - PNEUMATIC								
361031	ECS CONTROLLER							Component ATA:36
PN:6636108500-003	MOS/MSC	18-Jan-13	O/C	TSR 0				
SN:32V2L	HRS	2835.8		TSR 0				
	AFL	2345		TSR 0				
PROC. REF: AMM 36-10-01PROC. REF: AMM 36-10-01								
361040	APU BLEED AIR CHECK VALVE							Component ATA:36
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-10-09PROC. REF: AMM 36-10-09								
361050	LOAD CONTROL SHUTOFF VALVE (L5003)							Component ATA:36
PN:3876322-1	MOS/MSC	09-Sep-04	O/C	TSN 0				
SN:0158	HRS	16		TSN 0				
	AFL	12		TSN 0				
PROC. REF: AMM 36-10-10PROC. REF: AMM 36-10-10								
361053	NO. 1 ECS SHUTOFF (L37) VALVE							Component ATA:36
PN:3215468-1	MOS/MSC	21-Jul-23	O/C					
SN:1163	HRS	5076.3						
	AFL	4268						
PROC. REF: AMM 36-10-03PROC. REF: AMM 36-10-03								
361054	NO. 2 ECS SHUTOFF (L38) VALVE							Component ATA:36
PN:6621000000-061	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:670	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-10-03PROC. REF: AMM 36-10-03								
361055	NO. 1 BUTTERFLY SHUTOFF VALVE							Component ATA:36
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-10-03PROC. REF: AMM 36-10-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 36 - PNEUMATIC								
361056	NO. 2 BUTTERFLY SHUTOFF VALVE							Component ATA:36
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-10-03PROC. REF: AMM 36-10-03								
361065	LEFT TAILCONE HIGH PRESSURE SHUT-OFF VALVE (L39)							Component ATA:36
PN:6621000000-073	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:750	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-10-02PROC. REF: AMM 36-10-02								
361066	RIGHT TAILCONE HIGH PRESSURE SHUT-OFF VALVE (L40)							Component ATA:36
PN:3291216-3	MOS/MSC	22-Aug-11	O/C	TSR 0				
SN:1093C	HRS	2442.2		TSR 0				
	AFL	2000		TSR 0				
PROC. REF: AMM 36-10-02PROC. REF: AMM 36-10-02								
361120	NO. 1 PRESSURE SWITCH (S79)							Component ATA:36
PN:642019-3	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:0722	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-10-06PROC. REF: AMM 36-10-06								
361121	NO. 2 PRESSURE SWITCH (S88)							Component ATA:36
PN:642019-3	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:0701	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-10-06PROC. REF: AMM 36-10-06								
361122	LEFT HIGH PRESSURE BLEED AIR TUBE							Component ATA:36
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 36 - PNEUMATIC								
361123	RIGHT HIGH PRESSURE BLEED AIR TUBE							Component ATA:36
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
361125	LEFT PYLON LOW PRESSURE TEMPERATURE SENSOR							Component ATA:36
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
361126	RIGHT PYLON LOW PRESSURE TEMPERATURE SENSOR							Component ATA:36
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
361127	LEFT TAILCONE LOW PRESSURE (2.0 DIAMETER) CHECK VALVE							Component ATA:36
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
361128	RIGHT TAILCONE LOW PRESSURE (2.0 DIAMETER) CHECK VALVE							Component ATA:36
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
361215	LEFT HIGH PRESSURE BLEED AIR MANIFOLD							Component ATA:36
PN:LJ01212-001	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:190304-001	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-10-07PROC. REF: AMM 36-10-07								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 36 - PNEUMATIC								
361216 RIGHT HIGH PRESSURE BLEED AIR MANIFOLD								Component ATA:36
PN:LJ01212-002	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:170304-001	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-10-07PROC. REF: AMM 36-10-07								
361301 APU SERVO AIR CHECK VALVE								Component ATA:36
PN:6608295-3	MOS/MSC	09-Sep-04	O/C	TSN 0				
SN:1507	HRS	16		TSN 0				
	AFL	12		TSN 0				
PROC. REF: AMM 36-15-02PROC. REF: AMM 36-15-02								
361302 NO. 1 ENGINE SERVO AIR CHECK VALVE								Component ATA:36
PN:6608295-3	MOS/MSC	18-Jan-11	O/C	TSN 0				
SN:3297	HRS	2336.6		TSN 0				
	AFL	1905		TSN 0				
PROC. REF: AMM 36-15-02PROC. REF: AMM 36-15-02								
361303 NO. 2 ENGINE SERVO AIR CHECK VALVE								Component ATA:36
PN:6608295-3	MOS/MSC	18-Jan-11	O/C	TSN 0				
SN:3306	HRS	2336.6		TSN 0				
	AFL	1905		TSN 0				
PROC. REF: AMM 36-15-02PROC. REF: AMM 36-15-02								
362005 LEFT FORWARD TAILCONE OVERHEAT THERMOSTAT SWITCH (S145)								Component ATA:36
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-20-02PROC. REF: AMM 36-20-02								
362006 RIGHT FORWARD TAILCONE OVERHEAT THERMOSTAT SWITCH (S146)								Component ATA:36
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-20-02PROC. REF: AMM 36-20-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 36 - PNEUMATIC								
362007	LEFT AFT TAILCONE OVERHEAT THERMOSTAT SWITCH (S147)							Component ATA:36
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-20-02PROC. REF: AMM 36-20-02								
362008	RIGHT AFT TAILCONE OVERHEAT THERMOSTAT SWITCH (S148)							Component ATA:36
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-20-02PROC. REF: AMM 36-20-02								
364925	LEFT ECS CHECK VALVE							Component ATA:36
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-10-04PROC. REF: AMM 36-10-04								
364926	RIGHT ECS CHECK VALVE							Component ATA:36
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-10-04PROC. REF: AMM 36-10-04								
5-19-00-D3610002	BORESCOPE INSPECTION HP BLEED AIR MANIFOLD ASSEMBLY ATTACH BRACKET ASSEMBLY FOR CRACKS AT WELD.(IRN D3610002)							Service ATA:36
	MOS/MSC	07-Jul-04	N/A					
	HRS	0						
	AFL	0						
A3610000 ^S	** BLEED AIR SYSTEM - PERFORM FUNCTIONAL TEST							Service ATA:36
	MOS	09-Jul-24	24 (+14d/-14d)					AIRWORTHINESS
	HRS	5131.8	600 (+25/-25)					
	AFL	4323						
PROC. REF: AMM 36-10-00PROC. REF: AMM 36-10-00								
PKG:7								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 36 - PNEUMATIC								
A3610001	S	** PYLON OVERHEAT THERMOSTAT AND ELECTRICAL SYSTEM - PERFORM FUNCTIONAL TEST						Service ATA:36
	MOS	09-Jul-24	24 (+14d/-14d)					AIRWORTHINESS
	HRS	5131.8	600 (+25/-25)					
	AFL	4323						
PROC. REF: AMM 36-20-01PROC. REF: AMM 36-20-01								PKG:8
D3610002		LEFT HIGH PRESSURE BLEED AIR MANIFOLD - PERFORM BORESCOPE INSPECTION OF ATTACH BRACKET ASSEMBLY FOR CRACKS AT WELD						Service ATA:36
PN:LJ01212-001	MOS/MSC	07-Jul-04	O/C					
SN:190304-001	HRS	0						
	AFL	0						
PROC. REF: AMM 36-10-07PROC. REF: AMM 36-10-07								
D3610002		RIGHT HIGH PRESSURE BLEED AIR MANIFOLD - PERFORM BORESCOPE INSPECTION OF ATTACH BRACKET ASSEMBLY FOR CRACKS AT WELD						Service ATA:36
PN:LJ01212-002	MOS/MSC	07-Jul-04	O/C					
SN:170304-001	HRS	0						
	AFL	0						
PROC. REF: AMM 36-10-07PROC. REF: AMM 36-10-07								
P3610048		LEFT HIGH PRESSURE BLEED AIR MANIFOLD - PERFORM VISUAL INSPECTION						Service ATA:36
PN:LJ01212-001	MOS	27-Aug-13						
SN:190304-001	HRS	3014.2	3500 (+100/-100)		6514.2	6614.2	1059 (+100)	
	AFL	2498						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								
P3610048		RIGHT HIGH PRESSURE BLEED AIR MANIFOLD - PERFORM VISUAL INSPECTION						Service ATA:36
PN:LJ01212-002	MOS	27-Aug-13						
SN:170304-001	HRS	3014.2	3500 (+100/-100)		6514.2	6614.2	1059 (+100)	
	AFL	2498						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 36 - PNEUMATIC								
U3610075	^S	ECS BLEED AIR "Y" MANIFOLD - PERFORM BORESCOPE INSPECTION						Service ATA:36
	MOS	18-Nov-21						
	HRS	4737	4800 (+25/-25)					
	AFL	3987						
PROC. REF: AMM 36-10-00PROC. REF: AMM 36-10-00								PKG:25
Y3610061	^S	HIGH PRESSURE BLEED AIR SHUT-OFF VALVE IN-LINE FILTER - PERFORM CLEANING PROCEDURES						Service ATA:36
	MOS	09-Jul-24	24 (+14d/-14d)					
	HRS	5131.8	600 (+25/-25)					
	AFL	4323						
PROC. REF: AMM 36-10-02PROC. REF: AMM 36-10-02								PKG:8
ATA 38 - WATER/WASTE								
380001		TOILET SERVICE PANEL						Component ATA:38
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 38-30-05PROC. REF: AMM 38-30-05								
381009		TOILET HEATED DRAIN MAST						Component ATA:38
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
383001		TOILET --						Component ATA:38
PN:66383001-005	MOS/MSC	17-Oct-07	O/C	TSR 0				
SN:U2396	HRS	1174.8		TSR 0				
	AFL	963		TSR 0				
PROC. REF: AMM 38-30-01PROC. REF: AMM 38-30-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 38 - WATER/WASTE								
383002	TOILET TIMER							Component ATA:38
PN:9600-12B	MOS/MSC	09-Sep-04	O/C	TSN 0				
SN:T17759	HRS	16.9		TSN 0				
	AFL	12		TSN 0				
PROC. REF: AMM 38-30-02PROC. REF: AMM 38-30-02								
383005	TOILET WATER TANK							Component ATA:38
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
383010	TOILET TANK FLOAT SWITCH							Component ATA:38
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				CUSTOMER CODE
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
383011	LAVATORY SINK SHUT OFF VALVE							Component ATA:38
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
384025	TOILET PUMP							Component ATA:38
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
384051	TOILET MACERATOR							Component ATA:38
PN:5300-1	MOS/MSC	09-Oct-18	O/C	TSN 0				
SN:M4990	HRS	4052.9		TSN 0				
	AFL	3433		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition
ATA 38 - WATER / WASTE								
389050	TOILET CLEAN WATER PUMP							Component ATA:38
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
ATA 49 - AIRBORNE AUXILIARY POWER								
490060	APU ELECTRONIC CONTROL UNIT (ECU)							Component ATA:49
PN:2119560-3	MOS/MSC	09-Sep-04	O/C	TSN 0				
SN:84-G0102	HRS	16		TSN 0				
	AFL	12		TSN 0				
PROC. REF: AMM 49-60-04PROC. REF: AMM 49-60-04								
491011	APU MAINTENANCE CONTROL PANEL							Component ATA:49
PN:7088001-2	MOS/MSC	09-Sep-04	O/C	TSN 0				
SN:DC188	HRS	16		TSN 0				
	AFL	12		TSN 0				
PROC. REF: AMM 49-60-02PROC. REF: AMM 49-60-02								
491020	APU COCKPIT CONTROL PANEL							Component ATA:49
PN:7088000-1	MOS/MSC	09-Sep-04	O/C	TSN 0				
SN:DB212	HRS	16		TSN 0				
	AFL	12		TSN 0				
PROC. REF: AMM 49-60-01PROC. REF: AMM 49-60-01								
492001	APU - AUXILIARY POWER UNIT (APU) COMPRESSOR ROTOR. (P/N 3822523-2 - IRN H4900019) (P/N 3822523-003 OR 70722359-1 - IRN AE4900020) - REPLACE							Component ATA:49
PN:3822523-003	MOS	28-May-20		TSN 255, TSR 2				LIFE LIMIT
SN:980350107443	HRS	1669.7		TSN 1669.7, TSR 0				
	APUS	3985	12000	TSN 3985, TSR 0	12000		7147	
PROC. REF: AMM 49-10-01PROC. REF: AMM 49-10-01								
492005	APU - AUXILIARY POWER UNIT (APU) TURBINE ROTOR (P/N 3842340 OR 70722360-1)(IRN AE4900018) - CHANGE							Component ATA:49
PN:3842340-2	MOS	28-May-20		TSN 2				LIFE LIMIT
SN:19-156101-12700	HRS	1669.7		TSN 0				
	APUS	3985	4000	TSN 0	7985		3132	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 49 - AIRBORNE AUXILIARY POWER								
PROC. REF: AMM 49-10-01PROC. REF: AMM 49-10-01								
493071	APU - APU ASSEMBLY, FUEL CONTROL							Component ATA:49
PN:3883900-1	MOS/MSC	09-Jul-15	O/C	TSN 0				
SN:1502002	HRS	1345.32		TSN 0				
	APUS	3044		TSN 0				
PROC. REF: AMM 49-30-04PROC. REF: AMM 49-30-04								
494021	APU - APU LOW VOLTAGE IGNITER PLUG							Component ATA:49
PN:PN	MOS/MSC	19-Feb-99	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	APUS	0		TSN 0				
PROC. REF: AMM 49-40-02PROC. REF: AMM 49-40-02								
494050	APU IGNITION UNIT							Component ATA:49
PN:3888000-7	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:04021804937	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 49-40-04PROC. REF: AMM 49-40-04								
495001	TAILCONE APU COOLING FAN							Component ATA:49
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 49-50-01PROC. REF: AMM 49-50-01								
495002	TAILCONE ACCESS DOOR COOLING (B30) FAN							Component ATA:49
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
495040	APU THERMOSTAT (S175) SWITCH							Component ATA:49
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 49 - AIRBORNE AUXILIARY POWER								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
495041	APU THERMOSTAT (S176) SWITCH							Component ATA:49
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
495201	STRUT SUPPORT ASSEMBLY							Component ATA:49
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
495202	STRUT SUPPORT ASSEMBLY							Component ATA:49
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
496003	APU - BALL, ANNULAR BEARING							Component ATA:49
PN:3822570-1	MOS/MSC	28-May-20	O/C	TSN 2				
SN:19-162255-00839	HRS	1669.7		TSN 0				
	APUS	3985		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
497001	APU BITE INDICATOR							Component ATA:49
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 49-70-04PROC. REF: AMM 49-70-04								
499110	APU - SOAP CHECK OIL							Service ATA:49
	MOS	25-Nov-25						
	HRS	1935.1	500 (+20%/-20%)		2435.1	2535.1	448.4 (+100)	
	APUS	4762						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 49 - AIRBORNE AUXILIARY POWER								
PROC. REF: SIL SIL-49, SIL SIL-49PROC. REF: SIL SIL-49, SIL SIL-49								
49APU1	APU							Component ATA:49
PN:3800726-1	MOS/MSC	05-Jun-20	E/C					
SN:P-162	HRS							
	AFL							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
E4900016 ^S	APU BLEED AIR CHECK VALVE - PERFORM OPERATIONAL CHECK. VERIFY THAT VALVE HAS NOT FAILED OPEN.						Service	ATA:49
	MOS/MSC	07-Jul-04	N/A				JAA	
	HRS	0						
	AFL	0						
PKG:25								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
H4900011 ^S	** APU GENERATOR - PERFORM OVERVOLTAGE PROTECTION CHECK						Service	ATA:49
	MOS	24-Feb-23	48 (+14d/-14d)				AIRWORTHINESS	
	HRS	5067.1	1200 (+25/-25)					
	AFL	4262						
PKG:13								
PROC. REF: AMM 49-40-01PROC. REF: AMM 49-40-01								
K4900005	APU - APU ENGINE FUEL FILTER - REPLACE						Service	ATA:49
	MOS	12-Mar-20						
	HRS	1669.7	750 (+25/-25)		2914.7 (M)	2939.7	928 (+25)	
	APUS	3985						
PROC. REF: AMM 49-30-03PROC. REF: AMM 49-30-03								
L4900015.S	APU ENGINE FIRE EXTINGUISHER CONTAINER CARTRIDGE - SERVICE LIFE LIMIT						Service	ATA:49
PN:30600-22	MOS	26-Apr-24	144		30-Apr-36		3569 d	SERVICE LIFE LIMIT
SN:129	HRS	5128.5						
	AFL	4317						
PROC. REF: AMM 26-21-02PROC. REF: AMM 26-21-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 49 - AIRBORNE AUXILIARY POWER								
L4900015.T	APU ENGINE FIRE EXTINGUISHER CONTAINER CARTRIDGE - TOTAL LIFE LIMIT							Service ATA:49
	MOS	26-Apr-24	180		31-Jan-39		4575 d	LIFE LIMIT
	HRS	5128.5						
	AFL	4317						
	Manufacture Date:: 31-Jan-24							
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
O4900006	APU STARTER/GENERATOR - APU ENGINE STARTER/GENERATOR GEAR BOX DRIVE SPLINES - PERFORM VISUAL INSPECTION							Service ATA:49
PN:6608458-010	MOS	25-Aug-23						
SN:98231	HRS	5106.9						
	AFL	4299						
	APH	1813.1	1200 (+25/-25)		3013.1	3038.1	1026.4 (+25)	
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								
O4900008	APU - APU ENGINE CHIP DETECTOR - INSPECT FOR CONTAMINATION							Service ATA:49
	MOS	12-Mar-20						
	HRS	1669.7	750		2914.7 (M)		928	
	APUS	3985						
PROC. REF: AMM 49-90-05PROC. REF: AMM 49-90-05								
P4900009	APU - APU ENGINE - PERFORM OIL CHANGE							Service ATA:49
	MOS/MSC	15-Feb-10	N/A					
	HRS	734.72						
	APUS	1732						
PROC. REF: AMM 12-10-10PROC. REF: AMM 12-10-10								
T4900004	APU - APU ENGINE OIL FILTER - REPLACE							Service ATA:49
	MOS/MSC	15-Feb-10	N/A					NOT APPLICABLE
	HRS	734.72						
	APUS	1732						
PROC. REF: AMM 49-90-04PROC. REF: AMM 49-90-04								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 49 - AIRBORNE AUXILIARY POWER								
V4900003	APU STARTER/GENERATOR - PERFORM OVERHAUL REPLACE STARTER/ GENERATOR BRUSHES							Service ATA:49
PN:6608458-010	MOS/MSC		N/A					N/A EQUIPMENT NOT INSTALLED
SN:98231	HRS							
	AFL							
PROC. REF: AMM 49-40-01PROC. REF: AMM 49-40-01								
Y4900000 ^S	AUXILIARY POWER UNIT - PERFORM VISUAL INSPECTION OF EXTERNAL FIREBOX INSTALLATION AND ATTACHING COMPONENTS							Service ATA:49
	MOS	31-Jul-25	12 (+14d/-14d)					
	HRS	5307.6	300 (+25/-25)					
	AFL	4448						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								
Y4900002 ^S	AUXILIARY POWER UNIT FIRE EXTINGUISHER CONTAINER - PERFORM FUNCTIONAL TEST OF WIRING							Service ATA:49
	MOS	09-Jul-24	24 (+14d/-14d)					
	HRS	5131.8	600 (+25/-25)					
	AFL	4323						
PROC. REF: AMM 26-22-00PROC. REF: AMM 26-22-00								
Y4900010 ^S	APU ENGINE FIRE EXTINGUISHER CONTAINER - CHECK CONTAINER PRESSURE GAGE FOR PROPER PRESSURE							Service ATA:49
	MOS	31-Jul-25	12 (+14d/-14d)					
	HRS	5307.6	300 (+25/-25)					
	AFL	4448						
PROC. REF: AMM 26-22-00PROC. REF: AMM 26-22-00								
Y4900012 ^S	APU INLET SCREEN AND OPENING - PERFORM VISUAL INSPECTION							Service ATA:49
	MOS	31-Jul-25	12 (+14d/-14d)					
	HRS	5307.6	300 (+25/-25)					
	AFL	4448						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 49 - AIRBORNE AUXILIARY POWER								
Y4900013 ^S	APU EXHAUST DUCT AREA, INCLUDING FORWARD AND AFT APU EXHAUST FAIRINGS - PERFORM VISUAL INSPECTION							Service ATA:49
	MOS	31-Jul-25	12 (+14d/-14d)					
	HRS	5307.6	300 (+25/-25)					
	AFL	4448						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								PKG:2

ATA 52 - DOORS								
521001	UPPER CABIN DOOR							Component ATA:52
PN:4552100050V90-001	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:W266	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-10-01PROC. REF: AMM 52-10-01								

521002	LOWER CABIN DOOR							Component ATA:52
PN:4552100050V89-001	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:W252	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-10-01PROC. REF: AMM 52-10-01								

521010	LOWER ENTRY DOOR FORWARD GAS DAMPER ASSEMBLY							Component ATA:52
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-10-11PROC. REF: AMM 52-10-11								

521011	LOWER ENTRY DOOR AFT GAS DAMPER ASSEMBLY							Component ATA:52
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-10-11PROC. REF: AMM 52-10-11								

522001	EMERGENCY EXIT DOOR ASSEMBLY							Component ATA:52
PN:4552200076V36-001	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:45/252	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
PROC. REF: AMM 52-20-01PROC. REF: AMM 52-20-01								
522010	EMERGENCY EXIT DOOR WINDOW							Component ATA:52
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-20-06PROC. REF: AMM 52-20-06								
523001	TAILCONE BAGGAGE DOOR ASSEMBLY							Component ATA:52
PN:12045-557V1-001	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:0285	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
524001	TAILCONE ACCESS DOOR							Component ATA:52
PN:4552405151-005	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:0285	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-40-02PROC. REF: AMM 52-40-02								
524010	SPPR DOOR ASSY							Component ATA:52
PN:4533408469-001	MOS/MSC	26-Mar-07	O/C	TSN 4				
SN:UNKNOWN	HRS	1003.6		TSN 0				
	AFL	830		TSN 0				
PROC. REF: AMM 52-40-03PROC. REF: AMM 52-40-03								
A5210009 ^S	* EMERGENCY EXIT DOOR RETAINERS - PERFORM VISUAL INSPECTION. INSPECT DOOR STOP FITTINGS ON EMERGENCY EXIT DOOR FRAMES IN FLANGE RADII. (F.S. 374 AND 394).							Service ATA:52
	MOS	07-Jul-04						AIRWORTHINESS
	HRS	0	9600 (+25/-25)					
	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

PKG:26

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
A5210012	^S	* LOWER PASSENGER DOOR HINGE - PERFORM VISUAL INSPECTION. INSPECT PIANO HINGE LUGS AND FASTENERS.						Service ATA:52
	MOS	07-Jul-04						AIRWORTHINESS
	HRS	0	9600 (+25/-25)					
	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:26
A5210014	^S	* UPPER PASSENGER DOOR TENSION FITTINGS - PERFORM VISUAL INSPECTION. INSPECT THE FOLLOWING: A. TENSION STUDS AT RETAINING FLANGES. B. RADII AROUND FLANGE PERIPHERY.						Service ATA:52
	MOS	07-Jul-04						AIRWORTHINESS
	HRS	0	9600 (+25/-25)					
	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:26
AA5210055	^S	CABIN DOOR HANDLE RAMP ROLLER WHEEL - LUBRICATE						Service ATA:52
	MOS	24-Feb-23	48 (+14d/-14d)					
	HRS	5067.1	1200 (+25/-25)					
	AFL	4262						
PROC. REF: AMM 12-21-02PROC. REF: AMM 12-21-02								PKG:18
D5210015	^S	* EMERGENCY EXIT DOOR - PERFORM VISUAL INSPECTION. PAY PARTICULAR ATTENTION TO FLANGES AND FASTENER HOLES OF DOOR STOP FITTINGS.						Service ATA:52
	MOS	18-Nov-21						AIRWORTHINESS
	HRS	4737	4800 (+25/-25)					
	AFL	3987						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								PKG:25
E5210013	^S	* UPPER AND LOWER PASSENGER DOOR LATCH ARMS AND DOOR ATTACHMENTS - PERFORM VISUAL INSPECTION						Service ATA:52
	MOS	18-Nov-21						AIRWORTHINESS
	HRS	4737	4800 (+25/-25)					
	AFL	3987						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								PKG:25

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
F5210016	^S	* UPPER PASSENGER DOOR HINGE - PERFORM VISUAL INSPECTION. INSPECT UPPER SURFACE OF HINGE FINGERS AT BASE OF LUG.						Service ATA:52
	MOS	07-Jul-04						AIRWORTHINESS
	HRS	0	9600 (+25/-25)					
	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:26
M5240004		AVIONIC ACCESS DOORS - PERFORM AVIONICS DOOR GAP AND MISMATCH INSPECTION						Service ATA:52
	MOS	28-Apr-26	24 (+14d/-14d)	Adj -2d	30-Apr-28	10-May-28	647 d (+10)	
	HRS	5406.6						
	AFL	4513						
PROC. REF: AMM 52-40-01PROC. REF: AMM 52-40-01								
N5210010	^S	* LOWER PASSENGER DOOR TENSION BOLTS, BOLT RETAINERS, TENSION FITTINGS, AND DOOR ATTACHMENTS - PERFORM VISUAL INSPECTION						Service ATA:52
	MOS	01-Mar-19	96 (+14d/-14d)					AIRWORTHINESS
	HRS	4123.3	2400 (+25/-25)					
	AFL	3499						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:24
N5210011	^S	* UPPER AND LOWER PASSENGER DOOR LATCH PINS - PERFORM VISUAL INSPECTION. INSPECT BOLTS AND DOOR END RIB STRUCTURE AT LOCK PINS.						Service ATA:52
	MOS	01-Mar-19	96 (+14d/-14d)					AIRWORTHINESS
	HRS	4123.3	2400 (+25/-25)					
	AFL	3499						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:24
N5210017	^S	* UPPER PASSENGER DOOR TENSION BOLTS, BOLT RETAINERS, TENSION FITTINGS, AND DOOR ATTACHMENTS - PERFORM VISUAL INSPECTION						Service ATA:52
	MOS	01-Mar-19	96 (+14d/-14d)					AIRWORTHINESS
	HRS	4123.3	2400 (+25/-25)					
	AFL	3499						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:24

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
T5210003	^S	EXTERNAL LOWER PASSENGER/CREW DOOR CABLES - PERFORM VISUAL INSPECTION OF VISIBLE PORTION OF CABLES AND HANDLE AREA.						Service ATA:52
	MOS	24-Feb-23	48 (+14d/-14d)					
	HRS	5067.1	1200 (+25/-25)					
	AFL	4262						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								PKG:18
Y5210000	^S	AVIONICS COMPARTMENT ACCESS DOORS AND SEALS - PERFORM VISUAL INSPECTION						Service ATA:52
	MOS	24-Feb-23	48 (+14d/-14d)					
	HRS	5067.1	1200 (+25/-25)					
	AFL	4262						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								PKG:13
Y5210001	^S	TAILCONE ACCESS DOOR AND SEAL - PERFORM VISUAL INSPECTION OF DOOR, SEALS, AND LATCHES						Service ATA:52
	MOS	09-Jul-24	24 (+14d/-14d)					
	HRS	5131.8	600 (+25/-25)					
	AFL	4323						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								PKG:12
Y5210002	^S	BAGGAGE COMPARTMENT DOOR - PERFORM VISUAL INSPECTION OF DOORS, SEALS, AND LATCHES						Service ATA:52
	MOS	09-Jul-24	24 (+14d/-14d)					
	HRS	5131.8	600 (+25/-25)					
	AFL	4323						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								PKG:12
Y5210004	^S	UPPER AND LOWER PASSENGER/CREW DOOR - PERFORM VISUAL INSPECTION OF DOOR STRUCTURE, TENSION FITTINGS, AND HINGE AREA FOR CRACKS AND CORROSION.						Service ATA:52
	MOS	24-Feb-23	48 (+14d/-14d)					
	HRS	5067.1	1200 (+25/-25)					
	AFL	4262						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								PKG:18

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
Y5210005	^S	INTERNAL LOWER PASSENGER/CREW DOOR CABLES - PERFORM VISUAL INSPECTION. REMOVE STEP SKIN TO GAIN ACCESS TO CABLES.						Service ATA:52
	MOS	24-Feb-23	48 (+14d/-14d)					
	HRS	5067.1	1200 (+25/-25)					
	AFL	4262						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								PKG:18
Y5210006	^S	UPPER PASSENGER/CREW DOOR VENT DOOR SPRINGS - PERFORM VISUAL INSPECTION						Service ATA:52
	MOS	09-Jul-24	24 (+14d/-14d)					
	HRS	5131.8	600 (+25/-25)					
	AFL	4323						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								PKG:12
Y5210008	^S	EMERGENCY EXIT DOOR INTERNAL AND EXTERNAL HANDLE LATCHING MECHANISM. - PERFORM OPERATIONAL CHECK						Service ATA:52
	MOS	09-Jul-24	24 (+14d/-14d)					
	HRS	5131.8	600 (+25/-25)					
	AFL	4323						
PROC. REF: AMM 52-20-07PROC. REF: AMM 52-20-07								PKG:12
Y5240000	^S	OXYGEN SYSTEM SERVICING DOOR AND LATCHES - PERFORM VISUAL INSPECTION FOR CONDITION AND SECURITY. CHECK DECAL FOR CONDITION AND LEGIBILITY.						Service ATA:52
	MOS	24-Feb-23	48 (+14d/-14d)					
	HRS	5067.1	1200 (+25/-25)					
	AFL	4262						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								PKG:13
Y5240003	^S	SINGLE POINT REFUELING ACCESS DOOR - PERFORM VISUAL INSPECTION						Service ATA:52
	MOS	24-Feb-23	48 (+14d/-14d)					
	HRS	5067.1	1200 (+25/-25)					
	AFL	4262						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								PKG:14

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
Z5210053	CABIN MAIN ENTRY DOOR HANDLE - REPLACE							Service ATA:52
	MOS/MSC	05-Jul-21	N/A					
	HRS	4712.3						
	AFL	3963						
PROC. REF: AMM 52-10-08, AMM 52-10-13PROC. REF: AMM 52-10-08, AMM 52-10-13								
ATA 53 - FUSELAGE								
530001	FUSELAGE ASSEMBLY							Component ATA:53
PN:4553000010-001	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:L0252	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
531001	AFT PRESSURE BULKHEAD							Component ATA:53
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 53-10-01PROC. REF: AMM 53-10-01								
531040	LEFT TIE ROD END							Component ATA:53
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 53-10-04PROC. REF: AMM 53-10-04								
531041	RIGHT TIE ROD END							Component ATA:53
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 53-10-04PROC. REF: AMM 53-10-04								
531044	LEFT LOWER COUPE RAIL							Component ATA:53
PN:4556100007-011	MOS/MSC	19-Jun-12	N/A	TSN 0				NOT APPLICABLE
SN:UNKNOWN	HRS			TSN 0				
	AFL			TSN 0				
PROC. REF: AMM 53-10-04PROC. REF: AMM 53-10-04								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
531045	RIGHT LOWER COUPE RAIL							Component ATA:53
PN:4556100007-012	MOS/MSC	19-Jun-12	N/A	TSN 0				NOT APPLICABLE
SN:UNKNOWN	HRS			TSN 0				
	AFL			TSN 0				
PROC. REF: AMM 53-10-04PROC. REF: AMM 53-10-04								
535001	RADOME							Component ATA:53
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 53-50-01PROC. REF: AMM 53-50-01								
535601	LEFT DELTA FIN							Component ATA:53
PN:4555501000-015	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:S7549/A0041	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 53-56-01PROC. REF: AMM 53-56-01								
535602	RIGHT DELTA FIN							Component ATA:53
PN:4555501000-016	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:S7549/A0041	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 53-56-01PROC. REF: AMM 53-56-01								
545019	NO. 1 ENGINE AFT BEAM TO FRAME ATTACHMENT BOLT							Component ATA:53
PN:PN	MOS/MSC	07-Jul-04	H/T	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
A5310005 ^S	* FUSELAGE FUEL CELL CANTED BULKHEAD (F.S. 495) - PERFORM VISUAL INSPECTION, PAYING PARTICULAR ATTENTION TO MAIN CROSS MEMBER. INSPECT FLANGES AND ATTACHMENTS FOR CRACKING.							Service ATA:53
	MOS	18-Nov-21						AIRWORTHINESS
	HRS	4737	4800 (+25/-25)					
	AFL	3987						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45
Serial: 45-252
RegNo: N253SC
HRS: 5455.2
AFL: 4545
As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
A5310007	^S	* AFT PRESSURE BULKHEAD BOTTOM SHEAR DIAPHRAGM - PERFORM DETAILED VISUAL INSPECTION. INSPECT BULKHEAD POST ATTACHMENT FASTENER HOLES AND CONTROL CABLE SLOT.						Service ATA:53
	MOS	07-Jul-04						AIRWORTHINESS
	HRS	0	9600 (+25/-25)					
	AFL	0						
								PKG:26
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
A5323022	^S	* NOSE LANDING GEAR AFT WHEELBOX CLOSING STRUCTURE (F.S. 150 TO F.S.162) - PERFORM VISUAL INSPECTION. INSPECT THE FOLLOWING: A. PANEL. B. CHANNEL STIFFENERS. C. SUPPORT ANGLE. D. ANGLE STIFFENER. E. ZEE STIFFENER						Service ATA:53
	MOS	07-Jul-04						AIRWORTHINESS
	HRS	0	9600 (+25/-25)					
	AFL	0						
								PKG:26
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
A5323023	^S	* DRAG LINK ATTACHMENT LUG - PERFORM VISUAL INSPECTION						Service ATA:53
	MOS	18-Nov-21						AIRWORTHINESS
	HRS	4737	4800 (+25/-25)					
	AFL	3987						
								PKG:25
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								
A5360001	^S	DELTA FINS - WITH DELTA FINS REMOVED, VISUALLY INSPECT THE FOLLOWING: A. DELTA FIN AFT SPAR. B. DELTA FIN SUPPORT ANGLE. C. INSPECT STIFFENERS CONNECTING TO ATTACH FITTINGS.						Service ATA:53
	MOS	07-Jul-04						
	HRS	0	9600 (+25/-25)					
	AFL	0						
								PKG:26
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								
D5323039	^S	* MACHINED FUSELAGE FRAME AT FS 466 - PERFORM DETAILED VISUAL INSPECTION BETWEEN STRINGER 13 LEFT AND RIGHT, PAYING PARTICULAR ATTENTION TO THE BL 10 SPLICES. CONFIRM ANY CRACK INDICATIONS WITH EDDY CURRENT PROCEDURES.						Service ATA:53
	MOS	07-Jul-04						AIRWORTHINESS
	HRS	0	T:9600 (+25/-25)					
	AFL	0						
								PKG:25

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45
Serial: 45-252
RegNo: N253SC
HRS: 5455.2
AFL: 4545
As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								
E5310001	^S	* LONGERON, INTERNAL (BETWEEN FS 384 AND FS 433) - PERFORM VISUAL INSPECTION						Service ATA:53
	MOS	07-Jul-04						AIRWORTHINESS
	HRS	0	9600	(+25/-25)				
	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:26
E5310002	^S	* FLIGHT DECK LONGERON - PERFORM VISUAL INSPECTION (FS 149 - FS 196). INSPECT FLIGHT DECK LONGERON STIFFENERS, WEBS, AND CUTOUTS						Service ATA:53
	MOS	07-Jul-04						AIRWORTHINESS
	HRS	0	9600	(+25/-25)				
	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:26
E5310017	^S	* AFT PRESSURE BULKHEAD BOTTOM CROSSMEMBER (FS 457) - PERFORM DETAILED VISUAL INSPECTION. INSPECT TEE-SECTION AT FS 457 FLANGE AT ATTACHMENT OF PRESSURE FLOOR.						Service ATA:53
	MOS	07-Jul-04						AIRWORTHINESS
	HRS	0	9600	(+25/-25)				
	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:26
E5310018	^S	* AFT PRESSURE BULKHEAD PANEL FACING SHEETS (FS 457) - PERFORM VISUAL INSPECTION. INSPECT BOTH FRONT AND AFT OF FACING SHEETS.						Service ATA:53
	MOS	07-Jul-04						AIRWORTHINESS
	HRS	0	9600	(+25/-25)				
	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:26

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
E5323025	^S	* FORWARD/AFT WHEELBOX JOINT (FS 150) - PERFORM VISUAL INSPECTION. INSPECT SPLICE STRAP AFT OF FORWARD PRESSURE BULKHEAD AT INTERSECTION OF ATTACHMENT ANGLE AND FLIGHT DECK LONGERON.					Service	ATA:53
	MOS	07-Jul-04					AIRWORTHINESS	
	HRS	0	9600 (+25/-25)					
	AFL	0						
								PKG:26
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
E5323050	^S	* AFT POST/WINDSHIELD RETAINER ATTACHMENT - PERFORM EDDY CURRENT INSPECTION. INSPECT WINDSHIELD AFT POST AT WINDSHIELD RETAINER FASTENER HOLES.					Service	ATA:53
	MOS	18-Nov-21					AIRWORTHINESS	
	HRS	4737	4800 (+25/-25)					
	AFL	3987						
								PKG:25
PROC. REF: NDT PART 6/53-30-04PROC. REF: NDT PART 6/53-30-04								
E5323053	^S	* FRAME ATTACHMENTS TO UPPER AND LOWER COUPE RAILS (FS 171 TO FS 204) - PERFORM VISUAL INSPECTION. INSPECT THE FOLLOWING: A. FRAME ATTACHMENTS TO LOWER COUPE RAILS AT FS 171, FS 182, FS 196, AND FS 204. B. FRAME ATTACHMENTS TO UPPER COUPE RAILS AT FS 196 AND FS 204. C. GUSSETS AT FASTENER HOLES.					Service	ATA:53
	MOS	07-Jul-04					AIRWORTHINESS	
	HRS	0	9600 (+25/-25)					
	AFL	0						
								PKG:26
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
E5323054	^S	* TIE-ROD ASSEMBLY (FS 162) (ALUMINUM ENDS) - PERFORM VISUAL INSPECTION. INSPECT TIE-ROD ENDS, TIE-ROD TUBES, AND TIE-ROD BOLTS.					Service	ATA:53
	MOS	18-Nov-21					AIRWORTHINESS	
	HRS	4737	4800					
	AFL	3987						
								PKG:25
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								
E5323055	^S	* TIE-ROD ASSEMBLY (FS 162) (TITANIUM ENDS) - PERFORM VISUAL INSPECTION. INSPECT TIE-ROD ENDS, TIE-ROD TUBES, AND TIE-ROD BOLTS.					Service	ATA:53
	MOS	07-Jul-04					AIRWORTHINESS	
	HRS	0	9600					
	AFL	0						
								PKG:26

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45

Serial: 45-252

RegNo: N253SC

HRS: 5455.2

AFL: 4545

As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
E5323068	^S	* STRINGER 1RH BETWEEN F.S. 533 AND F.S. 543 - PERFORM VISUAL INSPECTION. INSPECT STRINGER 1 FLANGE AND SKIN ALONG STRINGER 1 BETWEEN F.S. 533 AND F.S. 543.						Service ATA:53
	MOS	07-Jul-04						AIRWORTHINESS
	HRS	0	9600 (+25/-25)					
	AFL	0						
								PKG:26
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
E5323073	^S	* FUSELAGE BOTTOM SKIN PANEL - PERFORM VISUAL INSPECTION. INSPECT CORNER RADIUS AT JUNCTION OF EXTERNAL LONGERON AND MID SPAR FRAME (F.S. 435).						Service ATA:53
	MOS	07-Jul-04						AIRWORTHINESS
	HRS	0	9600 (+25/-25)					
	AFL	0						
								PKG:26
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
E5323074	^S	* AUXILIARY SKIN PANEL - PERFORM VISUAL INSPECTION. INSPECT CORNER RADIUS AT JUNCTION OF KEEL BEAM AND REAR SPAR FRAME (F.S. 466).						Service ATA:53
	MOS	07-Jul-04						AIRWORTHINESS
	HRS	0	9600 (+25/-25)					
	AFL	0						
								PKG:26
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
E5350000	^S	* BOTTOM KEEL BEAM END PADS (F.S. 384 - F.S. 486) - PERFORM VISUAL INSPECTION. INSPECT END PADS AROUND BOLT HOLES AND IN RADII AT F.S. 433.						Service ATA:53
	MOS	07-Jul-04						AIRWORTHINESS
	HRS	0	9600 (+25/-25)					
	AFL	0						
								PKG:26
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information

S-Suppressed Requirement

*-Estimated Due(New Requirement)

(EFF)-Effective C/W

(M)-Manual Due

U-User Task

Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
F5323056	^S	* TIE-ROD FORK ENDS (ALUMINUM) - PERFORM FLUORESCENT PENETRANT INSPECTION						Service ATA:53
	MOS/MSC	07-Jul-04	N/A					NOT APPLICABLE
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 8/53-10-01PROC. REF: NDT PART 8/53-10-01								PKG:25
F5323081	^S	* TIE-ROD FORK ENDS - PERFORM FLUORESCENT PENETRANT INSPECTION						Service ATA:53
	MOS	07-Jul-04						AIRWORTHINESS
	HRS	0	9600					
	AFL	0						
PROC. REF: NDT PART 8/53-10-01PROC. REF: NDT PART 8/53-10-01								PKG:26
F5331021	^S	* FORWARD CANTED BULKHEAD (F.S. 630) - PERFORM VISUAL INSPECTION. INSPECT AT FRONT SPAR UPPER ATTACHMENT FASTENERS.						Service ATA:53
	MOS	18-Nov-21						AIRWORTHINESS
	HRS	4737	4800 (+25/-25)					
	AFL	3987						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								PKG:25
F5331022	^S	* MID CANTED BULKHEAD (F.S. 657) - PERFORM VISUAL INSPECTION AT MID SPAR UPPER ATTACHMENT FASTENERS						Service ATA:53
	MOS	07-Jul-04						AIRWORTHINESS
	HRS	0	9600 (+25/-25)					
	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:26
F5331023	^S	* AFT CANTED BULKHEAD (F.S. 682) - PERFORM VISUAL INSPECTION. INSPECT AT REAR SPAR ATTACHMENT FASTENERS.						Service ATA:53
	MOS	07-Jul-04						AIRWORTHINESS
	HRS	0	9600 (+25/-25)					
	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:26

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
F5331024 ^S	* VERTICAL STABILIZER FRONT SPAR ROOT BULKHEAD ATTACHMENT (F.S. 630) - PERFORM VISUAL INSPECTION. INSPECT FRONT SPAR ROOT BULKHEAD ATTACHMENT AT FASTENER HOLES.							Service ATA:53
	MOS	07-Jul-04						AIRWORTHINESS
	HRS	0	9600 (+25/-25)					
	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:26
F5331025 ^S	* VERTICAL STABILIZER MID SPAR ROOT BULKHEAD ATTACHMENT (F.S. 657) - PERFORM VISUAL INSPECTION. INSPECT MID SPAR ROOT BULKHEAD ATTACHMENT AT FASTENER HOLES.							Service ATA:53
	MOS	07-Jul-04						AIRWORTHINESS
	HRS	0	9600 (+25/-25)					
	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:26
F5331026 ^S	* VERTICAL STABILIZER REAR SPAR ROOT BULKHEAD ATTACHMENT (F.S. 682) - PERFORM VISUAL INSPECTION. INSPECT REAR SPAR ROOT BULKHEAD ATTACHMENT AT FASTENER HOLES.							Service ATA:53
	MOS	07-Jul-04						AIRWORTHINESS
	HRS	0	9600					
	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:26
H5323032	* EXTERIOR CABIN WINDOW COAMINGS (UNPAINTED) - PERFORM EDDY CURRENT INSPECTION							Service ATA:53
	MOS	09-Jul-24	24		31-Jul-26		8 d	AIRWORTHINESS
	HRS	5131	2400		7531		2075.8	
	AFL	4323						
PROC. REF: NDT PART 6/56-20-01PROC. REF: NDT PART 6/56-20-01								
L5311002 ^S	* NOSE LANDING GEAR ACTUATOR ATTACHMENT ON FORWARD PRESSURE BULKHEAD - PERFORM EDDY CURRENT INSPECTION. INSPECT ACTUATOR ATTACHMENT BRACKET LUGS, RADII, AND FASTENER HOLES.							Service ATA:53
	MOS	07-Jul-04						AIRWORTHINESS
	HRS	0						
	AFL	0	10000					
PROC. REF: NDT PART 6/32-12-00PROC. REF: NDT PART 6/32-12-00								PKG:27

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
L5311004 ^S	* NOSE LANDING GEAR TRUNNION FITTINGS - PERFORM VISUAL INSPECTION OF THE TRUNNION FITTINGS AND ATTACHMENT BOLTS							Service ATA:53
	MOS	07-Jul-04						AIRWORTHINESS
	HRS	0						
	AFL	0	10000					
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:27
L5311005 ^S	* NOSE LANDING GEAR TRUNNION FITTINGS AND SUPPORT STRUCTURE - PERFORM EDDY CURRENT INSPECTION OF THE TRUNNION SUPPORT STRUCTURE AT THE FORWARD PRESSURE BULKHEAD FLANGE							Service ATA:53
	MOS	07-Jul-04						AIRWORTHINESS
	HRS	0						
	AFL	0	10000					
PROC. REF: NDT PART 6/32-12-05PROC. REF: NDT PART 6/32-12-05								PKG:27
M5313001	FORWARD FUSELAGE SKIN - PERFORM PITOT-STATIC PROBE ZONE SKIN CONTOUR CHECK							Service ATA:53
	MOS	28-Apr-26	24 (+14d/-14d)	Adj -2d	30-Apr-28	10-May-28	647 d (+10)	
	HRS	5406.6						
	AFL	4513						
PROC. REF: AMM 53-00-01PROC. REF: AMM 53-00-01								
M5323021 ^S	* EXTERNAL LONGERON, FASTENER LOCATIONS, AND AREA AROUND WING ATTACHMENTS - PERFORM VISUAL INSPECTION. INSPECT LONGERON BETWEEN FS 398 AND FS 486, STRINGER 13 LEFT AND RIGHT							Service ATA:53
	MOS	07-Jul-04						AIRWORTHINESS
	HRS	0	9600 (+25/-25)					
	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:26
M5323034 ^S	* UPPER AND LOWER COUPE RAIL AND CENTER POST/WINDSHIELD RETAINER ATTACHMENT - PERFORM EDDY CURRENT INSPECTION							Service ATA:53
	MOS	07-Jul-04						AIRWORTHINESS
	HRS	0	9600 (+25/-25)					
	AFL	0						
PROC. REF: NDT PART 6/53-30-03PROC. REF: NDT PART 6/53-30-03								PKG:26

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
N5314000	^S	* EMERGENCY EXIT DOOR SKIN CUTOUT CORNERS AND DOUBLERS (F.S. 370 - F.S. 398) - PERFORM EDDY CURRENT INSPECTION						Service ATA:53
	MOS	01-Aug-21	96					AIRWORTHINESS
	HRS	4724.8	2400					
	AFL							
PROC. REF: NDT PART 6/53-30-01PROC. REF: NDT PART 6/53-30-01								PKG:19
N5323026	^S	* UPPER AND LOWER PASSENGER/CREW DOOR SKIN CUTOUT CORNERS (FS 224 - FS 256) - PERFORM EDDY CURRENT INSPECTION. INSPECT SKIN AT CORNERS OF PASSENGER/ CREW DOOR CUTOUT.						Service ATA:53
	MOS	01-Aug-21	96					AIRWORTHINESS
	HRS	4724.8	2400					
	AFL							
PROC. REF: NDT PART 6/53-30-02PROC. REF: NDT PART 6/53-30-02								PKG:19
P5310003	^S	* AFT PRESSURE BULKHEAD SUPPORT POST (FS 457) - PERFORM EDDY CURRENT INSPECTION						Service ATA:53
	MOS	07-Jul-04						AIRWORTHINESS
	HRS	0	9600 (+25/-25)					
	AFL	0						
PROC. REF: NDT PART 6/53-30-18PROC. REF: NDT PART 6/53-30-18								PKG:26
P5310004	^S	* AFT PRESSURE BULKHEAD FRAME PERIPHERY - PERFORM EDDY CURRENT INSPECTION						Service ATA:53
	MOS	18-Nov-21						AIRWORTHINESS
	HRS	4737	4800 (+25/-25)					
	AFL	3987						
PROC. REF: NDT PART 6/53-30-21PROC. REF: NDT PART 6/53-30-21								PKG:25
P5310006	^S	* FORWARD PRESSURE BULKHEAD - PERFORM EDDY CURRENT INSPECTION						Service ATA:53
	MOS	07-Jul-04						AIRWORTHINESS
	HRS	0	9600 (+25/-25)					
	AFL	0						
PROC. REF: NDT PART 6/53-30-07PROC. REF: NDT PART 6/53-30-07								PKG:26

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45
Serial: 45-252
RegNo: N253SC
HRS: 5455.2
AFL: 4545
As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
P5320001	^S	* FUSELAGE PRESSURE FLOOR STEP (FS 433 - FS 457) - PERFORM EDDY CURRENT INSPECTION						Service ATA:53
	MOS	07-Jul-04						AIRWORTHINESS
	HRS	0	9600 (+25/-25)					
	AFL	0						
PROC. REF: NDT PART 6/53-20-01PROC. REF: NDT PART 6/53-20-01								PKG:26
P5323024	^S	* FUSELAGE SKIN CUT-OUTS ABOVE FUEL CELL - PERFORM EDDY CURRENT INSPECTION						Service ATA:53
	MOS	18-Nov-21						AIRWORTHINESS
	HRS	4737	4800 (+25/-25)					
	AFL	3987						
PROC. REF: NDT PART 6/53-30-12PROC. REF: NDT PART 6/53-30-12								PKG:25
P5323027	^S	* FUSELAGE FRAME AT FS 412 - PERFORM EDDY CURRENT INSPECTION						Service ATA:53
	MOS	18-Nov-21						AIRWORTHINESS
	HRS	4737	4800 (+25/-25)					
	AFL	3987						
PROC. REF: NDT PART 6/53-30-20PROC. REF: NDT PART 6/53-30-20								PKG:25
P5323029	^S	* MACHINED SPAR FRAMES SYSTEMS CUTOUTS (FS 398, FS 412, FS 432, FS 466) - PERFORM EDDY CURRENT INSPECTION						Service ATA:53
	MOS	18-Nov-21						AIRWORTHINESS
	HRS	4737	4800 (+25/-25)					
	AFL	3987						
PROC. REF: NDT PART 6/53-30-15PROC. REF: NDT PART 6/53-30-15								PKG:25
P5323033	^S	* FUSELAGE SKIN AT EMERGENCY DOOR EGRESS-LIGHT AND WING INSPECTION LIGHT - PERFORM EDDY CURRENT INSPECTION						Service ATA:53
	MOS	07-Jul-04						AIRWORTHINESS
	HRS	0	9600 (+25/-25)					
	AFL	0						
PROC. REF: NDT PART 6/53-40-02PROC. REF: NDT PART 6/53-40-02								PKG:26

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
P5323037 ^S	* WINDSHIELD COUPE RAIL TIE ROD BRACKET - PERFORM EDDY CURRENT INSPECTION							Service ATA:53
	MOS	07-Jul-04						AIRWORTHINESS
	HRS	0	9600 (+25/-25)					
	AFL	0						
PROC. REF: NDT PART 6/53-30-09PROC. REF: NDT PART 6/53-30-09								PKG:26
P5323038 ^S	* WINDSHIELD CENTER POST TO UPPER COUPE RAIL JOINT ATTACHMENT - PERFORM EDDY CURRENT INSPECTION							Service ATA:53
	MOS	18-Nov-21						AIRWORTHINESS
	HRS	4737	4800					
	AFL	3987						
PROC. REF: NDT PART 6/53-30-22PROC. REF: NDT PART 6/53-30-22								PKG:25
P5323047 ^S	* PRESSURE CABIN FUSELAGE CROWN SKIN - PERFORM EDDY CURRENT INSPECTION							Service ATA:53
	MOS	01-Mar-19	96					AIRWORTHINESS
	HRS	4123.3	2400					
	AFL	3499						
PROC. REF: NDT PART 6/53-10-04PROC. REF: NDT PART 6/53-10-04								PKG:19
P5323049 ^S	* FUSELAGE SKIN AT UPPER AND LOWER COUPE RAIL RUN-OUT JOINTS - PERFORM EDDY CURRENT INSPECTION							Service ATA:53
	MOS	07-Jul-04						AIRWORTHINESS
	HRS	0	9600 (+25/-25)					
	AFL	0						
PROC. REF: NDT PART 6/53-30-11PROC. REF: NDT PART 6/53-30-11								PKG:26
P5323057 ^S	* PRESSURE CABIN SKIN AT FUSELAGE STATION 451 - PERFORM EDDY CURRENT INSPECTION							Service ATA:53
	MOS	01-Mar-19	96					AIRWORTHINESS
	HRS	4123.3	2400					
	AFL	3499						
PROC. REF: NDT PART 6/53-30-06PROC. REF: NDT PART 6/53-30-06								PKG:19

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
P5323058	^S	* FUSELAGE SKIN AT F.S. 504 - PERFORM EDDY CURRENT INSPECTION						Service ATA:53
	MOS	18-Nov-21						AIRWORTHINESS
	HRS	4737	4800 (+25/-25)					
	AFL	3987						
PROC. REF: NDT PART 6/53-30-13PROC. REF: NDT PART 6/53-30-13								PKG:25
P5323069	^S	* CIRCUMFERENTIAL SKIN JOINT AT FORWARD PRESSURE BULKHEAD - PERFORM EDDY CURRENT INSPECTION						Service ATA:53
	MOS	07-Jul-04						AIRWORTHINESS
	HRS	0	9600 (+25/-25)					
	AFL	0						
PROC. REF: NDT PART 6/53-30-08PROC. REF: NDT PART 6/53-30-08								PKG:26
P5323164	^S	* PERFORM FUSELAGE SKIN AND DOUBLER AROUND ECS DUCT CUTOUT - EDDY CURRENT INSPECTION.						Service ATA:53
	MOS	07-Jul-04						AIRWORTHINESS
	HRS	0	9600 (+25/-25)					
	AFL	0						
PROC. REF: NDT PART 6/53-40-01PROC. REF: NDT PART 6/53-40-01								PKG:26
P5323165	^S	* WINDSHIELD CENTER POST TO LOWER COUPE RAIL JOINT ATTACHMENT - PERFORM EDDY CURRENT INSPECTION						Service ATA:53
	MOS	07-Jul-04						AIRWORTHINESS
	HRS	0	9600 (+25/-25)					
	AFL	0						
PROC. REF: NDT PART 6/53-30-10PROC. REF: NDT PART 6/53-30-10								PKG:26
P5360006	^S	DELTA FIN ATTACH BOLT - PERFORM LIQUID PENETRANT INSPECTION						Service ATA:53
	MOS	07-Jul-04						
	HRS	0	9600 (+25/-25)					
	AFL	0						
PROC. REF: NDT PART 8/53-10-02PROC. REF: NDT PART 8/53-10-02								PKG:26

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
Q5310023	^S	FORWARD AND AFT FUEL CELL BAY STRUCTURE, ANGLE REINFORCEMENT, STRINGER 1, LEFT AND RIGHT - PERFORM DETAILED VISUAL INSPECTION OF HI-LITE COLLARS						Service ATA:53
	MOS	07-Jul-04						
	HRS	0	9600 (+25/-25)					
	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF							PKG:26	
Q5310025	^S	AFT FUSELAGE KEELBEAM LONGERON (LEFT AND RIGHT, BL 5.15, FS 466.30 - 495.12) AND AFT FUSELAGE KEELBEAM LOWER FRAME (FS 466.30, BL 9.55 LEFT THROUGH BL 9.55 RIGHT) - PERFORM DETAILED VISUAL INSPECTION OF HI-LITE COLLARS.						Service ATA:53
	MOS	07-Jul-04						
	HRS	0	9600 (+25/-25)					
	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF							PKG:26	
Q5323048	^S	* FUSELAGE (PRESSURE CABIN) - PERFORM EDDY CURRENT INSPECTION INSPECT PRESSURE CABIN SKIN (LONGITUDINAL SKIN CRACKING)						Service ATA:53
	MOS	18-Nov-21					AIRWORTHINESS	
	HRS	4737	4800 (+25/-25)					
	AFL	3987						
PROC. REF: NDT PART 6/53-30-05PROC. REF: NDT PART 6/53-30-05							PKG:25	
Q5323051	^S	* LONGITUDINAL JOINTS INSIDE PRESSURE CABIN (FS 220 - FS 457) AND SKIN WITHIN ONE STRINGER BAY OF JOINT - PERFORM EDDY CURRENT INSPECTION. INSPECT SKIN FASTENER HOLES ALONG JOINTS AT STRINGER 10 LEFT AND RH, STRINGER 2 RIGHT, AND STRINGER 18 RIGHT						Service ATA:53
	MOS	18-Nov-21					AIRWORTHINESS	
	HRS	4737	4800 (+25/-25)					
	AFL	3987						
PROC. REF: NDT PART 6/53-30-05PROC. REF: NDT PART 6/53-30-05							PKG:25	
Q5323059	^S	* STRINGER TO FRAME JOINTS (FS 162 TO FS 213) - PERFORM EDDY CURRENT INSPECTION. INSPECT SKIN, STRINGERS, AND FRAMES AT JOINTS.						Service ATA:53
	MOS	07-Jul-04					AIRWORTHINESS	
	HRS	0	9600					
	AFL	0						
							PKG:26	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
PROC. REF: NDT PART 6/53-30-05PROC. REF: NDT PART 6/53-30-05								
T5310027 ^S	* AFT PRESSURE BULKHEAD TOP MOUNTING STRUCTURE - PERFORM EDDY CURRENT INSPECTION.							Service ATA:53
	MOS	07-Jul-04						AIRWORTHINESS
	HRS	0	9600					
	AFL	0						
PROC. REF: NDT PART 6/53-30-17PROC. REF: NDT PART 6/53-30-17								
PKG:26								
T5321089 ^S	SEAT RAILS - PERFORM DETAILED INSPECTION OF SEAT RAIL (TRACK) SHEAR WEBS FOR CRACKING							Service ATA:53
	MOS	09-Jul-24	24 (+14d/-14d)					
	HRS	5131.8	600 (+25/-25)					
	AFL	4323						
PROC. REF: AMM 53-20-01PROC. REF: AMM 53-20-01								
PKG:7								
T5323028 ^S	* FUSELAGE TO WING ATTACH FITTINGS - PERFORM EDDY CURRENT INSPECTION							Service ATA:53
	MOS	18-Nov-21						AIRWORTHINESS
	HRS	4737	4800					
	AFL	3987						
PROC. REF: NDT PART 6/53-30-16PROC. REF: NDT PART 6/53-30-16								
PKG:25								
T5323166	* EXTERNAL SKIN CUT-OUTS/PENETRATIONS (PRESSURE CABIN) - PERFORM DETAILED VISUAL INSPECTION. INSPECT SKIN AND DOUBLERS AT ANTENNAS, ELECTRICAL COMPONENTS, AND ACCESS PANELS (EXCLUDING PITOT/STATIC PROBES, AOA STALL VANES, AND WING INSPECTION LIGHT).							Service ATA:53
	MOS	24-May-16	144		31-May-28		678 d	MANDATORY
	HRS	3549.6	9600		13149.6	13149.6	7694.4	
	AFL	2935						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								
V5323168	* LOWER COUPE RAIL RADIUS/WINDSCREEN RETAINER ATTACH - PERFORM EDDY CURRENT INSPECTION							Service ATA:53
	MOS/MSC	07-Jul-04	N/A					NOT APPLICABLE
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 6/53-30-23, NDT PART 6/53-30-24PROC. REF: NDT PART 6/53-30-23, NDT PART 6/53-30-24								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
Y5311001	^S	NOSE LANDING GEAR ACTUATOR ATTACH FITTING AND SURROUNDING STRUCTURE - PERFORM VISUAL INSPECTION						Service ATA:53
	MOS	24-Feb-23	48 (+14d/-14d)					
	HRS	5067.1	1200 (+25/-25)					
	AFL	4262						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								PKG:17
Y5311003	^S	NOSE LANDING GEAR TRUNNION FITTING AND SURROUNDING STRUCTURE - PERFORM VISUAL INSPECTION						Service ATA:53
	MOS	24-Feb-23	48 (+14d/-14d)					
	HRS	5067.1	1200 (+25/-25)					
	AFL	4262						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								PKG:17
Y5320000	^S	CENTER PEDESTAL - PERFORM VISUAL INSPECTION						Service ATA:53
	MOS	31-Jul-25	12 (+14d/-14d)					
	HRS	5307.6	300 (+25/-25)					
	AFL	4448						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								PKG:1
Y5321010	^S	FLOORBOARDS AROUND GALLEY, LAVATORY, AND WATER TANK - PERFORM VISUAL INSPECTION						Service ATA:53
	MOS	31-Jul-25	12 (+14d/-14d)					
	HRS	5307.6	300 (+25/-25)					
	AFL	4448						
PROC. REF: AMM 53-20-01PROC. REF: AMM 53-20-01								PKG:1
Y5321011	^S	TAILCONE BAGGAGE COMPARTMENT - PERFORM VISUAL INSPECTION						Service ATA:53
	MOS	09-Jul-24	24 (+14d/-14d)					
	HRS	5131.8	600 (+25/-25)					
	AFL	4323						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								PKG:8

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
Y5321088 ^S	SEAT RAILS - REMOVE FLOORBOARD 230AL AND PERFORM VISUAL INSPECTION OF SEAT RAILS.							Service ATA:53
	MOS	24-Feb-23	48 (+14d/-14d)					
	HRS	5067.1	1200 (+25/-25)					
	AFL	4262						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:13
Y5323020 ^S	EXTERNAL FUSELAGE (PRESSURE CABIN) - PERFORM VISUAL INSPECTION OF ALL CABIN SKINS FROM F.S. 100 TO F.S.458. PAY PARTICULAR ATTENTION TO ALL CUTOUTS AND SKIN JOINTS. NO FAIRING ACCESS REQUIRED.							Service ATA:53
	MOS	24-Feb-23	48 (+14d/-14d)					
	HRS	5067.1	1200 (+25/-25)					
	AFL	4262						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								PKG:13
Y5323031 ^S	EXTERIOR CABIN WINDOW COAMINGS AND SURROUNDING FUSELAGE SKIN - PERFORM VISUAL INSPECTION USING 10X MAGNIFICATION AND ADEQUATE LIGHTING.							Service ATA:53
	MOS	24-Feb-23	48 (+14d/-14d)					
	HRS	5067.1	1200 (+25/-25)					
	AFL	4262						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								PKG:13
Y5340007 ^S	WING ATTACH FITTINGS - PERFORM VISUAL INSPECTION							Service ATA:53
	MOS	01-Mar-19	96 (+14d/-14d)					
	HRS	4123.3	2400 (+25/-25)					
	AFL	3499						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								PKG:19
Y5360000 ^S	DELTA FINS - PERFORM VISUAL INSPECTION							Service ATA:53
	MOS	09-Jul-24	24 (+14d/-14d)					
	HRS	5131.8	600 (+25/-25)					
	AFL	4323						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								PKG:8

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
Z5323172	*SKIN CUT-OUT FOR Iridium ANTENNAS FS283.88 TO FS308.39 - PERFORM EDDY CURRENT INSPECTION							Service ATA:53
	MOS/MSC	07-Jul-04	N/A					AIRWORTHINESS
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 6/53-10-05PROC. REF: NDT PART 6/53-10-05								
ATA 54 - NACELLES/PYLONS								
545020	NO. 2 ENGINE AFT BEAM TO FRAME ATTACHMENT BOLT							Component ATA:54
PN:PN	MOS/MSC	07-Jul-04	H/T	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
545021	NO. 1 ENGINE AFT MOUNT TO END FITTING ATTACH BOLT							Component ATA:54
PN:PN	MOS/MSC	07-Jul-04	H/T	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
545022	NO. 2 ENGINE AFT MOUNT TO END FITTING ATTACH BOLT							Component ATA:54
PN:PN	MOS/MSC	07-Jul-04	H/T	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
545023	NO. 1 ENGINE TO AFT ENGINE MOUNT ATTACH BOLTS							Component ATA:54
PN:PN	MOS/MSC	07-Jul-04	H/T	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
545024	NO. 2 ENGINE TO AFT ENGINE MOUNT ATTACH BOLTS							Component ATA:54
PN:PN	MOS/MSC	07-Jul-04	H/T	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45
Serial: 45-252
RegNo: N253SC
HRS: 5455.2
AFL: 4545
As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 54 - NACELLES/PYLONS								
A5450022	* NO. 1 ENGINE AFT MOUNT TO END FITTING ATTACH BOLT - REPLACE OR PERFORM MAGNETIC PARTICLE INSPECTION							Service ATA:54
PN:PN	MOS	07-Jul-04						LIFE LIMIT
SN:UNKNOWN	HRS	0	9600		9600		4144.8	
	AFL	0						
A5450022	* NO. 2 ENGINE AFT MOUNT TO END FITTING ATTACH BOLT - REPLACE OR PERFORM MAGNETIC PARTICLE INSPECTION							Service ATA:54
PN:PN	MOS	07-Jul-04						LIFE LIMIT
SN:UNKNOWN	HRS	0	9600		9600		4144.8	
	AFL	0						
A5450026 ^S	* ENGINE DRAG STRUT - PERFORM EDDY CURRENT INSPECTION							Service ATA:54
	MOS	18-Nov-21						AIRWORTHINESS
	HRS	4737	4800 (+25/-25)					
	AFL	3987						
PROC. REF: NDT PART 6/54-50-01PROC. REF: NDT PART 6/54-50-01								
A5450028	NO. 1 ENGINE AFT ENGINE BEAM END FITTING - REPLACE							Service ATA:54
	MOS/MSC	07-Jul-04	N/A					N/A BY SERIAL NUMBER
	HRS	0						
	AFL	0						
PROC. REF: AMM 53-40-02PROC. REF: AMM 53-40-02								
AB5450054	LEFT FORWARD ENGINE BEAM AND BEAM FITTING - PERFORM VISUAL INSPECTION, PAYING PARTICULAR ATTENTION OF THE FOLLOWING: A. UPPER CAPPING PLATE AT FASTENER HOLES, AND CHANNEL FLANGE AT FASTENER HOLES. B. BOLT HOLES, ESPECIALLY UPPER BOLT HOLE ON AFT FLANGE.							Service ATA:54
	MOS	07-Jul-04						
	HRS	0	6000 (+100/-100)		6000	6100	544.8 (+100)	
	AFL	0						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 54 - NACELLES/PYLONS								
AB5450054	RIGHT FORWARD ENGINE BEAM AND BEAM FITTING - PERFORM VISUAL INSPECTION, PAYING PARTICULAR ATTENTION OF THE FOLLOWING: A. UPPER CAPPING PLATE AT FASTENER HOLES, AND CHANNEL FLANGE AT FASTENER HOLES. B. BOLT HOLES, ESPECIALLY UPPER BOLT HOLE ON AFT FLANGE.							Service ATA:54
	MOS	07-Jul-04						
	HRS	0	6000 (+100/-100)		6000	6100	544.8 (+100)	
	AFL	0						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								
E5450029 ^S	* AFT ENGINE BEAM - PERFORM VISUAL INSPECTION INSPECT UPPER CAPPING PLATE, AROUND FASTENER HOLES IN THE CAPPING PLATE, AND CHANNEL FLANGE.							Service ATA:54
	MOS	18-Nov-21						AIRWORTHINESS
	HRS	4737	4800 (+25/-25)					
	AFL	3987						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								
F5450019 ^S	* AFT ENGINE BEAM ATTACHMENT TO FRAMES - PERFORM VISUAL INSPECTION. INSPECT AFT ENGINE BEAM ATTACHMENT TO FRAMES.							Service ATA:54
	MOS	18-Nov-21						AIRWORTHINESS
	HRS	4737	4800 (+25/-25)					
	AFL	3987						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								
H5450012 ^S	* FRAMES 39/40 (F.S. 512/518) AT ENGINE BEAM ATTACHMENT - PERFORM EDDY CURRENT INSPECTION. INSPECT OUTER FLANGE AND FRAME WEB AT ENGINE BEAM ATTACHMENT.							Service ATA:54
	MOS	18-Nov-21						AIRWORTHINESS
	HRS	4737	4800 (+25/-25)					
	AFL	3987						
PROC. REF: NDT PART 6/54-50-03PROC. REF: NDT PART 6/54-50-03								
M5450015 ^S	* FORWARD ENGINE BEAM, SPAR CAP, AND WEB - PERFORM EDDY CURRENT INSPECTION							Service ATA:54
	MOS	18-Nov-21						AIRWORTHINESS
	HRS	4737	4800					
	AFL	3987						
PROC. REF: NDT PART 6/54-50-05PROC. REF: NDT PART 6/54-50-05								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 54 - NACELLES/PYLONS								
M5450018	^S	* FORWARD ENGINE MOUNT ATTACHMENT BOLTS - PERFORM FLUORESCENT LIQUID PENETRANT INSPECTION						Service ATA:54
	MOS	18-Nov-21						AIRWORTHINESS
	HRS	4737	4800					
	AFL	3987						
PROC. REF: NDT PART 8/71-20-01PROC. REF: NDT PART 8/71-20-01								PKG:25
M5450027		NO. 1 ENGINE FORWARD ENGINE BEAM END FITTING - REPLACE						Service ATA:54
	MOS/MSC		N/A					
	HRS							
	AFL							
PROC. REF: AMM 53-40-02, AMM 53-40-02PROC. REF: AMM 53-40-02, AMM 53-40-02								
P5450011	^S	* DRAG STRUT ATTACHMENT FITTINGS - PERFORM EDDY CURRENT INSPECTION						Service ATA:54
	MOS	18-Nov-21						AIRWORTHINESS
	HRS	4737	4800 (+25/-25)					
	AFL	3987						
PROC. REF: NDT PART 6/53-10-03PROC. REF: NDT PART 6/53-10-03								PKG:25
P5450016	^S	* FORWARD ENGINE BEAM END FITTING - PERFORM EDDY CURRENT INSPECTION						Service ATA:54
	MOS	18-Nov-21						AIRWORTHINESS
	HRS	4737	4800					
	AFL	3987						
PROC. REF: NDT PART 6/54-50-02PROC. REF: NDT PART 6/54-50-02								PKG:25
P5450017	^S	* FORWARD ENGINE BEAM TO FRAME ATTACH BOLT - PERFORM LIQUID PENETRANT INSPECTION						Service ATA:54
	MOS	18-Nov-21						AIRWORTHINESS
	HRS	4737	4800 (+25/-25)					
	AFL	3987						
PROC. REF: NDT PART 8/53-40-01PROC. REF: NDT PART 8/53-40-01								PKG:25

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 54 - NACELLES/PYLONS								
P5450020	* NO. 1 ENGINE AFT BEAM TO FRAME ATTACHMENT BOLT - REPLACE OR PERFORM LIQUID PENETRANT INSPECTION							Service ATA:54
PN:PN	MOS	07-Jul-04						LIFE LIMIT
SN:UNKNOWN	HRS	0	9600		9600		4144.8	
	AFL	0						
P5450020	* NO. 2 ENGINE AFT BEAM TO FRAME ATTACHMENT BOLT - REPLACE OR PERFORM LIQUID PENETRANT INSPECTION							Service ATA:54
PN:PN	MOS	07-Jul-04						LIFE LIMIT
SN:UNKNOWN	HRS	0	9600		9600		4144.8	
	AFL	0						
P5450021 ^S	* ENGINE AFT ISOLATOR MOUNT FITTINGS - PERFORM LIQUID PENETRANT INSPECTION							Service ATA:54
	MOS	18-Nov-21						AIRWORTHINESS
	HRS	4737	4800 (+25/-25)					
	AFL	3987						
PROC. REF: NDT PART 8/71-20-03PROC. REF: NDT PART 8/71-20-03								PKG:25
P5450023	* NO. 1 ENGINE TO AFT ENGINE MOUNT ATTACH BOLTS - REPLACE OR PERFORM LIQUID PENETRANT INSPECTION							Service ATA:54
PN:PN	MOS	07-Jul-04						LIFE LIMIT
SN:UNKNOWN	HRS	0	9600		9600		4144.8	
	AFL	0						
P5450023	* NO. 2 ENGINE TO AFT ENGINE MOUNT ATTACH BOLTS - REPLACE OR PERFORM LIQUID PENETRANT INSPECTION							Service ATA:54
PN:PN	MOS	07-Jul-04						LIFE LIMIT
SN:UNKNOWN	HRS	0	9600		9600		4144.8	
	AFL	0						
P5450024 ^S	* FUSELAGE FRAMES AT FS 543.55 AND 546.15 TO AFT ENGINE BEAM ATTACHMENT - PERFORM EDDY CURRENT INSPECTION.							Service ATA:54
	MOS	18-Nov-21						AIRWORTHINESS
	HRS	4737	4800 (+25/-25)					
	AFL	3987						
PROC. REF: NDT PART 6/53-30-14PROC. REF: NDT PART 6/53-30-14								PKG:25

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 54 - NACELLES/PYLONS								
P5450025	^S	* FORWARD ENGINE BEAM AND FRAMES AT ATTACH HOLES - PERFORM EDDY CURRENT INSPECTION						Service ATA:54
	MOS	18-Nov-21						AIRWORTHINESS
	HRS	4737	4800 (+25/-25)					
	AFL	3987						
PROC. REF: NDT PART 6/54-50-03PROC. REF: NDT PART 6/54-50-03								PKG:25
P5450030	^S	* AFT ENGINE BEAM END FITTING - PERFORM EDDY CURRENT INSPECTION						Service ATA:54
	MOS	18-Nov-21						AIRWORTHINESS
	HRS	4737	4800 (+25/-25)					
	AFL	3987						
PROC. REF: NDT PART 6/54-50-04PROC. REF: NDT PART 6/54-50-04								PKG:25
Y5410002	^S	PYLONS - PERFORM VISUAL INSPECTION. INSPECT HILITE COLLARS COMMON TO MAIN ENGINE BEAM EXTERNAL TO FUSELAGE.						Service ATA:54
	MOS	24-Feb-23	48 (+14d/-14d)					
	HRS	5067.1	1200 (+25/-25)					
	AFL	4262						
PROC. REF: AMM 54-00-01PROC. REF: AMM 54-00-01								PKG:14
ATA 55 - STABILIZERS								
551005	HORIZONTAL STABILIZER ASSEMBLY							Component ATA:55
PN:4555101002-027	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:A0028	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-40-01PROC. REF: AMM 27-40-01								
552031	LEFT ELEVATOR ASSEMBLY							Component ATA:55
PN:4555201001V46-001	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:0031	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-30-01PROC. REF: AMM 27-30-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45
Serial: 45-252
RegNo: N253SC
HRS: 5455.2
AFL: 4545
As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
552032	RIGHT ELEVATOR ASSEMBLY							Component ATA:55
PN:4555201001V46-002	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:A0030	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-30-01PROC. REF: AMM 27-30-01								
553000	TAILCONE/VERTICAL STABILIZER ASSEMBLY							Component ATA:55
PN:4555301001-001	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:A0027	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
554005	RUDDER ASSEMBLY							Component ATA:55
PN:4555400001V38-001	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:A0033	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-20-01PROC. REF: AMM 27-20-01								
A5510014 ^S	* VERTICAL STABILIZER PIVOT FITTING BOTTOM PLATE - PERFORM DETAILED VISUAL INSPECTION. INSPECT AFT PORTION OF BOTTOM PLATE THROUGH LIGHTENING HOLE IN TOP PLATE, FORWARD PORTION OF BOTTOM PLATE THROUGH TOP PLATE CUTOUTS, AND BOTTOM OF OUTSIDE EXPOSED SURFACE OF PIVOT FITTING							Service ATA:55
	MOS	07-Jul-04						AIRWORTHINESS
	HRS	0	9600 (+25/-25)					
	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:26
A5510021 ^S	* HORIZONTAL MID SPAR FROM CANTED RIB NUMBER 2 TO CANTED RIB NUMBER 3 - PERFORM DETAILED VISUAL INSPECTION							Service ATA:55
	MOS	07-Jul-04						AIRWORTHINESS
	HRS	0	9600 (+25/-25)					
	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:26

?-Insufficient Information
S-Suppressed Requirement
*-Estimated Due(New Requirement)
(EFF)-Effective C/W
(M)-Manual Due
U-User Task
Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
A5540000 ^S	* RUDDER RIB CAP (F.S. 698) - PERFORM VISUAL INSPECTION. INSPECT AROUND FASTENER HOLES AND LIGHTENING HOLES.							Service ATA:55
	MOS	07-Jul-04						AIRWORTHINESS
	HRS	0	9600 (+25/-25)					
	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:26
AA5510034	HORIZONTAL STABILIZER PRIMARY AND SECONDARY BOLTS AND BUSHINGS - PERFORM DETAILED INSPECTION							Service ATA:55
	MOS	29-Nov-18						
	HRS	4080.4	4800 (+25/-25)		8880.4	8905.4	3425.2 (+25)	
	AFL	3461						
PROC. REF: AMM 05-10-00, AMM 55-10-00PROC. REF: AMM 05-10-00, AMM 55-10-00								
E5510074 ^S	* HORIZONTAL STABILIZER REAR SPAR FROM CANTED RIB NUMBER 2 TO CANTED RIB NUMBER 3 - PERFORM VISUAL INSPECTION. INSPECT REAR SPAR CAP AND FASTENERS.							Service ATA:55
	MOS	07-Jul-04						AIRWORTHINESS
	HRS	0	9600 (+25/-25)					
	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:26
E5510075 ^S	* HORIZONTAL STABILIZER OUTBOARD SPARS AND SKINS OUTBOARD OF CANTED RIB NUMBER 3 - PERFORM VISUAL INSPECTION. INSPECT SPAR CAPS AND FASTENERS							Service ATA:55
	MOS	07-Jul-04						AIRWORTHINESS
	HRS	0	9600					
	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:26
E5510076 ^S	* HORIZONTAL STABILIZER FRONT SPAR FROM CANTED RIB NO. 2 TO CANTED RIB NO. 3 - PERFORM VISUAL INSPECTION. INSPECT FRONT SPAR CAP AND FASTENERS.							Service ATA:55
	MOS	07-Jul-04						AIRWORTHINESS
	HRS	0	9600 (+25/-25)					
	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:26

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
E5520003	^S	* ELEVATOR FRONT SPAR - PERFORM VISUAL INSPECTION. INSPECT SPAR CAP AT FASTENER HOLES						Service ATA:55
	MOS	07-Jul-04						AIRWORTHINESS
	HRS	0	9600 (+25/-25)					
	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:26
E5520004	^S	* ELEVATOR RIB NO. 1 CAP - PERFORM VISUAL INSPECTION OF RIB NO. 1 CAP CROSS SECTION AND RIB CAP FLANGES AT TORQUE TUBE						Service ATA:55
	MOS	07-Jul-04						AIRWORTHINESS
	HRS	0	9600 (+25/-25)					
	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:26
G5510000	^S	* HORIZONTAL STABILIZER ACTUATOR ATTACHMENT FITTING - PERFORM EDDY CURRENT INSPECTION						Service ATA:55
	MOS	18-Nov-21						AIRWORTHINESS
	HRS	4737	4800 (+25/-25)					
	AFL	3987						
PROC. REF: NDT PART 6/55-10-01PROC. REF: NDT PART 6/55-10-01								PKG:25
G5510023	^S	* HORIZONTAL STABILIZER ACTUATOR VERTICAL TAIL ATTACHMENT - PERFORM EDDY CURRENT INSPECTION						Service ATA:55
	MOS	18-Nov-21						AIRWORTHINESS
	HRS	4737	4800 (+25/-25)					
	AFL	3987						
PROC. REF: NDT PART 6/55-30-01PROC. REF: NDT PART 6/55-30-01								PKG:25
H5510033	^S	* HORIZONTAL STABILIZER ACTUATOR ATTACHMENT BOLTS - PERFORM LIQUID PENETRANT INSPECTION						Service ATA:55
	MOS	18-Nov-21						AIRWORTHINESS
	HRS	4737	4800 (+25/-25)					
	AFL	3987						
PROC. REF: NDT PART 8/27-40-01PROC. REF: NDT PART 8/27-40-01								PKG:25

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
L5540005 ^S	* RUDDER TRIM TAB - PERFORM EDDY CURRENT INSPECTION							Service ATA:55
	MOS	07-Jul-04						BRAZILIAN REQUIREMENT
	HRS	0	4800 (+25/-25)					
	AFL	0						
PROC. REF: NDT PART 6/55-30-08PROC. REF: NDT PART 6/55-30-08								PKG:25
M5510010	* HORIZONTAL STABILIZER AFT ROOT RIB - PERFORM EDDY CURRENT INSPECTION. INSPECT AFT ROOT RIB INTERNAL BETWEEN MID SPAR AND AFT SPAR AND UPPER AND LOWER SKINS EXTERNAL AT ATTACHMENT FASTENERS.							Service ATA:55
	MOS	01-Aug-21						AIRWORTHINESS
	HRS	4724.8	1200		5924.8		469.6	
	AFL							
PROC. REF: NDT PART 6/55-10-03PROC. REF: NDT PART 6/55-10-03								
M5540022	RUDDER TORQUE TUBE - PERFORM BORESCOPE INSPECTION							Service ATA:55
	MOS/MSC		N/A					
	HRS							
	AFL							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								
N5510005 ^S	* HORIZONTAL STABILIZER REAR SPAR CAP - PERFORM EDDY CURRENT INSPECTION. INSPECT REAR SPAR CAP AND WEB AT CENTER SPLICE							Service ATA:55
	MOS	01-Aug-21	96					AIRWORTHINESS
	HRS	4724.8	2400					
	AFL							
PROC. REF: NDT PART 6/55-10-05PROC. REF: NDT PART 6/55-10-05								PKG:20
N5510015 ^S	* VERTICAL STABILIZER PIVOT FITTING TOP PLATE - PERFORM EDDY CURRENT INSPECTION							Service ATA:55
	MOS	01-Aug-21	96 (+14d/-14d)					AIRWORTHINESS
	HRS	4724.8	2400 (+25/-25)					
	AFL							
PROC. REF: NDT PART 6/55-30-02PROC. REF: NDT PART 6/55-30-02								PKG:20

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
N5510016 ^S	* VERTICAL STABILIZER PIVOT FITTING TOWER SECTION FORWARD RADIUS - PERFORM EDDY CURRENT INSPECTION. INSPECT PIVOT FITTING AT TOWER SECTION RADIUS, PIVOT FITTING AND TOP PLATE AROUND ADJACENT FASTENERS, AND PIVOT FITTING SIDES AT TOWER SECTION RADIUS.							Service ATA:55
	MOS	01-Aug-21	96 (+14d/-14d)					AIRWORTHINESS
	HRS	4724.8	2400 (+25/-25)					
	AFL							
								PKG:20
PROC. REF: NDT PART 6/55-30-03PROC. REF: NDT PART 6/55-30-03								
N5510069 ^S	* HORIZONTAL STABILIZER MID SPAR FLANGE ROOT RIB ATTACHMENT - PERFORM EDDY CURRENT INSPECTION							Service ATA:55
	MOS	01-Aug-21	96					AIRWORTHINESS
	HRS	4724.8	2400					
	AFL							
								PKG:20
PROC. REF: NDT PART 6/55-10-02PROC. REF: NDT PART 6/55-10-02								
N5510082 ^S	* HORIZONTAL STABILIZER REAR SPAR FLANGE ROOT RIB ATTACHMENT - PERFORM EDDY CURRENT INSPECTION							Service ATA:55
	MOS	01-Aug-21	96					AIRWORTHINESS
	HRS	4724.8	2400					
	AFL							
								PKG:20
PROC. REF: NDT PART 6/55-10-04PROC. REF: NDT PART 6/55-10-04								
P5510006 ^S	* VERTICAL STABILIZER FRONT SPAR AND MID SPAR - PERFORM RADIOGRAPHIC INSPECTION							Service ATA:55
	MOS	07-Jul-04						AIRWORTHINESS
	HRS	0	9600 (+25/-25)					
	AFL	0						
								PKG:26
PROC. REF: NDT PART 2/55-30-01PROC. REF: NDT PART 2/55-30-01								
P5510008 ^S	* HORIZONTAL STABILIZER PRIMARY AND SECONDARY ATTACH BOLTS - PERFORM MAGNETIC PARTICLE INSPECTION							Service ATA:55
	MOS	07-Jul-04						AIRWORTHINESS
	HRS	0	9600 (+25/-25)					
	AFL	0						
								PKG:26
PROC. REF: NDT PART 7/55-30-02, NDT PART 7/55-30-03PROC. REF: NDT PART 7/55-30-02, NDT PART 7/55-30-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
P5510009	^S	* HORIZONTAL STABILIZER MID SPAR UPPER CAP BL 0.0 TO BL 4.0 - PERFORM X-RAY INSPECTION						Service ATA:55
	MOS	01-Mar-19	96 (+14d/-14d)					AIRWORTHINESS
	HRS	4123.3	2400 (+25/-25)					
	AFL	3499						
PROC. REF: NDT PART 2/55-10-03PROC. REF: NDT PART 2/55-10-03								PKG:20
P5510011	^S	* HORIZONTAL STABILIZER MID SPAR AND REAR SPAR UPPER FLANGE AT ROOT RIB - PERFORM RADIOGRAPHIC INSPECTION						Service ATA:55
	MOS	07-Jul-04						AIRWORTHINESS
	HRS	0	9600 (+25/-25)					
	AFL	0						
PROC. REF: NDT PART 2/55-10-01PROC. REF: NDT PART 2/55-10-01								PKG:26
P5510017	^S	* VERTICAL STABILIZER PIVOT FITTING TOWER SECTION - PERFORM EDDY CURRENT INSPECTION						Service ATA:55
	MOS	01-Mar-19	96 (+14d/-14d)					AIRWORTHINESS
	HRS	4123.3	2400 (+25/-25)					
	AFL	3499						
PROC. REF: NDT PART 6/55-30-05PROC. REF: NDT PART 6/55-30-05								PKG:20
P5510018	^S	* VERTICAL STABILIZER PIVOT FITTING LUGS - PERFORM EDDY CURRENT INSPECTION						Service ATA:55
	MOS	07-Jul-04						AIRWORTHINESS
	HRS	0	9600 (+25/-25)					
	AFL	0						
PROC. REF: NDT PART 6/55-30-04PROC. REF: NDT PART 6/55-30-04								PKG:26
P5510019	^S	* ELEVATOR HINGES ON HORIZONTAL STABILIZER - PERFORM EDDY CURRENT INSPECTION						Service ATA:55
	MOS	07-Jul-04						AIRWORTHINESS
	HRS	0	9600 (+25/-25)					
	AFL	0						
PROC. REF: NDT PART 6/55-20-02PROC. REF: NDT PART 6/55-20-02								PKG:26

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45
Serial: 45-252
RegNo: N253SC
HRS: 5455.2
AFL: 4545
As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
P5510020	^S	* HORIZONTAL MID SPAR UPPER CAP - PERFORM EDDY CURRENT INSPECTION						Service ATA:55
	MOS	07-Jul-04						AIRWORTHINESS
	HRS	0	9600 (+25/-25)					
	AFL	0						
PROC. REF: NDT PART 6/55-10-07PROC. REF: NDT PART 6/55-10-07								PKG:26
P5510024	^S	* ELEVATOR CONTROL HORN - PERFORM EDDY CURRENT INSPECTION						Service ATA:55
	MOS	07-Jul-04						AIRWORTHINESS
	HRS	0	9600 (+25/-25)					
	AFL	0						
PROC. REF: NDT PART 6/55-20-01PROC. REF: NDT PART 6/55-20-01								PKG:26
P5510070	^S	* HORIZONTAL STABILIZER FRONT SPAR - PERFORM RADIOGRAPHIC INSPECTION						Service ATA:55
	MOS	07-Jul-04						AIRWORTHINESS
	HRS	0	9600 (+25/-25)					
	AFL	0						
PROC. REF: NDT PART 2/55-10-02PROC. REF: NDT PART 2/55-10-02								PKG:26
P5510073	^S	* HORIZONTAL REAR SPAR UPPER CAP - PERFORM EDDY CURRENT INSPECTION						Service ATA:55
	MOS	07-Jul-04						AIRWORTHINESS
	HRS	0	9600 (+25/-25)					
	AFL	0						
PROC. REF: NDT PART 6/55-10-07PROC. REF: NDT PART 6/55-10-07								PKG:26
P5510092	^S	* HORIZONTAL STABILIZER UPPER SPAR SPLICE DOUBLER - PERFORM EDDY CURRENT INSPECTION						Service ATA:55
	MOS	01-Mar-19	96 (+14d/-14d)					AIRWORTHINESS
	HRS	4123.3	2400 (+25/-25)					
	AFL	3499						
PROC. REF: NDT PART 6/55-10-06PROC. REF: NDT PART 6/55-10-06								PKG:20

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
P5520001	^S	* ELEVATOR HINGE ATTACH BOLT - PERFORM MAGNETIC PARTICLE INSPECTION						Service ATA:55
	MOS	07-Jul-04						AIRWORTHINESS
	HRS	0	9600 (+25/-25)					
	AFL	0						
PROC. REF: NDT PART 7/27-30-01PROC. REF: NDT PART 7/27-30-01								PKG:26
P5520002	^S	* ELEVATOR HINGE PIN - PERFORM LIQUID PENETRANT INSPECTION						Service ATA:55
	MOS	07-Jul-04						AIRWORTHINESS
	HRS	0	9600 (+25/-25)					
	AFL	0						
PROC. REF: NDT PART 8/55-30-01PROC. REF: NDT PART 8/55-30-01								PKG:26
P5520021	^S	* ELEVATOR HINGE FITTINGS - PERFORM EDDY CURRENT INSPECTION						Service ATA:55
	MOS	07-Jul-04						AIRWORTHINESS
	HRS	0	9600 (+25/-25)					
	AFL	0						
PROC. REF: NDT PART 6/55-30-07PROC. REF: NDT PART 6/55-30-07								PKG:26
P5520022	^S	* ELEVATOR HINGE PRIMARY AND SECONDARY ATTACH BOLTS - PERFORM LIQUID PENETRANT INSPECTION						Service ATA:55
	MOS	07-Jul-04						AIRWORTHINESS
	HRS	0	9600 (+25/-25)					
	AFL	0						
PROC. REF: NDT PART 8/27-30-01, NDT PART 8/27-30-02PROC. REF: NDT PART 8/27-30-01, NDT PART 8/27-30-02								PKG:26
P5540001	^S	* RUDDER SPAR - PERFORM DETAILED VISUAL INSPECTION. INSPECT SPAR CAPS AND FASTENERS						Service ATA:55
	MOS	07-Jul-04						AIRWORTHINESS
	HRS	0	9600 (+25/-25)					
	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:26

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
P5540002	^S	* RUDDER ATTACH BOLT - PERFORM LIQUID PENETRANT INSPECTION						Service ATA:55
	MOS	07-Jul-04						AIRWORTHINESS
	HRS	0	9600					
	AFL	0						
PROC. REF: NDT PART 8/55-30-02PROC. REF: NDT PART 8/55-30-02								PKG:26
Q5510007	^S	* VERTICAL STABILIZER SKIN AND LOWER AFT SPAR CAP - PERFORM EDDY CURRENT INSPECTION						Service ATA:55
	MOS	07-Jul-04						AIRWORTHINESS
	HRS	0	9600 (+25/-25)					
	AFL	0						
PROC. REF: NDT PART 6/55-30-06PROC. REF: NDT PART 6/55-30-06								PKG:26
Q5530011	^S	* VERTICAL STABILIZER SKIN AND UPPER AFT SPAR CAP - PERFORM EDDY CURRENT INSPECTION						Service ATA:55
	MOS	01-Mar-19	96					AIRWORTHINESS
	HRS	4123.3	2400					
	AFL	3499						
PROC. REF: NDT PART 6/55-30-06PROC. REF: NDT PART 6/55-30-06								PKG:20
T5510004	^S	* RUDDER HINGE FITTINGS - PERFORM VISUAL INSPECTION. CONTROL SURFACE REMOVAL NOT REQUIRED.						Service ATA:55
	MOS	07-Jul-04						AIRWORTHINESS
	HRS	0	9600					
	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:26
W5510091		* HORIZONTAL STABILIZER HINGE PRIMARY AND SECONDARY PIVOT PIN INSTALLATION AND ATTACHING HARDWARE - PERFORM DETAILED VISUAL INSPECTION						Service ATA:55
	MOS	18-Nov-21						MANDATORY
	HRS	4737	625		5362		OVD	
	AFL	3987						
PROC. REF: AMM 05-10-00, AMM 55-10-00PROC. REF: AMM 05-10-00, AMM 55-10-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45
Serial: 45-252
RegNo: N253SC
HRS: 5455.2
AFL: 4545
As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
Y5510001	^S	HORIZONTAL STABILIZER - PERFORM EXTERNAL VISUAL INSPECTION						Service ATA:55
	MOS	24-Feb-23	48 (+14d/-14d)					
	HRS	5067.1	1200 (+25/-25)					
	AFL	4262						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								PKG:14
Y5510002	^S	ELEVATOR HINGES ON HORIZONTAL STABILIZER - PERFORM VISUAL INSPECTION. INSPECT HINGE LUGS ON HORIZONTAL TAIL SIDE OF JOINT. INSPECT HILITE COLLARS AT BL 0.0 AND OUTBOARD ELEVATOR HINGE.						Service ATA:55
	MOS	24-Feb-23	48 (+14d/-14d)					
	HRS	5067.1	1200 (+25/-25)					
	AFL	4262						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:14
Y5510003	^S	VERTICAL STABILIZER PIVOT FITTING - PERFORM VISUAL INSPECTION. INSPECT HI-LITE COLLARS COMMON TO THE PIVOT FITTING (MID SPAR, AFT SPAR, TOP PLATE, AND UP/DOWN SPRING BRACKET).						Service ATA:55
	MOS	24-Feb-23	48 (+14d/-14d)					
	HRS	5067.1	1200 (+25/-25)					
	AFL	4262						
PROC. REF: AMM 55-00-01PROC. REF: AMM 55-00-01								PKG:14
Y5510093	^S	HORIZONTAL STABILIZER - PERFORM VISUAL INSPECTION OF HI-LITE COLLARS IN THE FOLLOWING AREAS: - FORWARD SPAR TO BL 0.0 RIB - CENTER SPAR TO BL 0.0 RIB - CENTER SPAR SPLICE PLATE - AFT SPAR SPLICE PLATE - ROOT RIBS AT BL 3.70 (RIGHT AND LEFT) - UPPER DOUBLER SPAR SPLICE, BL 0.0 - HSTA UPPER ATTACH FITTING STRUCTURE						Service ATA:55
	MOS	24-Feb-23	48 (+14d/-14d)					
	HRS	5067.1	1200 (+25/-25)					
	AFL	4262						
PROC. REF: AMM 55-00-01PROC. REF: AMM 55-00-01								PKG:14
Y5510094	^S	LOWER BRACKET, HORIZONTAL STABILIZER TRIM ACTUATOR - PERFORM BORESCOPE INSPECTION OF HI-LITE COLLARS COMMON TO RIB NO. 6 AND MID SPAR.						Service ATA:55
	MOS	24-Feb-23	48 (+14d/-14d)					
	HRS	5067.1	1200 (+25/-25)					
	AFL	4262						
PROC. REF: AMM 55-10-00PROC. REF: AMM 55-10-00								PKG:14

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
Y5540012 ^S	RUDDER TORQUE TUBE - LOOSEN TORQUE TUBE BONDING CLAMP AND PERFORM DETAILED VISUAL INSPECTION OF AREA AROUND BONDING CLAMP FOR CORROSION.							Service ATA:55
	MOS	31-Jul-25	12 (+14d/-14d)					
	HRS	5307.6	300 (+25/-25)					
	AFL	4448						
PROC. REF: AMM 27-20-01PROC. REF: AMM 27-20-01								PKG:2
ATA 56 - WINDOWS								
561001	LEFT WINDSHIELD							Component ATA:56
PN:6656100001-003	MOS/MSC	22-Aug-17	O/C	TSN 1				
SN:2945	HRS	3796.4		TSN 0				
	AFL	3164		TSN 0				
PROC. REF: AMM 56-10-01, AMM 56-10-01PROC. REF: AMM 56-10-01, AMM 56-10-01								
561002	RIGHT WINDSHIELD							Component ATA:56
PN:6656100001-004	MOS/MSC	22-Aug-17	O/C	TSN 1				
SN:2958	HRS	3796.4		TSN 0				
	AFL	3164		TSN 0				
PROC. REF: AMM 56-10-01, AMM 56-10-01PROC. REF: AMM 56-10-01, AMM 56-10-01								
562010-1	LEFT NO.1 CABIN WINDOW							Component ATA:56
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01								
562010-10	RIGHT NO.5 CABIN WINDOW							Component ATA:56
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 56 - WINDOWS								
562010-11	LEFT NO.6 CABIN WINDOW							Component ATA:56
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01								
562010-12	RIGHT NO.6 CABIN WINDOW							Component ATA:56
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01								
562010-13	LEFT NO.7 CABIN WINDOW							Component ATA:56
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01								
562010-14	RIGHT NO.7 CABIN WINDOW							Component ATA:56
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01								
562010-15	LEFT NO.8 CABIN WINDOW							Component ATA:56
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01								
562010-16	EMERGENCY EXIT WINDOW							Component ATA:56
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-20-06PROC. REF: AMM 52-20-06								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 56 - WINDOWS								
562010-2	RIGHT NO.1 CABIN WINDOW							Component ATA:56
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01								
562010-3	LEFT NO.2 CABIN WINDOW							Component ATA:56
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01								
562010-4	RIGHT NO.2 CABIN WINDOW							Component ATA:56
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01								
562010-5	LEFT NO.3 CABIN WINDOW							Component ATA:56
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01								
562010-6	RIGHT NO.3 CABIN WINDOW							Component ATA:56
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01								
562010-7	LEFT NO.4 CABIN WINDOW							Component ATA:56
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 56 - WINDOWS								
562010-8	RIGHT NO.4 CABIN WINDOW							Component ATA:56
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01								
562010-9	LEFT NO.5 CABIN WINDOW							Component ATA:56
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 56-20-01PROC. REF: AMM 56-20-01								
L5600010 ^S	* CABIN WINDOWS (INCLUDING THE EMERGENCY EXIT WINDOW) - PERFORM DETAILED VISUAL INSPECTION							Service ATA:56
	MOS	18-Nov-21						AIRWORTHINESS
	HRS	4737	4800					
	AFL	3987						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								
N5600003	* LEFT WINDSHIELD - PERFORM ULTRASONIC INSPECTION OF STRUCTURAL PLIES							Service ATA:56
	MOS	01-Aug-14						AIRWORTHINESS
	HRS	3206.6	4800		8006.6		2551.4	
	AFL	2642						
PROC. REF: NDT PART 4/56-10-01PROC. REF: NDT PART 4/56-10-01								
N5600003	* RIGHT WINDSHIELD - PERFORM ULTRASONIC INSPECTION OF STRUCTURAL PLIES							Service ATA:56
	MOS	13-Aug-15						AIRWORTHINESS
	HRS	3451.1	4800		8251.1		2795.9	
	AFL	2836						
PROC. REF: NDT PART 4/56-10-01PROC. REF: NDT PART 4/56-10-01								
N5600012	* LEFT WINDSHIELD - PERFORM BOLT HOLE INSPECTION							Service ATA:56
	MOS	22-Aug-17						AIRWORTHINESS
	HRS	3796.4	4800		8596.4		3141.2	
	AFL	3164						
PROC. REF: AMM 56-10-01PROC. REF: AMM 56-10-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 56 - WINDOWS								
N5600012	* RIGHT WINDSHIELD - PERFORM BOLT HOLE INSPECTION							Service ATA:56
	MOS	22-Aug-17						AIRWORTHINESS
	HRS	3796.4	4800		8596.4		3141.2	
	AFL	3164						
PROC. REF: AMM 56-10-01PROC. REF: AMM 56-10-01								
W5600002	** WINDSHIELD - PERFORM RAIN REMOVAL COATING EFFECTIVENESS TEST							Service ATA:56
	MOS	07-May-25	12 (+14d/-14d)	Adj -11d	30-Apr-26	10-May-26	OVD	AIRWORTHINESS
	HRS	5263.7						
	AFL	4423						
PROC. REF: AMM 56-10-01, AMM 56-10-01PROC. REF: AMM 56-10-01, AMM 56-10-01								
Y5600000 ^S	WINDSHIELDS - PERFORM VISUAL INSPECTION (INTERIOR AND EXTERIOR)							Service ATA:56
	MOS	31-Jul-25	12 (+14d/-14d)					
	HRS	5307.6	300 (+25/-25)					
	AFL	4448						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								PKG:1
Y5600001 ^S	CABIN WINDOWS - PERFORM VISUAL INSPECTION							Service ATA:56
	MOS	09-Jul-24	24 (+14d/-14d)					
	HRS	5131.8	600 (+25/-25)					
	AFL	4323						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								PKG:7
Y5600013 ^S	WINDSHIELDS - PERFORM VISUAL INSPECTION OF THE AERODYNAMIC SEAL							Service ATA:56
	MOS	31-Jul-25	12 (+14d/-14d)					
	HRS	5307.6	300 (+25/-25)					
	AFL	4448						
PROC. REF: AMM 56-10-01, AMM 56-10-01PROC. REF: AMM 56-10-01, AMM 56-10-01								PKG:1
ATA 57 - WINGS								
571001	WING ASSEMBLY							Component ATA:57
PN:4557000004-001	MOS/MSC	07-Jul-04	O/C	TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
SN:14403830266	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 57-10-00PROC. REF: AMM 57-10-00								
571010	LEFT MAIN LANDING GEAR ACTUATOR FITTING							Component ATA:57
PN:PN	MOS	07-Jul-04		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0	20000	TSN 0	20000		15455	
PROC. REF: AMM 32-31-01PROC. REF: AMM 32-31-01								
571011	RIGHT MAIN LANDING GEAR ACTUATOR FITTING							Component ATA:57
PN:PN	MOS	07-Jul-04		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0	20000	TSN 0	20000		15455	
PROC. REF: AMM 32-31-01PROC. REF: AMM 32-31-01								
571066	REAR TRUNNION BREAK OUT BLOCK							Component ATA:57
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
573001	LEFT WINGLET FILLER							Component ATA:57
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
573002	RIGHT WINGLET FILLER							Component ATA:57
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
573089	RIGHT WING WINGLET							Component ATA:57
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 57-30-01PROC. REF: AMM 57-30-01								
573090	LEFT WING WINGLET							Component ATA:57
PN:4557300006-001	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:484532800266	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 57-30-01PROC. REF: AMM 57-30-01								
573091	LEFT WINGLET LEADING EDGE ASSEMBLY							Component ATA:57
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 57-30-01PROC. REF: AMM 57-30-01								
573092	RIGHT WING WINGLET							Component ATA:57
PN:4557300006-002	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:220275400266	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 57-30-01PROC. REF: AMM 57-30-01								
573093	RIGHT WINGLET LEADING EDGE ASSEMBLY							Component ATA:57
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 57-30-01PROC. REF: AMM 57-30-01								
574005	LEFT INBOARD LEADING EDGE							Component ATA:57
PN:4557400005-031	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:217153900266	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 57-40-01PROC. REF: AMM 57-40-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
574007	RIGHT INBOARD LEADING EDGE							Component ATA:57
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 57-40-01PROC. REF: AMM 57-40-01								
574011	LEFT INBOARD LEADING EDGE ACCESS SECTION							Component ATA:57
PN:4557400005-013	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:852984200266	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 57-40-01PROC. REF: AMM 57-40-01								
574013	RIGHT INBOARD LEADING EDGE ACCESS SECTION							Component ATA:57
PN:4557400005-014	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:5142837-00271	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 57-40-01PROC. REF: AMM 57-40-01								
574033	LEFT CENTER LEADING EDGE							Component ATA:57
PN:4557400005-033	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:1271253001266	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 57-40-01PROC. REF: AMM 57-40-01								
574035	RIGHT CENTER LEADING EDGE							Component ATA:57
PN:4557400005-034	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:197798900266	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 57-40-01PROC. REF: AMM 57-40-01								
574039	LEFT OUTBOARD LEADING EDGE ACCESS SECTION							Component ATA:57
PN:4557400005-023	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:472969500266	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 57-40-01PROC. REF: AMM 57-40-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
574041	RIGHT OUTBOARD LEADING EDGE ACCESS SECTION							Component ATA:57
PN:4557400005-024	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:278490900266	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 57-40-01PROC. REF: AMM 57-40-01								
574050	LEFT OUTBOARD LEADING EDGE							Component ATA:57
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 57-40-01PROC. REF: AMM 57-40-01								
574051	RIGHT OUTBOARD LEADING EDGE							Component ATA:57
PN:4557300003-014	MOS/MSC	26-Mar-07	O/C	TSN 0				
SN:253	HRS	1003.6		TSN 0				
	AFL	830		TSN 0				
PROC. REF: AMM 57-40-01PROC. REF: AMM 57-40-01								
575001	LEFT FLAP ASSEMBLY							Component ATA:57
PN:4557500006-007	MOS/MSC	25-Jan-21	O/C					
SN:019552600109	HRS	4567.6						
	AFL	3861						
PROC. REF: AMM 27-50-01PROC. REF: AMM 27-50-01								
575002	RIGHT FLAP ASSEMBLY							Component ATA:57
PN:4557500006-008	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:493227000213	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-50-01PROC. REF: AMM 27-50-01								
576001	LEFTAILERON							Component ATA:57
PN:4557600003-001	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:355081300266	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-10-02PROC. REF: AMM 27-10-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
576002	RIGHT AILERON							Component ATA:57
PN:4557600003-002	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:254247000266	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-10-02PROC. REF: AMM 27-10-02								
576003	UPPER AILERON QUADRANT ASSEMBLY							Component ATA:57
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-10-07PROC. REF: AMM 27-10-07								
576004	LOWER AILERON QUADRANT ASSEMBLY							Component ATA:57
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-10-07PROC. REF: AMM 27-10-07								
576010	LEFT AILERON BALANCE TAB ASSEMBLY --							Component ATA:57
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
576011	RIGHT AILERON BALANCE TAB ASSEMBLY --							Component ATA:57
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
576037	LEFT AILERON BOLTS (X3)							Component ATA:57
PN:PN	MOS/MSC	07-Jul-04	H/T	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-10-02PROC. REF: AMM 27-10-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
576038	RIGHT AILERON BOLTS (X3)							Component ATA:57
PN:PN	MOS/MSC	07-Jul-04	H/T	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-10-02PROC. REF: AMM 27-10-02								
577001	LEFT SPOILER --							Component ATA:57
PN:4557700003-021	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:0312	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-60-01PROC. REF: AMM 27-60-01								
577002	RIGHT SPOILER --							Component ATA:57
PN:4557700003-022	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:0320	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-60-01PROC. REF: AMM 27-60-01								
A5760004	* LEFT AILERON BOLTS (X3) - PERFORM MAGNETIC PARTICLE INSPECTION OR REPLACE							Service ATA:57
PN:PN	MOS	07-Jul-04						AIRWORTHINESS
SN:UNKNOWN	HRS	0	9600		9600		4144.8	
	AFL	0						
A5760004	* RIGHT AILERON BOLTS (X3) - PERFORM MAGNETIC PARTICLE INSPECTION OR REPLACE							Service ATA:57
PN:PN	MOS	07-Jul-04						AIRWORTHINESS
SN:UNKNOWN	HRS	0	9600		9600		4144.8	
	AFL	0						
AC5710190	* LEFT WING CENTER SECTION (PANELS 510AC, 510BC, 510BL AND 610BR REMOVED AND PANELS 510AL, 610AR, 720BL, AND 730BR LOWERED) - PERFORM VISUAL INSPECTION. INSPECT STRUCTURE FOR CORROSION OR DETERIORATION OF PROTECTIVE TREATMENT.							Service ATA:57
	MOS	21-Feb-22	96		28-Feb-30		1316 d	
	HRS	4819.5						
	AFL	4049						
PROC. REF: AMM 57-10-00PROC. REF: AMM 57-10-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
AC5710190	* RIGHT WING CENTER SECTION (PANELS 510AC, 510BC, 510BL AND 610BR REMOVED AND PANELS 510AL, 610AR, 720BL, AND 730BR LOWERED) - PERFORM VISUAL INSPECTION. INSPECT STRUCTURE FOR CORROSION OR DETERIORATION OF PROTECTIVE TREATMENT.							Service ATA:57
	MOS	21-Feb-22	96		28-Feb-30		1316 d	
	HRS	4819.5						
	AFL	4049						
PROC. REF: AMM 57-10-00PROC. REF: AMM 57-10-00								
AE5710035 ^S	* WING LOWER SKIN AT DRAIN HOLE (4 LOCATIONS) - PERFORM EDDY CURRENT INSPECTION							Service ATA:57
	MOS	18-Nov-21						AIRWORTHINESS
	HRS	4737	4800 (+25/-25)					
	AFL	3987						
PROC. REF: NDT PART 6/57-30-02PROC. REF: NDT PART 6/57-30-02								
AE5710187	* LOWER WING FUEL DRAIN HOLES (4 LOCATIONS) - PERFORM EDDY CURRENT INSPECTION							Service ATA:57
	MOS	EFF	72		11-Dec-31 *		1967 d	AIRWORTHINESS
	HRS							
	AFL							
PROC. REF: NDT PART 6/57-30-03PROC. REF: NDT PART 6/57-30-03								
E5710005 ^S	* WING CENTER SECTION SPAR UPPER CAPS - PERFORM VISUAL INSPECTION. INSPECT FRONT, MID, AND REAR SPAR UPPER CAPS FROM CENTERLINE TO SKIN TERMINATION AT WS 33.							Service ATA:57
	MOS	07-Jul-04						AIRWORTHINESS
	HRS	0	9600					
	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
E5710019 ^S	* WING BOX, UPPER SKIN, SKIN/STRINGER AND SPAR CAPS - PERFORM VISUAL INSPECTION. INSPECT UPPER WING SPAR CAPS, SKIN PANEL, AND STRINGERS OF OUTER WING							Service ATA:57
	MOS	07-Jul-04						AIRWORTHINESS
	HRS	0	9600 (+25/-25)					
	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
E5710020 ^S	* WING BOX RIBS - PERFORM VISUAL INSPECTION. INSPECT ALL WING BOX RIBS EXCEPT CLOSING RIB BETWEEN FRONT AND MID SPARS AND CLOSING RIB BETWEEN MID AND REAR SPAR.							Service ATA:57
	MOS	07-Jul-04						AIRWORTHINESS
	HRS	0	9600 (+25/-25)					
	AFL	0						
								PKG:26
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
E5750051	* FLAP MAIN TRACK ROLLERS - PERFORM VISUAL INSPECTION WITH FLAPS REMOVED							Service ATA:57
	MOS			TAC 0				AIRWORTHINESS
	HRS	0	T:10000		10000		4544.8	
	AFL							
PROC. REF: AMM 05-10-00, AMM 27-50-01PROC. REF: AMM 05-10-00, AMM 27-50-01								
E5750052	* FLAP NOSE ROLLERS - PERFORM VISUAL INSPECTION WITH FLAPS REMOVED							Service ATA:57
	MOS			TAC 0				AIRWORTHINESS
	HRS	0	T:7200		7200		1744.8	
	AFL							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								
E5760006 ^S	* AILERON BASIC STRUCTURE - PERFORM VISUAL INSPECTION							Service ATA:57
	MOS	07-Jul-04						AIRWORTHINESS
	HRS	0	9600 (+25/-25)					
	AFL	0						
								PKG:26
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
L5710124 ^S	* AILERON DRIVE SUPPORT - PERFORM ULTRASONIC INSPECTION							Service ATA:57
	MOS	18-Nov-21						AIRWORTHINESS
	HRS	4737	4800					
	AFL	3987						
								PKG:25
PROC. REF: NDT PART 4/27-10-01PROC. REF: NDT PART 4/27-10-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
N5710002	* WING BOX MID SPAR LOWER CAP, OUTBOARD OF JOINT AT WS 137 BETWEEN RIB NO. 7 AND 8 - PERFORM DIRECTED VISUAL INSPECTION. INSPECT MID SPAR LOWER CAP AND LOWER SKIN PANELS.							Service ATA:57
	MOS			TAC 0				AIRWORTHINESS
	HRS	0	T:9600		9600		4144.8	
	AFL							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								
N5710004 ^S	* WING CENTER SECTION REAR SPAR - PERFORM EDDY CURRENT INSPECTION. INSPECT REAR SPAR LOWER CAP FROM CENTERLINE TO WS 33.							Service ATA:57
	MOS	18-Nov-21						AIRWORTHINESS
	HRS	4737	4800 (+25/-25)					
	AFL	3987						
								PKG:25
PROC. REF: NDT PART 6/57-20-02PROC. REF: NDT PART 6/57-20-02								
N5710006 ^S	* WING CENTER SECTION FORWARD AND AFT RIBS AT WS 6 AND FORWARD RIBS AT WS 17 - PERFORM EDDY CURRENT INSPECTION							Service ATA:57
	MOS	18-Nov-21						AIRWORTHINESS
	HRS	4737	4800 (+25/-25)					
	AFL	3987						
								PKG:25
PROC. REF: NDT PART 6/57-10-06PROC. REF: NDT PART 6/57-10-06								
N5710008	* WING BOX MID SPAR LOWER CAP - PERFORM ULTRASONIC INSPECTION. INSPECT MID SPAR LOWER CAP AND LOWER SKIN PANELS BETWEEN WS 99 AND WS 137							Service ATA:57
	MOS							AIRWORTHINESS
	HRS	0	T:9600		9600		4144.8	
	AFL							
PROC. REF: NDT PART 4/57-30-03PROC. REF: NDT PART 4/57-30-03								
N5710009	* WING BOX MID SPAR LOWER CAP JOINT AT WS 137 - PERFORM X-RAY INSPECTION. INSPECT MID SPAR CENTER/OUTER JOINT							Service ATA:57
	MOS			TAC 0				AIRWORTHINESS
	HRS	0	T:9600		9600		4144.8	
	AFL							
PROC. REF: NDT PART 2/57-10-02PROC. REF: NDT PART 2/57-10-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45
Serial: 45-252
RegNo: N253SC
HRS: 5455.2
AFL: 4545
As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
N5710010	* WING BOX REAR SPAR LOWER CAP INBOARD OF JOINT AT WS 81 - PERFORM ULTRASONIC INSPECTION. INSPECT REAR SPAR LOWER CAP BETWEEN SKIN TERMINATION AT WS 48 AND CLOSING RIB AT WS 60.							Service ATA:57
	MOS	07-Jul-04		TAC 0				AIRWORTHINESS
	HRS	0	T:9600		9600		4144.8	
	AFL							
PROC. REF: NDT PART 4/57-30-01PROC. REF: NDT PART 4/57-30-01								
N5710011 ^S	* WING BOX REAR SPAR LOWER CAP JOINT AT WS 81 - PERFORM X-RAY INSPECTION. INSPECT CENTER AND OUTER REAR SPARS, LOWER SPLICE PLATE, AND LOWER SKIN BETWEEN WS 60 AND WS 90.							Service ATA:57
	MOS	07-Jul-04						AIRWORTHINESS
	HRS	0	T:9600 (+25/-25)					
	AFL	0						
								PKG:22
PROC. REF: NDT PART 2/57-10-03PROC. REF: NDT PART 2/57-10-03								
N5710012	* WING BOX REAR SPAR LOWER CAP OUTBOARD OF JOINT AT WS 81 TO RIB NUMBER 6 - PERFORM DETAILED VISUAL INSPECTION. INSPECT OUTER REAR SPAR LOWER CAP AND AFT LOWER SKIN PANEL OUTBOARD OF REAR SPLICE AT WS 90.							Service ATA:57
	MOS	07-Jul-23		TAC 0				AIRWORTHINESS
	HRS	0	T:9600		9600		4144.8	
	AFL							
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								
N5710013	* WING BOX REAR SPAR LOWER CAP SKIN TERMINATION AT MS 48 - PERFORM EDDY CURRENT INSPECTION. INSPECT REAR SPAR LOWER CAP BETWEEN WS 33 AND WS 48.							Service ATA:57
	MOS	07-Jul-23		TAC 0				AIRWORTHINESS
	HRS	0	T:10000		10000		4544.8	
	AFL							
PROC. REF: NDT PART 6/57-20-04PROC. REF: NDT PART 6/57-20-04								
N5710014 ^S	* WING BOX REAR SPAR FLAP TRACK CUTOUTS - PERFORM EDDY CURRENT INSPECTION. INSPECT FLAP TRACK CUTOUTS AT WS 65, WS 126, AND WS 184 ON REAR SPAR.							Service ATA:57
	MOS	07-Jul-04						AIRWORTHINESS
	HRS	0	T:9600 (+25/-25)					
	AFL	0						
								PKG:25
PROC. REF: NDT PART 6/57-20-01PROC. REF: NDT PART 6/57-20-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
N5710016	^S	* WING BOX BASIC SKIN/STRINGER, LOWER SKIN - PERFORM VISUAL INSPECTION. INSPECT OUTBOARD WING FORWARD AND AFT LOWER SKIN PANELS AND STRINGERS.						Service ATA:57
	MOS	07-Jul-04						AIRWORTHINESS
	HRS	0	T:9600 (+25/-25)					
	AFL	0						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								PKG:25
N5710017	^S	* WING BOX BASIC SKIN/STRINGER AT STRINGER RUN-OUT, LOWER SKIN - PERFORM VISUAL INSPECTION. INSPECT STRINGER RUN-OUTS IN FORWARD AND AFT LOWER SKIN PANELS.						Service ATA:57
	MOS	07-Jul-04						AIRWORTHINESS
	HRS	0	9600 (+25/-25)					
	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:26
N5710021	^S	* CENTER SECTION MID SPAR LOWER CAP - PERFORM EDDY CURRENT INSPECTION. INSPECT MID SPAR FROM CENTERLINE SPLICE PLATE TO SKIN TERMINATION AT MS 33.						Service ATA:57
	MOS	07-Jul-04						AIRWORTHINESS
	HRS	0	T:9600 (+25/-25)					
	AFL	0						
PROC. REF: NDT PART 6/57-10-02PROC. REF: NDT PART 6/57-10-02								PKG:22
N5710022	^S	* CENTER SECTION MID SPAR CENTERLINE JOINT - PERFORM EDDY CURRENT INSPECTION. INSPECT CENTER MID SPAR (CENTERLINE TO WS 17), LOWER SPLICE PLATE, AND CENTER MID SPAR JOINT FITTING LOWER CAP.						Service ATA:57
	MOS	07-Jul-04						AIRWORTHINESS
	HRS	0	T:9600					
	AFL	0						
PROC. REF: NDT PART 6/57-10-08, NDT PART 6/57-10-10PROC. REF: NDT PART 6/57-10-08, NDT PART 6/57-10-10								PKG:22
N5710023	^S	* CENTER SECTION FRONT SPAR LOWER CAP - PERFORM EDDY CURRENT INSPECTION. INSPECT CENTER WING FRONT SPAR LOWER CAP BETWEEN SKIN TERMINATIONS (WS 31 LEFT TO WS 31 RIGHT).						Service ATA:57
	MOS	07-Jul-04						AIRWORTHINESS
	HRS	0	T:9600 (+25/-25)					
	AFL	0						
PROC. REF: NDT PART 6/57-10-03PROC. REF: NDT PART 6/57-10-03								PKG:22

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
N5710026	* WING BOX MID SPAR LOWER CAP - PERFORM ULTRASONIC INSPECTION. INSPECT MID SPAR LOWER CAP OUTBOARD OF ROOT RIB AT WS 33 TO WS 99.							Service ATA:57
	MOS	07-Jul-23		TAC 0				AIRWORTHINESS
	HRS	0	T:10000		10000		4544.8	
	AFL							
PROC. REF: NDT PART 4/57-30-03PROC. REF: NDT PART 4/57-30-03								
N5710028 ^S	* WING BOX MID SPAR LOWER CAP, SKIN TERMINATION AT WS 33 - PERFORM BOLT HOLE EDDY CURRENT INSPECTION. INSPECT MID SPAR LOWER CAP UNDERNEATH ROOT RIB (WS 33) AT POINT OF SKIN TERMINATION.							Service ATA:57
	MOS	18-Nov-21						AIRWORTHINESS
	HRS	4737	4800					
	AFL	3987						
PROC. REF: NDT PART 6/57-10-11PROC. REF: NDT PART 6/57-10-11								
N5710031 ^S	* WING BOX SKIN ACCESS COVER HOLES - PERFORM EDDY CURRENT INSPECTION. INSPECT ACCESS HOLES IN FORWARD AND AFT LOWER SKIN PANELS.							Service ATA:57
	MOS	18-Nov-21						AIRWORTHINESS
	HRS	4737	4800 (+25/-25)					
	AFL	3987						
PROC. REF: NDT PART 6/57-30-01PROC. REF: NDT PART 6/57-30-01								
N5710037 ^S	* WING BOX FRONT SPAR LOWER CAP - PERFORM VISUAL INSPECTION. INSPECT FRONT SPAR LOWER CAP AND LOWER FORWARD SKIN OUTBOARD OF MID-SPAR STATION (MS) 55.							Service ATA:57
	MOS	07-Jul-04						AIRWORTHINESS
	HRS	0	T:9600 (+25/-25)					
	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
N5710084 ^S	SPOILER, CENTER HINGE SPOILER SIDE - PERFORM EDDY CURRENT INSPECTION							Service ATA:57
	MOS	01-Mar-19	96 (+14d/-14d)					
	HRS	4123.3	2400 (+25/-25)					
	AFL	3499						
PROC. REF: NDT PART 6/57-40-01PROC. REF: NDT PART 6/57-40-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45
Serial: 45-252
RegNo: N253SC
HRS: 5455.2
AFL: 4545
As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
N5710121	^S	* WING BOX MID SPAR, OUTBOARD OF RIB NUMBER 8 - PERFORM VISUAL INSPECTION AT WS 156 AND OUTBOARD TO WS 260						Service ATA:57
	MOS	07-Jul-04						AIRWORTHINESS
	HRS	0	T:9600 (+25/-25)					
	AFL	0						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								PKG:25
N5710122	^S	* WING BOX REAR SPAR, OUTBOARD OF RIB NUMBER 6 - PERFORM VISUAL INSPECTION AT WS 118 AND OUTBOARD TO WS 260						Service ATA:57
	MOS	18-Nov-21						AIRWORTHINESS
	HRS	4737	4800 (+25/-25)					
	AFL	3987						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								PKG:25
N5710123		* WING BOX MID SPAR LOWER CAP - PERFORM EDDY CURRENT INSPECTION AT TRUNNION FITTING						Service ATA:57
	MOS	07-Jul-23		TAC 0				AIRWORTHINESS
	HRS	0	T:9600		9600		4144.8	
	AFL							
PROC. REF: NDT PART 6/57-10-01PROC. REF: NDT PART 6/57-10-01								
N5710137	^S	* MID SPAR AT RIB NO. 2 NEAR WS 48 - PERFORM BOLT HOLE EDDY CURRENT INSPECTION						Service ATA:57
	MOS	18-Nov-21						AIRWORTHINESS
	HRS	4737	4800					
	AFL	3987						
PROC. REF: NDT PART 6/57-10-11APROC. REF: NDT PART 6/57-10-11A								PKG:25
N5710138	^S	* MID SPAR AT RIB NO. 3 NEAR WS 60 - PERFORM BOLT HOLE EDDY CURRENT INSPECTION						Service ATA:57
	MOS	18-Nov-21						AIRWORTHINESS
	HRS	4737	4800					
	AFL	3987						
PROC. REF: NDT PART 6/57-10-11APROC. REF: NDT PART 6/57-10-11A								PKG:25

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
N5710139 ^S	* FORWARD FLANGE FASTENERS AT REAR SPAR BETWEEN WS 52 AND WS 60 - PERFORM BOLT HOLE EDDY CURRENT INSPECTION							Service ATA:57
	MOS	07-Jul-04						AIRWORTHINESS
	HRS	0	T:9600 (+25/-25)					
	AFL	0						
PROC. REF: NDT PART 6/57-20-03PROC. REF: NDT PART 6/57-20-03								PKG:22
N5710148	* WING CENTER SECTION REAR SPAR - PERFORM EDDY CURRENT INSPECTION. INSPECT REAR SPAR LOWER CAP FROM CENTERLINE TO WS 33.							Service ATA:57
	MOS/MSC	07-Jul-04	N/A					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 6/57-20-02PROC. REF: NDT PART 6/57-20-02								
N5710149	* WING CENTER SECTION FORWARD AND AFT RIBS AT WS 6 AND FORWARD RIBS AT WS 17 - PERFORM EDDY CURRENT INSPECTION							Service ATA:57
	MOS/MSC	07-Jul-04	N/A					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 6/57-10-06PROC. REF: NDT PART 6/57-10-06								
N5710150	* WING BOX MID SPAR LOWER CAP - PERFORM ULTRASONIC INSPECTION. INSPECT MID SPAR LOWER CAP AND LOWER SKIN PANELS BETWEEN WS 99 AND WS 137.							Service ATA:57
	MOS/MSC	07-Jul-04	N/A					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 4/57-30-03PROC. REF: NDT PART 4/57-30-03								
N5710151	* WING BOX MID SPAR LOWER CAP JOINT AT WS 137 - PERFORM X-RAY INSPECTION. INSPECT MID SPAR CENTER/OUTER JOINT.							Service ATA:57
	MOS/MSC	07-Jul-04	N/A					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 2/57-10-02PROC. REF: NDT PART 2/57-10-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
N5710152	* WING BOX REAR SPAR LOWER CAP INBOARD OF JOINT AT WS 81 - PERFORM ULTRASONIC INSPECTION. INSPECT REAR SPAR LOWER CAP BETWEEN SKIN TERMINATION AT WS 48 AND CLOSING RIB AT WS 60.						Service	ATA:57
	MOS/MSC	07-Jul-04	N/A					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 4/57-30-01PROC. REF: NDT PART 4/57-30-01								
N5710153	* WING BOX REAR SPAR LOWER CAP JOINT AT WS 81 - PERFORM X-RAY INSPECTION. INSPECT CENTER AND OUTER REAR SPARS, LOWER SPLICE PLATE, AND LOWER SKIN BETWEEN WS 60 AND WS 90.						Service	ATA:57
	MOS/MSC	07-Jul-04	N/A					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 2/57-10-03PROC. REF: NDT PART 2/57-10-03								
N5710155	* WING BOX REAR SPAR LOWER CAP SKIN TERMINATION AT MS 48 - PERFORM EDDY CURRENT INSPECTION. INSPECT REAR SPAR LOWER CAP BETWEEN WS 33 AND WS 48.						Service	ATA:57
	MOS/MSC	07-Jul-04	N/A					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 6/57-20-04PROC. REF: NDT PART 6/57-20-04								
N5710157 ^S	* WING BOX BASIC SKIN/STRINGER AT STRINGER RUN-OUT, LOWER SKIN - PERFORM VISUAL INSPECTION. INSPECT STRINGER RUN-OUTS IN FORWARD AND AFT LOWER SKIN PANELS.						Service	ATA:57
	MOS/MSC	07-Jul-04	N/A				NOT APPLICABLE	
	HRS	0						
	AFL	0						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								PKG:25
N5710158	* CENTER SECTION FRONT SPAR LOWER CAP - PERFORM EDDY CURRENT INSPECTION. INSPECT CENTER WING FRONT SPAR LOWER CAP BETWEEN SKIN TERMINATIONS (WS 31 LEFT TO WS 31 RIGHT).						Service	ATA:57
	MOS/MSC	07-Jul-04	N/A					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 6/57-10-03PROC. REF: NDT PART 6/57-10-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
N5710159	* WING BOX MID SPAR LOWER CAP - PERFORM ULTRASONIC INSPECTION. INSPECT MID SPAR LOWER CAP OUTBOARD OF ROOT RIB AT WS 33 TO WS 99.							Service ATA:57
	MOS/MSC	07-Jul-04	N/A					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 4/57-30-03PROC. REF: NDT PART 4/57-30-03								
N5710160	* WING BOX MID SPAR LOWER CAP, SKIN TERMINATION AT WS 33 - PERFORM BOLT HOLE EDDY CURRENT INSPECTION. INSPECT MID SPAR LOWER CAP UNDERNEATH ROOT RIB (WS 33) AT POINT OF SKIN TERMINATION.							Service ATA:57
	MOS/MSC	07-Jul-04	N/A					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 6/57-10-11PROC. REF: NDT PART 6/57-10-11								
N5710161 ^S	* WING BOX SKIN ACCESS COVER HOLES - PERFORM EDDY CURRENT INSPECTION. INSPECT ACCESS HOLES IN FORWARD AND AFT LOWER SKIN PANELS.							Service ATA:57
	MOS/MSC	01-Mar-19	N/A					
	HRS	4123.3						
	AFL	3499						
PROC. REF: NDT PART 6/57-30-01PROC. REF: NDT PART 6/57-30-01								
N5710163	* CENTER SECTION MID SPAR CENTERLINE JOINT - PERFORM EDDY CURRENT INSPECTION. INSPECT CENTER MID SPAR (CENTERLINE TO WS 17), LOWER SPLICE PLATE, AND CENTER MID SPAR JOINT FITTING LOWER CAP.							Service ATA:57
	MOS/MSC	07-Jul-04	N/A					NOT APPLICABLE
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 6/57-10-08, NDT PART 6/57-10-10PROC. REF: NDT PART 6/57-10-08, NDT PART 6/57-10-10								
N5710164	* CENTER SECTION MID SPAR LOWER CAP - PERFORM EDDY CURRENT INSPECTION. INSPECT MID SPAR FROM CENTERLINE SPLICE PLATE TO SKIN TERMINATION AT MS 33.							Service ATA:57
	MOS/MSC	07-Jul-04	N/A					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 6/57-10-02PROC. REF: NDT PART 6/57-10-02								

PKG:22

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
N5710165	* WING BOX REAR SPAR FLAP TRACK CUT-OUTS - PERFORM EDDY CURRENT INSPECTION. INSPECT FLAP TRACK CUT-OUTS AT WS 65, WS 126, AND WS 184 ON REAR SPAR.							Service ATA:57
	MOS/MSC	07-Jul-04	N/A					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 6/57-20-01PROC. REF: NDT PART 6/57-20-01								
N5710168	* WING BOX MID SPAR LOWER CAP - PERFORM EDDY CURRENT INSPECTION AT TRUNNION FITTING							Service ATA:57
	MOS/MSC	07-Jul-04	N/A					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 6/57-10-01PROC. REF: NDT PART 6/57-10-01								
N5710169	* MID SPAR AT RIB NO. 2 NEAR WS 48 - PERFORM BOLT HOLE EDDY CURRENT INSPECTION							Service ATA:57
	MOS/MSC	07-Jul-04	N/A					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 6/57-10-11APROC. REF: NDT PART 6/57-10-11A								
N5710170	* MID SPAR AT RIB NO. 3 NEAR WS 60 - PERFORM BOLT HOLE EDDY CURRENT INSPECTION							Service ATA:57
	MOS/MSC	07-Jul-04	N/A					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 6/57-10-11APROC. REF: NDT PART 6/57-10-11A								
N5710171	* FORWARD FLANGE FASTENERS AT REAR SPAR BETWEEN WS 52 AND WS 60 - PERFORM BOLT HOLE EDDY CURRENT INSPECTION							Service ATA:57
	MOS/MSC	07-Jul-04	N/A					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 6/57-20-03PROC. REF: NDT PART 6/57-20-03								
N5710172	* WING BOX MID SPAR LOWER CAP - PERFORM ULTRASONIC INSPECTION AT TRUNNION FITTING							Service ATA:57
	MOS	07-Jul-23						
	HRS	0	T:9600		9600		4144.8	
	AFL							
PROC. REF: NDT PART 4/57-10-00PROC. REF: NDT PART 4/57-10-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
N5710173	* WING BOX MID SPAR LOWER CAP - PERFORM ULTRASONIC INSPECTION AT TRUNNION FITTING							Service ATA:57
	MOS/MSC	07-Jul-04	N/A					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 4/57-10-00PROC. REF: NDT PART 4/57-10-00								
N5710174	* WING BOX REAR SPAR LOWER CAP SKIN TERMINATION AT MS 48 - PERFORM ULTRASONIC INSPECTION. INSPECT REAR SPAR LOWER CAP BETWEEN WS 33 AND WS 48.							Service ATA:57
	MOS	07-Jul-23						AIRWORTHINESS
	HRS	0	T:10000		10000		4544.8	
	AFL							
PROC. REF: NDT PART 4/57-30-04PROC. REF: NDT PART 4/57-30-04								
N5710175	* WING BOX REAR SPAR LOWER CAP SKIN TERMINATION AT WS 48 - PERFORM ULTRASONIC INSPECTION. INSPECT REAR SPAR LOWER CAP BETWEEN WS 33 AND WS 48.							Service ATA:57
	MOS/MSC	07-Jul-04	N/A					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 4/57-30-04PROC. REF: NDT PART 4/57-30-04								
N5710176 ^S	* WING MID SPAR (CENTER SECTION) LOWER CAP AND CENTER JOINT FITTING - PERFORM ULTRASONIC INSPECTION							Service ATA:57
	MOS	07-Jul-04						AIRWORTHINESS
	HRS	0	T:9600 (+25/-25)					
	AFL	0						
PROC. REF: NDT PART 4/57-30-05PROC. REF: NDT PART 4/57-30-05								PKG:22
N5710177	* WING MID SPAR (CENTER SECTION) LOWER CAP AND CENTER JOINT FITTING - PERFORM ULTRASONIC INSPECTION							Service ATA:57
	MOS/MSC	07-Jul-04	N/A					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 4/57-30-05PROC. REF: NDT PART 4/57-30-05								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
N5750005 ^S	* FLAP MAIN TRACK HINGE FITTINGS, TRACK, AND FLAP BOX SIDES - PERFORM VISUAL INSPECTION. INSPECT MAIN TRACK HINGE FITTINGS ON TRACK AND FLAP BOX SIDES.							Service ATA:57
	MOS	07-Jul-04						AIRWORTHINESS
	HRS	0	T:9600 (+25/-25)					
	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								PKG:22
P5710001 ^S	* WING DRAG LINK ATTACH FITTING - PERFORM MAGNETIC PARTICLE INSPECTION							Service ATA:57
	MOS	07-Jul-04						AIRWORTHINESS
	HRS	0	T:9600 (+25/-25)					
	AFL	0						
PROC. REF: NDT PART 7/57-30-02PROC. REF: NDT PART 7/57-30-02								PKG:22
P5710007 ^S	* WING TO FUSELAGE ATTACH FITTINGS AND LINKS - PERFORM EDDY CURRENT INSPECTION							Service ATA:57
	MOS	18-Nov-21						AIRWORTHINESS
	HRS	4737	4800 (+25/-25)					
	AFL	3987						
PROC. REF: NDT PART 6/57-10-12PROC. REF: NDT PART 6/57-10-12								PKG:25
P5710015 ^S	* WING BOX REAR SPAR AT AILERON HINGE - PERFORM EDDY CURRENT INSPECTION							Service ATA:57
	MOS	18-Nov-21						AIRWORTHINESS
	HRS	4737	4800 (+25/-25)					
	AFL	3987						
PROC. REF: NDT PART 6/57-10-20PROC. REF: NDT PART 6/57-10-20								PKG:25
P5710018 ^S	* WING LOWER SKIN AT MID SPAR SPAN WISE JOINT - PERFORM EDDY CURRENT INSPECTION.							Service ATA:57
	MOS	07-Jul-04						AIRWORTHINESS
	HRS	0	9600 (+25/-25)					
	AFL	0						
PROC. REF: NDT PART 6/57-10-09PROC. REF: NDT PART 6/57-10-09								PKG:26

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
P5710024	^S	* WING REAR SPAR SIDE STAY FITTING SUPPORT STRUCTURE - PERFORM EDDY CURRENT INSPECTION.						Service ATA:57
	MOS	18-Nov-21						AIRWORTHINESS
	HRS	4737	4800 (+25/-25)					
	AFL	3987						
PROC. REF: NDT PART 6/57-20-06PROC. REF: NDT PART 6/57-20-06								PKG:25
P5710025	^S	* WING FRONT SPAR LOWER CAP FROM WS 33.0 TO WS 60.0 - PERFORM RADIOGRAPHIC INSPECTION						Service ATA:57
	MOS	07-Jul-04						AIRWORTHINESS
	HRS	0	T:9600 (+25/-25)					
	AFL	0						
PROC. REF: NDT PART 2/57-10-01PROC. REF: NDT PART 2/57-10-01								PKG:22
P5710029	^S	* WING MID-SPAR VERTICAL WEB - PERFORM EDDY CURRENT INSPECTION						Service ATA:57
	MOS	07-Jul-04						AIRWORTHINESS
	HRS	0	9600					
	AFL	0						
PROC. REF: NDT PART 6/57-10-07PROC. REF: NDT PART 6/57-10-07								PKG:26
P5710030	^S	* WING REAR SPAR VERTICAL WEB - PERFORM EDDY CURRENT INSPECTION						Service ATA:57
	MOS	07-Jul-04						AIRWORTHINESS
	HRS	0	9600 (+25/-25)					
	AFL	0						
PROC. REF: NDT PART 6/57-20-05PROC. REF: NDT PART 6/57-20-05								PKG:26
P5710032	^S	* WING RIB UPPER AFT FLANGE FILLET RADIUS AT WS 33.0 - PERFORM ULTRASONIC INSPECTION						Service ATA:57
	MOS	18-Nov-21						AIRWORTHINESS
	HRS	4737	4800 (+25/-25)					
	AFL	3987						
PROC. REF: NDT PART 4/57-30-02PROC. REF: NDT PART 4/57-30-02								PKG:25

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
P5710033 ^S	* WING ACCESS HOLE IN CLOSING RIB BETWEEN MID AND REAR SPAR - PERFORM EDDY CURRENT INSPECTION							Service ATA:57
	MOS	18-Nov-21						AIRWORTHINESS
	HRS	4737	4800 (+25/-25)					
	AFL	3987						
PROC. REF: NDT PART 6/57-10-05PROC. REF: NDT PART 6/57-10-05								PKG:25
P5710034 ^S	* WING BOX JOINT TO WINGLET - PERFORM EDDY CURRENT INSPECTION							Service ATA:57
	MOS	18-Nov-21						AIRWORTHINESS
	HRS	4737	4800 (+25/-25)					
	AFL	3987						
PROC. REF: NDT PART 6/57-10-13PROC. REF: NDT PART 6/57-10-13								PKG:25
P5710083 ^S	* FLAP BOX BASIC STRUCTURE - PERFORM EDDY CURRENT INSPECTION							Service ATA:57
	MOS	18-Nov-21						AIRWORTHINESS
	HRS	4737	4800 (+25/-25)					
	AFL	3987						
PROC. REF: NDT PART 6/57-40-02PROC. REF: NDT PART 6/57-40-02								PKG:25
P5710085 ^S	SPOILER UPPER SKIN - PERFORM EDDY CURRENT INSPECTION							Service ATA:57
	MOS	18-Nov-21						
	HRS	4737	4800 (+25/-25)					
	AFL	3987						
PROC. REF: NDT PART 6/57-10-16PROC. REF: NDT PART 6/57-10-16								PKG:25
P5710086 ^S	SPOILER BOLTS AND HINGE PINS - PERFORM MAGNETIC PARTICLE INSPECTION							Service ATA:57
	MOS	18-Nov-21						
	HRS	4737	4800 (+25/-25)					
	AFL	3987						
PROC. REF: NDT PART 7/27-10-01PROC. REF: NDT PART 7/27-10-01								PKG:25

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
P5710181	^S	* WING DRAG LINK TUBE - PERFORM MAGNETIC PARTICLE INSPECTION						Service ATA:57
	MOS	01-Mar-19						AIRWORTHINESS
	HRS	4123.3	T:9600 (+25/-25)					
	AFL	3499						
PROC. REF: NDT PART 7/57-30-01PROC. REF: NDT PART 7/57-30-01								PKG:22
P5710182	^S	* WING DRAG LINK ATTACH BOLTS - PERFORM LIQUID PENETRANT INSPECTION						Service ATA:57
	MOS	07-Jul-04						AIRWORTHINESS
	HRS	0	T:9600 (+25/-25)					
	AFL	0						
PROC. REF: NDT PART 8/57-10-01PROC. REF: NDT PART 8/57-10-01								PKG:22
P5710183	^S	* WING DRAG LINK ATTACH CLEVIS - PERFORM MAGNETIC PARTICLE INSPECTION						Service ATA:57
	MOS	07-Jul-04						AIRWORTHINESS
	HRS	0	T:9600 (+25/-25)					
	AFL	0						
PROC. REF: NDT PART 7/57-10-01PROC. REF: NDT PART 7/57-10-01								PKG:22
P5710184	^S	* WING ATTACH BOLTS - PERFORM FLUORESCENT PENETRANT INSPECTION						Service ATA:57
	MOS	18-Nov-21						AIRWORTHINESS
	HRS	4737	4800					
	AFL	3987						
PROC. REF: NDT PART 8/57-10-02PROC. REF: NDT PART 8/57-10-02								PKG:25
P5710185	^S	* WING ATTACH LINKS - PERFORM MAGNETIC PARTICLE INSPECTION						Service ATA:57
	MOS	18-Nov-21						AIRWORTHINESS
	HRS	4737	4800					
	AFL	3987						
PROC. REF: NDT PART 7/57-10-03PROC. REF: NDT PART 7/57-10-03								PKG:25

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
P5710186 ^S	* WING ATTACH FITTINGS AT MID SPAR AND REAR SPAR - PERFORM MAGNETIC PARTICLE INSPECTION							Service ATA:57
	MOS	18-Nov-21						AIRWORTHINESS
	HRS	4737	4800					
	AFL	3987						
PROC. REF: NDT PART 7/57-10-02PROC. REF: NDT PART 7/57-10-02								PKG:25
P5750002 ^S	* FLAP FRONT SPAR CUTOUTS - PERFORM EDDY CURRENT INSPECTION							Service ATA:57
	MOS	07-Jul-04						AIRWORTHINESS
	HRS	0	T:9600					
	AFL	0						
PROC. REF: NDT PART 6/57-10-15PROC. REF: NDT PART 6/57-10-15								PKG:22
P5750003 ^S	* FLAP NOSE ROLLER RIBS - PERFORM EDDY CURRENT INSPECTION							Service ATA:57
	MOS	18-Nov-21						AIRWORTHINESS
	HRS	4737	4800					
	AFL	3987						
PROC. REF: NDT PART 6/57-10-14PROC. REF: NDT PART 6/57-10-14								PKG:25
P5750004 ^S	* FLAP ACTUATOR SUPPORT RIBS - PERFORM EDDY CURRENT INSPECTION							Service ATA:57
	MOS	07-Jul-04						AIRWORTHINESS
	HRS	0	9600					
	AFL	0						
PROC. REF: NDT PART 6/57-10-21PROC. REF: NDT PART 6/57-10-21								PKG:26
P5750048 ^S	* FLAP TRACKS - PERFORM MAGNETIC PARTICLE INSPECTION							Service ATA:57
	MOS	07-Jul-04						AIRWORTHINESS
	HRS	0	9600					
	AFL	0						
PROC. REF: NDT PART 7/57-71-01PROC. REF: NDT PART 7/57-71-01								PKG:26

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
P5750049	^S	* FLAP NOSE ROLLER TRACKS - PERFORM MAGNETIC PARTICLE INSPECTION WITH FLAPS REMOVED						Service ATA:57
	MOS	07-Jul-04						AIRWORTHINESS
	HRS	0	9600					
	AFL	0						
PROC. REF: NDT PART 7/57-10-04PROC. REF: NDT PART 7/57-10-04								PKG:26
P5750053	^S	* FLAP TRACK SUPPORT RIBS - PERFORM EDDY CURRENT INSPECTION						Service ATA:57
	MOS	07-Jul-04						AIRWORTHINESS
	HRS	0	9600					
	AFL	0						
PROC. REF: NDT PART 6/57-10-17PROC. REF: NDT PART 6/57-10-17								PKG:26
P5750068	^S	* FLAP FRONT-SPAR RIB SUPPORT STRUCTURE - PERFORM EDDY CURRENT INSPECTION						Service ATA:57
	MOS	18-Nov-21						AIRWORTHINESS
	HRS	4737	4800					
	AFL	3987						
PROC. REF: NDT PART 6/57-10-26PROC. REF: NDT PART 6/57-10-26								PKG:25
P5760000	^S	* AILERON ACTUATOR HINGE FITTING - PERFORM EDDY CURRENT INSPECTION						Service ATA:57
	MOS	07-Jul-04						AIRWORTHINESS
	HRS	0	9600					
	AFL	0						
PROC. REF: NDT PART 6/57-10-25PROC. REF: NDT PART 6/57-10-25								PKG:26
P5760001	^S	* AILERON SKIN - PERFORM EDDY CURRENT INSPECTION						Service ATA:57
	MOS	07-Jul-04						AIRWORTHINESS
	HRS	0	9600					
	AFL	0						
PROC. REF: NDT PART 6/57-10-19PROC. REF: NDT PART 6/57-10-19								PKG:26

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
P5760002	^S	* AILERON BALANCE TAB HINGE FITTINGS - PERFORM EDDY CURRENT INSPECTION						Service ATA:57
	MOS	07-Jul-04						AIRWORTHINESS
	HRS	0	T:9600 (+25/-25)					
	AFL	0						
PROC. REF: NDT PART 6/57-60-01PROC. REF: NDT PART 6/57-60-01								PKG:22
P5760003	^S	* AILERON TRIM AND BALANCE TAB FRONT SPARS - PERFORM RADIOGRAPHIC INSPECTION						Service ATA:57
	MOS	18-Nov-21						AIRWORTHINESS
	HRS	4737	4800					
	AFL	3987						
PROC. REF: NDT PART 2/57-60-01PROC. REF: NDT PART 2/57-60-01								PKG:25
P5760005	^S	* AILERON HINGE LUGS AND FITTINGS - PERFORM EDDY CURRENT INSPECTION						Service ATA:57
	MOS	07-Jul-04						AIRWORTHINESS
	HRS	0	9600					
	AFL	0						
PROC. REF: NDT PART 6/57-10-24PROC. REF: NDT PART 6/57-10-24								PKG:26
P5760014	^S	* AILERON HINGE SUPPORT STRUCTURE - PERFORM EDDY CURRENT INSPECTION						Service ATA:57
	MOS	07-Jul-04						AIRWORTHINESS
	HRS	0	9600					
	AFL	0						
PROC. REF: NDT PART 6/57-10-23PROC. REF: NDT PART 6/57-10-23								PKG:26
P5770000	^S	SPOILER HINGE ASSEMBLIES AND ACTUATOR FITTING - PERFORM EDDY CURRENT INSPECTION						Service ATA:57
	MOS	18-Nov-21						
	HRS	4737	4800 (+25/-25)					
	AFL	3987						
PROC. REF: NDT PART 6/57-10-22PROC. REF: NDT PART 6/57-10-22								PKG:25

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
Q5710156 ^S	* WING BOX BASIC SKIN/STRINGER, LOWER SKIN - PERFORM VISUAL INSPECTION. INSPECT OUTBOARD WING FORWARD AND AFT LOWER SKIN PANELS AND STRINGERS.						Service	ATA:57
	MOS/MSC	01-Mar-19	N/A					
	HRS	4123.3						
	AFL	3499						
								PKG:22
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
Q5710162 ^S	* WING BOX FRONT SPAR LOWER CAP - PERFORM VISUAL INSPECTION. INSPECT FRONT SPAR LOWER CAP AND LOWER FORWARD SKIN OUTBOARD OF MID-SPAR STATION (MS) 55.						Service	ATA:57
	MOS/MSC	01-Mar-19	N/A					
	HRS	4123.3						
	AFL	3499						
								PKG:22
Q5710166 ^S	* WING BOX MID SPAR, OUTBOARD OF RIB NO. 8 - PERFORM VISUAL INSPECTION AT WS 156 AND OUTBOARD TO WS 260						Service	ATA:57
	MOS/MSC	01-Mar-19	N/A				NOT APPLICABLE	
	HRS	4123.3						
	AFL	3499						
								PKG:22
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								
Q5710167 ^S	* WING BOX REAR SPAR, OUTBOARD OF RIB NO. 6 - PERFORM VISUAL INSPECTION AT WS 118 AND OUTBOARD TO WS 260						Service	ATA:57
	MOS/MSC	01-Mar-19	N/A				NOT APPLICABLE	
	HRS	4123.3						
	AFL	3499						
								PKG:22
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								
U5710147 ^S	* WING BOX MID SPAR LOWER CAP, OUTBOARD OF JOINT AT WS 137 BETWEEN RIB NO. 7 AND NO. 8 - PERFORM DETAILED VISUAL INSPECTION. INSPECT MID SPAR LOWER CAP AND LOWER SKIN PANELS.						Service	ATA:57
	MOS	09-Jul-24	24				AIRWORTHINESS	
	HRS	5131.8	600					
	AFL	4323						
								PKG:10
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45
Serial: 45-252
RegNo: N253SC
HRS: 5455.2
AFL: 4545
As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
U5710154	^S	* WING BOX REAR SPAR LOWER CAP OUTBOARD OF JOINT AT WS 81 TO RIB NO. 6 - PERFORM DETAILED VISUAL INSPECTION. INSPECT OUTER REAR SPAR LOWER CAP AND AFT LOWER SKIN PANEL OUTBOARD OF REAR SPLICE AT WS 90.						Service ATA:57
	MOS	09-Jul-24	24					AIRWORTHINESS
	HRS	5131.8	600					
	AFL	4323						
								PKG:10
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
V5710039	^S	WINGLET SKIN - PERFORM EDDY CURRENT INSPECTION						Service ATA:57
	MOS	18-Nov-21						
	HRS	4737	4800 (+25/-25)					
	AFL	3987						
								PKG:25
PROC. REF: NDT PART 6/57-10-18PROC. REF: NDT PART 6/57-10-18								
Y5700001	^S	WINGLET - PERFORM VISUAL INSPECTION						Service ATA:57
	MOS	31-Jul-25	12 (+14d/-14d)					
	HRS	5307.6	300 (+25/-25)					
	AFL	4448						
								PKG:4
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								
Y5700002	^S	FLUX VALVE BRACKET - VISUALLY INSPECT FOR CRACKS						Service ATA:57
	MOS	31-Jul-25	12 (+14d/-14d)					
	HRS	5307.6	300 (+25/-25)					
	AFL	4448						
								PKG:4
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
Y5710000	^S	WING - PERFORM EXTERNAL VISUAL INSPECTION FROM BL 0.00 TO WS 260						Service ATA:57
	MOS	24-Feb-23	48 (+14d/-14d)					
	HRS	5067.1	1200 (+25/-25)					
	AFL	4262						
								PKG:16
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
Y5710180	^S	EXTERNAL LOWER WING SKIN - PERFORM VISUAL INSPECTION						Service ATA:57
	MOS	09-Jul-24	24 (+14d/-14d)					
	HRS	5131.8	600 (+25/-25)					
	AFL	4323						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								PKG:10
Y5730013	^S	AILERON BRUSH SEALS - PERFORM DETAILED INSPECTION						Service ATA:57
	MOS	31-Jul-25	12 (+14d/-14d)					
	HRS	5307.6	300 (+25/-25)					
	AFL	4448						
PROC. REF: AMM 57-60-01PROC. REF: AMM 57-60-01								PKG:4
Y5750067	^S	FLAP BRACKETS - PERFORM DETAILED VISUAL INSPECTION						Service ATA:57
	MOS	01-Mar-19	96 (+14d/-14d)					
	HRS	4123.3	2400 (+25/-25)					
	AFL	3499						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								PKG:22
Y5750069	^S	FLAPS - PERFORM VISUAL INSPECTION OF FLAP NOSE ROLLERS, FLAP TRACKS, FLAP NOSE ROLLER TRACKS, AND FLAP MAIN TRACK ROLLERS.						Service ATA:57
	MOS	31-Jul-25	12 (+14d/-14d)					
	HRS	5307.6	300 (+25/-25)					
	AFL	4448						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								PKG:4
Y5750071	^S	FLAPS - WITH FLAPS REMOVED, PERFORM DETAILED VISUAL INSPECTION OF FLAP NOSE ROLLERS, FLAP TRACKS, FLAP NOSE ROLLER TRACKS, AND FLAP MAIN TRACK ROLLERS.						Service ATA:57
	MOS	24-Feb-23	48 (+14d/-14d)					
	HRS	5067.1	1200 (+25/-25)					
	AFL	4262						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								PKG:16

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
710130 ^S	NO. 1 ENGINE - INSPECT TAILPIPE/LPT3 ROTOR ASSEMBLY-VISUALLY INSPECT FOR FOREIGN OBJECT DAMAGE, THERMAL DISTRESS, AND LEAKS.						Service	ATA:71
	MOS	26-Oct-22						
	HRS	4984.7	800 (+50/-300)					
	ENC	4197						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								PKG:0
710130 ^S	NO. 2 ENGINE - INSPECT TAILPIPE/LPT3 ROTOR ASSEMBLY-VISUALLY INSPECT FOR FOREIGN OBJECT DAMAGE, THERMAL DISTRESS, AND LEAKS.						Service	ATA:71
	MOS	26-Oct-22						
	HRS	4984.7	800 (+50/-300)					
	ENC	4197						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								PKG:0
710140 ^S	NO. 1 ENGINE - INSPECT INLET/FAN AREA - INSPECT FOR FOREIGN OBJECT DAMAGE AND LEAKAGE (REFER TO PARAGRAPH 4.B)						Service	ATA:71
	MOS	26-Oct-22						
	HRS	4984.7	800 (+50/-300)					
	ENC	4197						
PROC. REF: LMM 72-00-00, LMM 72-00-00PROC. REF: LMM 72-00-00, LMM 72-00-00								PKG:0
710140 ^S	NO. 2 ENGINE - INSPECT INLET/FAN AREA - INSPECT FOR FOREIGN OBJECT DAMAGE AND LEAKAGE (REFER TO PARAGRAPH 4.B)						Service	ATA:71
	MOS	26-Oct-22						
	HRS	4984.7	800 (+50/-300)					
	ENC	4197						
PROC. REF: LMM 72-00-00, LMM 72-00-00PROC. REF: LMM 72-00-00, LMM 72-00-00								PKG:0
711001	NO. 1 ENGINE FORWARD MOUNT						Component	ATA:71
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
711002	NO. 2 ENGINE FORWARD MOUNT							Component ATA:71
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00								
7120005 ^U	CHANGE NO. 2 ALL							Service ATA:71
	MOS/MSC		N/A					
	HRS							
	AFL							
7120005 ^{U S}	REPLACE NO. 2 ENGINE AFT ENGINE MOUNT ISOLATOR BONDED MOUNTING							Service ATA:71
PN:LM833-SA18	MOS/MSC	07-Jul-04	O/C	TAC 0				LIFE LIMIT
SN:LK0895	HRS	0		TAC 0				
	AFL	0		TAC 0				
7120006	REPLACE NO. 1 ENGINE ALL ENGINE MOUNT ISOLATOR FORWARD BONDED MOUNTING							Service ATA:71
	MOS	27-Aug-13		TAC 0				LIFE LIMIT
	HRS	3014.1	3500	TAC 0	6514.1		1058.9	
	AFL	2498		TAC 0				
7120006 ^U	REPLACE NO. 2 ENGINE AFT ENGINE MOUNT ISOLATOR BONDED MOUNTING							Service ATA:71
PN:LM833-SA18	MOS/MSC	27-Aug-13	O/C	TAC 0				LIFE LIMIT
SN:LK0895	HRS	3014.1		TAC 0				
	AFL	2498		TAC 0				
7120006 ^U	REPLACE NO. 2 ENGINE ALL ENGINE MOUNT ISOLATOR FORWARD BONDED MOUNTING							Service ATA:71
	MOS	27-Aug-13		TAC 0				LIFE LIMIT
	HRS	3014.1	3500	TAC 0	6514.1		1058.9	
	AFL	2498		TAC 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
712005	NO. 1 ENGINE - AFT ENGINE MOUNT - ISOLATOR ASSEMBLY							Component ATA:71
PN:LM-833-SA18	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:LK0910	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00								
712006	NO. 2 ENGINE - AFT ENGINE MOUNT - ISOLATOR ASSEMBLY							Component ATA:71
PN:LM833-SA18	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:LK0895	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00								
7120069 ^U	NO. 1 ALL							Service ATA:71
	MOS/MSC	27-Aug-13	N/A					
	HRS	3014.2						
	AFL	2498						
7120069 ^U	NO. 2 ALL							Service ATA:71
	MOS/MSC	27-Aug-13	N/A					
	HRS	3014.2						
	AFL	2498						
712007	NO. 1 ENGINE - FORWARD ENGINE MOUNT - UPPER ISOLATOR ASSEMBLY							Component ATA:71
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00								
7120070 ^U	CHANGE NO. 1 ALL							Service ATA:71
	MOS	07-Jul-04					LIFE LIMIT	
	HRS	0	6000 (+100/-100)	6000	6100	544.8 (+100)		
	AFL	0						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
7120070 ^U	CHANGE NO. 2 ALL							Service ATA:71
	MOS	07-Jul-04						LIFE LIMIT
	HRS	0	6000 (+100/-100)		6000	6100	544.8 (+100)	
	AFL	0						
7120070 ^{U S} REPLACE NO. 2 ENGINE AFT ENGINE MOUNT ISOLATOR BONDED MOUNTING								
PN:LM833-SA18	MOS/MSC	07-Jul-04	O/C	TAC 0				LIFE LIMIT
SN:LK0895	HRS	0		TAC 0				
	AFL	0		TAC 0				
7120073 ^U NO. 1 ALL								
	MOS/MSC	07-Jul-04	N/A					Service ATA:71
	HRS	0						NOT APPLICABLE
	AFL	0						
7120073 ^U NO. 2 ALL								
	MOS/MSC	07-Jul-04	N/A					Service ATA:71
	HRS	0						NOT APPLICABLE
	AFL	0						
712008 NO. 2 ENGINE - FORWARD ENGINE MOUNT - UPPER ISOLATOR ASSEMBLY								
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				Component ATA:71
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00								
712009 NO. 1 ENGINE - FORWARD ENGINE MOUNT - LOWER ISOLATOR ASSEMBLY								
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				Component ATA:71
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
712010	NO. 2 ENGINE - FORWARD ENGINE MOUNT - LOWER ISOLATOR ASSEMBLY							Component ATA:71
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: NDT PART 7/32-10-08, NDT PART 7/32-10-03, NDT PART 7/32-10-04, NDT PART 8/32-10-02, NDT PART 8/54-30-01, NDT PART 8/54-30-02, AMM 71-20-00PROC. REF: NDT PART 7/32-10-08, NDT PART 7/32-10-03, NDT PART 7/32-10-04, NDT PART 8/32-10-02, NDT PART 8/54-30-01, NDT PART 8/54-30-02, AMM 71-20-00								
712045	NO. 1 ENGINE AFT MOUNT							Component ATA:71
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00								
712046	NO. 2 ENGINE AFT MOUNT							Component ATA:71
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00								
712078	NO. 1 ENGINE AFT MOUNT BOLT							Component ATA:71
PN:4571408525-001	MOS/MSC	27-Aug-13	E/C					AIRWORTHINESS
SN:UNKNOWN	HRS	3014.2						
	AFL	2498						
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00								
712079	NO. 2 ENGINE AFT MOUNT BOLT							Component ATA:71
PN:4571408525-001	MOS/MSC	27-Aug-13	E/C					AIRWORTHINESS
SN:UNKNOWN	HRS	3014.2						
	AFL	2498						
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00								
714010 ^S	NO. 1 ENGINE - CHECK ELECTRICAL WIRES AND CONNECTIONS - VISUALLY INSPECT FOR SECURITY AND DAMAGE							Service ATA:71
	MOS	26-Oct-22						
	HRS	4984.7	800 (+50/-300)					
	ENC	4197						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								
PKG:0								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
714010 ^S	NO. 2 ENGINE - CHECK ELECTRICAL WIRES AND CONNECTIONS - VISUALLY INSPECT FOR SECURITY AND DAMAGE							Service ATA:71
	MOS	26-Oct-22						
	HRS	4984.7	800 (+50/-300)					
	ENC	4197						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								PKG:0
715010 ^S	NO. 1 ENGINE - CHECK PLUMBING LINES AND CONNECTIONS - VISUALLY INSPECT FOR SECURITY, LOOSE OR BROKEN CLAMPS OR BRACKETS, LEAKS, CRACKS, CUTS, OR RUBBING							Service ATA:71
	MOS	26-Oct-22						
	HRS	4984.7	800 (+50/-300)					
	ENC	4197						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								PKG:0
715010 ^S	NO. 2 ENGINE - CHECK PLUMBING LINES AND CONNECTIONS - VISUALLY INSPECT FOR SECURITY, LOOSE OR BROKEN CLAMPS OR BRACKETS, LEAKS, CRACKS, CUTS, OR RUBBING							Service ATA:71
	MOS	26-Oct-22						
	HRS	4984.7	800 (+50/-300)					
	ENC	4197						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								PKG:0
716005	NO. 1 ENGINE INLET NACELLE							Component ATA:71
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-10-01PROC. REF: AMM 71-10-01								
716006	NO. 2 ENGINE INLET NACELLE							Component ATA:71
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-10-01PROC. REF: AMM 71-10-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45
Serial: 45-252
RegNo: N253SC
HRS: 5455.2
AFL: 4545
As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
71EN1	NO. 1 ENGINE							Component ATA:71
PN:3060084-1	MOS/MSC		E/C					
SN:P-116538C	HRS							
	AFL							
PROC. REF: SIL F731-88, AMM 71-00-01PROC. REF: SIL F731-88, AMM 71-00-01								
71EN2	NO. 2 ENGINE							Component ATA:71
PN:3060084-1	MOS/MSC		E/C					
SN:P-116539C	HRS							
	AFL							
PROC. REF: SIL F731-88, AMM 71-00-01PROC. REF: SIL F731-88, AMM 71-00-01								
AD7120005	NO. 1 ENGINE - FORWARD ENGINE MOUNT - LOWER ISOLATOR ASSEMBLY - REPLACE BONDED MOUNTING							Service ATA:71
	MOS/MSC	07-Jul-04	N/A	TAC 0				
	HRS	0		TAC 0				
	AFL	0		TAC 0				
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00								
AD7120005 ^{U S}	REPLACE NO. 1 ENGINE AFT ENGINE MOUNT ISOLATOR FORWARD BONDED MOUNTING							Service ATA:71
PN:LM-833-SA18	MOS/MSC	07-Jul-04	O/C	TAC 0				LIFE LIMIT
SN:LK0910	HRS	0		TAC 0				
	AFL	0		TAC 0				
AD7120005	REPLACE NO. 1 ENGINE ALL ENGINE MOUNT ISOLATOR BONDED MOUNTING							Service ATA:71
	MOS/MSC	07-Jul-04	N/A					
	HRS	0						
	AFL	0						
AD7120006	NO. 1 ENGINE - FORWARD ENGINE MOUNT - LOWER ISOLATOR ASSEMBLY - REPLACE BONDED MOUNTING							Service ATA:71
	MOS	27-Aug-13		TAC 0				LIFE LIMIT
	HRS	3014.1	3500	TAC 0	6514.1		1058.9	
	AFL	2498		TAC 0				
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
AD7120006	NO. 1 ENGINE - FORWARD ENGINE MOUNT - UPPER ISOLATOR ASSEMBLY - REPLACE BONDED MOUNTING							Service ATA:71
	MOS	27-Aug-13		TAC 0				LIFE LIMIT
	HRS	3014.1	3500 (+100/-100)	TAC 0	6514.1	6614.1	1058.9 (+100)	
	AFL	2498		TAC 0				
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00								
AD7120006	NO. 2 ENGINE - FORWARD ENGINE MOUNT - LOWER ISOLATOR ASSEMBLY - REPLACE BONDED MOUNTING							Service ATA:71
	MOS	27-Aug-13		TAC 0				LIFE LIMIT
	HRS	3014.1	3500 (+100/-100)	TAC 0	6514.1	6614.1	1058.9 (+100)	
	AFL	2498		TAC 0				
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00								
AD7120006	NO. 2 ENGINE - FORWARD ENGINE MOUNT - UPPER ISOLATOR ASSEMBLY - REPLACE BONDED MOUNTING							Service ATA:71
	MOS	27-Aug-13		TAC 0				LIFE LIMIT
	HRS	3014.1	3500 (+100/-100)	TAC 0	6514.1	6614.1	1058.9 (+100)	
	AFL	2498		TAC 0				
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00								
AD7120006 ^U	REPLACE NO. 1 ENGINE AFT ENGINE MOUNT ISOLATOR BONDED MOUNTING							Service ATA:71
PN:LM-833-SA18	MOS/MSC	27-Aug-13	O/C	TAC 0				LIFE LIMIT
SN:LK0910	HRS	3014.1		TAC 0				
	AFL	2498		TAC 0				
AD7120070	NO. 1 ENGINE - FORWARD ENGINE MOUNT - LOWER ISOLATOR ASSEMBLY - REPLACE BONDED MOUNTING							Service ATA:71
	MOS/MSC	07-Jul-04	N/A	TAC 0				
	HRS	0		TAC 0				
	AFL	0		TAC 0				
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00								
AD7120070	NO. 1 ENGINE - FORWARD ENGINE MOUNT - UPPER ISOLATOR ASSEMBLY - REPLACE BONDED MOUNTING							Service ATA:71
	MOS/MSC	07-Jul-04	N/A	TAC 0				
	HRS	0		TAC 0				
	AFL	0		TAC 0				
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
AD7120070	NO. 2 ENGINE - FORWARD ENGINE MOUNT - LOWER ISOLATOR ASSEMBLY - REPLACE BONDED MOUNTING							Service ATA:71
	MOS/MSC	07-Jul-04	N/A	TAC 0				
	HRS	0		TAC 0				
	AFL	0		TAC 0				
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00								
AD7120070	NO. 2 ENGINE - FORWARD ENGINE MOUNT - UPPER ISOLATOR ASSEMBLY - REPLACE BONDED MOUNTING							Service ATA:71
	MOS/MSC	07-Jul-04	N/A	TAC 0				
	HRS	0		TAC 0				
	AFL	0		TAC 0				
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00								
AD7120075	NO. 1 ENGINE - AFT ENGINE MOUNT - ISOLATOR ASSEMBLY - PERFORM DETAILED INSPECTION OF AFT ISOLATOR ASSEMBLY AND ASSOCIATED PARTS							Service ATA:71
	MOS/MSC		MPI					
	HRS		3600 (+25/-25)		6614.1 (M)		1158.9	
	AFL							
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00								
AD7120075	NO. 2 ENGINE - AFT ENGINE MOUNT - ISOLATOR ASSEMBLY - PERFORM DETAILED INSPECTION OF AFT ISOLATOR ASSEMBLY AND ASSOCIATED PARTS							Service ATA:71
	MOS/MSC		MPI					
	HRS		3600 (+25/-25)		6614.1 (M)		1158.9	
	AFL							
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00								
K7120004	NO. 1 ENGINE - AFT ENGINE MOUNT - ISOLATOR ASSEMBLY - REPLACE HOUSING							Service ATA:71
PN:LM-833-SA18	MOS	07-Jul-04		TAC 0				LIFE LIMIT
SN:LK0910	HRS	0	15000	TAC 0	15000		9544.8	
	AFL	0		TAC 0				
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00								
K7120004	NO. 1 ENGINE - FORWARD ENGINE MOUNT - LOWER ISOLATOR ASSEMBLY - REPLACE HOUSING							Service ATA:71
	MOS	07-Jul-04		TAC 0				LIFE LIMIT
	HRS	0	15000	TAC 0	15000		9544.8	
	AFL	0		TAC 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00								
K7120004	NO. 1 ENGINE - FORWARD ENGINE MOUNT - UPPER ISOLATOR ASSEMBLY - REPLACE HOUSING							Service ATA:71
	MOS	07-Jul-04		TAC 0				LIFE LIMIT
	HRS	0	15000	TAC 0	15000		9544.8	
	AFL	0		TAC 0				
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00								
K7120004	NO. 2 ENGINE - AFT ENGINE MOUNT - ISOLATOR ASSEMBLY - REPLACE HOUSING							Service ATA:71
PN:LM833-SA18	MOS	07-Jul-04		TAC 0				LIFE LIMIT
SN:LK0895	HRS	0	15000	TAC 0	15000		9544.8	
	AFL	0		TAC 0				
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00								
K7120004	NO. 2 ENGINE - FORWARD ENGINE MOUNT - LOWER ISOLATOR ASSEMBLY - REPLACE HOUSING							Service ATA:71
	MOS	07-Jul-04		TAC 0				LIFE LIMIT
	HRS	0	15000	TAC 0	15000		9544.8	
	AFL	0		TAC 0				
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00								
K7120004	NO. 2 ENGINE - FORWARD ENGINE MOUNT - UPPER ISOLATOR ASSEMBLY - REPLACE HOUSING							Service ATA:71
	MOS	07-Jul-04		TAC 0				LIFE LIMIT
	HRS	0	15000	TAC 0	15000		9544.8	
	AFL	0		TAC 0				
PROC. REF: AMM 71-20-00PROC. REF: AMM 71-20-00								
K7120004 ^U	REPLACE ALL FORWARD AND AFT ENGINE MOUNT ISOLATOR HOUSINGS							Service ATA:71
	MOS	07-Jul-04						LIFE LIMIT
	HRS	0	15000 (+25/-25)		15000	15025	9544.8 (+25)	
	AFL	0						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
P7120001	S	* FORWARD ENGINE MOUNT - PERFORM EDDY CURRENT INSPECTION						Service ATA:71
	MOS	18-Nov-21						AIRWORTHINESS
	HRS	4737	4800					
	AFL	3987						
PROC. REF: NDT PART 6/71-10-01PROC. REF: NDT PART 6/71-10-01								PKG:25
Q7110004		NO. 1 ENGINE INLET - PERFORM TAP TEST						Service ATA:71
	MOS	21-Jul-23						
	HRS	5076.3	3500 (+100/-100)		8576.3	8676.3	3121.1 (+100)	
	AFL	4268						
PROC. REF: AMM 71-10-01PROC. REF: AMM 71-10-01								
Q7110004		NO. 2 ENGINE INLET - PERFORM TAP TEST						Service ATA:71
	MOS	21-Jul-23						
	HRS	5076.3	3500 (+100/-100)		8576.3	8676.3	3121.1 (+100)	
	AFL	4268						
PROC. REF: AMM 71-10-01PROC. REF: AMM 71-10-01								
Q7120002		NO. 1 ENGINE ALL ISOLATORS - PERFORM INSPECTION OF ISOLATORS AND ASSOCIATED PARTS						Service ATA:71
	MOS/MSC	07-Jul-04	N/A					
	HRS	0						
	AFL	0						
Q7120002		NO. 2 ENGINE ALL ISOLATORS - PERFORM INSPECTION OF ISOLATORS AND ASSOCIATED PARTS						Service ATA:71
	MOS/MSC	07-Jul-04	N/A					
	HRS	0						
	AFL	0						
R7100032		LEFT ENGINE NACELLE TUBES - PERFORM DETAILED VISUAL INSPECTION						Service ATA:71
	MOS/MSC	14-Apr-10	N/A					NOT APPLICABLE
	HRS	2077.5						
	AFL	1715						
PROC. REF: AMM 71-10-03PROC. REF: AMM 71-10-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
Y7100002	^S	LOWER ENGINE COWLING - VISUALLY INSPECT LATCH CHANNELS FOR CHAFING						Service ATA:71
	MOS	09-Jul-24	24 (+14d/-14d)					
	HRS	5131.8	600 (+25/-25)					
	AFL	4323						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								PKG:9
Y7110000	^S	ENGINE NACELLE - PERFORM VISUAL INSPECTION. INSPECT INLET BULKHEAD, STRUCTURE, PLUMBING, SKIN SPOT WELDS, ANTI-ICE OUTLET SCREEN, AND FASTENERS FOR SECURITY, CRACKS, AND GENERAL CONDITION.						Service ATA:71
	MOS	09-Jul-24	24 (+14d/-14d)					
	HRS	5131.8	600 (+25/-25)					
	AFL	4323						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								PKG:9
Y7110001	^S	ENGINE INLET LIP AND DUCT - PERFORM VISUAL INSPECTION						Service ATA:71
	MOS	09-Jul-24	24 (+14d/-14d)					
	HRS	5131.8	600 (+25/-25)					
	AFL	4323						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								PKG:9
Y7110002	^S	ENGINE STARTER/GENERATOR INLET AND EXHAUST DUCT AND SEALS - PERFORM VISUAL INSPECTION						Service ATA:71
	MOS	09-Jul-24	24 (+14d/-14d)					
	HRS	5131.8	600 (+25/-25)					
	AFL	4323						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								PKG:9
Y7110003	^S	ENGINE ALTERNATOR EXHAUST DUCT AND SEALS - PERFORM VISUAL INSPECTION						Service ATA:71
	MOS	09-Jul-24	24 (+14d/-14d)					
	HRS	5131.8	600 (+25/-25)					
	AFL	4323						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								PKG:9

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
Y7120000	^S	FORWARD ENGINE MOUNTS - PERFORM VISUAL INSPECTION						Service ATA:71
	MOS	31-Jul-25	12 (+14d/-14d)					
	HRS	5307.6	300 (+25/-25)					
	AFL	4448						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								PKG:3
ATA 72 - ENGINE								
72-AS-720005		NO. 1 ENGINE - INSPECT MAJOR PERIODIC PER MANUFACTURERS INSTRUCTIONS						Service ATA:72
	MOS	27-Aug-13						
	HRS	3014.1	3500 (+100)		(6514.1) 6514.1	6614.1	1058.9 (+100)	
	ENC	2498						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								
72-AS-720005		NO. 2 ENGINE - INSPECT MAJOR PERIODIC PER MANUFACTURERS INSTRUCTIONS						Service ATA:72
	MOS	27-Aug-13						
	HRS	3014.1	3500 (+100)		(6514.1) 6514.1	6614.1	1058.9 (+100)	
	ENC	2498						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								
72-AS-720006	^S	NO. 1 ENGINE - INSPECT COMB CHAMBER PLENUM CASE INSP PER MANUFACTURERS INSTRUCTIONS						Service ATA:72
	MOS	27-Aug-13						
	HRS	3014.1	3500 (+100/-100)					
	ENC	2498						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
72-AS-720006	^S	NO. 2 ENGINE - INSPECT COMB CHAMBER PLENUM CASE INSP PER MANUFACTURERS INSTRUCTIONS						Service ATA:72
	MOS	27-Aug-13						
	HRS	3014.1	3500 (+100/-100)					
	ENC	2498						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-AS-720007	NO. 1 ENGINE - INSPECT COMPRESSOR ZONE PER MANUFACTURERS INSTRUCTIONS							Service ATA:72
	MOS	22-Aug-13						
	HRS	3014.1	7000 (+200)		(10014.1) 10014.1	10214.1	4558.9 (+200)	
	ENC	2498						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								
72-AS-720007	NO. 2 ENGINE - INSPECT COMPRESSOR ZONE PER MANUFACTURERS INSTRUCTIONS							Service ATA:72
	MOS	22-Aug-13						
	HRS	3014.1	7000 (+200)		(10014.1) 10014.1	10214.1	4558.9 (+200)	
	ENC	2498						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								
72-AS-720008 ^S	NO. 1 ENGINE - INSPECT AGB PER MANUFACTURERS INSTRUCTIONS							Service ATA:72
	MOS	13-May-04						
	HRS	0	7000 (+200/-200)					
	ENC	0						
PROC. REF: LMM 72-60-02PROC. REF: LMM 72-60-02								
72-AS-720008 ^S	NO. 2 ENGINE - INSPECT AGB PER MANUFACTURERS INSTRUCTIONS							Service ATA:72
	MOS	13-May-04						
	HRS	0	7000 (+200/-200)					
	ENC	0						
PROC. REF: LMM 72-60-02PROC. REF: LMM 72-60-02								
72-AS-720010	NO. 1 ENGINE - ANALYSIS OIL AND FILTER (BASELINE/SPECIAL REQUIREMENT) (SOAP)							Service ATA:72
	MOS/MSC	09-Sep-04	A/R					
	HRS	16						
	ENC	12						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								
72-AS-720010	NO. 2 ENGINE - ANALYSIS OIL AND FILTER (BASELINE/SPECIAL REQUIREMENT) (SOAP)							Service ATA:72
	MOS/MSC	09-Sep-04	A/R					
	HRS	16						
	ENC	12						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								
72-AS-720011	NO. 1 ENGINE - REPLACE FUEL FILTER ELEMENT (25-HR INITIAL)							Service ATA:72
	MOS/MSC	09-Sep-04	A/R					
	HRS	16						
	ENC	12						
PROC. REF: LMM 73-21-02PROC. REF: LMM 73-21-02								
72-AS-720011	NO. 2 ENGINE - REPLACE FUEL FILTER ELEMENT (25-HR INITIAL)							Service ATA:72
	MOS/MSC	09-Sep-04	A/R					
	HRS	16						
	ENC	12						
PROC. REF: LMM 73-21-02PROC. REF: LMM 73-21-02								
720110	NO. 1 ENGINE - ACCESSORY GEARBOX							Component ATA:72
PN:3060827-2	MOS/MSC	13-May-04	O/C	TSN 0				
SN:S-1588	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: LMM 72-60-02, LMM 72-60-02PROC. REF: LMM 72-60-02, LMM 72-60-02								
720110	NO. 2 ENGINE - ACCESSORY GEARBOX							Component ATA:72
PN:3060827-2	MOS/MSC	13-May-04	O/C	TSN 0				
SN:S-1583	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: LMM 72-60-02, LMM 72-60-02PROC. REF: LMM 72-60-02, LMM 72-60-02								
723010 ^S	NO. 1 ENGINE - CHECK CARBON SEAL HEALTH							Service ATA:72
	MOS	13-May-21						
	HRS	4665.3	1600 (+50/-100)					
	ENC	3922						
PROC. REF: LMM 72-00-00, LMM 72-00-00PROC. REF: LMM 72-00-00, LMM 72-00-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
723010 ^S NO. 2 ENGINE - CHECK CARBON SEAL HEALTH Service ATA:72								
	MOS	13-May-21						
	HRS	4665.3	1600 (+50/-100)					
	ENC	3922						
PROC. REF: LMM 72-00-00, LMM 72-00-00PROC. REF: LMM 72-00-00, LMM 72-00-00								PKG:0
725007 NO. 1 ENGINE - HIGH PRESSURE TURBINE (HPT) NOZZLE ASSEMBLY Component ATA:72								
PN:PN	MOS/MSC	13-May-04	A/R	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 72.500	ENC	0		TSN 0				
PROC. REF: LMM 72-50-07, LMM 72-50-07PROC. REF: LMM 72-50-07, LMM 72-50-07								
725007 NO. 2 ENGINE - HIGH PRESSURE TURBINE (HPT) NOZZLE ASSEMBLY Component ATA:72								
PN:PN	MOS/MSC	13-May-04	A/R	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
WC#: 72.500	ENC	0		TSN 0				
PROC. REF: LMM 72-50-07, LMM 72-50-07PROC. REF: LMM 72-50-07, LMM 72-50-07								
725010 NO. 1 ENGINE - 1ST-STAGE LOW PRESSURE TURBINE (LPT) DISC Component ATA:72								
PN:3060625-1	MOS	22-Aug-13		TSN 111				LIFE LIMIT
SN:030322901987	HRS	3014.1		TSN 3014.1				
	ENC	2498	12000	TSN 2498	(12000) 12000		7455	
PROC. REF: LMM 72-50-04, LMM 72-50-04PROC. REF: LMM 72-50-04, LMM 72-50-04								
725010 NO. 2 ENGINE - 1ST-STAGE LOW PRESSURE TURBINE (LPT) DISC Component ATA:72								
PN:3060625-1	MOS	22-Aug-13		TSN 111				LIFE LIMIT
SN:020322904487	HRS	3014.1		TSN 3014.1				
	ENC	2498	12000	TSN 2498	(12000) 12000		7455	
PROC. REF: LMM 72-50-04, LMM 72-50-04PROC. REF: LMM 72-50-04, LMM 72-50-04								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45
Serial: 45-252
RegNo: N253SC
HRS: 5455.2
AFL: 4545
As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725020	NO. 1 ENGINE - 2ND-STAGE LOW PRESSURE TURBINE (LPT) DISC							Component ATA:72
PN:3060611-1	MOS	22-Aug-13		TSN 111				LIFE LIMIT
SN:03022902126	HRS	3014.1		TSN 3014.1				
	ENC	2498	12000	TSN 2498	(12000) 12000		7455	
PROC. REF: LMM 72-50-04, LMM 72-50-04PROC. REF: LMM 72-50-04, LMM 72-50-04								
725020	NO. 2 ENGINE - 2ND-STAGE LOW PRESSURE TURBINE (LPT) DISC							Component ATA:72
PN:3060611-1	MOS	22-Aug-13		TSN 111				LIFE LIMIT
SN:030322902124	HRS	3014.1		TSN 3014.1				
	ENC	2498	12000	TSN 2498	(12000) 12000		7455	
PROC. REF: LMM 72-50-04, LMM 72-50-04PROC. REF: LMM 72-50-04, LMM 72-50-04								
725030	NO. 1 ENGINE - 3RD-STAGE LOW PRESSURE TURBINE (LPT) DISC							Component ATA:72
PN:3060671-2	MOS	22-Aug-13		TSN 111				LIFE LIMIT
SN:03032902338	HRS	3014.1		TSN 3014.1				
	ENC	2498	12000	TSN 2498	(12000) 12000		7455	
PROC. REF: LMM 72-50-04, LMM 72-50-04PROC. REF: LMM 72-50-04, LMM 72-50-04								
725030	NO. 2 ENGINE - 3RD-STAGE LOW PRESSURE TURBINE (LPT) DISC							Component ATA:72
PN:3060671-2	MOS	22-Aug-13		TSN 111				LIFE LIMIT
SN:030322901447	HRS	3014.1		TSN 3014.1				
	ENC	2498	12000	TSN 2498	(12000) 12000		7455	
PROC. REF: LMM 72-50-04, LMM 72-50-04PROC. REF: LMM 72-50-04, LMM 72-50-04								
725040	NO. 1 ENGINE - HIGH PRESSURE TURBINE (HPT) DISC							Component ATA:72
PN:3060841-1	MOS	22-Aug-13		TSN 111				LIFE LIMIT
SN:031217200634	HRS	3014.1		TSN 3014.1				
	ENC	2498	10000	TSN 2498	(10000) 10000		5455	
PROC. REF: LMM 72-50-07, LMM 72-50-07PROC. REF: LMM 72-50-07, LMM 72-50-07								

?-Insufficient Information
S-Suppressed Requirement
*-Estimated Due(New Requirement)
(EFF)-Effective C/W
(M)-Manual Due
U-User Task
Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725040	NO. 2 ENGINE - HIGH PRESSURE TURBINE (HPT) DISC							Component ATA:72
PN:3060841-1	MOS	22-Aug-13		TSN 111				LIFE LIMIT
SN:031217200665	HRS	3014.1		TSN 3014.1				
	ENC	2498	10000	TSN 2498	(10000) 10000		5455	
PROC. REF: LMM 72-50-07, LMM 72-50-07PROC. REF: LMM 72-50-07, LMM 72-50-07								
725045	NO. 1 ENGINE - HIGH PRESSURE TURBINE (HPT) ASSY							Component ATA:72
PN:PN	MOS/MSC	13-May-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
725045	NO. 2 ENGINE - HIGH PRESSURE TURBINE (HPT) ASSY							Component ATA:72
PN:PN	MOS/MSC	13-May-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
725050	NO. 1 ENGINE - FAN DISC							Component ATA:72
PN:3060287-2	MOS	22-Aug-13		TSN 111				LIFE LIMIT
SN:030322901264	HRS	3014.1		TSN 3014.1				
	ENC	2498	20000	TSN 2498	(20000) 20000		15455	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725050	NO. 2 ENGINE - FAN DISC							Component ATA:72
PN:3060287-2	MOS	22-Aug-13		TSN 111				LIFE LIMIT
SN:030322901261	HRS	3014.1		TSN 3014.1				
	ENC	2498	20000	TSN 2498	(20000) 20000		15455	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45
Serial: 45-252
RegNo: N253SC
HRS: 5455.2
AFL: 4545
As Of: 23-Jul-2026
23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725060	NO. 1 ENGINE - 1ST-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC							Component ATA:72
PN:3060372-1	MOS	22-Aug-13		TSN 111				LIFE LIMIT
SN:030316002489	HRS	3014.1		TSN 3014.1				
	ENC	2498	10000	TSN 2498	(10000) 10000		5455	
PROC. REF: LMM 72-30-04PROC. REF: LMM 72-30-04								
725060	NO. 2 ENGINE - 1ST-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC							Component ATA:72
PN:3060372-1	MOS	22-Aug-13		TSN 111				LIFE LIMIT
SN:30316002475	HRS	3014.1		TSN 3014.1				
	ENC	2498	10000	TSN 2498	(10000) 10000		5455	
PROC. REF: LMM 72-30-04PROC. REF: LMM 72-30-04								
725070	NO. 1 ENGINE - 2ND-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC							Component ATA:72
PN:3060373-1	MOS	22-Aug-13		TSN 111				LIFE LIMIT
SN:040316000062	HRS	3014.1		TSN 3014.1				
	ENC	2498	10000	TSN 2498	(10000) 10000		5455	
PROC. REF: LMM 72-30-04PROC. REF: LMM 72-30-04								
725070	NO. 2 ENGINE - 2ND-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC							Component ATA:72
PN:3060373-1	MOS	22-Aug-13		TSN 111				LIFE LIMIT
SN:040316000064	HRS	3014.1		TSN 3014.1				
	ENC	2498	10000	TSN 2498	(10000) 10000		5455	
PROC. REF: LMM 72-30-04PROC. REF: LMM 72-30-04								
725080	NO. 1 ENGINE - 3RD-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC							Component ATA:72
PN:3060374-1	MOS	22-Aug-13		TSN 111				LIFE LIMIT
SN:030316002951	HRS	3014.1		TSN 3014.1				
	ENC	2498	20000	TSN 2498	(20000) 20000		15455	
PROC. REF: LMM 72-30-04PROC. REF: LMM 72-30-04								

?-Insufficient Information
S-Suppressed Requirement
*-Estimated Due(New Requirement)
(EFF)-Effective C/W
(M)-Manual Due
U-User Task
Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725080	NO. 2 ENGINE - 3RD-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC							Component ATA:72
PN:3060374-1	MOS	22-Aug-13		TSN 111				LIFE LIMIT
SN:030316002960	HRS	3014.1		TSN 3014.1				
	ENC	2498	20000	TSN 2498	(20000) 20000		15455	
PROC. REF: LMM 72-30-04PROC. REF: LMM 72-30-04								
725090	NO. 1 ENGINE - 4TH-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC							Component ATA:72
PN:3075326-5	MOS	22-Aug-13		TSN 111				LIFE LIMIT
SN:041365100318	HRS	3014.1		TSN 3014.1				
	ENC	2498	20000	TSN 2498	(20000) 20000		15455	
PROC. REF: LMM 72-30-04PROC. REF: LMM 72-30-04								
725090	NO. 2 ENGINE - 4TH-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC							Component ATA:72
PN:3075326-5	MOS	22-Aug-13		TSN 111				LIFE LIMIT
SN:041365100320	HRS	3014.1		TSN 3014.1				
	ENC	2498	20000	TSN 2498	(20000) 20000		15455	
PROC. REF: LMM 72-30-04PROC. REF: LMM 72-30-04								
725110	NO. 1 ENGINE - LOW PRESSURE COMPRESSOR TIE ROD							Component ATA:72
PN:3074744-1	MOS/MSC	13-May-04	O/C	TSN 0				
SN:04P05164	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: LMM 72-30-10, LMM 72-30-10PROC. REF: LMM 72-30-10, LMM 72-30-10								
725110	NO. 2 ENGINE - LOW PRESSURE COMPRESSOR TIE ROD							Component ATA:72
PN:3074744-1	MOS/MSC	13-May-04	O/C	TSN 0				
SN:04P05160	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: LMM 72-30-10, LMM 72-30-10PROC. REF: LMM 72-30-10, LMM 72-30-10								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725120	NO. 1 ENGINE - HIGH PRESSURE COMPRESSOR ROTOR IMPELLER							Component ATA:72
PN:3060371-1	MOS	22-Aug-13		TSN 111				LIFE LIMIT
SN:030322901200	HRS	3014.1		TSN 3014.1				
	ENC	2498	8000	TSN 2498	(8000) 8000		3455	
PROC. REF: LMM 72-50-06, LMM 72-50-06PROC. REF: LMM 72-50-06, LMM 72-50-06								
725120	NO. 2 ENGINE - HIGH PRESSURE COMPRESSOR ROTOR IMPELLER							Component ATA:72
PN:3060371-1	MOS	22-Aug-13		TSN 111				LIFE LIMIT
SN:030322902236	HRS	3014.1		TSN 3014.1				
	ENC	2498	8000	TSN 2498	(8000) 8000		3455	
PROC. REF: LMM 72-50-06, LMM 72-50-06PROC. REF: LMM 72-50-06, LMM 72-50-06								
725130	NO. 1 ENGINE - FAN SPINNER							Component ATA:72
PN:3060156-2	MOS	22-Aug-13						LIFE LIMIT
SN:030322901261	HRS	3014.1						
	ENC	2498	20000	TSN 2498	(20000) 20000		15455	
PROC. REF: LMM 72-70-01, LMM 72-70-01PROC. REF: LMM 72-70-01, LMM 72-70-01								
725130	NO. 2 ENGINE - FAN SPINNER							Component ATA:72
PN:3060156-2	MOS	22-Aug-13		TSN 111				LIFE LIMIT
SN:042784300043	HRS	3014.1		TSN 3014.1				
	ENC	2498	20000	TSN 2498	(20000) 20000		15455	
PROC. REF: LMM 72-70-01, LMM 72-70-01PROC. REF: LMM 72-70-01, LMM 72-70-01								
725140	NO. 1 ENGINE - FAN DRIVE SHAFT							Component ATA:72
PN:3060180-2	MOS/MSC	13-May-04	O/C	TSN 0				
SN:021366302837	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C / W	Interval	TSX/Adj.	Next Due (ENG/APU) A / C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725140	NO. 2 ENGINE - FAN DRIVE SHAFT							Component ATA:72
PN:3060180-2	MOS/MSC	13-May-04	O/C	TSN 0				
SN:031366303283	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725160	NO. 1 ENGINE - FORWARD ROTOR HIGH PRESSURE SEAL							Component ATA:72
PN:3060698-1	MOS	22-Aug-13		TSN 111				LIFE LIMIT
SN:040350100751	HRS	3014.1		TSN 3014.1				
	ENC	2498	7000	TSN 2498	(7000) 7000		2455	
PROC. REF: LMM 72-70-03, LMM 72-70-03PROC. REF: LMM 72-70-03, LMM 72-70-03								
725160	NO. 2 ENGINE - FORWARD ROTOR HIGH PRESSURE SEAL							Component ATA:72
PN:3060698-1	MOS	22-Aug-13		TSN 111				LIFE LIMIT
SN:040350100748	HRS	3014.1		TSN 3014.1				
	ENC	2498	7000	TSN 2498	(7000) 7000		2455	
PROC. REF: LMM 72-70-03, LMM 72-70-03PROC. REF: LMM 72-70-03, LMM 72-70-03								
725170	NO. 1 ENGINE - HIGH PRESSURE SHOULDERED SHAFT							Component ATA:72
PN:3060366-3	MOS/MSC	13-May-04	O/C	TSN 0				
SN:04P06035	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725170	NO. 2 ENGINE - HIGH PRESSURE SHOULDERED SHAFT							Component ATA:72
PN:3060366-3	MOS/MSC	13-May-04	O/C	TSN 0				
SN:04P04972	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725180	NO. 1 ENGINE - COMBUSTION PLENUM CASE							Component ATA:72
PN:3060534-4	MOS/MSC	13-May-04	O/C	TSN 0				
SN:04P04362	HRS	0		TSN 0				
	ENC	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45
Serial: 45-252
RegNo: N253SC
HRS: 5455.2
AFL: 4545
As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
PROC. REF: LMM 72-40-04, LMM 72-40-04PROC. REF: LMM 72-40-04, LMM 72-40-04								
725180	NO. 2 ENGINE - COMBUSTION PLENUM CASE							Component ATA:72
PN:3060534-4	MOS/MSC	13-May-04	O/C	TSN 0				
SN:04P04184	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: LMM 72-40-04, LMM 72-40-04PROC. REF: LMM 72-40-04, LMM 72-40-04								
725210	NO. 1 ENGINE - HIGH PRESSURE TURBINE FORWARD SEAL PLATE							Component ATA:72
PN:3060514-1	MOS	22-Aug-13		TSN 111				LIFE LIMIT
SN:020322905218	HRS	3014.1		TSN 3014.1				
	ENC	2498	10000	TSN 2498	(10000) 10000		5455	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725210	NO. 2 ENGINE - HIGH PRESSURE TURBINE FORWARD SEAL PLATE							Component ATA:72
PN:3060514-1	MOS	22-Aug-13		TSN 111				LIFE LIMIT
SN:020322905202	HRS	3014.1		TSN 3014.1				
	ENC	2498	10000	TSN 2498	(10000) 10000		5455	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725220	NO. 1 ENGINE - TURBINE INTERSTAGE TRANSITION DUCT							Component ATA:72
PN:3060694-6	MOS/MSC	13-May-04	O/C	TSN 0				
SN:04P01340	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725220	NO. 2 ENGINE - TURBINE INTERSTAGE TRANSITION DUCT							Component ATA:72
PN:3060694-6	MOS/MSC	13-May-04	O/C	TSN 0				
SN:04P01791	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information
S-Suppressed Requirement
*-Estimated Due(New Requirement)
(EFF)-Effective C/W
(M)-Manual Due
U-User Task
Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725230	NO. 1 ENGINE - LOW PRESSURE TURBINE (LPT) 1 NOZZLE SEAL SUPPORT							Component ATA:72
PN:3060693-1	MOS/MSC	13-May-04	O/C	TSN 0				
SN:04P06012	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: LMM 72-50-04, LMM 72-50-04PROC. REF: LMM 72-50-04, LMM 72-50-04								
725230	NO. 2 ENGINE - LOW PRESSURE TURBINE (LPT) 1 NOZZLE SEAL SUPPORT							Component ATA:72
PN:3060693-1	MOS/MSC	13-May-04	O/C	TSN 0				
SN:04P06013	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: LMM 72-50-04, LMM 72-50-04PROC. REF: LMM 72-50-04, LMM 72-50-04								
725240	NO. 1 ENGINE - LOW PRESSURE TURBINE (LPT) 1 NOZZLE ASSEMBLY							Component ATA:72
PN:3060666-7	MOS/MSC	13-May-04	O/C	TSN 0				
SN:04P07749	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: LMM 72-50-04, LMM 72-50-04PROC. REF: LMM 72-50-04, LMM 72-50-04								
725240	NO. 2 ENGINE - LOW PRESSURE TURBINE (LPT) 1 NOZZLE ASSEMBLY							Component ATA:72
PN:3060666-7	MOS/MSC	13-May-04	O/C	TSN 0				
SN:04P07750	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: LMM 72-50-04, LMM 72-50-04PROC. REF: LMM 72-50-04, LMM 72-50-04								
725250	NO. 1 ENGINE - FORWARD SHAFT HIGH PRESSURE TURBINE (HPT) COUPLING							Component ATA:72
PN:3060502-2	MOS/MSC	13-May-04	O/C	TSN 0				
SN:03P16788	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725250	NO. 2 ENGINE - FORWARD SHAFT HIGH PRESSURE TURBINE (HPT) COUPLING							Component ATA:72
PN:3060502-2	MOS/MSC	13-May-04	O/C	TSN 0				
SN:04P06794	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725260	NO. 1 ENGINE - AFT HIGH PRESSURE TURBINE (HPT) SHAFT COUPLING							Component ATA:72
PN:3060599-2	MOS/MSC	13-May-04	O/C	TSN 0				
SN:04P07279	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725260	NO. 2 ENGINE - AFT HIGH PRESSURE TURBINE (HPT) SHAFT COUPLING							Component ATA:72
PN:3060599-2	MOS/MSC	13-May-04	O/C	TSN 0				
SN:04P07280	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725270	NO. 1 ENGINE - NOZZLE LOW PRESSURE TURBINE (LPT) (A5) SEAL							Component ATA:72
PN:3073765-12	MOS/MSC	13-May-04	O/C	TSN 0				
SN:04P06269	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
725270	NO. 2 ENGINE - NOZZLE LOW PRESSURE TURBINE (LPT) (A5) SEAL							Component ATA:72
PN:3073765-12	MOS/MSC	13-May-04	O/C	TSN 0				
SN:04P06268	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
727006	NO. 1 ENGINE - LOWER FAN DUCT ASSEMBLY							Component ATA:72
PN:PN	MOS/MSC	13-May-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: LMM 72-70-05, LMM 72-70-05PROC. REF: LMM 72-70-05, LMM 72-70-05								
727006	NO. 2 ENGINE - LOWER FAN DUCT ASSEMBLY							Component ATA:72
PN:PN	MOS/MSC	13-May-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: LMM 72-70-05, LMM 72-70-05PROC. REF: LMM 72-70-05, LMM 72-70-05								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
727010 ^S	NO. 1 ENGINE - INSPECT BYPASS STATOR VANE ASSEMBLY.							Service ATA:72
	MOS	06-Sep-19						
	HRS	4261.4	1200 (+100/-200)					
	ENC	3621						
PROC. REF: LMM 72-70-04, LMM 72-70-04, LMM 72-70-04PROC. REF: LMM 72-70-04, LMM 72-70-04, LMM 72-70-04								PKG:0
727010 ^S	NO. 2 ENGINE - INSPECT BYPASS STATOR VANE ASSEMBLY.							Service ATA:72
	MOS	06-Sep-19						
	HRS	4261.4	1200 (+100/-200)					
	ENC	3621						
PROC. REF: LMM 72-70-04, LMM 72-70-04, LMM 72-70-04PROC. REF: LMM 72-70-04, LMM 72-70-04, LMM 72-70-04								PKG:0
ATA 73 - ENGINE FUEL AND CONTROL								
730110	NO. 1 ENGINE - FUEL CONTROL UNIT							Component ATA:73
PN:3070800-37	MOS/MSC	13-May-04	O/C	TSN 0				
SN:17635	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: LMM 73-20-01, LMM 73-20-01PROC. REF: LMM 73-20-01, LMM 73-20-01								
730110	NO. 2 ENGINE - FUEL CONTROL UNIT							Component ATA:73
PN:3070800-37	MOS/MSC	27-Jul-10	O/C	TSO 0				
SN:15267	HRS	2201.2		TSO 0				
	ENC	1808		TSO 0				
PROC. REF: LMM 73-20-01, LMM 73-20-01PROC. REF: LMM 73-20-01, LMM 73-20-01								
730120 ^S	NO. 1 ENGINE - REPLACE FUEL FILTER ELEMENT							Service ATA:73
	MOS	31-Jul-25						
	HRS	5307.6	600					
	ENC	4448						
PROC. REF: LMM 73-21-02, LMM 73-21-02PROC. REF: LMM 73-21-02, LMM 73-21-02								PKG:0

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45
Serial: 45-252
RegNo: N253SC
HRS: 5455.2
AFL: 4545
As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
730120 ^S	NO. 2 ENGINE - REPLACE FUEL FILTER ELEMENT							Service ATA:73
	MOS	31-Jul-25						
	HRS	5307.6	600					
	ENC	4448						
PROC. REF: LMM 73-21-02, LMM 73-21-02PROC. REF: LMM 73-21-02, LMM 73-21-02								PKG:0
731001	NO. 1 ENGINE - MOTIVE FLOW FUEL PUMP ASSEMBLY							Component ATA:73
PN:3060760-4	MOS/MSC	13-May-04	O/C	TSN 0				
SN:1559	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: LMM 73-21-02PROC. REF: LMM 73-21-02								
731001	NO. 2 ENGINE - MOTIVE FLOW FUEL PUMP ASSEMBLY							Component ATA:73
PN:3060760-4	MOS/MSC	13-May-04	O/C	TSN 0				
SN:1558	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: LMM 73-21-02PROC. REF: LMM 73-21-02								
732120 ^S	NO. 1 ENGINE - INSPECT MOTIVE FLOW FUEL PUMP DRIVE SPLINE							Service ATA:73
	MOS	31-Jul-25						
	HRS	5307.6	600 (+50/-100)					
	ENC	4448						
PROC. REF: LMM 72-00-00, LMM 73-21-04PROC. REF: LMM 72-00-00, LMM 73-21-04								PKG:0
732120 ^S	NO. 2 ENGINE - INSPECT MOTIVE FLOW FUEL PUMP DRIVE SPLINE							Service ATA:73
	MOS	31-Jul-25						
	HRS	5307.6	600 (+50/-100)					
	ENC	4448						
PROC. REF: LMM 72-00-00, LMM 73-21-04PROC. REF: LMM 72-00-00, LMM 73-21-04								PKG:0
733001	NO. 1 ENGINE FUEL FLOW TRANSDUCER							Component ATA:73
PN:7600021-1	MOS/MSC	28-Feb-17	O/C	TSN 0				
SN:611428	HRS	3694.5		TSN 0				
	AFL	3069		TSN 0				

?-Insufficient Information
S-Suppressed Requirement
*-Estimated Due(New Requirement)
(EFF)-Effective C/W
(M)-Manual Due
U-User Task
Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 73 - ENGINE FUEL AND CONTROL									
PROC. REF: AMM 73-31-01PROC. REF: AMM 73-31-01									
733002	NO. 2 ENGINE FUEL FLOW TRANSDUCER							Component	ATA:73
PN:7600021-1	MOS/MSC	12-Jan-12	O/C						
SN:517754	HRS	2565.5							
	AFL	2109							
PROC. REF: AMM 73-31-01PROC. REF: AMM 73-31-01									
733013	DUAL FUEL FLOW CONVERTER (DFFC)							Component	ATA:73
PN:6673308500-003	MOS/MSC	07-Jul-04	O/C	TSN 0					
SN:04050856	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 73-31-02PROC. REF: AMM 73-31-02									
733031	LEFT ENGINE FUEL TEMPERATURE BULB							Component	ATA:73
PN:MS28034-3	MOS/MSC	07-Jul-04	O/C	TSN 0					
SN:J5728	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 73-31-03PROC. REF: AMM 73-31-03									
733032	RIGHT ENGINE FUEL TEMPERATURE BULB							Component	ATA:73
PN:MS28034-3	MOS/MSC	07-Jul-04	O/C	TSN 0					
SN:J5733	HRS	0		TSN 0					
	AFL	0		TSN 0					
PROC. REF: AMM 73-31-03PROC. REF: AMM 73-31-03									
ATA 74 - IGNITION									
740140 ^S	NO. 1 ENGINE - REMOVE AND INSPECT 5 O'CLOCK IGNITER PLUG AND LEAD							Service	ATA:74
	MOS	13-May-21							
	HRS	4665.3	1600 (+50/-100)						
	ENC	3922							

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 74 - IGNITION								
740140 ^S	NO. 2 ENGINE - REMOVE AND INSPECT 5 O'CLOCK IGNITER PLUG AND LEAD							Service ATA:74
	MOS	13-May-21						
	HRS	4665.3	1600 (+50/-100)					
	ENC	3922						
								PKG:0
740160 ^S	NO. 1 ENGINE - REMOVE AND INSPECT 7 O'CLOCK IGNITER PLUG AND LEAD							Service ATA:74
	MOS	13-May-21						
	HRS	4665.3	1600 (+50/-100)					
	ENC	3922						
								PKG:0
PROC. REF: LMM 74-00-01PROC. REF: LMM 74-00-01								
740160 ^S	NO. 2 ENGINE - REMOVE AND INSPECT 7 O'CLOCK IGNITER PLUG AND LEAD							Service ATA:74
	MOS	13-May-21						
	HRS	4665.3	1600 (+50/-100)					
	ENC	3922						
								PKG:0
PROC. REF: LMM 74-00-01PROC. REF: LMM 74-00-01								
743001	TAIL CONE RELAY (P13) PANEL							Component ATA:74
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 74-30-01PROC. REF: AMM 74-30-01								
743001-1	EMERGENCY LIGHTING (P-51) RELAY							Component ATA:74
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
743005-1	K22 RELAY							Component ATA:74
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 74 - IGNITION								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
743005-2	K61 RELAY							Component ATA:74
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
ATA 76 - ENGINE CONTROLS								
761013	THROTTLE CONTROL MODULE							Component ATA:76
PN:6676101000-021	MOS/MSC	30-Nov-17	O/C	TSR 0				
SN:364	HRS	3855.5		TSR 0				
	AFL	3218		TSR 0				
PROC. REF: AMM 76-10-02PROC. REF: AMM 76-10-02								
761201	AFT LEFT THROTTLE CABLE							Component ATA:76
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 76-10-01PROC. REF: AMM 76-10-01								
761202	AFT RIGHT THROTTLE CABLE							Component ATA:76
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 76-10-01PROC. REF: AMM 76-10-01								
761203	LEFT FORWARD THROTTLE CABLE							Component ATA:76
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 76-10-01PROC. REF: AMM 76-10-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition
ATA 76 - ENGINE CONTROLS								
761204	RIGHT FORWARD THROTTLE CABLE							Component ATA:76
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 76-10-01PROC. REF: AMM 76-10-01								
761330	NO. 1 ENGINE - ENGINE (DEEC) COMPUTER							Component ATA:76
PN:2118882-1008	MOS/MSC	22-Feb-18	O/C	TSR 0				
SN:120-BH0057	HRS	3903.7		TSR 0				
	ENC	3260		TSR 0				
PROC. REF: LMM 76-10-02, LMM 76-10-02, LMM 76-10-02, LMM 76-10-02PROC. REF: LMM 76-10-02, LMM 76-10-02, LMM 76-10-02, LMM 76-10-02								
761330	NO. 2 ENGINE - ENGINE (DEEC) COMPUTER							Component ATA:76
PN:2118882-1008	MOS/MSC	14-May-14	O/C					
SN:52-AJ0118	HRS	3177.2						
	ENC	2611						
PROC. REF: LMM 76-10-02, LMM 76-10-02, LMM 76-10-02, LMM 76-10-02PROC. REF: LMM 76-10-02, LMM 76-10-02, LMM 76-10-02, LMM 76-10-02								
761330A	NO. 1 ENGINE - DOWNLOAD ENGINE (DEEC) COMPUTER ECTM							Service ATA:76
PN:2118882-1008	MOS	19-Mar-25						CUSTOMER CODE
SN:120-BH0057	HRS	5248	50		(5298) 5298		OVD	
	ENC	4416						
PROC. REF: MSC CAMP EHM ADENDUMPROC. REF: MSC CAMP EHM ADENDUM								
761330A	NO. 2 ENGINE - DOWNLOAD ENGINE (DEEC) COMPUTER ECTM							Service ATA:76
PN:2118882-1008	MOS	19-Mar-25						CUSTOMER CODE
SN:52-AJ0118	HRS	5248	50		(5298) 5298		OVD	
	ENC	4416						
PROC. REF: MSC CAMP EHM ADENDUMPROC. REF: MSC CAMP EHM ADENDUM								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition
ATA 76 - ENGINE CONTROLS								
Y7600000	^S	ENGINE DEEC WIRE HARNESS SHIELD OVERBRAIDS AND SHIELD TERMINATIONS - PERFORM VISUAL INSPECTION						Service ATA:76
	MOS	24-Feb-23	48 (+14d/-14d)					
	HRS	5067.1	1200 (+25/-25)					
	AFL	4262						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								PKG:15
Y7600001	^S	THRUST LEVER CONTROL MODULE - PERFORM FUNCTIONAL TEST						Service ATA:76
	MOS	24-Feb-23	48 (+14d/-14d)					
	HRS	5067.1	1200 (+25/-25)					
	AFL	4262						
PROC. REF: AMM 76-10-02PROC. REF: AMM 76-10-02								PKG:13
Y7610007	^S	ENGINE CONTROL CABLES - PERFORM VISUAL INSPECTION OF FORWARD AND AFT CABLE CONNECTIONS						Service ATA:76
	MOS	24-Feb-23	48 (+14d/-14d)					
	HRS	5067.1	1200 (+25/-25)					
	AFL	4262						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								PKG:14

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 77 - ENGINE INDICATING								
774001	ENGINE VIBRATION MONITOR BOX							Component ATA:77
PN:241-241-000-501	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:AA80444	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 77-41-01PROC. REF: AMM 77-41-01								
774010	P36 RELAY BOX							Component ATA:77
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 77-41-03PROC. REF: AMM 77-41-03								
774011	LEFT ENGINE VIBRATION ACCELEROMETER							Component ATA:77
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 77-41-02PROC. REF: AMM 77-41-02								
774012	RIGHT ENGINE VIBRATION ACCELEROMETER							Component ATA:77
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 77-41-02PROC. REF: AMM 77-41-02								
Y7741000 ^S	ENGINE VIBRATION MONITORING SYSTEM - PERFORM FUNCTIONAL TEST							Service ATA:77
	MOS	01-Mar-19	96 (+14d/-14d)					
	HRS	4123.3	2400 (+25/-25)					
	AFL	3499						
PROC. REF: AMM 77-41-00PROC. REF: AMM 77-41-00								
PKG:21								

ATA 78 - EXHAUST

783001	LEFT LOWER THRUST REVERSER							Component ATA:78
PN:LJ7830101-5	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:A30040276	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 78 - EXHAUST								
PROC. REF: AMM 78-31-00PROC. REF: AMM 78-31-00								
783002	RIGHT LOWER THRUST REVERSER							Component ATA:78
PN:LJ7830101-6	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:A30040276	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 78-31-00PROC. REF: AMM 78-31-00								
783025	TRANSFORMER/RECTIFIER ELECTRONIC CONTROL UNIT							Component ATA:78
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
783037	NO. 1 GPM HYDRAULIC CONTROL VALVE							Component ATA:78
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 78-32-10PROC. REF: AMM 78-32-10								
783038	NO. 2 GPM HYDRAULIC CONTROL VALVE							Component ATA:78
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 78-32-10PROC. REF: AMM 78-32-10								
783051	LEFT OUTBOARD THRUST REVERSER ACTUATOR							Component ATA:78
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 78-32-20PROC. REF: AMM 78-32-20								
783052	LEFT INBOARD THRUST REVERSER ACTUATOR							Component ATA:78
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 78 - EXHAUST								
PROC. REF: AMM 78-32-20PROC. REF: AMM 78-32-20								
783053	RIGHT INBOARD THRUST REVERSER ACTUATOR							Component ATA:78
PN:LJ7833100-3	MOS/MSC	21-Feb-22	O/C	TSO 0				
SN:A30041450	HRS	4819.5		TSO 0				
	AFL	4049		TSO 0				
PROC. REF: AMM 78-32-20PROC. REF: AMM 78-32-20								
783054	RIGHT OUTBOARD THRUST REVERSER ACTUATOR							Component ATA:78
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 78-32-20PROC. REF: AMM 78-32-20								
783061	NO. 1 CONTROL, THRUST REVERSER HYDRAULIC VALVE							Component ATA:78
PN:LJ7835101-7	MOS/MSC	08-May-06	O/C	TSN 0				
SN:0374	HRS	678.3		TSN 0				
	AFL	577		TSN 0				
PROC. REF: AMM 78-32-10PROC. REF: AMM 78-32-10								
783062	NO. 2 CONTROL, THRUST REVERSER HYDRAULIC VALVE							Component ATA:78
PN:LJ7835101-7	MOS/MSC	08-May-06	O/C	TSN 0				
SN:0348	HRS	678.3		TSN 0				
	AFL	577		TSN 0				
PROC. REF: AMM 78-32-10PROC. REF: AMM 78-32-10								
783101	LEFT THRUST REVERSER HYDRAULIC ISOLATION VALVE							Component ATA:78
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 78-30-02PROC. REF: AMM 78-30-02								
783102	RIGHT THRUST REVERSER HYDRAULIC ISOLATION VALVE							Component ATA:78
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45
Serial: 45-252
RegNo: N253SC
HRS: 5455.2
AFL: 4545
As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 78 - EXHAUST								
PROC. REF: AMM 78-30-02PROC. REF: AMM 78-30-02								
783150	LEFT HAND INBOARD LATCHBOX ACTUATOR						Component	ATA:78
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 78-32-30PROC. REF: AMM 78-32-30								
783150A	LEFT HAND OUTBOARD LATCHBOX ACTUATOR						Component	ATA:78
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 78-32-30PROC. REF: AMM 78-32-30								
783151	RIGHT HAND INBOARD LATCHBOX ACTUATOR						Component	ATA:78
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 78-32-30PROC. REF: AMM 78-32-30								
783151A	RIGHT HAND OUTBOARD LATCHBOX ACTUATOR						Component	ATA:78
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 78-32-30PROC. REF: AMM 78-32-30								
783210	LEFT THRUST REVERSER CONTROL VALVE						Component	ATA:78
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
783211	RIGHT THRUST REVERSER CONTROL VALVE						Component	ATA:78
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 78 - EXHAUST								
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								
783220	NO. 1 ENGINE THROTTLE RETARD ACTUATOR							Component ATA:78
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 78-32-40PROC. REF: AMM 78-32-40								
783221	NO. 2 ENGINE THROTTLE RETARD ACTUATOR							Component ATA:78
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 78-32-40PROC. REF: AMM 78-32-40								
783301	LEFT THRUST REVERSER CONTROL BOX							Component ATA:78
PN:6678300000-003	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:OBTE30012	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 78-33-10PROC. REF: AMM 78-33-10								
783302	RIGHT THRUST REVERSER CONTROL BOX							Component ATA:78
PN:6678300000-003	MOS/MSC	01-Mar-13	O/C	TSN 0				
SN:OBTE30865	HRS	2874.7		TSN 0				
	AFL	2375		TSN 0				
PROC. REF: AMM 78-33-10PROC. REF: AMM 78-33-10								
783320	LEFT OUTBOARD THRUST REVERSER WIRE HARNESS							Component ATA:78
PN:PN	MOS/MSC	07-Jul-04	C/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 78-33-20PROC. REF: AMM 78-33-20								
783321	LEFT INBOARD THRUST REVERSER WIRE HARNESS							Component ATA:78
PN:PN	MOS/MSC	07-Jul-04	C/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45
Serial: 45-252
RegNo: N253SC
HRS: 5455.2
AFL: 4545
As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 78 - EXHAUST								
PROC. REF: AMM 78-33-20PROC. REF: AMM 78-33-20								
783322RIGHT INBOARD THRUST REVERSER WIRE HARNESS								Component ATA:78
PN:PN	MOS/MSC	07-Jul-04	C/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 78-33-20PROC. REF: AMM 78-33-20								
783323RIGHT OUTBOARD THRUST REVERSER WIRE HARNESS								Component ATA:78
PN:PN	MOS/MSC	07-Jul-04	C/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 78-33-20PROC. REF: AMM 78-33-20								
D7830078 ^S ** THRUST REVERSER SYSTEM THROTTLE RETARD ACTUATOR - PERFORM OPERATIONAL CHECK								Service ATA:78
	MOS	01-Mar-19	96 (+14d/-14d)					AIRWORTHINESS
	HRS	4123.3	2400 (+25/-25)					
	AFL	3499						
PROC. REF: AMM 78-32-40PROC. REF: AMM 78-32-40								PKG:21
H7830081 ^S THRUST REVERSERS - REMOVE LINK ROD ASSEMBLIES AND PERFORM MAGNETIC PARTICLE INSPECTION								Service ATA:78
	MOS	01-Mar-19	96 (+14d/-14d)					
	HRS	4123.3	2400 (+25/-25)					
	AFL	3499						
PROC. REF: NDT PART 7/78-30-01PROC. REF: NDT PART 7/78-30-01								PKG:21
H7830082 ^S THRUST REVERSERS - REMOVE THRUST REVERSER DOOR ASSEMBLIES AND PERFORM EDDY CURRENT INSPECTION OF PIVOT FITTING AND DOOR HINGES								Service ATA:78
	MOS	01-Mar-19	96 (+14d/-14d)					
	HRS	4123.3	2400 (+25/-25)					
	AFL	3499						
PROC. REF: NDT PART 6/78-30-02, NDT PART 6/78-30-03PROC. REF: NDT PART 6/78-30-02, NDT PART 6/78-30-03								PKG:21

?-Insufficient Information
S-Suppressed Requirement
*-Estimated Due(New Requirement)
(EFF)-Effective C/W
(M)-Manual Due
U-User Task
Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 78 - EXHAUST								
R7830007	THRUST REVERSER - PERFORM CONDUCTIVITY CHECK OF RIGHT THRUST REVERSER DOOR SKIN AND COWL ADJACENT TO APU EXHAUST							Service ATA:78
	MOS	22-Feb-21						
	HRS	4572.6						
	AFL	3864						
	APH	1706.2	1200 (+25/-25)		2906.2	2931.2	919.5 (+25)	
PROC. REF: NDT PART 6/78-30-01PROC. REF: NDT PART 6/78-30-01								
Y7830000 ^S	EXHAUST NOZZLE - PERFORM VISUAL INSPECTION							Service ATA:78
	MOS	01-Mar-19	96 (+14d/-14d)					
	HRS	4123.3	2400 (+25/-25)					
	AFL	3499						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								PKG:21
Y7830001 ^S	THRUST REVERSER INNER FAN DUCT ASSEMBLY - PERFORM VISUAL INSPECTION. INSPECT FROM EXHAUST END ONLY.							Service ATA:78
	MOS	24-Feb-23	48 (+14d/-14d)					
	HRS	5067.1	1200 (+25/-25)					
	AFL	4262						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								PKG:15
Y7830002 ^S	THRUST REVERSER DOOR AND HINGE FITTINGS - PERFORM VISUAL INSPECTION							Service ATA:78
	MOS	24-Feb-23	48 (+14d/-14d)					
	HRS	5067.1	1200 (+25/-25)					
	AFL	4262						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								PKG:15
Y7830003 ^S	THRUST REVERSER PRIMARY ACTUATOR AND LATCH ASSEMBLY - PERFORM VISUAL INSPECTION							Service ATA:78
	MOS	24-Feb-23	48 (+14d/-14d)					
	HRS	5067.1	1200 (+25/-25)					
	AFL	4262						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								PKG:15

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026 23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 78 - EXHAUST								
Y7830004	^S	THRUST REVERSER HYDRAULIC CONTROL VALVE (HCV), THROTTLE RETARD ACTUATOR, AND ASSOCIATED PLUMBING - PERFORM VISUAL INSPECTION						Service ATA:78
	MOS	24-Feb-23	48 (+14d/-14d)					
	HRS	5067.1	1200 (+25/-25)					
	AFL	4262						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								PKG:15
Y7830005	^S	THRUST REVERSER DOOR SEALS AND RETAINERS - PERFORM VISUAL INSPECTION						Service ATA:78
	MOS	24-Feb-23	48 (+14d/-14d)					
	HRS	5067.1	1200 (+25/-25)					
	AFL	4262						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								PKG:15
Y7830006	^S	THRUST REVERSER WIRE HARNESS - PERFORM VISUAL INSPECTION						Service ATA:78
	MOS	24-Feb-23	48 (+14d/-14d)					
	HRS	5067.1	1200 (+25/-25)					
	AFL	4262						
PROC. REF: AMM 05-10-00PROC. REF: AMM 05-10-00								PKG:15
ATA 79 - OIL								
790110		NO. 1 ENGINE - OIL PUMP						Component ATA:79
PN:3060785-3	MOS/MSC	02-May-12	O/C	TSO 0				
SN:001405700183	HRS	2665		TSO 0				
	ENC	2193		TSO 0				
PROC. REF: LMM 79-20-03, LMM 79-20-03PROC. REF: LMM 79-20-03, LMM 79-20-03								
790110		NO. 2 ENGINE - OIL PUMP						Component ATA:79
PN:3060785-2	MOS/MSC	20-Apr-11	O/C	TSO 0				
SN:071405701299	HRS	2381.5		TSO 0				
	ENC	1940		TSO 0				
PROC. REF: LMM 79-20-03, LMM 79-20-03PROC. REF: LMM 79-20-03, LMM 79-20-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 79 - OIL								
790130 ^S	NO. 1 ENGINE - ANALYSIS OIL AND FILTER (SOAP)							Service ATA:79
	MOS	31-Jul-25						
	HRS	5307.6	150 (+100)					
	ENC	4448						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								PKG:0
790130 ^S	NO. 2 ENGINE - ANALYSIS OIL AND FILTER (SOAP)							Service ATA:79
	MOS	31-Jul-25						
	HRS	5307.6	150 (+100)					
	ENC	4448						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								PKG:0
790140 ^S	NO. 1 ENGINE - PERFORM OIL CHANGE							Service ATA:79
	MOS	06-Sep-19						
	HRS	4261.4	1200 (+100/-200)					
	ENC	3621						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								PKG:0
790140 ^S	NO. 2 ENGINE - PERFORM OIL CHANGE							Service ATA:79
	MOS	06-Sep-19						
	HRS	4261.4	1200 (+100/-200)					
	ENC	3621						
PROC. REF: LMM 72-00-00PROC. REF: LMM 72-00-00								PKG:0
790150 ^S	NO. 1 ENGINE - INSPECT CHIP DETECTOR FOR CONTAMINATION AND PERFORM RESISTANCE CHECK							Service ATA:79
	MOS	31-Jul-25						
	HRS	5307.6	600 (+50/-100)					
	ENC	4448						
PROC. REF: LMM 79-10-01PROC. REF: LMM 79-10-01								PKG:0

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition
ATA 79 - OIL								
790150 ^S	NO. 2 ENGINE - INSPECT CHIP DETECTOR FOR CONTAMINATION AND PERFORM RESISTANCE CHECK							Service ATA:79
	MOS	31-Jul-25						
	HRS	5307.6	600 (+50/-100)					
	ENC	4448						
PROC. REF: LMM 79-10-01PROC. REF: LMM 79-10-01								PKG:0
790160 ^S	NO. 1 ENGINE - INSPECT CHIP DETECTOR FOR CONTAMINATION							Service ATA:79
	MOS	31-Jul-25						
	HRS	5307.6	150 (+100)					
	ENC	4448						
PROC. REF: LMM 79-10-01PROC. REF: LMM 79-10-01								PKG:0
790160 ^S	NO. 2 ENGINE - INSPECT CHIP DETECTOR FOR CONTAMINATION							Service ATA:79
	MOS	31-Jul-25						
	HRS	5307.6	150 (+100)					
	ENC	4448						
PROC. REF: LMM 79-10-01PROC. REF: LMM 79-10-01								PKG:0
792008	NO. 1 ENGINE - OIL FLOW REDUCTION VALVE							Component ATA:79
PN:PN	MOS/MSC	13-May-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: LMM 79-20-08, LMM 79-20-08PROC. REF: LMM 79-20-08, LMM 79-20-08								
792008	NO. 2 ENGINE - OIL FLOW REDUCTION VALVE							Component ATA:79
PN:3061156-1	MOS/MSC	06-Jun-12	O/C					
SN:UNKNOWN	HRS	2692.4						
	ENC	2213						
PROC. REF: LMM 79-20-08, LMM 79-20-08PROC. REF: LMM 79-20-08, LMM 79-20-08								
792037	NO. 1 OIL PRESSURE SWITCH							Component ATA:79
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45
Serial: 45-252
RegNo: N253SC
HRS: 5455.2
AFL: 4545
As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 79 - OIL								
PROC. REF: AMM 79-30-02PROC. REF: AMM 79-30-02								
792038	NO. 2 OIL PRESSURE SWITCH							Component ATA:79
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 79-30-02PROC. REF: AMM 79-30-02								
792250	NO. 1 ENGINE - PRESSURE BREATHER VALVE							Component ATA:79
PN:3075323-3	MOS/MSC	22-Aug-13	O/C	TSN 0				
SN:UNKNOWN	HRS	3014.1		TSN 0				
	ENC	2498		TSN 0				
PROC. REF: LMM 79-20-02, LMM 79-20-02PROC. REF: LMM 79-20-02, LMM 79-20-02								
793001	NO. 1 ENGINE OIL PRESSURE TRANSDUCER							Component ATA:79
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 79-30-01PROC. REF: AMM 79-30-01								
793002	NO. 2 ENGINE OIL PRESSURE TRANSDUCER							Component ATA:79
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 79-30-01PROC. REF: AMM 79-30-01								
793011	LEFT TEMPERATURE OIL BULB							Component ATA:79
PN:MS28034-3	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:J5933	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 79-30-03PROC. REF: AMM 79-30-03								
793012	RIGHT TEMPERATURE OIL BULB							Component ATA:79
PN:MS28034-3	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:J5413	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: LEARJET 45 Serial: 45-252 RegNo: N253SC HRS: 5455.2 AFL: 4545 As Of: 23-Jul-2026

23-Jul-2026 11:11 AM

PN & SN	Unit	C / W	Interval	TSX / Adj.	Next Due (ENG / APU) A / C	Max Limit	Remaining	Disposition
ATA 79 - OIL								
PROC. REF: AMM 79-30-03PROC. REF: AMM 79-30-03								
793013	APU TEMPERATURE OIL BULB							Component ATA:79
PN:PN	MOS/MSC	07-Jul-04	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 79-30-03PROC. REF: AMM 79-30-03								
793315 ^S	NO. 1 ENGINE - CHECK OIL FILTER BYPASS VALVE CIRCUIT/THERMAL LOCKOUT SWITCH							Service ATA:79
	MOS	06-Sep-19						
	HRS	4261.4	600 (+50/-100)					
	ENC	3621						
PKG:0								
793315 ^S	NO. 2 ENGINE - CHECK OIL FILTER BYPASS VALVE CIRCUIT/THERMAL LOCKOUT SWITCH							Service ATA:79
	MOS	06-Sep-19						
	HRS	4261.4	600 (+50/-100)					
	ENC	3621						
PKG:0								
ATA 85 - FUEL CELL SYSTEMS								
859000	SUBMIT LOGBOOK ENTRIES FOR ELOGBOOK							Service ATA:85
	MOS/MSC	07-Jul-04	A/R					
	HRS	0						
	AFL	0						
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C / W (M)-Manual Due U-User Task Ex-Excluded Task