



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Program Types

AIRCRAFT	SERIAL/REGNO: 560-0572 / N174JS	MODEL: 560 - CITATION ENCORE	MANUFACTURER: TEXTRON AVIATION INC.
UTILIZATION:	N/A		
OPERATING REGULATION:	N/A		
REGION OF OPERATION:	NORMAL ENVIRONMENT		
OPTIONAL EQUIPMENT:	N/A		
ENGINE NO. 1	SERIAL/PART: PCE-DC0072 / 3041960 -01	MODEL: PW535A	MANUFACTURER: PRATT & WHITNEY CANADA CORP.
UTILIZATION:	N/A		
OPERATING REGULATION:	N/A		
REGION OF OPERATION:	N/A		
OPTIONAL EQUIPMENT:	N/A		
ENGINE NO. 2	SERIAL/PART: PCE-DC0071 / 3041960 -01	MODEL: PW535A	MANUFACTURER: PRATT & WHITNEY CANADA CORP.
UTILIZATION:	N/A		
OPERATING REGULATION:	N/A		
REGION OF OPERATION:	N/A		
OPTIONAL EQUIPMENT:	N/A		

These program types are defined in the OEM manual and can differ from your other settings. These selections will impact the active OEM interval defined on the aircraft status.

As an example,

1. Your aircraft might be EASA registered but you choose to follow the OEM recommended interval for Transport Canada. In that case the operating regulation would be TCCA and can be set to EASA if OEM did not specify intervals for EASA operation.
2. Region of Operation is driven from the OEM manual and the selection between Airframe, Engine and APU can differ since the OEM manual can have requirements dependent on different regions of operation.



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
051255G	INSPECT MAIN SHIP BATTERY GILL	KBOI		7638-44T G03319453	MTH 06-May-2026 HRS 7273.7 LDG 6035		18 1800		30-Nov-2027 9073.7	18 m 22 d 1800
055013	EXPOSURE TO HIGH WINDS WHILE THE AIRCRAFT IS PARKED CHECK				MTH 28-Jun-2001		A/R			
055601 RIGHT	INSPECT WINDSHIELD INSPECTION	KBOI			MTH 11-Mar-2025 HRS 7039.5 LDG 5798		24 300		31-Mar-2027 7339.5	10 m 23 d 65.8
055604 LEFT	INSPECT COCKPIT SIDE WINDOW INSPECTION	KBOI			MTH 11-Mar-2025 HRS 7039.5 LDG 5798		24 300		31-Mar-2027 7339.5	10 m 23 d 65.8
5-12-01 051201	PHASE 1	KBOI			MTH 01-Apr-2025 HRS 7042.1 LDG 5800		24 300		30-Apr-2027 7342.1	11 m 22 d 68.4
5-12-02 051202	PHASE 2	KBOI			MTH 01-Apr-2025 HRS 7042.1 LDG 5800		24 300		30-Apr-2027 7342.1	11 m 22 d 68.4
5-12-03 051203	PHASE 3	KBOI			MTH 01-Apr-2025 HRS 7042.1 LDG 5800		24 300		30-Apr-2027 7342.1	11 m 22 d 68.4
5-12-04 051204	PHASE 4	KBOI			MTH 01-Apr-2025 HRS 7042.1 LDG 5800		24 300		30-Apr-2027 7342.1	11 m 22 d 68.4
5-12-05A 051205 : A	PHASE INSPECTION 5A	KBOI			MTH 27-Jan-2026 HRS 7238.8 LDG 6012		36 1200		31-Jan-2029 8438.8	32 m 23 d 1165.1
5-12-05B 051205 : B	PHASE INSPECTION 5B	KBOI			MTH 27-Jan-2026 HRS 7238.8 LDG 6012		36 1200		31-Jan-2029 8438.8	32 m 23 d 1165.1
5-12-05C 051205 : C	PHASE INSPECTION 5C	KBOI	-	-	MTH 06-May-2026 HRS 7273.7 LDG 6035		36 1200		31-May-2029 8473.7	36 m 23 d 1200
5-12-05D 051205 : D	PHASE INSPECTION 5D	KBOI	-	-	MTH 06-May-2026 HRS 7273.7 LDG 6035		36 1200		31-May-2029 8473.7	36 m 23 d 1200
5-12-05E 051205 : E	PHASE INSPECTION 5E	KBOI			MTH 09-Nov-2023 HRS 6693 LDG 5506		36 1200		30-Nov-2026 7893	6 m 22 d 619.3
5-12-05F 051205 : F	PHASE INSPECTION 5F	KBOI			MTH 09-Nov-2023 HRS 6693 LDG 5506		36 1200		30-Nov-2026 7893	6 m 22 d 619.3
5-12-05G 051205 : G	PHASE INSPECTION 5G	KBOI			MTH 06-Feb-2024 HRS 6773.6 LDG 5563		36 1200		28-Feb-2027 7973.6	9 m 20 d 699.9
5-12-05H 051205 : H	PHASE INSPECTION 5H	KBOI			MTH 06-Feb-2024 HRS 6773.6 LDG 5563		36 1200		28-Feb-2027 7973.6	9 m 20 d 699.9
5-12-05I 051205 : I	PHASE INSPECTION 5I	KBOI			MTH 06-Feb-2024 HRS 6773.6 LDG 5563		36 1200		28-Feb-2027 7973.6	9 m 20 d 699.9
5-12-05J 051205 : J	PHASE INSPECTION 5J	KBOI			MTH 06-Nov-2024 HRS 6982.9 LDG 5748		36 1200		30-Nov-2027 8182.9	18 m 22 d 909.2
5-12-05K 051205 : K	PHASE INSPECTION 5K	KBOI			MTH 13-Jan-2025 HRS 7016.1 LDG 5777		36 1200		31-Jan-2028 8216.1	20 m 23 d 942.4



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
5-12-05L 051205 : L	PHASE INSPECTION 5L	KBOI		MTH 27-Jan-2026 HRS 7238.8 LDG 6012			36 1200		31-Jan-2029 8438.8	32 m 23 d 1165.1
5-12-0B	PHASE B	KBOI		MTH 18-Nov-2025 HRS 7214 LDG 5993			150		7364	90.3
5-12-11 051211	PHASE 11	KBOI		MTH 27-Jan-2026 HRS 7238.8 LDG 6012			6		31-Jul-2026	2 m 23 d
5-12-13 051213	PHASE 13	BOI		MTH 22-Sep-2017 HRS 4990.5 LDG 4153			5000		9990.5	2716.8
5-12-14 051214	PHASE 14	*CF		MTH 28-Jun-2001 HRS 0			12000		12000	4726.3
5-12-15 051215	PHASE 15	*CF		MTH 28-Jun-2001 HRS 0			10000		10000	2726.3
5-12-16 051216	PHASE 16	*CF		MTH 28-Jun-2001 HRS 0			10000		10000	2726.3
5-12-17 051217	PHASE 17	*CF		MTH 28-Jun-2001 HRS 0			10000		10000	2726.3
5-12-18 051218	PHASE 18	KBOI		MTH 27-Jan-2026 HRS 7238.8 LDG 6012			12		31-Jan-2027	8 m 23 d
PHASE 56 SHOULD BE ACCOMPLISHED IN CONJUNCTION WITH THE PHASE 18. PHASE 56 ADDED PER REV 21 TO 560 MM. OCTOBER 2005										
A262003 CABIN 051208	INSPECT/WEIGH PORTABLE HALON FIRE EXTINGUISHER	KBOI		C352 F-75057620	MTH 06-May-2026 HRS 7273.7 LDG 6035		12		31-May-2027	12 m 23 d
Weight Check Date: 06-May-2026										
A262003 COCKPIT 051208	INSPECT/WEIGH PORTABLE HALON FIRE EXTINGUISHER	KBOI		C352 F-75058817	MTH 06-May-2026 HRS 7273.7 LDG 6035		12		31-May-2027	12 m 23 d
Weight Check Date: 06-May-2026										
5-12-20	PHASE 20 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)	KBOI		MTH 11-Mar-2025 HRS 7039.5 LDG 5798			24			
341068 051220 : ADU	CALIBRATION TEST SECONDARY FLIGHT ADU (91.411)	KBOI		MTH 11-Mar-2025 HRS 7039.5 LDG 5798			24		31-Mar-2027	10 m 23 d
Calibration Date: 11-Mar-2025										
A341008 051220	PERFORM STATIC PORT HEIGHT AND SLOPE CHECK (AIRPLANES -0260 AND ON CERTIFIED FOR RVSM)	KBOI		MTH 11-Mar-2025 HRS 7039.5 LDG 5798			24		31-Mar-2027	10 m 23 d
B341010 NO. 1 051220 : ADC	CALIBRATION TEST AIR DATA COMPUTER (FAR 91.411) AIRPLANES -0260 THRU -0643	KBOI		7014700-602 00094080	MTH 11-Mar-2025 HRS 7039.5 LDG 5798		24		31-Mar-2027	10 m 23 d
Calibration Date: 11-Mar-2025										
B341010 NO. 2 051220 : ADC#2	CALIBRATION TEST AIR DATA COMPUTER (FAR 91.411) AIRPLANES -0260 THRU -0643	KBOI		7014700-602 01024716	MTH 11-Mar-2025 HRS 7039.5 LDG 5798		24		31-Mar-2027	10 m 23 d
Calibration Date: 11-Mar-2025										
B345001 NO. 1 051220 : XPDR1	CALIBRATION TEST ATC TRANSPONDER (FAR 91.413)	KBOI		7517400-902 01035057	MTH 11-Mar-2025 HRS 7039.5 LDG 5798		24		31-Mar-2027	10 m 23 d
Calibration Date: 11-Mar-2025										

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
B345001 NO. 2 <i>051220 : XPDR2</i> Calibration Date: 11-Mar-2025	CALIBRATION TEST ATC TRANSPONDER (FAR 91.413)	KBOI		7517400-902 01065520	MTH 11-Mar-2025 HRS 7039.5 LDG 5798		24		31-Mar-2027	10 m 23 d
5-12-21	PHASE 21 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)	KBOI			MTH 13-Jan-2025 HRS 7016.1 LDG 5777		24			
A237003 <i>051221 : CVR</i>	INSPECT CVR UNDERWATER LOCATOR BEACON	KBOI		DK120/90 AT121833	MTH 13-Jan-2025 HRS 7016.1 LDG 5777		24		31-Jan-2027	8 m 23 d
B237004 <i>051221 : CVR</i>	OPERATIONAL TEST CVR UNDERWATER LOCATOR BEACON	KBOI		DK120/90 AT121833	MTH 13-Jan-2025 HRS 7016.1 LDG 5777		24		31-Jan-2027	8 m 23 d
5-12-30 <i>051230</i>	PHASE 30	KBOI			MTH 11-Mar-2025 HRS 7039.5 LDG 5798		600		7639.5	365.8
5-12-32 <i>051232</i>	PHASE 32	*CF			MTH 28-Jun-2001 LDG 0		15000		15000	8965
5-12-33 <i>051233</i>	PHASE 33	*CF			MTH 28-Jun-2001 LDG 0		15000		15000	8965
5-12-34 <i>051234</i>	PHASE 34	KBOI			MTH 09-Nov-2023 HRS 6693 LDG 5506		6725		13418	6144.3
5-12-48	PHASE 48 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)				MTH 28-Jun-2001		72			
B262004 CABIN <i>051248 : A</i>	EMPTY/INSPECT/RECHARGE PORTABLE HALON FIRE EXTINGUISHER	KBOI		C352 F-75057620	MTH 06-May-2026 HRS 7273.7 LDG 6035		72		31-May-2031	60 m 23 d
Inspection Date: 31-May-2025										
B262004 COCKPIT <i>051248 : F</i>	EMPTY/INSPECT/RECHARGE PORTABLE HALON FIRE EXTINGUISHER	KBOI		C352 F-75058817	MTH 06-May-2026 HRS 7273.7 LDG 6035		72		31-May-2031	60 m 23 d
Inspection Date: 31-May-2025										
5-12-49 <i>051249</i>	PHASE 49	KBOI			MTH 16-Jul-2024 HRS 6902.2 LDG 5671		36 1200		31-Jul-2027 8102.2	14 m 23 d 828.5
5-12-51	PHASE 51 (NOT CURRENTLY USED)	BOI			MTH 29-Nov-2011 HRS 3250.9 LDG 2704		N/R			
5-12-54	PHASE 54	KBOI			MTH 27-Jan-2026 HRS 7238.8 LDG 6012		12 600		31-Jan-2027 7838.8	8 m 23 d 565.1
5-12-56 <i>051256</i>	PHASE 56	KBOI			MTH 01-Dec-2025 HRS 7220.7 LDG 5998		12		31-Dec-2026	7 m 23 d
5-12-59	PHASE 59 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)	BOI			MTH 07-May-2014 HRS 3941.6 LDG 3291		A/R			



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
A561004 RIGHT INBOARD	PERFORM CO-PILOTS INNER WINDOW COPILOT SIDE WINDOW INSPECTION	BOI		5511285-6 SN-UNKNOWN	MTH 07-May-2014 HRS 3941.6 LDG 3291		A/R			
A561004 RIGHT OUTBOARD	PERFORM CO-PILOTS OUTER WINDOW COPILOT'S SIDE WINDOW INSPECTION	BOI		PAS5511285-78 18578	MTH 07-May-2014 HRS 3941.6 LDG 3291		A/R			
5-12-60	PHASE 60	KBOI			MTH 06-May-2026 HRS 7273.7 LDG 6035		500		7773.7	500
5-12-61	PHASE 61				MTH 28-Jun-2001 HRS 0		13200		13200	5926.3
5-12-62	PHASE 62				MTH 28-Jun-2001 HRS 0		15600		15600	8326.3
5-12-63	PHASE 63				MTH 28-Jun-2001 HRS 0		15600		15600	8326.3
5-12-64 051264	PHASE 64	KBOI			MTH 27-Jan-2026 HRS 7238.8 LDG 6012		6		31-Jul-2026	2 m 23 d
5-12-65	PHASE 65	KBOI			MTH 13-Sep-2024 HRS 6939.2 LDG 5702 ACH 496.7		500		996.7	470.7
5-12-66	PHASE 66	BOI			MTH 15-Jun-2016 HRS 4632.7 LDG 3869 ACH 365.5		6000		10632.7	3359
5-12-67	PHASE 67				MTH HRS		10000		10000	2726.3
5-12-68	PHASE 68	KBOI			MTH 11-Oct-2022 HRS 6300.3 LDG 5199		1200		7500.3	226.6
5-12-MA 0512MA	PHASE MA	KBOI			MTH 06-Oct-2025 HRS 7161.9 LDG 5940		150		7311.9	38.2
5-12-MC 0512MC	PHASE MC	KBOI			MTH 21-Mar-2024 HRS 6806 LDG 5590		1456		8262	988.3
5-12-MD 0512MD	PHASE MD	KBOI			MTH 19-Nov-2021 HRS 6081.6 LDG 5027		2523		8604.6	1330.9
5-12-ME 0512ME	PHASE ME	B01			MTH 06-Jun-2016 HRS 4627.4 LDG 3864 ACH 365.5		4450		9077.4	1803.7
5-12-MF 0512MF	PHASE MF	KBOI			MTH 19-Nov-2021 HRS 6081.6 LDG 5027		5000		11081.6	3807.9
5-12-MG	PHASE MG (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)				MTH 28-Jun-2001 LDG 0		10000			
A325009 0512MG	INSPECT NOSE GEAR FORK/PISTON NOSE LANDING GEAR FORK	*CF		6642000-3 SN-UNKNOWN	MTH 28-Jun-2001 LDG 0		10000		10000	3965



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
5-12-MI <i>0512MI</i>	PHASE MI	KBOI		MTH HRS LDG	26-May-2022 6208.8 5124		5130		11338.8	4065.1
5-12-MJ <i>0512MJ</i>	PHASE MJ	KBOI		MTH HRS LDG	20-Nov-2020 5883 4868		5900		11783	4509.3
5-12-MK <i>0512MK</i>	PHASE MK	KBOI		MTH HRS LDG	09-Nov-2023 6693 5506		6725		13418	6144.3
5-12-ML	PHASE ML	KBOI		MTH HRS LDG	11-Mar-2025 7039.5 5798		300		7339.5	65.8
5-12-MN	PHASE MN	KBOI		MTH HRS LDG	04-Sep-2025 7126.8 5910		24		30-Sep-2027	16 m 22 d
790040 E1	INSTALL NEW OIL FILTER	KBOI		MTH HRS LDG	01-Apr-2025 7042.1 5800		24 900		30-Apr-2027 7942.1	11 m 22 d 668.4
790040 E2	INSTALL NEW OIL FILTER	KBOI		MTH HRS LDG	01-Apr-2025 7042.1 5800		24 900		30-Apr-2027 7942.1	11 m 22 d 668.4
051254 E1	MINOR INSPECTION	KBOI		MTH HRS LDG	06-May-2026 7273.7 6035		12 600		31-May-2027 7873.7	12 m 23 d 600
051254 E2	MINOR INSPECTION	KBOI		MTH HRS LDG	06-May-2026 7273.7 6035		12 600		31-May-2027 7873.7	12 m 23 d 600
12-26-00-601	15 DAY HIGH EXPOSURE AREAS - AIRPLANE ZONE 1 WASH			DAYS	28-Jun-2001		A/R			
12-26-00-602	45 DAY MEDIUM EXPOSURE AREAS - AIRPLANE ZONE 2 WASH			DAYS	28-Jun-2001		A/R			
12-26-00-603	90 DAY LOW EXPOSURE AREAS - AIRPLANE ZONE 3 WASH			DAYS	28-Jun-2001		A/R			
215012	REPLACE MOTOR COMPRESSOR DRIVE MOTOR BRUSHES (COMPRESSOR MOTORS P/N 1134104-1, -5 OR FWA1134104-1, -5 ONLY)	KBOI		1134104-1 2383	MTH HRS LDG ACH	13-Sep-2024 6939.2 5702 496.7	500		996.7	470.7
256011	RECERTIFICATION ALL LIFEVESTS	KBOI		MTH HRS LDG	27-Jul-2021 6020.4 4975		60		31-Jul-2026	2 m 23 d
26-22-00-782 CABIN <i>051247 : A</i>	CABIN MOUNTED HALON-TYPE FIRE EXTINGUISHER - HYDROSTATIC TEST	KBOI		C352 F-75057620	MTH HRS LDG	06-May-2026 7273.7 6035	144		31-Jan-2031	56 m 23 d
26-22-00-782 COCKPIT <i>051247 : F</i>	COCKPIT MOUNTED HALON-TYPE FIRE EXTINGUISHER - HYDROSTATIC TEST	KBOI		C352 F-75058817	MTH HRS LDG	06-May-2026 7273.7 6035	144		31-Jan-2031	56 m 23 d
26-22-00-783 AFT <i>051223 : A</i>	AFT ENGINE FIRE EXTINGUISHER CONTAINER - HYDROSTATIC TEST	KBOI		30401102 46215B1	MTH HRS LDG	06-May-2026 7273.7 6035	60		31-May-2031	60 m 23 d

Hydro Check Date: 04-May-2026



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
26-22-00-783 FORWARD <i>051223 : F</i>	FORWARD ENGINE FIRE EXTINGUISHER CONTAINER - HYDROSTATIC TEST	KBOI		30401102 46221B1	MTH 06-May-2026 HRS 7273.7 LDG 6035		60		31-May-2031	60 m 23 d
Hydro Check Date: 04-May-2026										
263005 FORWARD LEFT <i>262003 : FL</i>	REPLACE FORWARD LEFT (SERVICE LIFE) CARTRIDGE	BOI		AE13083-5 A493	MTH 21-Oct-2022 HRS 6308.2 LDG 5208		120	1	30-Sep-2032	76 m 22 d
263007 FORWARD RIGHT <i>262003 : FR</i>	REPLACE FORWARD RIGHT (SERVICE LIFE) CARTRIDGE	BOI		AE13083-5 A482	MTH 21-Oct-2022 HRS 6308.2 LDG 5208		120	1	30-Sep-2032	76 m 22 d
263009 AFT LEFT <i>262003 : AL</i>	REPLACE AFT LEFT (SERVICE LIFE) CARTRIDGE	BOI		AE13083-5 A485	MTH 21-Oct-2022 HRS 6308.2 LDG 5208		120	1	30-Sep-2032	76 m 22 d
263011 AFT RIGHT <i>262003 : AR</i>	REPLACE AFT RIGHT (SERVICE LIFE) CARTRIDGE	BOI		AE13083-5 A489	MTH 21-Oct-2022 HRS 6308.2 LDG 5208		120	1	30-Sep-2032	76 m 22 d
28-00-02-220	MICROBIOLOGICAL CONTAMINATION INSPECTION (AIRPLANES NOT USING THE BIOCIDAL PREVENTATIVE TREATMENT)									
					MTH 28-Jun-2001		A/R			
28-00-02-221	MICROBIOLOGICAL CONTAMINATION INSPECTION (AIRPLANES USING THE BIOCIDAL PREVENTATIVE TREATMENT)									
					MTH 28-Jun-2001		A/R			
32-31-09-280 <i>051222 : GEAR</i>	PNEUMATIC (NITROGEN) STORAGE BOTTLE - HYDROSTATIC TEST	KBOI		212940-2 12483	MTH 21-Aug-2025 HRS 7123 LDG 5904		36		30-Jun-2028	25 m 22 d
Hydro Check Date: 02-Jun-2025										
324201 LEFT	NON DESTRUCTIVE TEST MLG WHEEL ASSEMBLY	KBOI		3-1607-1 2063	MTH 01-Jul-2025 HRS 7088 LDG 5860		T/C			
324201 RIGHT	NON DESTRUCTIVE TEST MLG WHEEL ASSEMBLY	KBOI		3-1607 0058	MTH 11-Mar-2025 HRS 7039.5 LDG 5798		T/C			
324202	NON DESTRUCTIVE TEST NOSE WHEEL ASSEMBLY	KBOI		3-1418 5225	MTH 14-Apr-2026 HRS 7270 LDG 6033		T/C			
350004 <i>051222 : OXY</i>	HYDROSTATIC TEST OXYGEN CYLINDER	KBOI		176176-64 1161477001	MTH 01-Aug-2025 HRS 7114.8 LDG 5894		36		31-Jul-2028	26 m 23 d
Hydro Check Date: 30-Jul-2025										
710010 E1	COMPRESSOR DESALINATION WASH	KBOI			MTH 07-May-2021 HRS 5940.4 LDG 4907		A/R			
710010 E2	COMPRESSOR DESALINATION WASH	KBOI			MTH 07-May-2021 HRS 5940.4 LDG 4907		A/R			
710015 E1	PERFORM RECOVERY WASH				MTH		A/R			



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
710015 E2	PERFORM RECOVERY WASH			MTH			A/R			
710050 E1	DO A FIVE POINT PERFORMANCE UNCAPPED CALIBRATION RUN	KBOI		MTH HRS LDG	06-May-2026 7273.7 6035		12 600		31-May-2027 7873.7	12 m 23 d 600
710050 E2	DO A FIVE POINT PERFORMANCE UNCAPPED CALIBRATION RUN	KBOI		MTH HRS LDG	06-May-2026 7273.7 6035		12 600		31-May-2027 7873.7	12 m 23 d 600
710060 E1 <i>057106 : E1**L</i>	DISCONNECT EACH WIRING HARNESS CONNECTOR, CLEAN, INSPECT, RECONNECT AND PERFORM ENGINE CHECKS REQUIRED FOLLOWING WIRING HARNESS REPLACEMENT	KBOI		MTH HRS LDG	21-Mar-2024 6806 5590		900		7706	432.3
710060 E2 <i>057106 : E2**R</i>	DISCONNECT EACH WIRING HARNESS CONNECTOR, CLEAN, INSPECT, RECONNECT AND PERFORM ENGINE CHECKS REQUIRED FOLLOWING WIRING HARNESS REPLACEMENT	KBOI		MTH HRS LDG	21-Mar-2024 6806 5590		900		7706	432.3
720010 E1 <i>710001 : E1**L</i>	OVERHAUL ENGINE	UNK		MTH HRS LDG	14-Jul-2017 4930.9 4107		5000		9930.9	2657.2
720010 E2 <i>710001 : E2**R</i>	OVERHAUL ENGINE	UNK		MTH HRS LDG	12-Jul-2017 4930.9 4107		5000		9930.9	2657.2
720020 E1 <i>057120 : E1**L</i>	INSPECTION LOW UTILIZATION	UNK		MTH HRS LDG	14-Jul-2017 4930.9 4107		120		31-Jul-2027	14 m 23 d
720020 E2 <i>057120 : E2**R</i>	INSPECTION LOW UTILIZATION	UNK		MTH HRS LDG	12-Jul-2017 4930.9 4107		120		31-Jul-2027	14 m 23 d
720060 E1 <i>051225A : E1**L</i>	HOT SECTION INSPECTION	UNK		MTH HRS LDG	16-Mar-2026 7251.1 6021		2500		9751.1	2477.4
720060 E2 <i>051225A : E2**R</i>	HOT SECTION INSPECTION	UNK		MTH HRS LDG	16-Mar-2026 7251.1 6021		2500		9751.1	2477.4
720075 E1	LP COMPRESSOR SHAFT - DISCARD AT SCHEDULED OVERHAUL			PN SN-UNKNOWN MTH	28-Jun-2001		A/R			
720075 E2	LP COMPRESSOR SHAFT - DISCARD AT SCHEDULED OVERHAUL			PN SN-UNKNOWN MTH	28-Jun-2001		A/R			
720080 E1	DISCARD HP TURBINE NUT AND KEYWASHER			MTH HRS			5000		9930.9	2657.2
720080 E2	DISCARD HP TURBINE NUT AND KEYWASHER			MTH HRS			5000		9930.9	2657.2
724050 E1	DISCARD HIGH PRESSURE TURBINE BLADES	UNK		MTH HRS LDG	14-Jul-2017 4930.9 4107		-			
724050 E2	DISCARD HIGH PRESSURE TURBINE BLADES	UNK		MTH HRS LDG	12-Jul-2017 4930.9 4107		-			
725060 E1	DISCARD TURBINE SUPPORT CASE			MTH LDG	28-Jun-2001 23		12200		12223	6188



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
725060 E2	DISCARD TURBINE SUPPORT CASE			MTH LDG	28-Jun-2001 23		12200		12223	6188
731030 E1	INSTALL NEW FUEL FILTER	KBOI		MTH HRS LDG	01-Apr-2025 7042.1 5800		24 900		30-Apr-2027 7942.1	11 m 22 d 668.4
<i>052803 : E1**L</i>										
731030 E2	INSTALL NEW FUEL FILTER	KBOI		MTH HRS LDG	01-Apr-2025 7042.1 5800		24 900		30-Apr-2027 7942.1	11 m 22 d 668.4
<i>052803 : E2**R</i>										
731100 E1	INSPECT EMERGENCY FUEL SHUTOFF LEVER AND CABLE	KBOI		MTH HRS LDG	01-Apr-2025 7042.1 5800		24 900		30-Apr-2027 7942.1	11 m 22 d 668.4
<i>052805 : E1**L</i>										
731100 E2	INSPECT EMERGENCY FUEL SHUTOFF LEVER AND CABLE	KBOI		MTH HRS LDG	01-Apr-2025 7042.1 5800		24 900		30-Apr-2027 7942.1	11 m 22 d 668.4
<i>052805 : E2**R</i>										
731120 E1	REPLACE FUEL MANIFOLD ASSEMBLY //INSPECT WITH BOROSCOPE FUEL MANIFOLD	BOI		PN SN-UNKNOWN	MTH HRS LDG		N/A			
<i>052807 : E1**L</i>					26-May-2016 4639.8 3875					
731120 E2	REPLACE FUEL MANIFOLD ASSEMBLY //INSPECT WITH BOROSCOPE FUEL MANIFOLD	BOI		PN SN-UNKNOWN	MTH HRS LDG		N/A			
<i>052807 : E2**R</i>					26-May-2016 4639.8 3875					
731150 E1	OVERHAUL OR REFURBISH FLOW DIVIDER FLOW DIVIDER			MTH HRS			5000		9930.9	2657.2
				823660-02 F64796						
731150 E2	OVERHAUL OR REFURBISH FLOW DIVIDER FLOW DIVIDER			MTH HRS			5000		9930.9	2657.2
				823660-02 F51268						
731200 E1	OVERHAUL/REFURBISH FUEL NOZZLES	UNK		MTH HRS LDG	16-Mar-2026 7251.1 6021		5000		12251.1	4977.4
731200 E2	OVERHAUL/REFURBISH FUEL NOZZLES	UNK		MTH HRS LDG	16-Mar-2026 7251.1 6021		5000		12251.1	4977.4
732150 E1	OVERHAUL - FUEL CONTROL UNIT AND PUMP			MTH HRS LDG	12-Aug-2021 6024.5 4981		5000	352	10672.5	3398.8
				1012633-49 F59723						
732150 E2	OVERHAUL - FUEL CONTROL UNIT AND PUMP			MTH HRS LDG	12-Aug-2021 6024.5 4981		5000	1342.7	9681.8	2408.1
				1012633-49 F84727						
750100 E1	OVERHAUL OR REFURBISH ANTI-ICING VALVE			MTH HRS			5000		9930.9	2657.2
750100 E2	OVERHAUL OR REFURBISH ANTI-ICING VALVE			MTH HRS			5000		9930.9	2657.2
751030 E1	REPLACE INTERCOMPRESSORBLEEDVALVE SERVOVALVE	UNK		MTH HRS LDG	14-Jul-2017 4930.9 4107		-			



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLOTT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
751030 E2	REPLACE INTERCOMPRESSORBLEEDVALVE SERVOVALVE	UNK			MTH 12-Jul-2017 HRS 4930.9 LDG 4107		-			
790020 E1	CHANGE OIL	BOI			MTH 15-Mar-2013 HRS 3677.6 LDG 3078		A/R			
790020 E2	CHANGE OIL	BOI			MTH 23-Jan-2013 HRS 3617.1 LDG 3030		A/R			
790050 E1	PERFORM ENGINE OIL ANALYSIS	KBOI			MTH 26-Jan-2026 HRS 7238.8 LDG 6012		6 250		26-Jul-2026 7488.8	2 m 18 d 215.1
790050 E2	PERFORM ENGINE OIL ANALYSIS	KBOI			MTH 27-Jan-2026 HRS 7238.8 LDG 6012		6 250		27-Jul-2026 7488.8	2 m 19 d 215.1
790060 E1	FUEL TO OIL HEAT EXCHANGER - OVERHAUL OR REFURBISH	UNK			MTH 14-Jul-2017 HRS 4930.9 LDG 4107		5000		9930.9	2657.2
790060 E2	FUEL TO OIL HEAT EXCHANGER - OVERHAUL OR REFURBISH				MTH HRS		5000		9930.9	2657.2

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
211002	EMERGENCY PRESSURE VALVE	BOI		4713-19 0053	MTH 06-Mar-2004 HRS 942		O/C	0		
212004	OVERHEAD CABIN FAN	KBOI		9912323-2 (BC61A-901-2) 1139A	MTH 13-Jan-2025 HRS 7016.1 LDG 5777		1000	0	8016.1	742.4
212006	COCKPIT DEFOGGER FAN	KBOI		5703-4 259	MTH 13-Sep-2024 HRS 6939.2 LDG 5702		3500	0	10439.2	3165.5
212009	FLOW DIVIDER CABIN UNDERFLOOR ACTUATOR	*CF		NYLC50466-2 1734	MTH 28-Jun-2001		O/C			
212011	TEMP DUCT SENSOR	*CF		27221274 6AT243	MTH 28-Jun-2001		O/C			
213005 NO. 1	MASS FLOW CONTROL VALVE	KBOI		1H124-12 8AY35	MTH 25-Apr-2023 HRS 6500.5 LDG 5359		O/C			
213005 NO. 2	MASS FLOW CONTROL VALVE	BOI		1H124-12 5BA11	MTH 27-Mar-2012 HRS 3317.7 LDG 2774		O/C			
213006	CABIN ALTITUDE CONTROLLER	KBOI	G	52770-116 1875	MTH 26-Sep-2024 HRS 6944.6 LDG 5706		O/C			
213007 NO. 1	PRIMARY OUTFLOW VALVE	BOI		52771-318 K868	MTH 24-Oct-2002 HRS 582		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
213007 NO. 2	SECONDARY OUTFLOW VALVE 9912409-8	*CF		52772-112 879	MTH 28-Jun-2001		O/C			
213008	MANUAL TOGGLE VALVE 9912409-4	*CF	A	52773-001 1046	MTH 28-Jun-2001		O/C			
215001	ACM REFRIGERATOR PACKAGE ASSEMBLY *CF			782343-5 200103019	MTH 28-Jun-2001		O/C			
215004	AIR CYCLE MACHINE BOI			738384-26 9812072	MTH 09-Oct-2017 HRS 5009.1 LDG 4171		5000	0	10009.1	2735.4
RECOMMENDED ECONOMIC OVERHAUL PERIOD DEFINED BY HAMILTON STANDARD.										
215005	ACM BYPASS VALVE *CF			754751-2 SN-UNKNOWN	MTH 28-Jun-2001		O/C			
215008	DUCT OVERHEAT SENSOR *CF			1173T42-1 2967	MTH 28-Jun-2001		O/C			
215009 NO. 1	ACM OVERHEAT SWITCH 410 BOI			1173T0635 N/A	MTH 12-May-2014 HRS 3944.3 LDG 3294		O/C	0 0		
215016	AC COMPRESSOR KBOI			1134160 11832	MTH 13-Sep-2024 HRS 6939.2 LDG 5702		O/C			
215017	AC CONDENSER 9912459-1	*CF		1134400-17 537	MTH 28-Jun-2001		O/C			
215021	MOTOR *CF			1134104-1 2383	MTH 28-Jun-2001		O/C			
215022	AFT EVAPORATOR BOI			1134240-3 732	MTH 12-May-2003 HRS 747		O/C	0		
215023	FWD EVAPORATOR *CF			1134240-2 584	MTH 28-Jun-2001		O/C			
215024	PRESSURE SWITCH *CF			1250232-4 4992	MTH 28-Jun-2001		O/C			
215025	BAROMETRIC SWITCH *CF			GBC300-82 0110344	MTH 28-Jun-2001		O/C			
216001	CABIN TEMPERATURE SENSOR *CF			1942T100-11 796	MTH 28-Jun-2001		O/C			
216002	CABIN TEMPERATURE CONTROLLER 9912069-22 BOI			754661-5 99034812	MTH 25-Sep-2019 HRS 5569.2 LDG 4645		O/C			
216003	DUCT TEMPERATURE SENSOR 9912069-14 *CF			754691-3 00124558	MTH 28-Jun-2001		O/C			
216010	DOOR ACTUATOR MOTOR ASSEMBLY 9910059-3 *CF			5A3032 SN-UNKNOWN	MTH 28-Jun-2001		O/C			
217001	WATER SEPARATOR 9912069-13 *CF			738386-3 200101177	MTH 28-Jun-2001		O/C			
221009	AUTOPILOT CONTROL PC-400 *CF		A	7003897-923 01012229	MTH 28-Jun-2001		O/C			
221010 AILERON	SERVO SM-200 BOI			4006719-906 04048429	MTH 01-Apr-2015 HRS 4222.5 LDG 3533		O/C	0 0		
221010 ELEVATOR	SERVO SM-200 KBOI			4006719-904 00013471	MTH 29-Apr-2022 HRS 6178.8 LDG 5102		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
221010 RUDDER	SERVO SM-200	*CF		4006719-906 00124852	MTH 28-Jun-2001		O/C			
231003	KTR953 HF RECEIVER/EXCITER KTR-953	ICT		064-01015-0001 31703	MTH 08-Dec-2001 HRS 159		O/C	264		
231004 NO. 2	COUPLER-POWER AMP -- ICT			064-01017-0001 17071	MTH 08-Dec-2001 HRS 159		O/C	150		
231005	KCU951/KFS594 HIGH FREQUENCY CONTROLLER KFS-594	ICT		071-01274-0002 3704	MTH 08-Dec-2001 HRS 159		O/C	683		
231007	KA594 HIGH FREQUENCY ADAPTER KA-594	ICT		071-01268-0001 4328	MTH 08-Dec-2001 HRS 159		O/C	150		
232004	TRANSCEIVER PHONE	*CF	16	724855-801 MSA2231	MTH 28-Jun-2001		O/C			
232005 CABIN	HANDSET PHONE	BOI		725729-815 MX43300	MTH 05-Apr-2002 HRS 332		O/C	0		
232006 COCKPIT	HANDSET PHONE	BOI		725729-815WH MX45129	MTH 28-Dec-2012 HRS 3555.5 LDG 2980		O/C			
232007	PHONE ANTENNA	*CF		DMNI24-19-1 1087	MTH 28-Jun-2001		O/C			
232008 NO. 1	VHF INTEGRATED CONTROL UNIT SMF	AN		7510733-666 01036108	MTH 19-Mar-2018 HRS 5075.9 LDG 4240		O/C			
232008 NO. 2	VHF INTEGRATED CONTROL UNIT SMF			7510733-666 01066568	MTH 19-Mar-2018 HRS 5075.9 LDG 4240		O/C			
232010 NO. 1	VHF COMMUNICATION TRANSCEIVER TR-833	*CF		7510763-901 01033510	MTH 28-Jun-2001		O/C			
232010 NO. 2	VHF COMMUNICATION TRANSCEIVER TR-833	*CF		7510763-901 01053911	MTH 28-Jun-2001		O/C			
232013 NO. 1	COMM CLUSTER MODULE XC-833	*CF	J	7510784-835 01026377	MTH 28-Jun-2001		O/C			
232013 NO. 2	COMM CLUSTER MODULE XC-833	*CF	J	7510784-835 01056923	MTH 28-Jun-2001		O/C			
232018	CDBR REPEATER	*CF		724864-801 MSK6483	MTH 28-Jun-2001		O/C			
232019	MAGNASTAR DUPLEXER *CF			620317-2 01476	MTH 28-Jun-2001		O/C			
235001 NO. 1	AUDIO AMPLIFIER AV-850A	BOI	Y	7511001-915 01026270	MTH 06-Jan-2014 HRS 3849.7 LDG 3223		O/C			
235001 NO. 2	AUDIO AMPLIFIER AV-850A	BOI	Y	7511001-915 990330805	MTH 06-Jan-2014 HRS 3849.7 LDG 3223		O/C			
237001	COCKPIT VOICE RECORDER A200S	*CF	3	S200-0012-00 000113579	MTH 28-Jun-2001		O/C			
237004	CVR CONTROLLER	*CF		S251-1120-00 000120648	MTH 28-Jun-2001		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
237006	CVR UNDERWATER LOCATOR BEACON	KBOI		DK120/90 AT121833	MTH 08-Jan-2019 HRS 5309.1 LDG 4459		O/C	4 0 0		
237006A	REPLACE ULB (CVR) BATTERY	KBOI		DK120/90 AT207830	MTH 13-Sep-2024 HRS 6939.2 LDG 5702		72	3	30-Jun-2030	49 m 22 d
237010	CVR IMPACT SWITCH	*CF		6895-D-2-X-5-5 2564	MTH 28-Jun-2001		O/C			
242001 NO. 1	STATIC INVERTER	KBOI		PC-251-123H 11413	MTH 11-Jul-2025 HRS 7089.8 LDG 5866		O/C			
242001 NO. 2	STATIC INVERTER	BOI		PC-251-123H 11038	MTH 15-Oct-2020 HRS 5860.6 LDG 4850		O/C			
243001 LEFT	STARTER/GENERATOR 9912125-5	KBOI		300SGL129Q-2 3887XL	MTH 21-Mar-2024 HRS 6806 LDG 5590		1000	0	7806	532.3
243001 RIGHT	STARTER/GENERATOR 9912125-5	KBOI		300SGL129Q-2 5169XL	MTH 21-Mar-2024 HRS 6806 LDG 5590		1000	0	7806	532.3
243003 NO. 1	GENERATOR CONTROL UNIT *CF	A		51525-001F Y1103	MTH 28-Jun-2001		O/C			
243003 NO. 2	GENERATOR CONTROL UNIT *CF	A		51525-001F Y1086	MTH 28-Jun-2001		O/C			
243004 NO. 1	AMMETER	*CF		C662501-0104 B21258	MTH 28-Jun-2001		O/C			
243004 NO. 2	AMMETER	ICT		C662501-0104 B21711	MTH 19-Jul-2001 HRS 9		O/C	0		
243005	DC VOLTMETER	ICT		C662502-0101 1464	MTH 23-Sep-2001 HRS 95		O/C	0		
243007	MAIN SHIP BATTERY	KBOI		7638-44T G03319453	MTH 06-May-2026 HRS 7273.7 LDG 6035		O/C	0 0		
243008	BATTERY TEMP MONITOR- *CF			1529-1 3020	MTH 28-Jun-2001		O/C			
243009	BATTERY TEMP GAGE *CF			1229-1 2656	MTH 28-Jun-2001		O/C			
243010	BATTERY TEMP SENSOR	BOI		S3597-9 N/A	MTH 26-Sep-2012 HRS 3465.3 LDG 2896		O/C	0 0 0		
243015	BATTERY DISCONNECT RELAY	BOI		A876K CM-49614	MTH 21-Sep-2016 HRS 4744.7 LDG 3960 ACH 379.7		O/C			
243016	CURRENT/VOLTAGE SENSOR *CF			1645-1-3 2533	MTH 28-Jun-2001		O/C			
245002	CABIN ALTITUDE SWITCH 9910095-6	BOI		GB300NA161 1105642	MTH 29-Apr-2011 HRS 3130.9 LDG 2599		O/C	0 0		



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
252010	CABIN BRIEFER COMPUTER *CF			PBS250-1-S8-C560 0894	MTH 28-Jun-2001		O/C			
252011 <i>252010 : CTRL</i>	CABIN BRIEFER CONTROL *CF			PBS250-2G5 0929	MTH 28-Jun-2001		O/C			
256002	EMERGENCY LOCATOR TRANSMITTER ELT-110-4	BOI	C406	453-0150 170-05855	MTH 15-Dec-2008 HRS 2454.4 LDG 2058		O/C	0 0 0		
256003	EMERGENCY LOCATOR TRANSMITTER BEACON BATTERY KBOI			452-0133 1009584-040	MTH 28-May-2024 HRS 6879.4 LDG 5646		DUE DUE DUE DUE	0 0 0 0	31-Aug-2029	39 m 23 d
Expiration Date: 31-Aug-2029										
256004 NO. 1	ELT ANTENNA	BOI		110-340 248708	MTH 15-Dec-2008 HRS 2454.4 LDG 2058		O/C	0 0 0		
261001 NO. 1 ENGINE	FIRE DETECTOR SENSOR 9912036-3 *CF			244-18882 SN-UNKNOWN	MTH 28-Jun-2001		O/C			
261001 NO. 2 ENGINE	FIRE DETECTOR SENSOR 9912036-3 *CF			244-18882 SN-UNKNOWN	MTH 28-Jun-2001		O/C			
261002 NO. 1	FIRE DETECTOR CONTROL 9912036-12 *CF			377-02838 0106013	MTH 28-Jun-2001		O/C			
261002 NO. 2	FIRE DETECTOR CONTROL 9912036-12 *CF			377-02838 0103002	MTH 28-Jun-2001		O/C			
262001 AFT	ENGINE FIRE BOTTLE 9912048-2	BOI		30401102 46215B1	MTH 04-May-2006 HRS 1539		O/C	58		
262001 FORWARD	ENGINE FIRE BOTTLE 9912048-2	BOI		30401102 46221B1	MTH 04-May-2006 HRS 1539		O/C	58		
262002 CABIN	PORTABLE HALON FIRE EXTINGUISHER HALON 1211	KBOI		C352 F-75057620	MTH 06-May-2026 HRS 7273.7 LDG 6035		O/C			
262002 COCKPIT	PORTABLE HALON FIRE EXTINGUISHER HALON 1211	KBOI		C352 F-75058817	MTH 06-May-2026 HRS 7273.7 LDG 6035		O/C			
262003 AFT LEFT	(MAX LIFE) CARTRIDGE KBOI			AE13083-5 A485	MTH 21-Oct-2022 HRS 6308.2 LDG 5208		120		30-Sep-2032	76 m 22 d
Manufacture Date: 22-Sep-2022										
262003 AFT RIGHT	(MAX LIFE) CARTRIDGE KBOI			AE13083-5 A489	MTH 21-Oct-2022 HRS 6308.2 LDG 5208		120		30-Sep-2032	76 m 22 d
Manufacture Date: 22-Sep-2022										
262003 FORWARD LEFT	(MAX LIFE) CARTRIDGE KBOI			AE13083-5 A493	MTH 21-Oct-2022 HRS 6308.2 LDG 5208		120		30-Sep-2032	76 m 22 d
Manufacture Date: 22-Sep-2022										
262003 FORWARD RIGHT	(MAX LIFE) CARTRIDGE KBOI			AE13083-5 A482	MTH 21-Oct-2022 HRS 6308.2 LDG 5208		120		30-Sep-2032	76 m 22 d
Manufacture Date: 22-Sep-2022										
272002 RIGHT	STICK SHAKER CONTROL *CF	A		201 5058	MTH 28-Jun-2001		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
273002	TRIM MIXER ACTUATOR *CF			44430-3657 T778	MTH 28-Jun-2001		O/C			
273003	ELEVATOR TRIM ACTUATOR *CF			6361215-21 SN-UNKNOWN	MTH 28-Jun-2001		O/C			
273003 LEFT	ELEVATOR TRIM ACTUATOR *CF			6361215-22 SN-UNKNOWN	MTH 28-Jun-2001		O/C			
275001	FLAP CONTROL VALVE BOI			66720 3270	MTH 26-Dec-2012 HRS 3555.5 LDG 2980		O/C	0 0		
275003 NO. 1	FLAP ACTUATOR 9912007-1	*CF		1535000-1 1338	MTH 28-Jun-2001		O/C			
275003 NO. 2	FLAP ACTUATOR 9912007-1	*CF		1535000-1 1332	MTH 28-Jun-2001		O/C			
275004 LEFT WING LEFT INBOARD	AFT FLAP ROLLER BOI			CC50380 SN-UNKNOWN	MTH 01-Sep-2021 HRS 6041.4 LDG 4992		5000	0	9992	3957
275004 LEFT WING LEFT OUTBOARD	AFT FLAP ROLLER BOI			CC50380 SN-UNKNOWN	MTH 01-Sep-2021 HRS 6041.4 LDG 4992		5000	0	9992	3957
275004 LEFT WING RIGHT INBOARD	AFT FLAP ROLLER BOI			CC50380 SN-UNKNOWN	MTH 01-Sep-2021 HRS 6041.4 LDG 4992		5000	0	9992	3957
275004 LEFT WING RIGHT OUTBOARD	AFT FLAP ROLLER BOI			CC50380 SN-UNKNOWN	MTH 01-Sep-2021 HRS 6041.4 LDG 4992		5000	0	9992	3957
275004 RIGHT WING LEFT INBOARD	AFT FLAP ROLLER BOI			CC-50380 SN-UNKNOWN	MTH 01-Sep-2021 HRS 6041.4 LDG 4992		5000	0	9992	3957
275004 RIGHT WING LEFT OUTBOARD	AFT FLAP ROLLER BOI			CC50380 SN-UNKNOWN	MTH 01-Sep-2021 HRS 6041.4 LDG 4992		5000	0	9992	3957
275004 RIGHT WING RIGHT INBOARD	AFT FLAP ROLLER BOI			CC50380 SN-UNKNOWN	MTH 01-Sep-2021 HRS 6041.4 LDG 4992		5000	0	9992	3957
275004 RIGHT WING RIGHT OUTBOARD	AFT FLAP ROLLER BOI			CC50380 SN-UNKNOWN	MTH 01-Sep-2021 HRS 6041.4 LDG 4992		5000	0	9992	3957
276001 NO. 1	SPEED BRAKE ACTUATOR 9912344-1	*CF		1535500-1 1681	MTH 28-Jun-2001		O/C			
276001 NO. 2	SPEED BRAKE ACTUATOR 9912344-1	BOI		1535500-1 546	MTH 18-Nov-2013 HRS 3820.3 LDG 3196		O/C	0 0 0		
276002	SPEED BRAKE FLAP CONTROL VALVE *CF			66720 2225	MTH 28-Jun-2001		O/C			
276003	SAFETY SPDBK VALVE *CF			68930 1088	MTH 28-Jun-2001		O/C			
280001 LEFT	FUEL FLOAT VALVE 9914268-5	*CF		60221-4 458	MTH 28-Jun-2001		O/C			
280001 RIGHT	FUEL FLOAT VALVE 9914268-5	*CF		60221-4 435	MTH 28-Jun-2001		O/C			
280003 LEFT	PRESSURE RELIEF VALVE 9912501-2	*CF		840203-105 2196XP	MTH 28-Jun-2001		O/C			
280003 RIGHT	PRESSURE RELIEF VALVE 9912501-2	*CF		840203-105 2108XP	MTH 28-Jun-2001		O/C			
280004 LEFT	PILOT HIGH LEVEL VALVE 9914107-1	*CF		61087 2709	MTH 28-Jun-2001		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
280004 RIGHT	PILOT HIGH LEVEL VALVE 9914107-1	*CF		61087 2202	MTH 28-Jun-2001		O/C			
280006 LEFT	SINGLE POINT REFUEL VALVE *CF			80002-101 SN-UNKNOWN	MTH 28-Jun-2001		O/C			
280006 RIGHT	SINGLE POINT REFUEL VALVE *CF			80002-101 SN-UNKNOWN	MTH 28-Jun-2001		O/C			
280007 LEFT	DEFUEL SINGLE PT VALVE *CF			61084-2 441	MTH 28-Jun-2001		O/C			
280007 RIGHT	DEFUEL SINGLE PT VALVE *CF			61084-2 438	MTH 28-Jun-2001		O/C			
280008 LEFT	MANUAL FUEL SHUTOFF VALVE 9914107-3	*CF		61086 1987	MTH 28-Jun-2001		O/C			
280008 RIGHT	MANUAL FUEL SHUTOFF VALVE 9914107-3	*CF		61086 1944	MTH 28-Jun-2001		O/C			
282001 NO. 1	ELECTRIC FUEL BOOST PUMP 9912553-1	*CF		1C7-23 2AU12	MTH 28-Jun-2001		O/C			
282001 NO. 2	ELECTRIC FUEL BOOST PUMP 9912553-1	*CF		1C7-23 2AT6	MTH 28-Jun-2001		O/C			
284001 NO. 1	FUEL LOW LEVEL SWITCH *CF			L16H-9 250	MTH 28-Jun-2001		O/C			
284001 NO. 2	FUEL LOW LEVEL SWITCH *CF			L16H-9 240	MTH 28-Jun-2001		O/C			
284002 LEFT	FUEL QTY COMPENSATOR 9912556-5	BOI		10635B02Y03 07111383	MTH 04-Dec-2015 HRS 4452.7 LDG 3711 ACH 365.2		O/C			
284003	FUEL TEMP INDICATOR *CF			C307FT A06065	MTH 28-Jun-2001		O/C			
284011 LEFT	FUEL QTY PROBE 9912556-2	*CF		10634T10Y00 B552	MTH 28-Jun-2001		O/C			
284011 RIGHT	FUEL QTY PROBE 9912556-2	*CF		10634T10Y00 B773	MTH 28-Jun-2001		O/C			
284012 LEFT	FUEL QTY PROBE 9912556-3	*CF		10634T08Y00 B0573	MTH 28-Jun-2001		O/C			
284012 RIGHT	FUEL QTY PROBE 9912556-3	*CF		10634T08Y00 0588	MTH 28-Jun-2001		O/C			
284013 LEFT	FUEL QTY PROBE 9912556-4	*CF		10634T09Y00 B512	MTH 28-Jun-2001		O/C			
284013 RIGHT	FUEL QTY PROBE 9912556-4	*CF		10634T09Y00 B511	MTH 28-Jun-2001		O/C			
284014 LEFT	FUEL QTY PROBE 9912498-3	*CF		10634T04Y00 B934	MTH 28-Jun-2001		O/C			
284014 RIGHT	FUEL QTY PROBE 9912498-3	*CF		10634T04Y00 B967	MTH 28-Jun-2001		O/C			
284015 LEFT	FUEL QTY PROBE 9912498-4	BOI		10634T05Y00 B960	MTH 10-Feb-2016 HRS 4510.3 LDG 3758 ACH 365.5		O/C			
284015 RIGHT	FUEL QTY PROBE 9912498-4	KBOI		10634T05Y00 MN11399	MTH 11-Oct-2018 HRS 5254.8 LDG 4412		O/C			
284016 LEFT	FUEL QTY PROBE 9912498-5	*CF		10634T01Y00 B969	MTH 28-Jun-2001		O/C			
284016 RIGHT	FUEL QTY PROBE 9912498-5	*CF		10634T01Y00 B945	MTH 28-Jun-2001		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
284017 LEFT	FUEL QTY PROBE 9912498-6	*CF		10634T06Y00 B872	MTH 28-Jun-2001		O/C			
284017 RIGHT	FUEL QTY PROBE 9912498-6	*CF		10634T06Y00 B864	MTH 28-Jun-2001		O/C			
291001	MAIN HYD RESERVOIR 9912542-1	*CF		7470 152	MTH 28-Jun-2001		O/C			
291002 LEFT	HYDRAULIC PUMP 9912062-4	*CF		24195-LAA 3384	MTH 28-Jun-2001		O/C			
291002 RIGHT	HYDRAULIC PUMP 9912062-4	*CF		24195-LAA 3379	MTH 28-Jun-2001		O/C			
291005 NO. 1	CK VALVE HYDRAULIC FLOW SWITCH 9912194-3	*CF		3520020100-4 05096	MTH 28-Jun-2001		O/C			
291005 NO. 2	CK VALVE HYDRAULIC FLOW SWITCH 9912194-3	*CF		3520020100-4 05117	MTH 28-Jun-2001		O/C			
291007 NO. 1	MOTOR ACTUATOR VALVE *CF			AV24B1325C5 T90328	MTH 28-Jun-2001		O/C			
291007 NO. 2	MOTOR ACTUATOR VALVE *CF			AV24B1325C5 T90959	MTH 28-Jun-2001		O/C			
291008	THERMAL RELIEF VALVE *CF			OAS5322-3-1700 1000	MTH 28-Jun-2001		O/C			
291009	PRESSURE RELIEF VALVE KBOI			4614 1842A	MTH 11-Dec-2015 HRS 4471.3 LDG 3724 ACH 365.2		O/C			
291012	SOLENOID BYPASS VALVE *CF			61510-1 1784A	MTH 28-Jun-2001		O/C			
301001 LEFT	TEMP CONTROL SL002 SWITCH KBOI			1173T42-3 4078	MTH 27-Dec-2013 HRS 3849.7 LDG 3223		O/C	0 0 0		
301001 RIGHT	TEMP CONTROL SR002 SWITCH *CF			1173T42-3 3004	MTH 28-Jun-2001		O/C			
301001 WING	ANTI-ICE BLEED AIR CROSSFLOW ISOLATION VALVE 9912403-2	*CF		2602-36 0421	MTH 28-Jun-2001		O/C			
301002 NO. 1	HORIZONTAL STABILIZER DEICE BOOT KBOI			P29S-5D5225-05 NFX1660	MTH 04-Jan-2024 HRS 6735.1 LDG 5542		O/C	0 0		
301002 NO. 2	HORIZONTAL STABILIZER DEICE BOOT KBOI			P29S-5D5225-06 NDF8140	MTH 08-Jan-2019 HRS 5309.1 LDG 4459		O/C	0 0		
301004 LEFT WING	ANTI-ICE BLEED AIR PRESSURE REG SHUTOFF VT001 VLV 9912495-1	BOI		1962-00-7 0669	MTH 01-May-2012 HRS 3353.5 LDG 2801		O/C	3925 3925		
301004 RIGHT WING	ANTI-ICE BLEED AIR PRESSURE REG SHUTOFF VT002 VLV 9912495-1	*CF		1962-00-7 1020	MTH 28-Jun-2001		O/C			
301005 NO. 1	DEICE PRESSURE ST003 SWITCH *CF			1106P55-1 1465	MTH 28-Jun-2001		O/C			
301005 NO. 2	DEICE PRESSURE ST004 SWITCH *CF			1106P55-1 1494	MTH 28-Jun-2001		O/C			
301008 LEFT	DEICE CONTROL SLV19 VLV *CF			3D2353-06 N17785	MTH 28-Jun-2001		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
301008 RIGHT	DEICE CONTROL SLV18 VLV *CF			3D2353-06 N17798	MTH 28-Jun-2001		O/C			
302003 LEFT ENGINE	LEFT ENGINE ANTI-ICE SOLENOID VALVE KBOI			1946-00-19 / 9912495 -4 4637	MTH 21-Mar-2024 HRS 6806 LDG 5590		O/C			
302003 RIGHT ENGINE	RIGHT ENGINE ANTI-ICE SOLENOID VALVE BOI			1946-00-19 / 9912495 4 2241	MTH 15-Aug-2019 HRS 5542.2 LDG 4623		O/C			
302004 LEFT ENGINE	INLET TEMPERATURE S95 SWITCH KBOI			1173T0759 1101	MTH 14-Mar-2016 HRS 4536.7 LDG 3784		O/C			
302005 LEFT	ANTI ICING VALVE 3119722-04	KBOI		540-0406-4 GA2156	MTH 18-Dec-2024 HRS 7007.3 LDG 5772		O/C			
302005 RIGHT	ANTI ICING VALVE 3119722-04	KBOI		540-0406-4 3513	MTH 22-Nov-2024 HRS 6986.2 LDG 5752		O/C			
302008 RIGHT ENGINE	INLET TEMPERATURE S94 SENSOR KBOI			1173T0759 1107	MTH 14-Mar-2016 HRS 4536.7 LDG 3784		O/C			
303001 LEFT	PITOT TUBE KSAT			PH1100-1-VC 1066104	MTH 19-Jun-2010 HRS 2886 LDG 2393		O/C	0 0		
303001 RIGHT	PITOT TUBE *CF			PH1100-1-VC SN-UNKNOWN	MTH 28-Jun-2001		O/C			
304001	BLEED AIR MONITOR- *CF			1169-1 3053	MTH 28-Jun-2001		O/C			
304002	ANTI-ICE BLEED AIR WNDSHLD HEAT EXCHANGER 9912041-2 *CF			10654A 563	MTH 28-Jun-2001		O/C			
304004	ALCOHOL WINDSHIELD ANTI-ICE PUMP *CF			476411 SN-UNKNOWN	MTH 28-Jun-2001		O/C			
304005	TEMP CONTROL VALVE 9912085-1 *CF			27241287 3AU31	MTH 28-Jun-2001		O/C			
304006	ANTI-ICE BLEED AIR WNDSHLD TEMP XMTR26 SENSOR 9912085-6 *CF			1E58-1 1AU10	MTH 28-Jun-2001		O/C			
304007	ANTI-ICE BLEED AIR WNDSHLD HEAT EXCHANGER PRESS S130 SWITCH *CF			1115P25 3463	MTH 28-Jun-2001		O/C			
304009	WINDSHIELD ANTI-ICE BLEED AIR CONTROL VALVE 9912086-4 *CF			67410-2 3391	MTH 28-Jun-2001		O/C			
312001 COPILOT	DIGITAL CLOCK *CF			M877A5V 12188	MTH 28-Jun-2001		O/C			
312001 PILOT	DIGITAL CLOCK *CF			M877A5V 12164	MTH 28-Jun-2001		O/C			
313001	FLIGHT HOUR RECORDER 85071 *CF			C664503-0104 SN-UNKNOWN	MTH 28-Jun-2001		O/C			
313003 NO. 1	ACCELEROMETER AG-222 *CF			7000992 008411	MTH 28-Jun-2001		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
313003 NO. 2	ACCELEROMETER AG-222	*CF		7000992 008644	MTH 28-Jun-2001		O/C			
313003	EGPWS ACCELEROMETER	*CF		979-0223-001 3083	MTH 28-Jun-2001		O/C			
315001	MASTER WARNING ANNUNCIATOR 9912559-1	*CF		1730-1-1 0117151	MTH 28-Jun-2001		O/C			
321001 LEFT <i>321001T : T-L</i>	MAIN LANDING GEAR ASSEMBLY	*CF		6541510-1 004	MTH 28-Jun-2001		O/C			
321002 RIGHT <i>321002T : T-R</i>	MAIN LANDING GEAR ASSEMBLY	*CF		6541510-2 004	MTH 28-Jun-2001		O/C			
321004 LEFT	MAIN LANDING GEAR UPPER OLEO CAP	*CF		6541521-2 SN-UNKNOWN	MTH 28-Jun-2001		O/C			
321004 RIGHT	MAIN LANDING GEAR UPPER OLEO CAP	*CF		6541521-2 SN-UNKNOWN	MTH 28-Jun-2001		O/C			
321005 LEFT	MAIN LANDING GEAR OLEO OUTER BEARING	*CF		6541425-6 SN-UNKNOWN	MTH 28-Jun-2001 LDG 0		21800	0	21800	15765
321005 RIGHT	MAIN LANDING GEAR OLEO OUTER BEARING	*CF		6541425-6 SN-UNKNOWN	MTH 28-Jun-2001 LDG 0		21800	0	21800	15765
321006 LEFT	MAIN LANDING GEAR ORIFICE FITTING BOI			6541428-3 SN-UNKNOWN	MTH 11-Mar-2003 HRS 691 LDG 544		O/C	0		
321006 RIGHT	MAIN LANDING GEAR ORIFICE FITTING	*CF		6541428-1 SN-UNKNOWN	MTH 28-Jun-2001		O/C			
321007 LEFT	MAIN LANDING GEAR TRAILING LINK	*CF		6541516-1 SN-UNKNOWN	MTH 28-Jun-2001 LDG 0		9800	0	9800	3765
321007 RIGHT	MAIN LANDING GEAR TRAILING LINK	*CF		6541516-2 SN-UNKNOWN	MTH 28-Jun-2001 LDG 0		9800	0	9800	3765
321008 LEFT MAIN LANDING GEAR	OLEO ASSEMBLY	BOI		6541520-2 N/A	MTH 21-Aug-2020 HRS 5810.5 LDG 4811		31900	2530	34181	28146
321008 RIGHT MAIN LANDING GEAR	OLEO ASSEMBLY	BOI		6541520-4 N/A	MTH 15-Nov-2017 HRS 5038.5 LDG 4196		31900	4196	31900	25865
321009 LEFT MAIN LANDING GEAR	TRUNNION MACHINING	*CF		6541561-1 SN-UNKNOWN	MTH 28-Jun-2001 LDG 0		50100	0	50100	44065
321009 RIGHT MAIN LANDING GEAR	TRUNNION MACHINING	*CF		6541561-2 SN-UNKNOWN	MTH 28-Jun-2001 LDG 0		50100	0	50100	44065
322001 <i>322001T : T</i>	NOSE LANDING GEAR ASSEMBLY	*CF		6642000-54 030	MTH 28-Jun-2001 LDG 0		22566	0	22566	16531
322002	NOSE SHIMMY DAMPER	*CF		5543001-11 205X11	MTH 28-Jun-2001		O/C			
322004 <i>322004T : T</i>	NOSE GEAR FORK/PISTON	*CF		6642000-3 SN-UNKNOWN	MTH 28-Jun-2001 LDG 0		13061	0	13061	7026
323003 <i>323003T : T</i>	NOSE LANDING GEAR ACTUATOR			1548500-9 878	MTH 04-May-2005 HRS 1202 LDG 1009		15000	0	16009	9974
323004 LEFT	MLG UPLOCK ACTUATOR	*CF		6527504-1 56	MTH 28-Jun-2001		O/C			
323004 NOSE	UPLOCK ACTUATOR	*CF		5527504-2 3011	MTH 28-Jun-2001		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
323004 RIGHT	MLG UPLOCK ACTUATOR *CF			6527504-1 61	MTH 28-Jun-2001		O/C			
323006	PNEUMATIC BLOWDOWN/EMERGENCY BRAKE BOTTLE 9912103-3	KBOI		212940-2 12483	MTH 21-Aug-2025 HRS 7123 LDG 5904		288	2	30-Jun-2049	277 m 22 d
Manufacture Date: 02-Jun-2025										
323007	LANDING GEAR CONTROL VALVE *CF			71839 0220	MTH 28-Jun-2001		O/C			
323008	DUMP VALVE *CF			OAS5319-1 1062	MTH 28-Jun-2001		O/C			
323015 LEFT <i>323001T : T-L</i>	SIDE BRACE ACTUATOR 9912569-1			1556600-3 0390	MTH 06-Jun-2008 HRS 2286 LDG 1907		50100	0	52007	45972
323016 RIGHT <i>323002T : T-R</i>	SIDE BRACE ACTUATOR 9912569-2 ICT			1556600-4 079	MTH 11-Mar-2005 HRS 1156 LDG 973		50100	973	50100	44065
323019	EMERGENCY AIR BOTTLE GAUGE *CF			2341128 010923	MTH 28-Jun-2001		O/C	0		
324001 LEFT	MLG WHEEL ASSEMBLY 9912561-5			3-1607-1 2063	MTH 01-Jul-2025 HRS 7088 LDG 5860		O/C	0 0		
324001 RIGHT	MLG WHEEL ASSEMBLY 9912561-4	KBOI		3-1607 0058	MTH 15-May-2023 HRS 6522.6 LDG 5369		O/C			
324002	NOSE WHEEL ASSEMBLY 9914069-2	KBOI		3-1418 5225	MTH 14-Apr-2026 HRS 7270 LDG 6033		O/C			
324003 LEFT	MLG BRAKE ASSEMBLY 9912561-3	KBOI		2-1656 0546	MTH 01-Nov-2024 HRS 6980.3 LDG 5744		O/C			
324004 RIGHT	MLG BRAKE ASSEMBLY 9912561-3	KBOI		2-1656 0262	MTH 18-Aug-2025 HRS 7120.5 LDG 5900		O/C			
324005 LEFT	MLG TIRE 9912467-2	KBOI		229K48-2 32221156	MTH 01-Jul-2025 HRS 7088 LDG 5860		O/C	0 0 0		
324005 RIGHT	MLG TIRE 9912467-2	KBOI		229K48-2 31230856	MTH 11-Mar-2025 HRS 7039.5 LDG 5798		O/C	0 0 0		
324006	NOSE TIRE	KBOI		031-631-8 0357T00396	MTH 14-Apr-2026 HRS 7270 LDG 6033		O/C	0 0		
324010 LEFT	MLG SHUTTLE VALVE			211-111 2521	MTH 31-May-2007 HRS 1862 LDG 1566		O/C	0		
324010 RIGHT	MLG SHUTTLE VALVE *CF			98120 2651	MTH 28-Jun-2001		O/C			
324013	BRAKE METERING VALVE 9912562-1	BOI		32-079 227	MTH 30-Dec-2008 HRS 2454		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
324014	EMERGENCY AIR BRAKE VALVE *CF			895232-0875 V887	MTH 28-Jun-2001		O/C			
324019	BRAKE PRESS PUMP ASSEMBLY 9912166-3 *CF			640931 5627	MTH 28-Jun-2001		O/C			
324021	POWER BRAKE ANTISKID VALVE 9912489-4 BOI			39-837 614	MTH 07-May-2018 HRS 5119.9 LDG 4281		O/C			
324022	BRAKE CONTROL BOX 9912564-2 *CF			142-021 141	MTH 28-Jun-2001		O/C			
324023	ANTISKID ACCUMULATOR *CF			57C57652 1477	MTH 28-Jun-2001		O/C			
324024 LEFT	MLG WHEEL TRANSDUCER 9912305-2 *CF			40-955 SN-UNKNOWN	MTH 28-Jun-2001		O/C			
324024 RIGHT	MLG WHEEL TRANSDUCER 9912305-2 *CF			40-955 SN-UNKNOWN	MTH 28-Jun-2001		O/C			
324025	PRESSURE SWITCH *CF			GPP1250-46 0105053	MTH 28-Jun-2001		O/C			
324026	POWER BRAKE ASSEMBLY MOTOR *CF			MP50B1 1673	MTH 28-Jun-2001		O/C			
324027	FAULT DISPLAY UNIT 9912305-9 *CF			42-92750 830A	MTH 28-Jun-2001		O/C			
324101	PARKING BRAKE VALVE 9912388-2 KGJT			95905 1484A	MTH 31-Oct-2013 HRS 3799.6 LDG 3181		O/C	0 0 0		
324102	PRESSURE SWITCH BOI			D45C-31 1118	MTH 19-Mar-2013 HRS 3654.6 LDG 3055		O/C	0 0 0		
325001	NOSE STEERING BUNGEE ASSEMBLY *CF			5565624-20 SN-UNKNOWN	MTH 28-Jun-2001		O/C			
326005 LEFT	MAIN GEAR UP & LOCKED SWITCH KBOI			65-430087 N/A	MTH 09-Aug-2017 HRS 4939.5 LDG 4120		O/C	0 0		
326005 RIGHT	MAIN GEAR UP & LOCKED SWITCH *CF			65-430087 SN-UNKNOWN	MTH 28-Jun-2001		O/C			
326005	NOSE GEAR UP & LOCKED SWITCH *CF			65-430087 SN-UNKNOWN	MTH 28-Jun-2001		O/C			
331001 NO. 1	LIGHT PANEL DIMMER *CF			273-1 0103028	MTH 28-Jun-2001		O/C			
331001 NO. 2	LIGHT PANEL DIMMER *CF			273-1 0103054	MTH 28-Jun-2001		O/C			
331001 NO. 3	LIGHT PANEL DIMMER *CF			273-1 0103064	MTH 28-Jun-2001		O/C			
331011	INVT-115V EL PANEL KBOI			EM2044-1 244A	MTH 25-Jul-2016 HRS 4686.7 LDG 3918 ACH 365.5		O/C			
332001 NO. 1	CU31 INDIRECT LIGHT POWER UNIT BOI			AL750PS 25932	MTH 18-Nov-2013 HRS 3820.3 LDG 3196		O/C	0 0 0		
332001 NO. 2	CU30 INDIRECT LIGHT POWER UNIT *CF			AL750PS 11849	MTH 28-Jun-2001		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
332001 NO. 3	CU29 INDIRECT LIGHT POWER UNIT *CF			AL750PS 11850	MTH 28-Jun-2001		O/C			
332001 NO. 4	CU28 INDIRECT LIGHT POWER UNIT *CF			AL750PS 12082	MTH 28-Jun-2001		O/C			
332001 NO. 5	CU27 INDIRECT LIGHT POWER UNIT *CF			AL750PS 12083	MTH 28-Jun-2001		O/C			
332001 NO. 6	CU26 INDIRECT LIGHT POWER UNIT *CF			AL750PS 12084	MTH 28-Jun-2001		O/C			
332001 NO. 7	CU25 INDIRECT LIGHT POWER UNIT *CF			AL750PS 12085	MTH 28-Jun-2001		O/C			
332001 NO. 8	CU24 INDIRECT LIGHT POWER UNIT *CF			AL750PS 12086	MTH 28-Jun-2001		O/C			
334003 NO. 1	STROBE POWER SUPPLY KBOI			01-0790101-05 00268	MTH 16-Dec-2022 HRS 6373.8 LDG 5259		O/C			
334003 NO. 2	STROBE POWER SUPPLY KBOI			01-0790101-05 00380	MTH 16-Dec-2022 HRS 6373.8 LDG 5259		O/C			
335001 MID	EMERGENCY BATTERY PACK KBOI			CBS28-1 007690	MTH 15-Mar-2023 HRS 6471.7 LDG 5338		O/C			
341006	PITOT PRESSURE SWITCH BOI			D37C15 SN-UNKNOWN	MTH 19-Feb-2004 HRS 930		O/C	0		
341011	ANGLE OF ATTACK STALL WARNING COMPUTER *CF			C-13106-1 510	MTH 28-Jun-2001		O/C			
341012	AOA SENSOR *CF			C-12717-1 553	MTH 28-Jun-2001		O/C			
341014	ANGLE OF ATTACK INDEXER ICT			C12763-1 473	MTH 20-Oct-2001 HRS 148		O/C	0		
341016	SECONDARY FLIGHT ADU *CF		1	27101-01-01 M006843	MTH 28-Jun-2001		O/C			
341017	SECONDARY FLIGHT DISPLAY BOI			38102-00-01 M008444	MTH 29-Apr-2003 HRS 727		O/C	603		
342001	MAGNETIC COMPASS BOI			C660501-0301 N/A	MTH 25-Jan-2017 HRS 4822.9 LDG 4020 ACH 384.7		O/C	0 0		
342023	RADAR CONTROLLER WC-880 *CF			7008471-407 01035580	MTH 28-Jun-2001		O/C			
342042 NO. 1	MODE FLIGHT DIRECTOR SELECTOR MS-560 *CF			7018341-803 01031858	MTH 28-Jun-2001		O/C			
342043 NO. 1	VERTICAL FLIGHT DIRECTOR GYRO VG-14A *CF		M	7000622-901 01049189	MTH 28-Jun-2001		O/C			
342043 NO. 2	VERTICAL FLIGHT DIRECTOR GYRO VG-14A KBOI		K	7000622-901 01069221	MTH 26-Aug-2025 HRS 7124.7 LDG 5907		O/C			
342044 NO. 1	RATE OF TURN GYRO RG-204 ICT		K	7007453-903 01035266	MTH 06-Aug-2001 HRS 36		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
342048 NO. 1	AIR DATA COMPUTER AZ-850			7014700-602 00094080	MTH 10-Nov-2004 HRS 1085		O/C	1072		
342048 NO. 2	AIR DATA COMPUTER AZ-850	*CF		7014700-602 01024716	MTH 28-Jun-2001		O/C			
342049 NO. 1	DIRECTIONAL GYRO C-14D	KBOI	G	4020577-3 9385464	MTH 21-Aug-2025 HRS 7123 LDG 5904		O/C			
342049 NO. 2	DIRECTIONAL GYRO C-14D	KBOI	G	4020577-3 96086029	MTH 26-Aug-2025 HRS 7124.7 LDG 5907		O/C			
342050 NO. 1	FLUX DETECTOR FX-220	*CF		2594484 0014490	MTH 28-Jun-2001		O/C			
342050 NO. 2	FLUX DETECTOR FX-220	*CF		2594484 0014496	MTH 28-Jun-2001		O/C			
342052	REMOTE COMPENSATOR CS-412	*CF	B	2593379-1 01013076	MTH 28-Jun-2001		O/C			
342053 STANDBY	HSI INDICATOR HSI-315A	BOI		520-3150-003 18213	MTH 26-Jul-2004 HRS 1037		O/C	1564		
342063 NO. 1	REMOTE COURSE CONTROL RI-553	*CF		7016954-907 01031274	MTH 28-Jun-2001		O/C			
342069	MULTIFUNCTION DISPLAY CONTROLLER MC-800	*CF	B	7007062-941 01022488	MTH 28-Jun-2001		O/C			
342078 NO. 1	DISPLAY GUIDANCE COMPUTER IC-600	BOI	AL	7017000-80174 00033200	MTH 01-Jul-2020 HRS 5782 LDG 4791		O/C			
342078 NO. 2	DISPLAY GUIDANCE COMPUTER IC-600	*CF	AG	7017000-81172 00083562	MTH 28-Jun-2001		O/C			
342079 COPILOT	PRIMARY FLIGHT DISPLAY CONTROLLER DC-550	*CF	D	7016986-747 01033503	MTH 28-Jun-2001		O/C			
342079 PILOT	PRIMARY FLIGHT DISPLAY CONTROLLER DC-550	*CF	D	7016986-747 01033501	MTH 28-Jun-2001		O/C			
342080 CNTR	EFIS DISPLAY DU-870	BOI	H	7014300-901 01038923	MTH 20-Feb-2013 HRS 3620.8 LDG 3026		O/C			
342080 NO. 1	EFIS DISPLAY DU-870	ICT		7014300-901 97102553	MTH 16-Aug-2001 HRS 46		O/C	0		
342080 NO. 2	EFIS DISPLAY DU-870	BOI	H	7014300-901 0710G702	MTH 20-Feb-2013 HRS 3620.8 LDG 3026		O/C			
342081 NO. 1	BEZEL DISPLAY UNIT BL-870	*CF		7014331-931 01033546	MTH 28-Jun-2001		O/C			
342081 NO. 2	BEZEL DISPLAY UNIT BL-870	*CF		7014331-931 01033547	MTH 28-Jun-2001		O/C			
342081	MFD BEZEL DISPLAY UNIT BL-871	KBOI		7014332-841 01024815	MTH 11-Oct-2022 HRS 6300.3 LDG 5199		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
342177	PS-850/PS-855 EMERGENCY POWER SUPPLY	KBOI		501-1712-02 4241	MTH 08-Jan-2018 HRS 5053.8 LDG 4210		O/C			
344003	PRIMUS 650 RADAR RECEIVER/TRANSMITTER WU-660	KSAT	L	7021450-601 01022803	MTH 19-Jun-2010 HRS 2886 LDG 2393		O/C			
344022	RADIO ALT TRANSCEIVER RT-300	KBOI	AF	7001840-936 0312B032	MTH 04-Aug-2017 HRS 4935.5 LDG 4115 ACH 389.4		O/C			
344023 AFT	RECEIVER RADIO ALT ANTENNA *CF			S67-2002-4 10463	MTH 28-Jun-2001		O/C			
344023 FORWARD	TRANSMITTER RADIO ALT ANTENNA *CF			S67-2002-4 10459	MTH 28-Jun-2001		O/C			
344024	GROUND PROXIMITY WARNING SYS COMPUTER S3100-195	SAT		965-1076-040-210-210 2205	MTH 15-Jan-2005 HRS 1117		O/C	1117		
345004 AFT	TRANSPONDER ANTENNA 85226	*CF		DMNI50-2-2 77749	MTH 28-Jun-2001		O/C			
345004 FORWARD	TRANSPONDER ANTENNA 85226	*CF		DMNI50-2-2 77748	MTH 28-Jun-2001		O/C			
345004 TOP AFT	DIV TRANSPONDER ANTENNA 85226	*CF		DMNI50-2-2 77756	MTH 28-Jun-2001		O/C			
345004 TOP FORWARD	DIV TRANSPONDER ANTENNA 85226	*CF		DMNI50-2-2 78509	MTH 28-Jun-2001		O/C			
345007 AFT	DME ANTENNA 85226	*CF		DMNI50-2-2 77750	MTH 28-Jun-2001		O/C			
345007 FORWARD	DME ANTENNA 85226	*CF		DMNI50-2-2 77259	MTH 28-Jun-2001		O/C			
345010 NO. 1	NAVIGATION ANTENNA	KGJT		CI201-1-L 394086	MTH 31-Oct-2013 HRS 3799.6 LDG 3181		O/C	0 0 0		
345010 NO. 2	NAVIGATION ANTENNA	KGJT		CI-120-1-L 403605	MTH 31-Oct-2013 HRS 3799.6 LDG 3181		O/C	0 0 0		
345014 NO. 1	ADF ANTENNA ANT-462A	*CF		622-7383-001 01034750	MTH 28-Jun-2001		O/C			
345014 NO. 2	ADF ANTENNA ANT-462A	*CF		622-7383-001 01034980	MTH 28-Jun-2001		O/C			
345015	LP/LPV MONITOR-	SMF		3116-52-1110 1237	MTH 19-Mar-2018 HRS 5075.9 LDG 4240		O/C			
345017	MARKER BEACON ANTENNA *CF			31-10-01 3657	MTH 28-Jun-2001		O/C			
345018	GLIDESLOPE ANTENNA SAT			RGS10-48 12562	MTH 20-Aug-2010 HRS 2940.4 LDG 2438		O/C	0 0		
345027 NO. 1	NAV MODULE NV-850	*CF		7510134-731 01096385	MTH 28-Jun-2001		O/C			
345027 NO. 2	NAV MODULE NV-850	ICT		7510134-731 95121827	MTH 11-Sep-2001 HRS 81		O/C	0		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
345028 NO. 2	ADF MODULE DF-850	*CF	K	7510114-901 98082526	MTH 28-Jun-2001		O/C			
345029 NO. 1	NAV CLUSTER MODULE XN-850	*CF		7510164-921 98082992	MTH 28-Jun-2001		O/C			
345029 NO. 2	NAV CLUSTER MODULE XN-850	ICT		7510164-921 95121754	MTH 11-Sep-2001 HRS 81		O/C	0		
345030	CLEARANCE DELIVERY CONTROL CD-850	*CF	G	7513000-835 01011740	MTH 28-Jun-2001		O/C			
345031	NAVIGATION(FMS) COMPUTER UNS-1ESPW	KBOI	12	3019-41-201 542	MTH 11-Mar-2024 HRS 6796.2 LDG 5584		O/C			
345034 NO. 1	ATC TRANSPONDER XS-852			7517400-902 01035057	MTH 01-Mar-2005 HRS 1156		O/C	0		
345034 NO. 2	ATC TRANSPONDER XS-852	*CF	G	7517400-902 01065520	MTH 28-Jun-2001		O/C			
345035 NO. 1	DME INDICATOR DI-851	*CF	A	7513006-911 01032182	MTH 28-Jun-2001		O/C			
345035 NO. 2	DME INDICATOR DI-851	*CF	A	7513006-911 01032163	MTH 28-Jun-2001		O/C			
345036 NO. 1	DME RECEIVER TRANSMITTER DM-850	*CF		7510184-902 02056457	MTH 28-Jun-2001		O/C			
345036 NO. 2	DME RECEIVER TRANSMITTER DM-850	ICT		7510184-902 96011626	MTH 11-Sep-2001 HRS 81		O/C	0		
345038 NO. 1	INTERGRATED NAV UNIT RNZ-850	BOI		7510100-731 98082930	MTH 26-Sep-2012 HRS 3465.3 LDG 2896		O/C			
345038 NO. 2	INTERGRATED NAV UNIT RNZ-850	BOI		7510100-733 96011707	MTH 29-Dec-2003 HRS 885		O/C	0		
345077	DATA TRANSFER UNIT KGJT			1408-00-1 2414	MTH 31-Oct-2013 HRS 3799.6 LDG 3181		O/C	0 0 0		
345088 NO. 1	RADIO MANAGEMENT UNIT KBOI	AM		7013270-983 05054813	MTH 14-Jan-2019 HRS 5324.7 LDG 4465		O/C			
345088 NO. 2	RADIO MANAGEMENT UNIT SMF	AM		7013270-983 17079663	MTH 19-Mar-2018 HRS 5075.9 LDG 4240		O/C	0 0		
345093	GPS ANTENNA KGJT			10708 8031	MTH 31-Oct-2013 HRS 3799.6 LDG 3181		O/C	0 0 0		
346001	TCAS PROCESSOR TPU-67A	KBOI		066-01146-1211 X41455	MTH 22-Feb-2016 HRS 4516.1 LDG 3764 ACH 365.5		O/C			
346002 BOTTOM	TCAS ANTENNA ANT-67A	*CF		071-01548-0100 9975	MTH 28-Jun-2001		O/C			
346002 TOP	TCAS ANTENNA ANT-67A	*CF		071-01548-0100 9851	MTH 28-Jun-2001		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
346002	XM SATELLITE ANTENNA BOI			CI420-1 271139	MTH 10-Mar-2009 HRS 2522		O/C	0		
346006	TCAS CONFIGURATION MODULE CM2000	*CF	1	071-00097-0100 8109	MTH 28-Jun-2001		O/C			
350006	OXYGEN FILLER VALVE BOI			9912057-13 5603	MTH 07-Feb-2011 HRS 3087.8 LDG 2555		O/C	0 0 0		
351001	OXYGEN PRESSURE GAUGE MD-97	*CF		C668512-0101 M20360	MTH 28-Jun-2001		O/C	0		
351002	OXYGEN PRESSURE SWITCH *CF			P24032 0193	MTH 28-Jun-2001		O/C			
351004 COPILOT	OXYGEN MASK 9914067-41	KBOI		MC10-15-109 68896	MTH 05-Dec-2024 HRS 7005.7 LDG 5770		72	0	31-Dec-2030	55 m 23 d
351004 PILOT	OXYGEN MASK 9914067-41	KBOI		MC10-15-109 61371	MTH 27-Jan-2026 HRS 7238.8 LDG 6012		72	1 0 0	31-Dec-2031	67 m 23 d
351005	OXYGEN SUPPLY REGULATOR *CF			172170-01 3309	MTH 28-Jun-2001		O/C	0		
351006	OXYGEN CYLINDER ZC369-64 PB DOT3HT1850	KBOI		176176-64 1161477001	MTH 14-Sep-2023 HRS 6638 LDG 5465		288	11	31-Oct-2046	245 m 23 d
Manufacture Date: 01-Oct-2022										
361003	PNEUMATIC REGULATOR 9912510-1	*CF		1H75-18 1AU20	MTH 28-Jun-2001		O/C			
361004	BLEED AIR CROSS *CF			5267-00-3 0176	MTH 28-Jun-2001		O/C			
361006 LEFT	PRECOOLER ACTUATOR 9914519-4	BOI		1E50-2 11AN64	MTH 07-Dec-2016 HRS 4799.6 LDG 4003		O/C	0 0 0		
361006 RIGHT	PRECOOLER ACTUATOR 9914519-4	KBOI		1E50-2 1BB20	MTH 11-Oct-2021 HRS 6060.5 LDG 5010		O/C	0 0 0		
361013 LEFT	REPLACE LEFT HEAT EXCHANGER PRECOOLER KBOI			8230-3 S4883T0650	MTH 08-Jan-2018 HRS 5053.8 LDG 4210 ACH 404.7		4800	0	9853.8	2580.1
361013 RIGHT	REPLACE RIGHT HEAT EXCHANGER PRECOOLER KBOI			8230-3 S4883T0649	MTH 08-Jan-2018 HRS 5053.8 LDG 4210 ACH 404.7		4800	0	9853.8	2580.1
361101 LEFT	OVERTEMP BLEED AIR SWITCH 9914149-2	*CF		1173T181-2 2874	MTH 28-Jun-2001		O/C			
361101 RIGHT	OVERTEMP BLEED AIR SWITCH 9914149-2	*CF		1173T181-2 2900	MTH 28-Jun-2001		O/C			
361102 LEFT	BLEED AIR SENSOR 9914519-2	*CF		1E51-1 2AU18	MTH 28-Jun-2001		O/C			
361102 RIGHT	BLEED AIR SENSOR 9914519-2			1E51-1 7AY287	MTH 10-Nov-2004 HRS 1085		O/C	0		
521001	CABIN DOOR SEAL 9912075-4	KBOI		S15501-4 4444	MTH 27-Jan-2026 HRS 7238.8 LDG 6012		O/C	0 0		



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
521002	EMERGENCY EXIT SEAL	KBOI		6511266-19 NSN	MTH 27-Jan-2026 HRS 7238.8 LDG 6012		O/C	0 0		
521003	SECONDARY DOOR SEAL	KBOI		R881515 NSN	MTH 27-Jan-2026 HRS 7238.8 LDG 6012		O/C	0 0		
531001 LEFT 531001T : L	NOSE LANDING GEAR TRUNNION SUPPORT *CF			6613056-3 SN-UNKNOWN	MTH 28-Jun-2001 LDG 0		11539	0	11539	5504
531001 RIGHT 531001T : R	NOSE LANDING GEAR TRUNNION SUPPORT *CF			6613056-4 SN-UNKNOWN	MTH 28-Jun-2001 LDG 0		11539	0	11539	5504
531202 NOSE LANDING GEAR 531202T : N	ACTUATOR FITTING *CF			6511105-1 SN-UNKNOWN	MTH 28-Jun-2001 LDG 0		22556	0	22556	16521
561001 NO. 1	LEFTHAND MAIN WINDSHIELD ASSY, (LH) UNK			9912064-15 10288	MTH 14-Aug-2020 HRS 5809.7 LDG 4809		O/C			
561002 NO. 2	RIGHTHAND MAIN WINDSHIELD ASSY, (RH) UNK			9912064-16 10257	MTH 14-Aug-2020 HRS 5809.7 LDG 4809		O/C			
561003	FOUL WEATHER WINDOW KBOI			5511275-201 N/A	MTH 21-Feb-2024 HRS 6786.1 LDG 5575		O/C	0 0 0		
561005 LEFT INBOARD	PILOTS INNER WINDOW *CF			5511285-5 SN-UNKNOWN	MTH 28-Jun-2001		O/C			
561005 LEFT OUTBOARD	PILOTS OUTER WINDOW KSMF			5511285-47 -NSN-	MTH 14-Jun-2018 HRS 5135.8 LDG 4301		O/C	0 0		
561005 RIGHT INBOARD	CO-PILOTS INNER WINDOW *CF			5511285-6 SN-UNKNOWN	MTH 28-Jun-2001		O/C			
561005 RIGHT OUTBOARD	CO-PILOTS OUTER WINDOW KGJT			PAS5511285-78 18578	MTH 31-Oct-2013 HRS 3799.6 LDG 3181		O/C	0 0 0		
562001 L1 562002 : L1	CABIN DOOR WINDOW 9912207-8 *CF			161100-03 SN-UNKNOWN	MTH 28-Jun-2001		O/C			
562001 L2	CABIN WINDOW 9912207-8 *CF			161100-03 SN-UNKNOWN	MTH 28-Jun-2001		O/C			
562001 L3	CABIN WINDOW 9912207-8 *CF			161100-03 SN-UNKNOWN	MTH 28-Jun-2001		O/C			
562001 L4	CABIN WINDOW 9912207-8 *CF			161100-03 SN-UNKNOWN	MTH 28-Jun-2001		O/C			
562001 L5	CABIN WINDOW 9912207-8 *CF			161100-03 SN-UNKNOWN	MTH 28-Jun-2001		O/C			
562001 L6	CABIN WINDOW 9912207-8 *CF			161100-03 SN-UNKNOWN	MTH 28-Jun-2001		O/C			
562001 L7	CABIN WINDOW 9912207-8 *CF			161100-03 SN-UNKNOWN	MTH 28-Jun-2001		O/C			
562001 R1	EMERGENCY DOOR WINDOW 9912207-8 *CF			161100-03 SN-UNKNOWN	MTH 28-Jun-2001		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
562001 R2	CABIN WINDOW 9912207-8	*CF		161100-03 SN-UNKNOWN	MTH 28-Jun-2001		O/C			
562001 R3	CABIN WINDOW 9912207-8	*CF		161100-03 SN-UNKNOWN	MTH 28-Jun-2001		O/C			
562001 R4	CABIN WINDOW 9912207-8	*CF		161100-03 SN-UNKNOWN	MTH 28-Jun-2001		O/C			
562001 R5	CABIN WINDOW 9912207-8	*CF		161100-03 SN-UNKNOWN	MTH 28-Jun-2001		O/C			
562001 R6	CABIN WINDOW 9912207-8	*CF		161100-03 SN-UNKNOWN	MTH 28-Jun-2001		O/C			
562001 R 7	CABIN WINDOW 9912207-8	*CF		161100-03 SN-UNKNOWN	MTH 28-Jun-2001		O/C			
572001 LEFT AFT	MLG TRUNNION FITTING ASSEMBLY *CF			6522634-5 SN-UNKNOWN	MTH 28-Jun-2001 LDG 0		23900	0	23900	17865
572001 LEFT FORWARD	MLG TRUNNION FITTING ASSEMBLY *CF			6522640-1 SN-UNKNOWN	MTH 28-Jun-2001 LDG 0		23900	0	23900	17865
572001 RIGHT AFT	MLG TRUNNION FITTING ASSEMBLY *CF			6522634-6 SN-UNKNOWN	MTH 28-Jun-2001 LDG 0		23900	0	23900	17865
572001 RIGHT FORWARD	MLG TRUNNION FITTING ASSEMBLY *CF			6522640-2 SN-UNKNOWN	MTH 28-Jun-2001 LDG 0		23900	0	23900	17865
574003 LEFT <i>574003T : T-L</i>	MLG SIDE BRACE SUPPORT FITTING *CF			6521525-1 SN-UNKNOWN	MTH 28-Jun-2001 LDG 0		50100	0	50100	44065
574004 RIGHT <i>574004T : T-R</i>	MLG SIDE BRACE SUPPORT FITTING *CF			6521525-2 SN-UNKNOWN	MTH 28-Jun-2001 LDG 0		50100	0	50100	44065
712001 LEFT	ENGINE AFT ISOLATOR 9912547-2	*CF		LM456SA2 LK0716	MTH 28-Jun-2001 HRS 0		10000	0	10000	2726.3
712001 RIGHT	ENGINE AFT ISOLATOR 9912547-2	*CF		LM456SA2 LK0619	MTH 28-Jun-2001 HRS 0		10000	0	10000	2726.3
712002 LEFT BOTTOM	FORWARD ENGINE ISOLATOR 9912547-1	*CF		LM456SA1 LK0174	MTH 28-Jun-2001 HRS 0		10000	0	10000	2726.3
712002 LEFT TOP	FORWARD ENGINE ISOLATOR 9912547-1	*CF		LM456SA1 LK0190	MTH 28-Jun-2001 HRS 0		10000	0	10000	2726.3
712002 RIGHT BOTTOM	FORWARD ENGINE ISOLATOR 9912547-1	*CF		LM456SA1 LK0204	MTH 28-Jun-2001 HRS 0		10000	0	10000	2726.3
712002 RIGHT TOP	FORWARD ENGINE ISOLATOR 9912547-1	*CF		LM456SA1 LK0195	MTH 28-Jun-2001 HRS 0		10000	0	10000	2726.3
712005	ENGINE VIBRATION MONITOR- 9912519-2	*CF		2789 020115	MTH 28-Jun-2001		O/C			
71EN1 NO. 1 <i>710001 : E1**L</i>	ENGINE 9912545-1	KBOI		PW535A PCE-DC0072	MTH 24-Jul-2017 HRS 4930.9 LDG 4107		E/C	4907.9		
71EN2 NO. 2 <i>710001 : E2**R</i>	ENGINE 9912545-1	KBOI		PW535A PCE-DC0071	MTH 24-Jul-2017 HRS 4930.9 LDG 4107		E/C	4907.9		
721010 E1	GEARBOX	UNK		3078180-01 SN-UNKNOWN	MTH 14-Jul-2017 HRS 4930.9 LDG 4107		O/C	0 0 0		
721010 E2	GEARBOX	UNK		3078180-01 SN-UNKNOWN	MTH 12-Jul-2017 HRS 4930.9 LDG 4107		O/C	0 0 0		



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
722001 E1	OIL PUMP	UNK		3052415-01 43A134	MTH 14-Jul-2017 HRS 4930.9 LDG 4107		O/C	0 4907.9 4084		
722001 E2	OIL PUMP	UNK		3052415-01 3A696	MTH 12-Jul-2017 HRS 4930.9 LDG 4107		O/C	0 4907.9 4084		
722608 E1	LP COMPRESSOR FAN ROTOR *CF			3054281-01 A000NBLB	MTH 28-Jun-2001 LDG 23 ACCC YC		15000	0	15023	8988 8988
722608 E2	LP COMPRESSOR FAN ROTOR *CF			3054281-01 A000NN12	MTH 28-Jun-2001 LDG 23 ACCC YC		15000	0	15023	8988 8988
722609 E1	LP COMPRESSOR BOOST ROTOR *CF			3041742-01 A000N9CX	MTH 28-Jun-2001 LDG 23 ACCC YC		15000	0	15023	8988 8988
722609 E2	LP COMPRESSOR BOOST ROTOR UNK			3041742-01 A000N9AW	MTH 12-Jul-2017 HRS 4930.9 LDG 4107 ACCC YC		15000	4084 4084	15023	8988 8988
722610 E1	LP COMPRESSOR SHAFT			PN SN-UNKNOWN	MTH 28-Jun-2001		H/T H/T	0		
722610 E2	LP COMPRESSOR SHAFT			PN SN-UNKNOWN	MTH 28-Jun-2001		H/T H/T	0		
723705 E1	2ND-STAGE TURBINE DISK *CF			3053812-01 A000N4FD	MTH 28-Jun-2001 LDG 23 ACCC YC		13500	0	13523	7488 7488
723705 E2	2ND-STAGE TURBINE DISK *CF			3053812-01 A000PH32	MTH 28-Jun-2001 LDG 23 ACCC YC		13500	0	13523	7488 7488
724001 E1 INNER	COMBUSTION LINER *CF			3052890-01 A000NCNL	MTH 28-Jun-2001		O/C			
724001 E1 OUTER	COMBUSTION LINER *CF			3042613-01 A000MHNP	MTH 28-Jun-2001		O/C			
724001 E2 INNER	COMBUSTION LINER *CF			3052890-01 A000PRMC	MTH 28-Jun-2001		O/C			
724001 E2 OUTER	COMBUSTION LINER *CF			3042613-01 A000NTRF	MTH 28-Jun-2001		O/C			
724006 E1	3RD-STAGE TURBINE DISK UNK			3055823-01 A000NRPR	MTH 14-Jul-2017 HRS 4930.9 LDG 4107 ACCC YC		13500	4084 4084	13523	7488 7488
724006 E2	3RD-STAGE TURBINE DISK UNK			3055823-01 A000NRR4	MTH 12-Jul-2017 HRS 4930.9 LDG 4107 ACCC YC		13500	4084 4084	13523	7488 7488
724706 E1	1ST-STAGE TURBINE DISK *CF			3053331-01 A000P827	MTH 28-Jun-2001 LDG 23 ACCC YC		10000	0	10023	3988 3988



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
724706 E2	1ST-STAGE TURBINE DISK *CF			3053331-01 A000NEFT	MTH 28-Jun-2001 LDG 23 ACCC YC		10000	0	10023	3988 3988
724707 E1	HIGH TURBINE BLADES UNK			3041871-01 VARIOUS	MTH 14-Jul-2017 HRS 4930.9 LDG 4107		O/C			
724707 E2	HIGH TURBINE BLADES UNK			3041871-01 VARIOUS	MTH 12-Jul-2017 HRS 4930.9 LDG 4107		O/C			
724708 E1	1ST-STAGE HP COMPRESSOR ROTOR UNK			3070301-01 A000MP33	MTH 14-Jul-2017 HRS 4930.9 LDG 4107 ACCC YC		10000	4084 4084	10023	3988 3988
724708 E2	1ST-STAGE HP COMPRESSOR ROTOR UNK			3070301-01 A000MP31	MTH 12-Jul-2017 HRS 4930.9 LDG 4107 ACCC YC		10000	4084 4084	10023	3988 3988
724709 E1	2ND-STAGE HP COMPRESSOR ROTOR *CF			3052662-01 A000MTE5	MTH 28-Jun-2001 LDG 23 ACCC YC		13500	0	13523	7488 7488
724709 E2	2ND-STAGE HP COMPRESSOR ROTOR *CF			3052662-01 A000MTE2	MTH 28-Jun-2001 LDG 23 ACCC YC		13500	0	13523	7488 7488
724825 E1	CENTRIFUGAL IMPELLER *CF			3052661-01 A000MH8F	MTH 28-Jun-2001 LDG 23 ACCC YC		13500	0	13523	7488 7488
724825 E2	CENTRIFUGAL IMPELLER *CF			3052661-01 A000MH8K	MTH 28-Jun-2001 LDG 23 ACCC YC		13500	0	13523	7488 7488
731004 NO. 1	LOW FUEL PRESSURE SWITCH 9912033-2 *CF			1103P0448 SN-UNKNOWN	MTH 28-Jun-2001		O/C			
731004 NO. 2	LOW FUEL PRESSURE SWITCH 9912033-2 *CF			1103P0448 SN-UNKNOWN	MTH 28-Jun-2001		O/C			
733002	FUEL FLOW/QUANTITY INDICATOR 9912560-5 BOI			10537N04M02 01020677	MTH 30-Dec-2008 HRS 2454		O/C	2454		
733003 NO. 1	FUEL FLOW TRANSMITER 9914413-1 *CF			9-231-28 L8086 L7969	MTH 28-Jun-2001		O/C			
733003 NO. 2	FUEL FLOW TRANSMITER 9914413-1 *CF			9-231-28 L8039	MTH 28-Jun-2001		O/C			
731002 E1	FLOW DIVIDER 3052780-02 UNK			823660-02 F64796	MTH 14-Jul-2017 HRS 4930.9 LDG 4107		O/C	0 0 0		
731002 E2	FLOW DIVIDER 3052780-02 UNK			823660-02 F51268	MTH 12-Jul-2017 HRS 4930.9 LDG 4107		O/C	0 4907.9 4084		
731125 E1	FUEL MANIFOLD ASSEMBLY			PN SN-UNKNOWN	MTH 28-Jun-2001		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
731125 E2	FUEL MANIFOLD ASSEMBLY			PN SN-UNKNOWN	MTH 28-Jun-2001		O/C	0		
732000 E1	TEMPERATURE SENSOR 3052375-03	UNK		818487-4 KC-07-3951	MTH 14-Jul-2017 HRS 4930.9 LDG 4107		O/C	0 2827.9 0		
732000 E2	TEMPERATURE SENSOR 3052375-03	UNK		818487-4 KC-16-11689	MTH 12-Jul-2017 HRS 4930.9 LDG 4107		O/C	0 0 0		
732001 E1	FUEL CONTROL UNIT	KBOI		1012633-49 F59723	MTH 12-Aug-2021 HRS 6024.5 LDG 4981		O/C	352		
732001 E2	FUEL CONTROL UNIT	KBOI		1012633-49 F84727	MTH 12-Aug-2021 HRS 6024.5 LDG 4981		O/C			
732005 E1	N2 SPEED SENSOR	UNK		3052370-01 CH475	MTH 14-Jul-2017 HRS 4930.9 LDG 4107		O/C	0 4907.9 0		
732005 E2	N2 SPEED SENSOR	UNK		3052370-01 CH476	MTH 12-Jul-2017 HRS 4930.9 LDG 4107		O/C	4907.9		
732006 E1	N1 SPEED SENSOR	UNK		3052630-01 CH170	MTH 14-Jul-2017 HRS 4930.9 LDG 4107		O/C	0 4907.9 4084		
732006 E2	N1 SPEED SENSOR	UNK		3052630-01 CH180	MTH 12-Jul-2017 HRS 4930.9 LDG 4107		O/C	0 4907.9 4084		
741001 E1	EXCITER IGNITION 31J2807-07	UNK		500335-1 NNA11140142	MTH 14-Jul-2017 HRS 4930.9 LDG 4107		O/C	18 428.9 0		
741001 E2	EXCITER IGNITION 31J2807-07	BOI		500335-1 NNA05047428	MTH 19-Jan-2010 HRS 2763		O/C	0		
742001 E1 INBOARD	IGNITER 3070508-01	KBOI		502600-1 NNA19110049	MTH 06-Feb-2024 HRS 6773.6 LDG 5563		O/C	0 0 0		
742001 E1 OUTBOARD	IGNITER 3070508-01	BOI		502600-1 NNA15280130	MTH 20-Jul-2018 HRS 5164.3 LDG 4326		O/C	0 0		
742001 E2 INBOARD	IGNITER 3070508-01	KBOI		502600-1 NNA19060070	MTH 06-Feb-2024 HRS 6773.6 LDG 5563		O/C	0 0 0		
742001 E2 OUTBOARD	IGNITER 3070508-01	KBOI		502600-1 NNA22400209	MTH 06-Feb-2024 HRS 6773.6 LDG 5563		O/C	0 0 0		



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
742002 E1 INBOARD	SHORT IGNITOR LEAD	UNK		3127408-01 NNA16280086	MTH 14-Jul-2017 HRS 4930.9 LDG 4107		O/C	6 85 64		
742002 E2 INBOARD	SHORT IGNITOR LEAD	UNK		3127408-01 NNA16280059	MTH 12-Jul-2017 HRS 4930.9 LDG 4107		O/C	6 85 64		
742003 E1 OUTBOARD	LONG IGNITOR LEAD	UNK		3127408-02 NNA16140248	MTH 14-Jul-2017 HRS 4930.9 LDG 4107		O/C	6 85 64		
742003 E2 OUTBOARD	LONG IGNITOR LEAD	UNK		3127408-02 NNA16100275	MTH 12-Jul-2017 HRS 4930.9 LDG 4107		O/C	6 85 64		
750001 E1	BLEED VALVE CONTROL 3052768-02	UNK		822728-2-003 04067257	MTH 14-Jul-2017 HRS 4930.9 LDG 4107		O/C	0 0 0		
750001 E2	BLEED VALVE CONTROL 3052768-02	UNK		822728-2-003 06055105	MTH 12-Jul-2017 HRS 4930.9 LDG 4107		O/C	0 0 0		
753001 E1	LINEAR TRANSFORMER *CF			3052372-01 1599	MTH 28-Jun-2001		O/C			
753001 E2	LINEAR TRANSFORMER *CF			3052372-01 1600	MTH 28-Jun-2001		O/C			
753002 E1	INTERCOMPRESSOR BLEED VALVE SERVO VALVE	UNK		3075987-01 TR4847	MTH 14-Jul-2017 HRS 4930.9 LDG 4107		O/C	2043.5		
753002 E2	INTERCOMPRESSOR BLEED VALVE SERVO VALVE	UNK		3075987-01 TR4867	MTH 12-Jul-2017 HRS 4930.9 LDG 4107		O/C	1794.9		
761002	SYNCHRONIZER CONTROL BOX *CF			213693 12239980	MTH 28-Jun-2001		O/C			
761003	ENGINE SYNC ACTUATOR *CF			5485-066 12365217	MTH 28-Jun-2001		O/C			
771010 771004	N1 FAN TACHOMETER INDICATOR 9912560-1	BOI		10535N04M00 0005651AB	MTH 30-Dec-2008 HRS 2454		O/C	0		
771011 771005	N2 TURBINE TACHOMETER INDICATOR 9912560-4	*CF		10536N04M00 0006651	MTH 28-Jun-2001		O/C			
773001 LEFT ENGINE	ACCELEROMETER *CF			6222SM15 17739	MTH 28-Jun-2001		O/C			
773001 RIGHT ENGINE	ACCELEROMETER *CF			6222SM15 17749	MTH 28-Jun-2001		O/C			
780011 LEFT	THRUST REVERSER/ARM PRESSURE SWITCH BOI			6607A7-45 L049850	MTH 11-Feb-2011 HRS 3092.1 LDG 2558		O/C	0 0 0		
780011 RIGHT	THRUST REVERSER/ARM PRESSURE SWITCH			6607A7-45 M066104	MTH 03-Jan-2012 HRS 3256.7 LDG 2710		O/C			
783001 LEFT ENGINE	THRUST REVERSER ASSEMBLY 9912546-1	*CF		03ND-78002-1 0073	MTH 28-Jun-2001		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
783001 RIGHT ENGINE	THRUST REVERSER ASSEMBLY 9912546-2	*CF		03ND-78002-2 0072	MTH 28-Jun-2001		O/C			
783002 LEFT ENGINE	THRUST REVERSER CONTROL VALVE 3435	*CF		65680 3435	MTH 28-Jun-2001		O/C			
783002 RIGHT ENGINE	THRUST REVERSER CONTROL VALVE 3530	*CF		65680 3530	MTH 28-Jun-2001		O/C			
783003 LEFT ENGINE	THRUST REVERSER ISOLATION VALVE 4203	*CF		13027-4 4203	MTH 28-Jun-2001		O/C			
783003 RIGHT ENGINE	THRUST REVERSER ISOLATION VALVE 4207	*CF		13027-4 4207	MTH 28-Jun-2001		O/C			
783010 LEFT INBOARD	THRUST REVERSER ACTUATOR SN-UNKNOWN	*CF		53ND-78203-5 SN-UNKNOWN	MTH 28-Jun-2001		O/C			
783010 LEFT OUTBOARD	THRUST REVERSER ACTUATOR SN-UNKNOWN	*CF		53ND-78203-5 SN-UNKNOWN	MTH 28-Jun-2001		O/C			
783010 RIGHT INBOARD	THRUST REVERSER ACTUATOR SN-UNKNOWN	*CF		53ND-78203-5 SN-UNKNOWN	MTH 28-Jun-2001		O/C			
783010 RIGHT OUTBOARD	THRUST REVERSER ACTUATOR BOI			53ND-78203-5 1963	MTH 09-May-2011 HRS 3131.4 LDG 2600		O/C	0 0		
793001	OIL TEMP INDICATOR KBOI			10536N04M00/991256 0-4 01050685A	MTH 10-Nov-2023 HRS 6693 LDG 5506		O/C	0 0 0		
793002 LEFT ENGINE	OIL TEMPERATURE TRANSMITTER 03498	*CF		102-00083 03498	MTH 28-Jun-2001		O/C			
793002 RIGHT ENGINE	OIL TEMPERATURE TRANSMITTER 03494	*CF		102-00083 03494	MTH 28-Jun-2001		O/C			
793004 LEFT ENGINE	OIL PRESSURE TRANSMITTER 9912464-1	*CF		APTE-237D-1000- 250D 65392133	MTH 28-Jun-2001		O/C			
793004 RIGHT ENGINE	OIL PRESSURE TRANSMITTER 9912464-1	*CF		APTE-237D-1000- 250D 653910295	MTH 28-Jun-2001		O/C			
793006 LEFT ENGINE	LOW OIL PRESSURE SWITCH 9912466-2	*CF		1153P0098-01 0342	MTH 28-Jun-2001		O/C			
793006 RIGHT ENGINE	LOW OIL PRESSURE SWITCH 9912466-2	*CF		1153P0098-01 SN-UNKNOWN	MTH 28-Jun-2001		O/C			

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL 560-03-02 R01	SUPPLEMENTAL TYPE CERTIFICATE (STC) (SUPERSEDED BY CIL-03-01)			INFORMATIONAL			-			
	MOC :									
SB 560-03-06 R01	OPERATIONAL CERTIFICATION REQUIREMENTS - U.S. TO CANADIAN CONVERSION			OPTIONAL			-			
	MOC :									
SB 560-03-06	OPERATIONAL CERTIFICATION REQUIREMENTS - U.S. TO CANADIAN CONVERSION (SUPERSEDED BY 560-03-06 R01)			OPTIONAL			-			
	MOC :									
SL CIL-03-01	SUPPLEMENTAL TYPE CERTIFICATE (STC)			INFORMATIONAL			-			
	MOC :									
SL CIL-99-01 R01	USE OF CORROSION INHIBITING COMPOUNDS			INFORMATIONAL			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL CIL-99-01	USE OF CORROSION INHIBITING COMPOUNDS			INFORMATIONAL			-			
	MOC :									
SL CIL-99-02	AVOID OPERATIONS ON RUNWAYS TREATED WITH RUNWAY DE-ICE (RDI) FLUIDS. AIRCRAFT WASHING RECOMMENDED AFTER EXPOSURE TO RDI FLUIDS			RECOMMENDED MTH			-			
	MOC :									
SL CIL-99-03 R01	CORROSION PREVENTION AND CONTROL PROGRAM (CPCP)			RECOMMENDED			-			
	MOC :									
SL CIL-99-03	CORROSION PREVENTION AND CONTROL PROGRAM (CPCP) (SUPERSEDED BY CIL-99-03 R01)			RECOMMENDED MTH			-			
	MOC :									
SL CIL-99-04	MISCELLANEOUS - INCREMENTAL LIBRARY UPDATES FOR CESVIEW			INFORMATIONAL			-			
	MOC :									
SL 560-99-02 R06	CESCOM PRICES (THIS SL CANCELS SL560-99-02 R5 AND PREVIOUS)			INFORMATIONAL			-			
	MOC :									
SL 560-99-04	MISCELLANEOUS - CESSNA PART NUMBER SUFFIXES FOR REMANUFACTURED PARTS			INFORMATIONAL			A/R			
	MOC :									
SL 560-99-05	MISCELLANEOUS - CESSNA SERVICE DOCUMENT CHANGE NOTIFICATION			INFORMATIONAL			A/R			
	MOC :									
SL 560-99-07	MISCELLANEOUS - TRANSMITTAL OF ROCKWELL COLLINS OPERATORS BULLETIN (OPSB) 0166-17 - THE FMS MAY TURN IN THE WRONG DIRECTION AFTER SEQUENCING A "CLIMB TO" ALTITUDE THAT WAS MANUALLY EDITED OR TEMPERATURE COMPENSATED			INFORMATIONAL			-			
	MOC :									
SL 560-05-08 05SL-08	TRANSMITTAL OF PRATT & WHITNEY CANADA MAINTENANCE MANUAL TEMPORARY REVISION. 05-3 SCHEDULED MAINTNENCE CHECKS	BOI		INFORMATIONAL	MTH 02-Jun-2003 HRS 756		OPEN OPEN OPEN			Complete
	MOC : COMPLIED WITH									
SL 560-05-12	TIME LIMITS / MAINTENANCE CHECKS - HEAT EXCHANGER LIFE LIMIT			INFORMATIONAL			-			
	MOC :									
SB 560-12-01	ADDITIONAL APPROVED FUEL ANTI-ICE ADDITIVES (SUPERSEDED BY 560-12-01 R01)			INFORMATIONAL			-			
	MOC :									
SL CIL-99-01 R02	USE OF CORROSION INHIBITING COMPOUNDS			INFORMATIONAL			-			
	MOC :									
SL CIL-20-01 R02	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL			INFORMATIONAL			-			
	MOC :									
SL CIL-20-01 R03- CN	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL			CANCELLED			-			
	MOC :									
SL CIL-20-01	CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL (SUPERSEDED BY CIL-20-01 R01)			INFORMATIONAL			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL 560-20-01 R25	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL (SUPERSEDED BY SL560-20-01 R26) INFORMATIONAL									
	MOC :									
SL 560-20-04	STANDARD PRACTICES - CESSNA STANDARD PRACTICES MANUAL INFORMATIONAL									
	MOC :									
SB 560-21-17 21SB-17	CABIN FAN AND DEFOG BLOWER WIRING IMPROVEMENT (SUPERSEDED BY 560-21-17 R01)	BOI		DISCRETIONARY	MTH 23-Oct-2003 HRS 840		-			Complete
	MOC : COMPLIED WITH									
SB 560-21-18 21SB-18	CABIN OUTFLOW VALVE SOLENOID IMPROVEMENT	BOI		MANDATORY	MTH 24-Oct-2002 HRS 582		-			Complete
	MOC : COMPLIED WITH									
SB 560-21-19 R01 21SB-19 : 560R1	EMERGENCY PRESSURIZATION BLEED AIR VALVE RELOCATION (SUPERSEDED BY 560-21-19 R02)	BOI		RECOMMENDED	MTH 04-Apr-2003 HRS 714		A/R			Complete
	MOC : COMPLIED WITH									
SB 560-21-22 21SB-22	AFT EVAPORATOR DRAIN MAST RELOCATION	ICT		DISCRETIONARY	MTH 11-Mar-2005 HRS 1156		-			Complete
	MOC : COMPLIED WITH									
SB 560-21-24 21SB-24	RAM AIR DUCT IMPROVEMENT	ICT		DISCRETIONARY	MTH 11-Mar-2005 HRS 1156		-			Complete
	MOC : COMPLIED WITH									
SB 560-21-25 21SB-25	EMERGENCY PRESSURIZATION VALVE AND PRINTED CIRCUIT BOARD (PCB) INSTALLATION IMPROVEMENT			DISCRETIONARY	MTH		-			
	MOC :									
SB 560-21-26 21SB-26	DEFOG BLOWER BONDING JUMPER	BOI		RECOMMENDED	MTH 27-Apr-2007 HRS 1842		A/R			Complete
	MOC : COMPLIED WITH									
SB 560-21-27 21SB-27	PARTICULATE TRAP INSTALLATION (SUPERSEDED BY 560-21-27 R01)	BOI		RECOMMENDED	MTH 06-Jun-2006 HRS 1568		-			Complete
	MOC : COMPLIED WITH									
SB 560-21-28 21SB-28	ALTITUDE PRESSURE SENSOR IMPROVEMENT			OPTIONAL	MTH		A/R			
	MOC :									
SB 560-21-32 21SB-32	PRESSURIZATION OUTFLOW VALVE PLUMBING IMPROVEMENT	BOI		RECOMMENDED	MTH 13-Dec-2017 HRS 5050 LDG 4206 ACH 404.7		A/R			Complete
	MOC : COMPLIED WITH - COMPLIED WITH SERVICE BULLETIN SB560-21-32 REFERENCING THE CESSNA 560 MAINT. MANUAL AND INSTRUCTIONS IN THE BULLETIN. OPERATIONAL AND LEAK CHECKED GOOD.									
SB 560-21-34 21SB-34	AIR CONDITIONING FAN MOTOR WIRING MODIFICATION			OPTIONAL	MTH		A/R			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB 560-21-35	TEMPERATURE CONTROLLER IMPROVEMENT			OPTIONAL	MTH		A/R			
	MOC :									
SB 560-21-36	TAILCONE WIRE PROTECTION INSTALLATION	BOI		MANDATORY	MTH 13-Jan-2011 HRS 3069.3 LDG 2539		A/R			Complete
	MOC :									
	COMPLIED WITH - COMPLIED WITH SERVICE BULLETIN 560-21-36 THIS DATE. THIS IS A ONE TIME BULLETIN, NO FURTHER ACTION REQUIRED. (NO DAMAGE NOTED ON WIRE INSPECTION)									
SL CIL-21-01	COMPRESSOR MOTOR BRUSH LIFE LIMIT			INFORMATIONAL			-			
	MOC :									
SL CIL-21-02 R01	ENVIRONMENTAL HOUR METER INSTALLATION	KBOI		MANDATORY	MTH 04-Aug-2014 HRS 4010.1 LDG 3356		-			N/A
	MOC :									
	NOT APPLICABLE - THIS SERVICE LETTER DOES NOT APPLY. VAPOR COOLING SYSTEM WAS CESSNA INSTALLED AND HAS HOUR METER WITH CORRECT WIRING.									
SL CIL-21-02	ENVIRONMENTAL HOUR METER INSTALLATION (SUPERSEDED BY CIL-21-02 R01)			OPTIONAL			-			
	MOC :									
SL 560-21-11 21SL-11	RAM AIR INLET DRAIN LINE INSPECTION (SUPERSEDED BY SL560-21-11 R01)	BOI		RECOMMENDED	MTH 07-Jun-2002 HRS 407		A/R			Complete
	MOC :									
	COMPLIED WITH									
SL 560-21-13 21SL-13	PRESSURIZATION CONTROLLER WIRING CHANGE	BOI		MANDATORY	MTH 16-May-2003 HRS 751		-			Complete
	MOC :									
	COMPLIED WITH									
SL 560-21-15 R02 21SL-15 : 560R2	INSPECTION OF THE PRESSURIZATION STATIC LINE			MANDATORY	MTH 12-Jun-2008 HRS 2291		A/R			Complete
	MOC :									
	COMPLIED WITH									
SL 560-21-15 21SL-15	INSPECTION OF THE PRESSURIZATION STATIC LINE (SUPERSEDED BY SL560-21-15 R01)	BOI		SUPERSEDED	MTH 02-Oct-2007 HRS 1966		A/R			Complete
	MOC :									
	COMPLIED WITH - INTENT ACCOMPLISHED DURING PREVIOUS MAINTENANCE OR THROUGH ALTERNATE METHOD OF COMPLIANCE.									
SL 560-21-16 21SL-16	AIR CONDITIONING - AIR CONDITIONING EXHAUST DOOR SHAFT SPACER INSPECTION	BOI		DISCRETIONARY	MTH 27-Mar-2007 HRS 1817		A/R			Complete
	MOC :									
	COMPLIED WITH									
SB 560-23-27 R04 23SB-27 : 560R4	COCKPIT SPEAKER MUTE SWITCH INSTALLATION	*CF		OPTIONAL	MTH		A/R			
	MOC :									
SB 560-23-32 23SB-32	RNZ-850 NAVIGATION RADIO UPGRADE (SUPERSEDED BY 560-23-32 R01)	BOI		MANDATORY	MTH 29-Dec-2003 HRS 885		A/R			Complete
	MOC :									
	COMPLIED WITH									
SB 560-23-38 R02	COMMUNICATIONS - RADIO MANAGEMENT UNIT (RM855) INSTALLATION	SMF		OPTIONAL	MTH 19-Mar-2018 HRS 5075.9 LDG 4240		-			Complete
	MOC :									
	COMPLIED WITH - COMPLIED WITH CESSNA SERVICE BULLETIN SB560-23-38. OPERATIONAL CHECK NORMAL.									



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB 560-23-38	COMMUNICATIONS - RADIO MANAGEMENT UNIT (RM855) INSTALLATION (SUPERSEDED BY 560-23-38 R01)									
				OPTIONAL	MTH		A/R			
	MOC :									
SL 560-23-16 23SL-16	AIRSHOW RELIABILITY IMPROVEMENTS AND SERVICE PACK SOFTWARE UPGRADE (SUPERSEDED BY SL560-23-16 R01)									
		BOI		RECOMMENDED	MTH 03-Dec-2002 HRS 604		-			Complete
	MOC : COMPLIED WITH - NOT APPLICABLE-EQUIPMENT NOT INSTALLED									
SL 560-23-17 23SL-17	TRANSMITTAL OF HONEYWELL SERVICE BULLETIN A21-3851-001									
				RECOMMENDED	MTH 01-Dec-2005 HRS 1371		-			Complete
	MOC : COMPLIED WITH									
SL 560-23-19 23SL-19	COMMUNICATIONS - TRANSMITTAL OF HONEYWELL SERVICE BULLETIN 7511001-23-6026 SRZ-850/851INTEGRATED RADIO SYSTEM - REMOVE THE RISK OF AUDIO FEEDBACK WHEN POWER IS TURNEDON									
				DISCRETIONARY	MTH		-			
	MOC :									
SB 560-24-29 24SB-29	NO SMOKING LIGHT WIRING MODIFICATION									
		BOI		OPTIONAL	MTH		-			
	MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME									
SB 560-24-34 24SB-34	IGNITER RELAY UPGRADE									
		ICT		RECOMMENDED	MTH 08-Dec-2001 HRS 159		-			Complete
	MOC : COMPLIED WITH									
SB 560-24-37 R01 24SB-37 : 560R1	MAIN POWER WIRE ANCHOR IMPROVEMENT (SUPERSEDED BY 560-24-37 R02)									
		BOI		RECOMMENDED	MTH 21-Nov-2002 HRS 590		-			Complete
	MOC : COMPLIED WITH									
SB 560-24-40 24SB-40	BATTERY TIE DOWN ROD REPLACEMENT									
		BOI		ON ATTRITION	MTH 11-Oct-2002 HRS 572		-			Complete
	MOC : COMPLIED WITH									
SB 560-24-41 24SB-41	CIRCUIT BREAKER AMPERAGE INCREASE FOR THE MEGGITT SECONDARY FLIGHT DISPLAY (SUPERSEDED BY 560-24-41 R01)									
		BOI		OPTIONAL	MTH 30-Dec-2003 HRS 885		A/R			Complete
	MOC : COMPLIED WITH									
SB 560-24-46	ELECTRICAL POWER - BATTERY TEMPERATURE INDICATOR GAGE BLANKING PLATE INSTALLATION									
				OPTIONAL			-			
	MOC :									
SB 560-24-47 R01	ELECTRICAL POWER - TIME DELAY RELAY INSTALLATION									
				OPTIONAL	MTH		-			
	MOC :									
SB 560-24-47	ELECTRICAL POWER - TIME DELAY RELAY INSTALLATION									
				OPTIONAL			-			
	MOC :									
SB 560-25-08 25SB-08	AFT JUMP SEAT INSTALLATION									
		*CF		OPTIONAL	MTH		-			
	MOC :									
SB 560-25-28 25SB-28	FORWARD AND AFT DIVIDER IMPROVEMENT									
				OPTIONAL	MTH		-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB 560-25-29 R01 25SB-29 : 560R1	GLARESHIELD LEATHER STRIP INSTALLATION			OPTIONAL	MTH		-			
MOC :										
SB 560-25-30 25SB-30	SEAT TRACK STRUCTURE MODIFICATION	ICT		DISCRETIONARY	MTH 11-Mar-2005 HRS 1156		-			Complete
MOC : COMPLIED WITH										
SB 560-25-31 R02 25SB-31	ARTEX C406-2 THREE-FREQUENCY EMERGENCY LOCATOR TRANSMITTER (ELT)			OPTIONAL			A/R			
MOC :										
SB 560-25-31 25SB-31	ARTEX C406-2 THREE-FREQUENCY EMERGENCY LOCATOR TRANSMITTER (ELT) (SUPERSEDED BY 560-25-31 R01)	BOI		SUPERSEDED			A/R			
MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
SL 560-25-06 25SL-06	EQUIPMENT/FURNISHINGS - CABIN SYSTEMS AIRSHOW 400 DIGITAL INTERFACE UNIT (DIU) 920040 SERVICE BULLETIN 920040-44-01 SAVE MAIN CPU CMOS SETUP SETTINGS TO FLASH MEMORY			OPTIONAL	MTH		A/R			
MOC :										
SL 560-25-09 25SL-09	EQUIPMENT/FURNISHINGS - TRANSMITTAL OF PACIFIC SCIENTIFIC AEROSPACE SERVICE BULLETIN SB 25-1111432, INFORMATION REGARDING THE POTENTIAL FAILURE OF THE GUARDED ROTARYBUCKLE PLASTIC HANDLE	BOI		MANDATORY	MTH 14-Oct-2009 HRS 2659		A/R			N/A
MOC : NOT APPLICABLE										
SL 560-25-10 25SL-10	EQUIPMENT/FURNISHINGS - TRANSMITTAL OF ROCKWELL COLLINS SERVICE BULLETIN 9200XX-44-4 AIRSHOW 400 DIGITAL INTERFACE UNIT (DIU) AND AIRSHOW GENESYS DATA COMMUNICATION UNIT (DCU)			DISCRETIONARY	MTH		A/R			
MOC :										
SB 560-26-01 26SB-01	FIRE BOTTLE WIRE IDENTIFICATION SLEEVE INSTALLATION			MANDATORY	DAYS 02-May-2005 HRS 1202		A/R			Complete
MOC : COMPLIED WITH										
ASL 560-26-01 26ASL-01	FIRE PROTECTION - TRANSMITTAL OF MEGGITT SAFETY SYSTEMS SERVICE BULLETIN 26-36 - THERMISTORS DETECTORS			MANDATORY	MTH 07-Feb-2008 HRS 2125		A/R			N/A
MOC : NOT APPLICABLE - NOT APPLICABLE										
SL CIL-26-01	FIRE PROTECTION - FIRE EXTINGUISHER BOTTLE CARTRIDGE GROUND STUD TORQUING (SUPERSEDED BY CIL-26-01 R01)	BOI		MANDATORY	MTH 20-May-2016 HRS 4611.7 LDG 3848 ACH 365.5		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH CIL-26-01 REFERENCING THE CIL AND THE CESSNA 560 MAINT.MANUAL. NO DEFECTS FOUND.										
SL 560-26-02 R01	FIRE PROTECTION - FIRE BOTTLE WIRE VERIFICATION AND TEST	KBOI		MANDATORY	DAYS 30-Sep-2024 HRS 6950.8 LDG 5711		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH SL560-26-02 REV 1 BY ENSURING CORRECT FIRE BOTTLE WIRE INSTALLATION PER STEP 6 OF LETTERS ACCOMPLISHMENT INSTRUCTIONS.										



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB 560-27-16 27SB-16	ELEVATOR ELECTRIC TRIM PRINTED CIRCUIT BOARD REPLACEMENT	BOI		MANDATORY	MTH 18-Aug-2004 HRS 1044		A/R			Complete
MOC : COMPLIED WITH										
SB 560-27-19 27SB-19	FLIGHT CONTROLS - FLAP FOLLOW-UP CABLE IMPROVEMENT			DISCRETIONARY	MTH 30-Nov-2007 HRS 2044		A/R			Complete
MOC : COMPLIED WITH										
SB 560-27-20 R02 27SB-20 : 560R2	FLIGHT CONTROLS - RUDDER PEDAL POSITION IMPROVEMENT	BOI		RECOMMENDED	MTH 02-Nov-2011 HRS 3236.9 LDG 2696		300			
MOC : DEFERRED										
SB 560-27-21 27SB-21	FLIGHT CONTROLS - RUDDER SYSTEM GUARD TUBE IMPROVEMENT			DISCRETIONARY	MTH		A/R			
MOC :										
SB 560-27-22 27SB-22	FLIGHT CONTROLS - RUDDER PEDAL SUPPORT IMPROVEMENT			DISCRETIONARY	MTH		A/R			
MOC :										
SB 560-27-23	FLIGHT CONTROLS - ELEVATOR BELLCRANK SUPPORT BRACKET INSPECTION AND REPAIR	BOUI		MANDATORY	MTH 12-Nov-2010 HRS 3018.2 LDG 2508		A/R			Complete
MOC : COMPLIED WITH - C/W CESSNA SERVICE BULLETIN 560-27-23, FLIGHT CONTROLS-ELEVATOR BELLCRANK SUPPORT BRACKET INSPECTION. NO DAMAGE FOUND AND GAP IS MORE THAN.010 INCHES.										
SL 560-27-04 27SL-04	ELEVATOR TORQUE TUBE INSPECTION	BOI		MANDATORY	MTH 25-Jun-2003 HRS 777		A/R			Complete
MOC : COMPLIED WITH										
SL 560-27-08 27SL-08	LOWER CABLE GUARD INSPECTION	BOI		RECOMMENDED	MTH 11-Dec-2003 HRS 879		-			Complete
MOC : COMPLIED WITH										
SL 560-27-11 27SL-11	FLAP FOLLOW-UP CABLE IMPROVEMENT	BOI		MANDATORY	MTH 15-May-2007 HRS 1857		A/R			Complete
MOC : COMPLIED WITH										
SL 560-27-12 27SL-12	FLIGHT CONTROLS - RUDDER PEDAL POSITIONING INSPECTION	BOI		MANDATORY	MTH 26-Sep-2006 HRS 1660		A/R			Complete
MOC : COMPLIED WITH										
SL 560-27-13 27SL-13	RUDDER PEDAL SUPPORT INSPECTION			RECOMMENDED	MTH 05-Jun-2006 HRS 1566		-			Complete
MOC : COMPLIED WITH										
SL 560-27-14 27SL-14	FLIGHT CONTROLS - AILERON TRIM STOP BLOCK INSPECTION	BOI		MANDATORY	MTH 22-Dec-2010 HRS 3066 LDG 2535		A/R			Complete
MOC : COMPLIED WITH - CESSNA SERVICE LETTER 560-27-14 PCW ON 03/10/2009 @ 2522.0 HRS. AND 2108 LANDINGS. NO DISCREPANCIES FOUND										



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL 560-27-15	FLIGHT CONTROLS - AUTOPILOT WIRE HARNESS POSITION	B01		MANDATORY	DAYS 09-Sep-2016 HRS 4737.4 LDG 3954 ACH 379.7		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH THIS SERVICE LETTER BY INSTALLING SPIRAL WRAP ON AUTO PILOT CONTROL HEAD WIRE HARNESS IN CENTER CONSOLE WITH CONNECTOR FACING LEFT, OPERATIONAL CHECKED AUTO PILOT, ANDEVERYTHING CHECKED GOOD.										
SL 560-27-16	FLIGHT CONTROLS - CONTROL LOCK CABLE ASSEMBLY SWIVEL SEAL INSPECTION	KBOI		RECOMMENDED	MTH 13-Jan-2025 HRS 7016.1 LDG 5777		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH SL560-27-16 BY INSPECTING CONTROL LOCK CABLE ASSEMBLY SWIVEL SEAL. NO DEFECTS NOTED. WORK PERFORMED IN REF LETTERS ACCOMPLISHMENT INSTRUCTIONS.										
SB 560-28-08 28SB-08	FUEL LOW PRESSURE TIME DELAY	BOI		OPTIONAL	MTH 02-May-2002 HRS 361		-			Complete
MOC : COMPLIED WITH										
SB 560-28-09 28SB-09	SINGLE-POINT REFUEL INDUCED IMBALANCE IMPROVEMENT	BOI		DISCRETIONARY	MTH 13-Nov-2002 HRS 590		-			Complete
MOC : COMPLIED WITH										
SB 560-28-11 28SB-11	WING FUEL BOOST PUMP WIRE ROUTING IMPROVEMENT	BOI		MANDATORY	MTH 26-May-2004 HRS 990		-			Complete
MOC : COMPLIED WITH										
SB 560-28-12 28SB-12	FUEL - SINGLE POINT REFUELING LINE CLAMP INSTALLATION (SUPERSEDED BY 560-28-12 R01)			SUPERSEDED	MTH 30-Nov-2007 HRS 2044		A/R			Complete
MOC : COMPLIED WITH										
SB 560-28-14 R01 28SB-14	FUEL - FUEL CHECK VALVE MODIFICATION	BOI		RECOMMENDED	MTH 02-Nov-2011 HRS 3236.9 LDG 2696		-			
MOC : DEFERRED										
SB 560-28-14 28SB-14	FUEL - FUEL CHECK VALVE MODIFICATION (SUPERSEDED BY 560-28-14 R01)			RECOMMENDED	MTH	14	A/R			
MOC :										
ASL 560-28-07 R01 28ASL07 : 560R1	SINGLE POINT REFUELING (SPR) TUBE INSPECTION			MANDATORY	MTH 21-Nov-2005 HRS 1361		A/R			Complete
MOC : COMPLIED WITH										
SL CIL-28-01	FUEL - MICROBIOLOGICAL CONTAMINATION IN AIRCRAFT FUEL TANKS AND FUEL SYSTEMS			INFORMATIONAL			-			
MOC :										
SL 560-28-05 28SL-05	WING FUEL SUMP CADMIUM SPACER INSPECTION	BOI		MANDATORY	MTH 26-May-2004 HRS 990		A/R			Complete
MOC : COMPLIED WITH										
SL 560-28-09	FUEL - FUEL LINE INSPECTION	BOI		MANDATORY	DAYS 03-Feb-2012 HRS 3285.9 LDG 2734		A/R			Complete
MOC : COMPLIED WITH										



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB 560-29-05 29SB-05	LANDING GEAR RETURN LINE CHECK VALVE REPLACEMENT (SUPERSEDED BY 560-29-05 R01)	ICT		SUPERSEDED	MTH 08-Dec-2001 HRS 159		A/R			Complete
MOC : COMPLIED WITH										
SB 560-29-08 R01 29SB-08	HYDRAULIC PRESSURE LINE ROUTING IMPROVEMENT	BOI		RECOMMENDED	MTH 30-Mar-2012 HRS 3317.7 LDG 2774		A/R			Complete
MOC : COMPLIED WITH - COMPLIED WITH CESSNA SERVICE BULLETIN 560-29-08R1, HYDRAULIC PRESSURE LINE ROUTING IMPROVEMENT BY INSTALLING KIT, P/N SB560-29-08. GROUND RUNUP AND CHECKED FOR LEAKS. WORK PERFORMED I/A/W THE INSTRUCTIONS PROVIDED IN THE BULLETIN AND THE CESSNA 560 MAINT. MANUAL.										
SB 560-29-08 29SB-08	HYDRAULIC PRESSURE LINE ROUTING IMPROVEMENT (SUPERSEDED BY 560-29-08 R01)			RECOMMENDED			A/R			
MOC :										
ASL 560-29-07 R02 29ASL07 : 560R2	TAILCONE HYDRAULIC TUBE INSPECTION (SUPERSEDED BY ASL560-29-07 R03)			SUPERSEDED	MTH 08-Apr-2005 HRS 1176		A/R			Complete
MOC : COMPLIED WITH										
ASL 560-29-07 R03 29ASL07 : 560R3	TAILCONE HYDRAULIC TUBE INSPECTION (SUPERSEDED BY ASL560-29-07 R04)			SUPERSEDED	MTH 08-Apr-2005 HRS 1176		A/R			Complete
MOC : COMPLIED WITH										
ASL 560-29-07 R04 29ASL07 : 560R4	TAILCONE HYDRAULIC TUBE INSPECTION			MANDATORY	MTH 08-Apr-2005 HRS 1176		A/R			Complete
MOC : COMPLIED WITH										
SL 560-29-08 29SL-08	HYDRAULIC POWER - HYDRAULIC FIREWALL SHUT-OFF VALVE INSPECTION			MANDATORY	MTH 07-Sep-2007 HRS 1943		A/R			Complete
MOC : COMPLIED WITH										
SB 560-30-12 30SB-12	TAIL DE-ICE PLUMBING IMPROVEMENT	BOI		DISCRETIONARY	MTH 21-Jan-2004 HRS 902		-			Complete
MOC : COMPLIED WITH										
SB 560-30-13 30SB-13	WINDSHIELD ANTI-ICE ORIFICE REMOVAL (SUPERSEDED BY 560-30-13 R01)	BOI		SUPERSEDED	MTH 20-Oct-2004 HRS 1072		A/R			Complete
MOC : COMPLIED WITH										
SB 560-30-16 R01 30SB-16	CLEARANCE INCREASE FOR THE WINDSHIELD BLEED AIR DUCT AND THE BRAKE PUSHROD ASSEMBLY			RECOMMENDED	MTH 11-May-2012 HRS 3373.8 LDG 2816		-			Complete
MOC : COMPLIED WITH										
SL CIL-30-01 R01 30SL-08 : 560R3	APPROVED DEICING PROGRAM UPDATES	*CF		SUPERSEDED	MTH		A/R			
MOC :										
SL 560-30-08 R03 30SL-08 : 560R3	ICE AND RAIN PROTECTION - APPROVED DEICING PROGRAM UPDATES (SUPERSEDED BY SL560-30-08 R04)			SUPERSEDED	MTH		A/R			
MOC :										

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL 560-30-11 30SL-11	WING ANTI-ICE VALVE REPLACEMENT			OPTIONAL	MTH		-			
	MOC :									
SL 560-30-12 30SL-12	WING OVERTEMPERATURE SWITCH SEALANT INSTALLATION			DISCRETIONARY	MTH		-			
	MOC :									
SB 560-31-10 31SB-10	BLEED AIR OVERHEAT ANNUNCIATION TIME DELAY IMPROVEMENT	BOI		DISCRETIONARY	MTH 17-Jun-2003 HRS 765		-			Complete
	MOC : COMPLIED WITH									
SB 560-31-12 31SB-12	ANNUNCIATOR PANEL DIODE INSTALLATION	BOI		DISCRETIONARY	MTH 10-Oct-2003 HRS 825		-			Complete
	MOC : COMPLIED WITH									
SL CIL-31-01	INDICATING/RECORDING SYSTEMS - CVR, FDR, AND CVDR 90-DAY BATTERY UNDERWATER LOCATOR BEACON (ULB) INSTALLATION			INFORMATIONAL			-			
	MOC :									
SB 560-32-24 32SB-24	BRAKE SYSTEM HIGH PRESSURE SWITCH IMPROVEMENT	BOI		RECOMMENDED	MTH 16-Oct-2002 HRS 573		-			Complete
	MOC : COMPLIED WITH									
SB 560-32-25 32SB-25	BRAKE LOW PRESSURE NON-CANCELABLE MASTER CAUTION IMPROVEMENT (SUPERSEDED BY 560-32-25 R01)	BOI		SUPERSEDED	MTH 30-Dec-2003 HRS 885		A/R			Complete
	MOC : COMPLIED WITH									
SB 560-32-26 32SB-26	LANDING GEAR AND EMERGENCY BRAKE AIR BLOW DOWN STORAGE BOTTLE ACTUATOR ARM IMPROVEMENT	BOI		RECOMMENDED	MTH 07-Jun-2002 HRS 407		-			Complete
	MOC : COMPLIED WITH									
SB 560-32-28 R01 32SB-28 : 560R1	MAIN LANDING GEAR ACTUATOR MODIFICATION (SUPERSEDED BY 560-32-28 R02)	ICT		SUPERSEDED	MTH 11-Mar-2005 HRS 1156		A/R			Complete
	MOC : COMPLIED WITH									
SB 560-32-29 32SB-29	NOSE LANDING GEAR TIRE INSPECTION (SUPERSEDED BY 560-32-29 R01)	BOI		SUPERSEDED	MTH 20-Apr-2004 HRS 964		A/R			Complete
	MOC : COMPLIED WITH									
SB 560-32-30 32SB-30	NLG ACTUATOR REPLACEMENT	BOI		MANDATORY	MTH 04-May-2005 HRS 1202		-			Complete
	MOC : COMPLIED WITH									
SB 560-32-33 32SB-33	LANDING GEAR - BRAKE HYDRAULIC PACK FILTER BOWL REPLACEMENT	BOI		RECOMMENDED	MTH 18-Feb-2010 HRS 2785		A/R			Complete
	MOC : COMPLIED WITH									
SB 560-32-40	LANDING GEAR - 250 POUND ZERO FUEL WEIGHT AND 200 POUND GROSS WEIGHT INCREASE (SUPERSEDED BY 560-32-40 R01)	BOI		SUPERSEDED	MTH 21-May-2010 HRS 2870 LDG 2385		A/R			Complete
	MOC : COMPLIED WITH									

NOTE: Item Codes in *italics* show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB 560-32-43	LANDING GEAR - LANDING GEAR WARNING HORN REPLACEMENT OPTIONAL						-			
	MOC :									
SL CIL-32-01	IMPROVED NOSE WHEEL GREASE SEAL			INFORMATIONAL			-			
	MOC :									
SL CIL-32-03	NLG UPLOCK ROLLER BRACKET INSPECTION BOI			RECOMMENDED	MTH 01-Dec-2014 HRS 4131.1 LDG 3449		-			Complete
	MOC :									
SL CIL-32-04	WIRELESS TIRE PRESSURE MONITORING SYSTEM INSTALLATION INFORMATIONAL						-			
	MOC :									
SL CIL-32-06	LANDING GEAR - WIRELESS TIRE PRESSURE SENSOR FILL VALVE TORQUE VERIFICATION INFORMATIONAL						-			
	MOC :									
SL 560-32-37 32SL-37	LANDING GEAR - NOSE LANDING GEAR ACTUATOR UNLOCK PRESSURE TEST SUPERSEDED				MTH 14-May-2003 HRS 747		A/R			Complete
	MOC :									
SL 560-32-40 R01 32SL-40 : 560R1	NOSE LANDING GEAR ICE PROTECTION BOOT INSTALLATION OPTIONAL				MTH		-			
	MOC :									
SL 560-32-45 32SL-45	LANDING GEAR - TRANSMITTAL OF GOODRICH SERVICE LETTER 2056 BOI			RECOMMENDED	MTH 22-Dec-2010 HRS 3066 LDG 2535		150			Complete
	MOC :									
SL 560-32-47 R01	TRAILING LINK FORWARD BORE CORROSION PROTECTION RECOMMENDED						-			
	MOC :									
SL 560-32-47 32SL-47	LANDING GEAR - TRAILING LINK FORWARD BORE CORROSION PROTECTION (SUPERSEDED BY SL560-32-47 R01) BOI			RECOMMENDED	MTH 24-Apr-2014 HRS 3926.1 LDG 3283		-			Complete
	MOC :									
COMPLY WITH SL550-32-86 (MODEL 550 BRAVO) OR SL560-32-47 (MODEL 560) AS APPLICABLE AT THE NEXT PHASE 22.										
	MOC :									
SL 560-32-48 32SL-48	LANDING GEAR - TRANSMITTAL OF GOODRICH SERVICE LETTER SL2060, LANDING GEAR - MAIN WHEEL ASSEMBLY - INTRODUCTION OF AN IMPROVED OPTIONAL THERMAL RELIEF PLUG ASSEMBLY			OPTIONAL	MTH		A/R			
	MOC :									
SL 560-32-50 32SL-50	LANDING GEAR - EMERGENCY GEAR RELEASE INSPECTION BOI			MANDATORY	MTH 02-Feb-2010 HRS 2762		A/R			Complete
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB 560-33-20 33SB-20	WING TIP LANDING LIGHT ASSEMBLY 250W LAMP INSTALLATION BOI			OPTIONAL	MTH 15-Nov-2016 HRS 4791.9 LDG 3993 ACH 379.7		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH SB560-33-20 REFERENCING THE INSTRUCTIONS IN THE SERVICE BULLETIN. OPERATIONAL CHECKS GOOD.										
SB 560-33-22 33SB-22	LIGHTS - LED TAIL POSITION LIGHT INSTALLATION OPTIONAL			MTH			A/R			
MOC :										
SB 560-33-24 33SB-24	CHART LIGHT MODIFICATION OPTIONAL			MTH			-			
MOC :										
SB 560-33-27 33SB-27	LIGHTS - LED POSITION, TAIL POSITION, AND ANTI-COLLISION (PTA) LIGHT INSTALLATION OPTIONAL			MTH			A/R			
MOC :										
SB 560-33-28 33SB-28	LIGHTS - LED BEACON LIGHT INSTALLATION OPTIONAL			MTH			A/R			
MOC :										
SB 560-33-31 33SB-31	LED TAIL FLOODLIGHT UPGRADE OPTIONAL			MTH			A/R			
MOC :										
SB 560-33-32	LED REPLACEMENT LIGHT FOR THE BAGGAGE COMPARTMENT OPTIONAL						A/R			
MOC :										
SB 560-33-33 R01	LED REPLACEMENT LIGHT FOR THE WING LANDING/TAXI LIGHT ASSEMBLY OPTIONAL						-			
MOC :										
SB 560-33-33	LIGHTS - LED REPLACEMENT LIGHT FOR THE WING LANDING/TAXI LIGHT ASSEMBLY (SUPERSEDED BY 560-33-33 R01) OPTIONAL						A/R			
MOC :										
SB 560-33-35	LED LANDING GEAR INDICATION LIGHT INSTALLATION OPTIONAL						A/R			
MOC :										
SL CIL-33-01	TRANSMITTAL OF RADIANT POWER CORP. SB-RPC-001, PROCEDURE TO REPLACE OBSOLETE CONNECTOR ASSEMBLY FOR CBS28 EMERGENCY BATTERY INFORMATIONAL						-			
MOC :										
SL 560-33-09 R01 33SL-09 : 560R1	LANDING/TAXI LIGHT INSPECTION BOI			RECOMMENDED	MTH 03-May-2002 HRS 361		-			Complete
MOC : COMPLIED WITH										
SL 560-33-09 33SL-09	LANDING /TAXI LIGHT INSPECTION (SUPERSEDED BY SL560-33-09 R01) BOI			SUPERSEDED	MTH 13-Mar-2002 HRS 300		A/R			Complete
MOC : COMPLIED WITH										
SB 560-34-102 34SB-102	NAVIGATION - SECONDARY FLIGHT DISPLAY AIRSPEED INDICATION IMPROVEMENT BOI			MANDATORY	MTH 25-Nov-2008 HRS 2443		A/R			Complete
MOC : COMPLIED WITH										



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB 560-34-105 <i>34SB-105</i>	TCAS RAIN COVER INSTALLATION			RECOMMENDED	MTH 03-Dec-2004 HRS 1100		-			Complete
MOC : COMPLIED WITH - NOT APPLICABLE										
SB 560-34-109 <i>34SB-109</i>	5 AMP-HOUR STANDBY GYRO BATTERY INSTALLATION	KBOI		OPTIONAL	MTH 08-Jan-2018 HRS 5053.8 LDG 4210 ACH 404.7		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH SB560-34-109 BY REPLACEMENT OF STANDBY GYRO BATTERY. ALL WORK IN REFERENCE TO SB560-34-109 AND CESSNA MAINTENANCE MANUAL. OPERATIONAL CHECKS OK.										
SB 560-34-111 R02 <i>34SB-111 : 560R2</i>	NAVIGATION - HONEYWELL TRANSPONDER UPGRADE FOR ELEMENTARY SURVEILLANCE			OPTIONAL	MTH		A/R			
MOC :										
SB 560-34-123 <i>34SB-123</i>	HONEYWELL MARK VII EGPWS SOFTWARE UPDATE TO VERSION -219-219			OPTIONAL	MTH		-			
MOC :										
SB 560-34-124 R01 <i>34SB-124 : 560R1</i>	RUNWAY AWARENESS ADVISORY SYSTEM (RAAS) INSTALLATION			OPTIONAL	MTH		A/R			
MOC :										
SB 560-34-125 R02 <i>34SB-125 : 560R2</i>	NAVIGATION - HONEYWELL PRIMUS 1000 PHASE III SOFTWARE UPGRADE	BOI		RECOMMENDED	MTH 30-Dec-2008 HRS 2454		A/R			Complete
MOC : COMPLIED WITH										
SB 560-34-128 R03 <i>34SB-128 : 560R3</i>	NAVIGATION - ENHANCED SURVEILLANCE TRANSPONDER INSTALLATION			OPTIONAL	MTH		A/R			
MOC :										
SB 560-34-130 <i>34SB-130</i>	NAVIGATION - HONEYWELL PRIMUS 1000 IC-615 WITH VGP MODE SOFTWARE UPGRADE			DISCRETIONARY	MTH		A/R			
MOC :										
SB 560-34-131 <i>34SB-131</i>	RUNWAY AWARENESS AND ADVISORY SYSTEM (RAAS) AUDIO INHIBIT SWITCH INSTALLATION			OPTIONAL	MTH		A/R			
MOC :										
SB 560-34-133 <i>34SB-133</i>	NAVIGATION - UNIVERSAL AVIONICS UPGRADE TO SOFTWARE CONTROL NUMBER (SCN) 802.2			OPTIONAL	MTH		A/R			
MOC :										
SB 560-34-136 R03 <i>34SB-136 : 560R3</i>	NAVIGATION - MEGGITT MARK I SECONDARY FLIGHT DISPLAY INDICATOR AND AIR DATA COMPUTER UNIT REPLACEMENT OR MARK II SECONDARY FLIGHT DISPLAY INDICATOR REPLACEMENT (SUPERSEDED BY 560-34-136 R04)			OPTIONAL			-			
MOC :										
SB 560-34-136 R04 <i>34SB-136 : 560R4</i>	NAVIGATION - MEGGITT MARK I SECONDARY FLIGHT DISPLAY INDICATOR AND AIR DATA UNIT REPLACEMENT OR MARK II SECONDARY FLIGHT DISPLAY INDICATOR REPLACEMENT			OPTIONAL			-			
MOC :										
SB 560-34-138 R01 <i>34SB-138 : 560R1</i>	NAVIGATION - GNS-XDXLS FMS SOFTWARE UPGRADE TO MOD 8			OPTIONAL	MTH		A/R			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB 560-34-154 R01	INSTALLATION OF SCN 802.8 FOR UNS-1 FMS			RECOMMENDED			-			
	MOC :									
SB 560-34-154	INSTALLATION OF SCN 802.8 FOR UNS-1 FMS (SUPERSEDED BY 560-34-154 R01)			RECOMMENDED			A/R			
	MOC :									
SB 560-34-155 R01	UNIVERSAL FMS WAAS UPGRADE			OPTIONAL			-			
	MOC :									
SB 560-34-155	UNIVERSAL FMS WAAS UPGRADE (SUPERSEDED BY 560-34-155 R01)	KGJT		OPTIONAL	MTH 31-Oct-2013 HRS 3799.6 LDG 3181		-			Complete
	MOC :									
	COMPLIED WITH - COMPLIED WITH SERVICE BULLETIN SB560-34-155, UNIVERSAL FMS / WAAS UPGRADE. REMOVED EXISTING UNS-1CSP AND INSTALLED A NEW UPGRADED UNS-1ESPW FMS SYSTE									
SB 560-34-156 R01	NAVIGATION - UNIVERSAL SOLID STATE DATA TRANSFER UNIT (SSDTU) UPGRADE			OPTIONAL			-			
	MOC :									
SB 560-34-156	NAVIGATION - UNIVERSAL SOLID STATE DATA TRANSFER UNIT (SSDTU) UPGRADE	KGJT			MTH 31-Oct-2013 HRS 3799.6 LDG 3181		-			Complete
	MOC :									
	COMPLIED WITH - COMPLIED WITH SERVICE BULLETIN SB560-34-156 UNIVERSAL SOLID STATE DATA TRANSFER UNIT UPGRADE. REMOVED EXISTING DTU-100 AND INSTALLED NEW UPGRADED SOLID STATE DATA TRANSFER UNIT(SSDTU)									
SB 560-34-162	NAVIGATION - HONEYWELL TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM II (TCAS II) VERSION 7.1 SOFTWARE UPDATE			OPTIONAL			-			
	MOC :									
SB 560-34-164 R01	NAVIGATION - AUTOMATIC DEPENDENT SURVEILLANCE BROADCAST (ADS-B) OUT TRANSPONDER INSTALLATION (SUPERSEDED BY 560-34-164 R02)			OPTIONAL			-			
	MOC :									
SB 560-34-164 R02	NAVIGATION - AUTOMATIC DEPENDENT SURVEILLANCE BROADCAST (ADS-B) OUT TRANSPONDER INSTALLATION	SMF		OPTIONAL	MTH 19-Mar-2018 HRS 5075.9 LDG 4240		-			Complete
	MOC :									
	COMPLIED WITH - COMPLIED WITH INSTRUCTIONS IN CESSNA SERVICE BULLETIN SB560-34-164 REV.02. OPERATIONAL CHECK NORMAL. UPDATED THE AFM AND SUPPLIED FLIGHT CREW FLIGHT CREW OPERATIONS SUMMARY.									
SB 560-34-164 R03	NAVIGATION - AUTOMATIC DEPENDENT SURVEILLANCE BROADCAST (ADS-B) OUT TRANSPONDER INSTALLATION			OPTIONAL			-			
	MOC :									
SB 560-34-164	NAVIGATION - AUTOMATIC DEPENDENT SURVEILLANCE BROADCAST (ADS-B) OUT TRANSPONDER INSTALLATION (SUPERSEDED BY 560-34-164 R01)			OPTIONAL			-			
	MOC :									
SB 560-34-165	NAVIGATION - UNIVERSAL UNS-1ESPW FMS SOFTWARE UPGRADE 1000.8	SMF		OPTIONAL	MTH 19-Mar-2018 HRS 5075.9 LDG 4240		-			Complete
	MOC :									
	COMPLIED WITH - COMPLIED WITH SB560-34-165 BY UPGRADING FMS & LPV MONITOR TO SCN 1000.8, OPERATIONAL CHECK NORMAL. UPDATED THE AFM AND SUPPLIED FLIGHT CREW FLIGHT CREW OPERATIONS SUMMARY.									
SB 560-34-168	NAVIGATION - STALL WARNING HORN REPLACEMENT			OPTIONAL			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB 560-34-169	NAVIGATION - ALTERNATE PITOT PROBE INSTALLATION OPTIONAL						-			
MOC :										
SB 560-34-17 34SB-17	ADI 330 REWIRE FROM NAVIGATION 1 TO NAVIGATION 2 REPEATER	BOI		OPTIONAL	MTH 01-Apr-2003 HRS 707		-			Complete
MOC : COMPLIED WITH										
ASL 560-34-21 34ASL21	TRANSMITTAL OF HONEYWELL TECHNICAL NEWSLETTER A23-3850-001	BOI		MANDATORY	MTH 10-Apr-2003 HRS 714		A/R			Complete
MOC : COMPLIED WITH										
SL CIL-34-01	TRANSMIT UNIVERSAL AVIONICS ALERT SERVICE BULLETIN 3XXX.()-34-3508 INFORMATIONAL						-			
MOC :										
SL CIL-34-02	TRANSMITTAL OF HONEYWELL SIL D201301000032, PRIMUS II INTEGRATED RADIO SYSTEM	BOI		MANDATORY	MTH 15-May-2013 HRS 3689.3 LDG 3089		-			Complete
MOC : COMPLIED WITH - THIS SERVICE LETTER IS COMPLETE BY COMPLIANCE OF AD2010-07-02 WITH MOD STATUS OF THE NAV UNIT MOD AS, AND THE NAV MODULE MOD T. (09/26/2012 @ 3465.3HRS.)										
SL CIL-34-03 R01	TRANSMITTAL OF HONEYWELL SERVICE BULLETIN 7014300-22-16, MODIFICATION (MOD) R TO DU-870 DISPLAY UNIT PN 7014300-901 AND -902; DECREASE FAILURE RATE OF HIGH VOLTAGE POWER SUPPLY (HVPS) BECAUSE OF HIGH HUMIDITY (SUPERSEDED BY CIL-34-03 R02)						-			
MOC : RECOMMENDED										
SL CIL-34-03 R02	TRANSMITTAL OF HONEYWELL SERVICE BULLETIN 7014300-22-16, MODIFICATION (MOD) R TO DU-870 DISPLAY UNIT PN 7014300-901 AND -902; DECREASE FAILURE RATE OF HIGH VOLTAGE POWER SUPPLY (HVPS) BECAUSE OF HIGH HUMIDITY INFORMATIONAL						-			
MOC :										
SL CIL-34-03	TRANSMITTAL OF HONEYWELL SERVICE BULLETIN 7014300-22-16, MODIFICATION (MOD) R TO DU-870 DISPLAY UNIT PN 7014300-901 AND -902; DECREASE FAILURE RATE OF HIGH VOLTAGE POWER SUPPLY (HVPS) BECAUSE OF HIGH HUMIDITY (SUPERSEDED BY CIL-34-03 R01)						-			
MOC : RECOMMENDED										
SL CIL-34-09 R01	NAVIGATION - TRANSMITTAL OF HONEYWELL SERVICE INFORMATION LETTER FMZ-2000/2010 - FLIGHT MANAGEMENT SYSTEM (FMS) SOFTWARE VERSION 6.1 (FMS 6.1) UPGRADE AND CONSOLIDATION INFORMATIONAL						-			
MOC :										
SL CIL-34-09	NAVIGATION - TRANSMITTAL OF HONEYWELL SERVICE BULLETIN FMZ-2000/2010 - FLIGHT MANAGEMENT SYSTEM (FMS) SOFTWARE VERSION 6.1 (FMS 6.1) UPGRADE AND CONSOLIDATION INFORMATIONAL						-			
MOC :										
COM MC ALL - 007	GPS/SBAS APPROACH DOWNGRADES DUE TO GEOMAGNETIC ACTIVITY INFORMATIONAL MTH						-			
MOC :										
SL 560-34-20 34SL-20	TRANSMITTAL OF HONEYWELL PUBLICATION NUMBER A21-3440-001 RECOMMENDED				MTH 03-Dec-2004 HRS 1100		-			Complete
MOC : COMPLIED WITH - NOT APPLICABLE-EQUIPMENT NOT INSTALLED										
SL 560-34-23 R01	GNS-XL FLIGHT MANAGEMENT SYSTEM (FMS) MOD 4 UPGRADE RECOMMENDED						-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL 560-34-23 34SL-23	GNS-XL FLIGHT MANAGEMENT SYSTEM (FMS) MOD 4 UPGRADE (SUPERSEDED BY SL560-34-23 R01)	BOI		RECOMMENDED	MTH 31-Dec-2003 HRS 885		-			Complete
MOC : COMPLIED WITH - NOT APPLICABLE-EQUIPMENT NOT INSTALLED										
SL 560-34-24 34SL-24	TRANSMITTAL OF HONEYWELL SERVICE BULLETIN 7014700-34-0040	BOI		RECOMMENDED	MTH 06-Oct-2003 HRS 820		-			Complete
MOC : COMPLIED WITH										
SL 560-34-28 34SL-28	HONEYWELL SOFTWARE BULLETIN SWB TPU 67A-SW8			DISCRETIONARY	MTH		-			
MOC :										
SL 560-34-29 34SL-29	ELEMENTARY SURVEILLANCE TRANSPONDER PRODUCT IMPROVEMENT			MANDATORY	MTH 02-Oct-2007 HRS 1966		-			N/A
MOC : NOT APPLICABLE - NOT APPLICABLE-EQUIPMENT NOT INSTALLED										
SL 560-34-36 34SL-36	NAVIGATION - TRANSMITTAL OF HONEYWELL SWB MST 67A-SW5	BOI		RECOMMENDED	MTH 02-Nov-2011 HRS 3236.9 LDG 2696		300			N/A
MOC : NOT APPLICABLE										
SL 560-34-40	NAVIGATION - TRANSMITTAL OF ROCKWELL COLLINS SERVICE INFORMATION LETTER 16-1 FUNCTION OF RESET OVERRIDE MODE SWITCH ON XM WEATHER RECEIVER FOR PROLINE 21/PROLINE FUSION			INFORMATIONAL			-			
MOC :										
SL 560-34-42	NAVIGATION - IMPLEMENT AIRPLANE FLIGHT MANUAL (AFM) CHANGES			MANDATORY	MTH		-			
MOC :										
SL 560-34-44 R01	NAVIGATION - TRANSMITTAL OF UNIVERSAL AVIONICS SERVICE BULLETIN NUMBER 3019.(.)-34-3769 INSTALLATION OF MOD 19 IN THE UNS-1ESPW FM:			RECOMMENDED	MTH		-			
MOC :										
SL 560-34-44	NAVIGATION - TRANSMITTAL OF UNIVERSAL AVIONICS SERVICE BULLETIN NUMBER 3116.(.)-34-3769 INSTALLATION OF MOD 19 IN THE UNS-1ESPW FM:	KBOI		RECOMMENDED	MTH 02-Apr-2025 HRS 7042.1 LDG 5800		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH SL560-34-44 BY REMOVAL AND REINSTALLATION OF LP/LPV MONITOR AFTER COMPLIANCE OF UNIVERSAL SERVICE BULLETIN NUMBER 3116.(.)-34-3771, INCORPORATING MOD 9. MODIFICATION PERFORMED BY UNIVERSAL AVIONICS SYSTEMS, REPAIR STATION NUMBER UZNR483N, WORK ORDER FC0000886, 8130-3 DATED 31 MAR 2025. OPERATIONAL CHECKS OK. ALL WORK IN REFERENCE TO TEXTRON 560 MM.										
SB 560-35-08 35SB-08	OXYGEN SYSTEM INSTALLATION IMPROVEMENT	BOI		MANDATORY	MTH 29-Apr-2005 HRS 1202		-			Complete
MOC : COMPLIED WITH										
SB 560-35-09 R01 35SB-09 : 560R1	EROS MLD20-506 OXYGEN MASK INSTALLATION			OPTIONAL	MTH		-			
MOC :										
SB 560-35-12 35SB-12	EROS MLD20-510 OXYGEN MASK INSTALLATION			OPTIONAL	MTH		-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL CIL-35-05	OXYGEN - TRANSMITTAL OF ZODIAC AEROSPACE SB MCF-SBU-35-001	BOI		MANDATORY	MTH DAYS 02-Feb-2016 HRS 4498.9 LDG 3752		-			N/A
MOC : NOT APPLICABLE - CIL-35-05 IS NOT APPLICABLE BY PART NUMBER OF THE OXYGEN MASKS										
SL 560-35-06	OXYGEN - OXYGEN BOTTLE INSPECTION			INFORMATIONAL	MTH		A/R			
MOC :										
SL 560-35-07 R01	OXYGEN - TRANSMITTAL OF INTERTECHNIQUE SERVICE BULLETIN MXH-35-240			MANDATORY			-			
MOC :										
SL 560-35-07 R02	OXYGEN - TRANSMITTAL OF INTERTECHNIQUE SERVICE BULLETIN MXH-35-240			MANDATORY			-			
MOC :										
SL 560-35-07	OXYGEN - TRANSMITTAL OF INTERTECHNIQUE SERVICE BULLETIN MXH-35-240 (SUPERSEDED BY SL560-35-07 R01)	BOI		MANDATORY	MTH 11-Oct-2011 HRS 3227.5 LDG 2686		-			N/A
MOC : NOT APPLICABLE										
SB 560-36-02 R01 36SB-02 : 560R1	DOOR SEAL VALVE REPLACEMENT AND WATER TRAP INSTALLATION			OPTIONAL	MTH		-			
MOC :										
SB 560-36-03 R03 36SB-03 : 560R3	PNEUMATIC - WIDE CARGO DOOR SEAL LINE WATER TRAP INSTALLATION	BOI		OPTIONAL	MTH		A/R			
MOC :										
SL 560-36-02 36SL-02	ENGINE BLEED AIR COUPLING SAFETY WIRE ADDITION	BOI		RECOMMENDED	MTH 01-May-2002 HRS 361		-			Complete
MOC : COMPLIED WITH										
SB 560-52-04 R01 52SB-04 : 560R1	WIDE DOOR MODIFICATION INSTALLATION (SUPERSEDED BY 560-52-04 R02)	*CF		OPTIONAL	MTH		-			
MOC :										
SB 560-52-14	MODIFICATION OF COMPOSITE STEP RATE CONTROL ATTACHMENTS	BOI		RECOMMENDED	MTH 08-Nov-2011 HRS 3243.4 LDG 2700		A/R			Complete
MOC : COMPLIED WITH										
SB 560-52-15 R01 52SB-15 : 560R1	ENTRY DOOR CABLE REPLACEMENT	BOI		RECOMMENDED	MTH 07-Aug-2003 HRS 793		-			Complete
MOC : COMPLIED WITH										
SB 560-52-16 52SB-16	CABIN ENTRANCE DOOR THRESHOLD STEP CLOSEOUT IMPROVEMENT	BOI		RECOMMENDED	MTH 08-Apr-2003 HRS 714		-			Complete
MOC : COMPLIED WITH										
SB 560-52-17 R01 52SB-17 : 560R1	DOORS - IMPROVEMENT FOR THE CABIN ENTRY STEPS			OPTIONAL	MTH		A/R			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB 560-52-21	WIDE DOOR INSTALLATION MODIFICATION			OPTIONAL			-			
	MOC :									
ASL 560-52-04 52ASL-04	DOORS - EMERGENCY DOOR INSPECTION			MANDATORY	MTH 30-Nov-2007 HRS 2044		A/R			Complete
	MOC : COMPLIED WITH									
ASL 560-52-05	DOORS - EMERGENCY EXIT INSPECTION	BOI		MANDATORY	DAYS 03-Feb-2011 HRS 3086.2 LDG 2552		A/R			Complete
	MOC : COMPLIED WITH - COMPLIED WITH THIS ALERT SERVICE LETTER AND FOUND EMERGENCY EXIT, AND DOOR SEAL TO BE IN GOOD CONDITION, APPLIED PETROLEUM JELLY TO SEAL AND RE-INSTALLED IN AIRCRAFT.									
SB 560-53-30 R01	FUSELAGE - FORWARD SHEAR TIE BOLT REPLACEMENT (SUPERSEDED BY 560-53-30 R02)			MANDATORY			-			
	MOC :									
SB 560-53-30 53SB-30	FUSELAGE - FOWARD SHEAR TIE BOLT REPLACEMENT (SUPERSEDED BY 560-53-30 R01)	ICT		MANDATORY	MTH 08-Dec-2001 HRS 159		-			Complete
	MOC : COMPLIED WITH									
SB 560-53-31 53SB-31	TAILCONE RIVET INSPECTION/INSTALLATION	BOI		RECOMMENDED	MTH 12-Sep-2002 HRS 514		-			Complete
	MOC : COMPLIED WITH - PREVIOUSLY COMPLIED WITH AT FACTORY OR IS A FACTORY OPTION.									
SB 560-53-32 53SB-32	CABIN FRAME INSPECTION/REPAIR	SAT		MANDATORY	MTH 15-Jan-2005 HRS 1117		-			Complete
	MOC : COMPLIED WITH									
SB 560-53-33 53SB-33	TAILCONE FRAME IMPROVEMENT	BOI		MANDATORY	MTH 25-Aug-2003 HRS 798		-			Complete
	MOC : COMPLIED WITH									
SB 560-53-35 53SB-35	TAILCONE GROUND RECEPTACLE INSTALLATION			OPTIONAL	MTH		-			
	MOC :									
SB 560-53-36 53SB-36	FUSELAGE - FORWARD PRESSURE BULKHEAD FASTENER INSPECTION			MANDATORY	MTH 09-Apr-2007 HRS 1827		A/R			Complete
	MOC : COMPLIED WITH									
SB 560-53-37 53SB-37	FUSELAGE - MAIN CARRY-THRU SPAR FASTENER INSPECTION (SUPERSEDED BY 560-53-37 R01)	BOI		SUPERSEDED	MTH 30-Dec-2008 HRS 2454		A/R			Complete
	MOC : COMPLIED WITH									
SL 560-53-06 53SL-06	INTERCOSTAL DRAINAGE PATH INSPECTION (SUPERSEDED BY SL560-53-06 R01)	BOI		RECOMMENDED	MTH 19-Sep-2005 HRS 1310		-			Complete
	MOC : COMPLIED WITH									
SB 560-54-05 54SB-05	NACELLE OIL DOOR HINGE IMPROVEMENT	BOI		RECOMMENDED	MTH 15-May-2002 HRS 371		-			Complete
	MOC : COMPLIED WITH									



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL 560-54-01 R01	NACELLES/ PYLONS - PYLON DRAIN HOLE INSPECTION	KBOI		RECOMMENDED	MTH 07-Jan-2016 HRS 4479 LDG 3732		-			N/A
MOC : NOT APPLICABLE - THIS REVISION DOES NOT AFFECT PREVIOUSLY COMPLIED WITH ITEM.										
SL 560-54-01	PYLON DRAIN HOLE INSPECTION (SUPERSEDED BY SL560-54-01 R01)	BOI		RECOMMENDED	MTH 19-Dec-2014 HRS 4163.3 LDG 3476		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH CESSNA SERVICE LETTER SL560-54-01, PYLON DRAIN HOLE INSPECTION. PANELS A & B HAVE DRAIN HOLES, ADDED A DRAIN HOLE TO C PANEL REFERENCING THE INSTRUCTIONS CONTAINED IN THE SERVICE LETTER.										
SL 560-55-03 R01	STABILIZERS - HORIZONTAL STABILIZER RIB BORESCOPE INSPECTION (SUPERSEDED BY SL560-55-03 R02)			MANDATORY			-			
MOC :										
SL 560-55-03 R02	HORIZONTAL STABILIZER RIB BORESCOPE INSPECTION			MANDATORY	MTH		-			
MOC :										
SL 560-55-03	HORIZONTAL STABILIZER RIB BORESCOPE INSPECTION (SUPERSEDED BY SL560-55-03 R01)			MANDATORY	MTH		-			
MOC :										
ASL 560-29-07 29ASL07	TAILCONE HYDRAULIC TUBE INSPECTION (SUPERSEDED BY ASL560-29-07 R01)			SUPERSEDED	MTH 08-Apr-2005 HRS 1176		A/R			Complete
MOC : COMPLIED WITH										
SB 560-71-05 R01 71SB-05 : 560R1	POWER PLANT - ENGINE BLEED AIR TUBE CLAMP REPLACEMENT			RECOMMENDED	MTH 11-May-2007 HRS 1857		A/R			Complete
MOC : COMPLIED WITH										
SB 560-71-05 71SB-05	ENGINE BLEED AIR TUBE ASSEMBLY SUPPORT IMPROVEMENT (SUPERSEDED BY 560-71-05 R01)	BOI		RECOMMENDED	MTH 18-Mar-2004 HRS 952		-			Complete
MOC : COMPLIED WITH										
SB 560-71-06 71SB-06	ENGINE HYDRAULIC LINE REPLACEMENT	BOI		RECOMMENDED	MTH 24-Feb-2006 HRS 1485		-			Complete
MOC : COMPLIED WITH										
SB 560-71-08 71SB-08	POWER PLANT - ENGINE INLET FLANGE IMPROVEMENT	BOI		RECOMMENDED	MTH 21-Nov-2011 HRS 3247.1 LDG 2702		300			Complete
MOC : COMPLIED WITH										
SB 560-71-09 R01	ENGINE FUEL MANIFOLD DRAIN LINE INSTALLATION (SUPERSEDED BY 560-71-09 R02)			OPTIONAL			-			
MOC :										
SB 560-71-09 R02 NO. 1 ENGINE	FUEL MANIFOLD DRAIN LINE INSTALLATION	KBOI		OPTIONAL	MTH 24-Jul-2017 HRS 4930.9 LDG 4107		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH SB560-71-09 R2 ON #1 SIDE IN REFERENCE TO APPLICABLE SERVICE BULLETIN INSTRUCTIONS.										



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB 560-71-09 R02 NO. 2 ENGINE	FUEL MANIFOLD DRAIN LINE INSTALLATION	KBOI		OPTIONAL	MTH 24-Jul-2017 HRS 4930.9 LDG 4107		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH SB560-71-09 R2 ON #2 SIDE IN REFERENCE TO APPLICABLE SERVICE BULLETIN INSTRUCTIONS.										
SB 560-71-09	ENGINE FUEL MANIFOLD DRAIN LINE INSTALLATION (SUPERSEDED BY 560-71-09 R01)		OPTIONAL				-			
MOC :										
SL CIL-71-01	TRANSMITTAL OF PRATT & WHITNEY CANADA SERVICE BULLETIN 30463		OPTIONAL				-			
MOC :										
SL 560-71-06 R01 71SL-06 : 560R1	ENGINE ELECTRICAL GROUND LUG INSPECTION			RECOMMENDED	MTH 09-Mar-2004 HRS 945		-			Complete
MOC : COMPLIED WITH										
SL 560-71-06 71SL-06	ENGINE ELECTRICAL GROUND LUG INSPECTION (SUPERSEDED BY SL560-71-06 R01)	BOI		SUPERSEDED	MTH 09-Mar-2004 HRS 945		A/R			Complete
MOC : COMPLIED WITH										
SL 560-71-07 71SL-07	ENGINE HYDRAULIC PRESSURE LINE/FUEL LINE INSPECTION			RECOMMENDED	MTH 29-Apr-2005 HRS 1202		-			Complete
MOC : COMPLIED WITH										
SL 560-71-09 71SL-09	P&WC SI 17-2005			MANDATORY	MTH 20-Mar-2006 HRS 1501		A/R			Complete
MOC : COMPLIED WITH										
SL 560-71-10 71SL-10	POWER PLANT - ENGINE WIRE BUNDLE INSPECTION	BOI		RECOMMENDED	MTH 29-Aug-2012 HRS 3447.6 LDG 2879		300			Complete
MOC : COMPLIED WITH										
SL 560-72-18 72SL-18	TRANSMITTAL OF PRATT & WHITNEY CANADA SERVICE BULLETIN PW500-72-30170, REVISION 1, TURBOFAN ENGINE - REPLACEMENT OF BELLOWS SEAL FOR CABIN BLEED AIR TUBES (SUPERSEDED BY SL560-72-18 R01)	BOI		SUPERSEDED	MTH 12-Nov-2002 HRS 590		A/R			Complete
MOC : COMPLIED WITH										
SL 560-72-19 72SL-19	ENGINE - TRANSMITTAL OF P&WC SB PW500-72-30217, INSPECTION OF TURBOFAN ENGINE FUEL TUBE	BOI		RECOMMENDED	MTH 11-Jul-2002 HRS 461		A/R			Complete
MOC : COMPLIED WITH										
SL 560-72-22 72SL-22	ENGINE - TRANSMITTAL OF PRATT & WHITNEY CANADA SERVICE BULLETIN PW500-72-30252 NUMBER FOUR BEARING OIL PRESSURE AND OIL SCAVENGE TUBES - REPLACEMENT OF	BOI		RECOMMENDED	MTH 14-Oct-2009 HRS 2659		A/R			Complete
MOC : COMPLIED WITH										
SL 560-72-27 LEFT ENGINE 72SL-27 : E1**L	TRANSMITTAL OF PRATT AND WHITNEY CANADA (P&WC) SERVICE BULLETIN PW500-72-30409, TURBOFAN ENGINE HYDROMECHANICAL FUEL CONTROL UNIT - REPLACEMENT,MODIFICATION OF	KEAU		MANDATORY	MTH 28-Jun-2001		A/R			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL 560-72-27 RIGHT ENGINE 72SL-27 : E2**R	TRANSMITTAL OF PRATT AND WHITNEY CANADA (P&WC) SERVICE BULLETIN PW500-72-30409, TURBOFAN ENGINE HYDROMECHANICAL FUEL CONTROL UNIT - REPLACEMENT,MODIFICATION OF	BOI		MANDATORY	MTH 02-Nov-2011 HRS 3236.9 LDG 2696		A/R			Complete
MOC : COMPLIED WITH										
SL 560-72-28 72SL-28	TRANSMITTAL OF PRATT AND WHITNEY CANADA SERVICE BULLETIN PW500-72-30382,MODIFICATION OF THE TURBINE EXHAUST CONE, INNER BY-PASS DUCT ASSEMBLY, FUEL MANIFOLD, FUEL SHUT-OFF CABLE GROMMETS AND COVER PLATE FAIRING	BOI		RECOMMENDED	MTH 02-Nov-2011 HRS 3236.9 LDG 2696		300			Complete
MOC : COMPLIED WITH - CESSNA SERVICE LETTER SL560-72-28 WAS PREVIOUSLY COMPLIED WITH 04/29/2011 AT 3130.9 HRS										
SB PW500-72-30131 R2 E1	REPLACEMENT OF COLD START VALVE ASSEMBLY CATEGORY 3						A/R			
MOC :										
SB PW500-72-30131 R2 E2	REPLACEMENT OF COLD START VALVE ASSEMBLY CATEGORY 3						A/R			
MOC :										
SB PW500-72-30141 R1 E1	COMPRESSOR STATOR ASSEMBLY - REPLACEMENT/MODIFICATION OF CATEGORY 7						A/R			
MOC :										
SB PW500-72-30141 R1 E2	COMPRESSOR STATOR ASSEMBLY - REPLACEMENT/MODIFICATION OF CATEGORY 7						A/R			
MOC :										
SB PW500-72-30151 R02 E1	REPLACEMENT/MODIFICATION OF GAS GENERATOR CASE CATEGORY 7						-			
MOC :										
SB PW500-72-30151 R02 E2	REPLACEMENT/MODIFICATION OF GAS GENERATOR CASE CATEGORY 7						-			
MOC :										
SB PW500-72-30151 R03 E1	REPLACEMENT/MODIFICATION OF GAS GENERATOR CASE CATEGORY 7						-			
MOC :										
SB PW500-72-30151 R03 E2	REPLACEMENT/MODIFICATION OF GAS GENERATOR CASE CATEGORY 7						-			
MOC :										
SB PW500-72-30156 R1 E1	REPLACEMENT OF ANTI-ICING VALVE UNK			CATEGORY 7	MTH 14-Jul-2017 HRS 4930.9 LDG 4107		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30156 R1 E2	REPLACEMENT OF ANTI-ICING VALVE CATEGORY 7						-			
MOC :										
SB PW500-72-30158 R1 E1	REPLACEMENT OF HIGH PRESSURE COMPRESSOR SHAFT CATEGORY 7						-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30158 R1 E2	REPLACEMENT OF HIGH PRESSURE COMPRESSOR SHAFT			CATEGORY 7			-			
	MOC :									
SB PW500-72-30176 R2 E1	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY			CATEGORY 7			-			
	MOC :									
SB PW500-72-30176 R2 E2	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY			CATEGORY 7			-			
	MOC :									
SB PW500-72-30177 E1	REPLACEMENT OF HIGH PRESSURE (HPT) SEAL RING	UNK		CATEGORY 6	MTH 20-Dec-2008 HRS 2477.4 LDG 2081		-			Complete
	MOC :	COMPLIED WITH								
SB PW500-72-30184 R2 E1	REPLACEMENT OF FUEL NOZZLE			CATEGORY 7			-			
	MOC :									
SB PW500-72-30184 R2 E2	REPLACEMENT OF FUEL NOZZLE			CATEGORY 7			-			
	MOC :									
SB PW500-72-30191 R1 E1	REPLACEMENT TURBINE EXHAUST CASE ASSEMBLY			CATEGORY 7			-			
	MOC :									
SB PW500-72-30191 R1 E2	REPLACEMENT TURBINE EXHAUST CASE ASSEMBLY			CATEGORY 7			-			
	MOC :									
SB PW500-72-30202 R1 E1	INTRODUCTION OF RE-PROFILED GRAFOIL GASKETS			CATEGORY 5			-			
	MOC :									
SB PW500-72-30202 R1 E2	INTRODUCTION OF RE-PROFILED GRAFOIL GASKETS			CATEGORY 5			-			
	MOC :									
SB PW500-72-30202 R2 E1	INTRODUCTION OF RE-PROFILED GRAFOIL GASKETS			CATEGORY 5			-			
	MOC :									
SB PW500-72-30202 R2 E2	INTRODUCTION OF RE-PROFILED GRAFOIL GASKETS			CATEGORY 5			-			
	MOC :									
SB PW500-72-30217 R03 E1	INSPECTION OF FUEL TUBE						-			N/A
	MOC :	NOT APPLICABLE - EFFECTED PARTS NOT INSTALLED								
SB PW500-72-30217 R03 E2	INSPECTION OF FUEL TUBE						-			N/A
	MOC :	NOT APPLICABLE - EFFECTED PARTS NOT INSTALLED								



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30256 R1 E1	REPLACEMENT OF INTERMEDIATE CASE ASSEMBLY			CATEGORY 7			-			
	MOC :									
SB PW500-72-30256 R1 E2	REPLACEMENT OF INTERMEDIATE CASE ASSEMBLY			CATEGORY 7			-			
	MOC :									
SB PW500-72-30258 R2 E1	REPLACEMENT OF COMBUSTION CHAMBER LINER			CATEGORY 7			-			
	MOC :									
SB PW500-72-30258 R2 E2	REPLACEMENT OF COMBUSTION CHAMBER LINER			CATEGORY 7			-			
	MOC :									
SB PW500-72-30264 R3 E1	REPLACEMENT OF STARTER-GENERATOR-DRIVE GEARSHAFT AND PLAIN SEAL			CATEGORY 8			A/R			
	MOC :									
SB PW500-72-30264 R3 E2	REPLACEMENT OF STARTER-GENERATOR-DRIVE GEARSHAFT AND PLAIN SEAL	UNK		CATEGORY 8	MTH 12-Jul-2017 HRS 4930.9 LDG 4107		A/R			Complete
	MOC :	COMPLIED WITH								
SB PW500-72-30264 R4 E1	REPLACEMENT OF STARTER-GENERATOR-DRIVE GEARSHAFT AND PLAIN SEAL	UNK		CATEGORY 8	MTH 14-Jul-2017 HRS 4930.9 LDG 4107		-			Complete
	MOC :	COMPLIED WITH								
SB PW500-72-30264 R4 E2	REPLACEMENT OF STARTER-GENERATOR-DRIVE GEARSHAFT AND PLAIN SEAL			CATEGORY 8			-			
	MOC :									
SB PW500-72-30266 R1 E1	REPLACEMENT/MODIFICATION OF IGNITION EXCITER			CATEGORY 7			A/R			
	MOC :									
SB PW500-72-30266 R1 E2	REPLACEMENT/MODIFICATION OF IGNITION EXCITER			CATEGORY 7			A/R			
	MOC :									
SB PW500-72-30271 R01 E1	MODIFICATION/REPLACEMENT OF FAN ROTOR BALANCING ASSY			CATEGORY 6			-			
	MOC :									
SB PW500-72-30271 R01 E2	MODIFICATION/REPLACEMENT OF FAN ROTOR BALANCING ASSY			CATEGORY 6			-			
	MOC :									
SB PW500-72-30271 E1	MODIFICATION/REPLACEMENT OF FAN ROTOR BALANCING ASSEMBLY	UNK		CATEGORY 6	MTH 14-Jul-2017 HRS 4930.9 LDG 4107		-			Complete
	MOC :	COMPLIED WITH								



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30271 E2	MODIFICATION/REPLACEMENT OF FAN ROTOR BALANCING ASSEMBLY	UNK		CATEGORY 6	MTH 12-Jul-2017 HRS 4930.9 LDG 4107		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30273 R1 E1	INTRODUCTION OF FUEL PRESSURE TUBE REPLACEMENT AND ATTENUATOR			CATEGORY 3			-			
MOC :										
SB PW500-72-30273 R1 E2	INTRODUCTION OF FUEL PRESSURE TUBE REPLACEMENT AND ATTENUATOR			CATEGORY 3			-			
MOC :										
SB PW500-72-30282 R01 E1	REPLACEMENT OF FUEL NOZZLE PREFORMED PACKINGS			CATEGORY 6			-			
MOC :										
SB PW500-72-30282 R01 E2	REPLACEMENT OF FUEL NOZZLE PREFORMED PACKINGS			CATEGORY 6			-			
MOC :										
SB PW500-72-30282 E1	REPLACEMENT OF FUEL NOZZLE PREFORMED PACKINGS	UNK		CATEGORY 6	MTH 14-Jul-2017 HRS 4930.9 LDG 4107		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30282 E2	REPLACEMENT OF FUEL NOZZLE PREFORMED PACKINGS	UNK		CATEGORY 6	MTH 12-Jul-2017 HRS 4930.9 LDG 4107		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30291 R1 E1	REPLACEMENT OF FIRST-STAGE-HIGH-COMPRESSOR-ROTOR	UNK		CATEGORY 6	MTH 14-Jul-2017 HRS 4930.9 LDG 4107		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30291 R1 E2	REPLACEMENT OF FIRST-STAGE-HIGH-COMPRESSOR-ROTOR	UNK		CATEGORY 6	MTH 12-Jul-2017 HRS 4930.9 LDG 4107		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30300 R3 E1	REPLACEMENT OF OIL PUMP PLAIN SEAL	UNK		CATEGORY 6	MTH 14-Jul-2017 HRS 4930.9 LDG 4107		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30300 R3 E2	REPLACEMENT OF OIL PUMP PLAIN SEAL	UNK		CATEGORY 6	MTH 12-Jul-2017 HRS 4930.9 LDG 4107		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30305 R01 E1	REPLACEMENT/MODIFICATION OF TURBINE CASE ASSEMBLY			CATEGORY 7			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30305 R01 E2	REPLACEMENT/MODIFICATION OF TURBINE CASE ASSEMBLY			CATEGORY 7			-			
	MOC :									
SB PW500-72-30306 R05 E1	NEW TRANSFER TUBES WITH HEAT SHIELD			CATEGORY 5			-			
	MOC :									
SB PW500-72-30306 R05 E2	NEW TRANSFER TUBES WITH HEAT SHIELD			CATEGORY 5			-			
	MOC :									
SB PW500-72-30306 R4 E1	NEW TRANSFER TUBES WITH HEAT SHIELD	UNK		CATEGORY 5	MTH 20-Dec-2008 HRS 2477.4 LDG 2081		-			Complete
	MOC :	COMPLIED WITH								
SB PW500-72-30308 E1	REPLACEMENT OF COMPRESSOR RETAINING NUT	UNK		CATEGORY 6	MTH 14-Jul-2017 HRS 4930.9 LDG 4107		-			Complete
	MOC :	COMPLIED WITH								
SB PW500-72-30308 E2	REPLACEMENT OF COMPRESSOR RETAINING NUT	UNK		CATEGORY 6	MTH 12-Jul-2017 HRS 4930.9 LDG 4107		-			Complete
	MOC :	COMPLIED WITH								
SB PW500-72-30309 R4 E1	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL			CATEGORY 8			-			
	MOC :									
SB PW500-72-30309 R4 E2	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL			CATEGORY 8			-			
	MOC :									
SB PW500-72-30315 R1 PART A E1	REPLACEMENT REPLACEMENT OF VANE RINGS ASSEMBLY COMPRESSOR-INLET OF FIRST STAGE VANE RING			CATEGORY 7			-			
	MOC :									
SB PW500-72-30315 R1 PART A E2	REPLACEMENT REPLACEMENT OF VANE RINGS ASSEMBLY COMPRESSOR-INLET OF FIRST STAGE VANE RING			CATEGORY 7			-			
	MOC :									
SB PW500-72-30315 R1 PART B E1	REPLACEMENT REPLACEMENT OF VANE RINGS ASSEMBLY COMPRESSOR-INLET OF BOTH VANE RINGS			CATEGORY 7			-			
	MOC :									
SB PW500-72-30315 R1 PART B E2	REPLACEMENT REPLACEMENT OF VANE RINGS ASSEMBLY COMPRESSOR-INLET OF BOTH VANE RINGS			CATEGORY 7			-			
	MOC :									
SB PW500-72-30315 R1 E1	REPLACEMENT OF VANE RINGS ASSEMBLY COMPRESSOR-INLET			CATEGORY 6			-			
	MOC :									
SB PW500-72-30315 R1 E2	REPLACEMENT OF VANE RINGS ASSEMBLY COMPRESSOR-INLET			CATEGORY 6			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30316 R1 E1	REPLACEMENT OF TRANSFER TUBE ASSEMBLY	UNK		CATEGORY 5	MTH 20-Dec-2008 HRS 2477.4 LDG 2081		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30325 R03 E1	REPLACEMENT OF OIL-PUMP PLAIN SEAL			CATEGORY 6			-			
MOC :										
SB PW500-72-30325 R03 E2	REPLACEMENT OF OIL-PUMP PLAIN SEAL			CATEGORY 6			-			
MOC :										
SB PW500-72-30325 R1 E1	REPLACEMENT OF OIL-PUMP PLAIN SEAL	UNK		CATEGORY 6	MTH 14-Jul-2017 HRS 4930.9 LDG 4107		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30325 R1 E2	REPLACEMENT OF OIL-PUMP PLAIN SEAL	UNK		CATEGORY 6	MTH 12-Jul-2017 HRS 4930.9 LDG 4107		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30325 R2 E1	REPLACEMENT OF OIL-PUMP PLAIN SEAL			CATEGORY 6			-			
MOC :										
SB PW500-72-30325 R2 E2	REPLACEMENT OF OIL-PUMP PLAIN SEAL			CATEGORY 6			-			
MOC :										
SB PW500-72-30327 E1	REPLACEMENT OF NO. 4 BEARING CARBON SEAL	UNK		CATEGORY 6	MTH 20-Dec-2008 HRS 2477.4 LDG 2081		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30328 E1	FIELD REPLACEMENT OF SPARE FAN ROTOR BALANCING ASSEMBLY			CATEGORY 7			-			
MOC :										
SB PW500-72-30328 E2	FIELD REPLACEMENT OF SPARE FAN ROTOR BALANCING ASSEMBLY			CATEGORY 7			-			
MOC :										
SB PW500-72-30332 R03 E1	REPLACEMENT OF ACCESSORY GEARBOX DRIVE SHAFT ANNULAR BALL BEARING			CATEGORY 6			-			
MOC :										
SB PW500-72-30332 R03 E2	REPLACEMENT OF ACCESSORY GEARBOX DRIVE SHAFT ANNULAR BALL BEARING			CATEGORY 6			-			
MOC :										
SB PW500-72-30332 R04 E1	REPLACEMENT OF ACCESSORY GEARBOX DRIVE-SHAFT ANNULAR BALL-BEARING			CATEGORY 6			-			
MOC :										
SB PW500-72-30332 R04 E2	REPLACEMENT OF ACCESSORY GEARBOX DRIVE-SHAFT ANNULAR BALL-BEARING			CATEGORY 6			-			
MOC :										

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30332 R2 E1	REPLACEMENT OF ACCESSORY GEARBOX DRIVE SHAFT ANNULAR BALL BEARING	UNK		CATEGORY 6	MTH 14-Jul-2017 HRS 4930.9 LDG 4107		A/R			Complete
MOC : COMPLIED WITH										
SB PW500-72-30332 R2 E2	REPLACEMENT OF ACCESSORY GEARBOX DRIVE SHAFT ANNULAR BALL BEARING	UNK		CATEGORY 6	MTH 12-Jul-2017 HRS 4930.9 LDG 4107		A/R			Complete
MOC : COMPLIED WITH										
SB PW500-72-30336 R1 E1	REPLACEMENT / MODIFICATION OF HYDROMECHANICAL FUEL CONTROL			CATEGORY 7			-			
MOC :										
SB PW500-72-30336 R1 E2	REPLACEMENT / MODIFICATION OF HYDROMECHANICAL FUEL CONTROL			CATEGORY 7			-			
MOC :										
SB PW500-72-30340 E1	REPLACEMENT OF IGNITERS AND IGNITION CABLES	UNK		CATEGORY 7	MTH 20-Dec-2008 HRS 2477.4 LDG 2081		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30343 R5 E1	REPLACEMENT OF SERVO VALVE FOR THE INTERCOMPRESSOR-BLEED-VALVE			CATEGORY 7			A/R			
MOC :										
SB PW500-72-30343 R5 E2	REPLACEMENT OF SERVO VALVE FOR THE INTERCOMPRESSOR-BLEED-VALVE			CATEGORY 7			A/R			
MOC :										
SB PW500-72-30343 R6 E1	REPLACEMENT OF SERVO VALVE FOR THE INTERCOMPRESSOR-BLEED-VALVE			CATEGORY 7			-			
MOC :										
SB PW500-72-30343 R6 E2	REPLACEMENT OF SERVO VALVE FOR THE INTERCOMPRESSOR-BLEED-VALVE			CATEGORY 7			-			
MOC :										
SB PW500-72-30344 R1 E1	REPLACEMENT OF VARIOUS CADMIUM PLATED PARTS			CATEGORY 7			-			
MOC :										
SB PW500-72-30344 R1 E2	REPLACEMENT OF VARIOUS CADMIUM PLATED PARTS			CATEGORY 7			-			
MOC :										
SB PW500-72-30353 R1 E1	REPLACEMENT OF INTERSHAFT CARBON SEALS	UNK		CATEGORY 6	MTH 14-Jul-2017 HRS 4930.9 LDG 4107		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30353 R1 E2	REPLACEMENT OF INTERSHAFT CARBON SEALS	UNK		CATEGORY 6	MTH 12-Jul-2017 HRS 4930.9 LDG 4107		-			Complete
MOC : COMPLIED WITH										



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30356 R2 E1	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL WITH ADDITIONAL PROTECTIVE SCREENS			CATEGORY 6			-			
	MOC :									
SB PW500-72-30356 R2 E2	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL WITH ADDITIONAL PROTECTIVE SCREENS			CATEGORY 6			-			
	MOC :									
SB PW500-72-30356 E1	REPLACEMENT/MODIFICATION HYDROMECHANICAL FUEL CONTROL WITH ADDITIONAL PROTECTIVE SCREENS	UNK		CATEGORY 6	MTH 20-Dec-2008 HRS 2477.4 LDG 2081		-			Complete
	MOC :									
SB PW500-72-30359 R1 E2	REPLACEMENT OF AIR/OIL SEPARATOR	UNK		CATEGORY 7	MTH 12-Jul-2017 HRS 4930.9 LDG 4107		-			Complete
	MOC :									
SB PW500-72-30364 R02 E1	ACCESSORY GEARBOX PLAIN SEALS - REPLACEMENT			CATEGORY 7			-			
	MOC :									
SB PW500-72-30364 R02 E2	ACCESSORY GEARBOX PLAIN SEALS - REPLACEMENT			CATEGORY 7			-			
	MOC :									
SB PW500-72-30364 R03 E1	REPLACEMENT OF ACCESSORY GEARBOX PLAIN SEALS			CATEGORY 7			-			
	MOC :									
SB PW500-72-30364 R03 E2	REPLACEMENT OF ACCESSORY GEARBOX PLAIN SEALS			CATEGORY 7			-			
	MOC :									
SB PW500-72-30364 R1 E1	REPLACEMENT ACCESSORY GEARBOX PLAIN SEALS						-			
	MOC :									
SB PW500-72-30364 R1 E2	REPLACEMENT ACCESSORY GEARBOX PLAIN SEALS						-			
	MOC :									
SB PW500-72-30374 E1	INSPECTION TURBINE EXHAUST CASE OUTER-WALL THICKNESS	UNK		CATEGORY 5	MTH 14-Jul-2017 HRS 4930.9 LDG 4107		-			Complete
	MOC :									
SB PW500-72-30374 E2	INSPECTION TURBINE EXHAUST CASE OUTER-WALL THICKNESS	UNK		CATEGORY 5	MTH 12-Jul-2017 HRS 4930.9 LDG 4107		-			Complete
	MOC :									
SB PW500-72-30376 R1 E1	REPLACEMENT/MODIFICATION OF OIL PUMP ASSEMBLY AND OIL-PUMP-DRIVE SPUR GEAR			CATEGORY 7			A/R			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30376 R1 E2	REPLACEMENT/MODIFICATION OF OIL PUMP ASSEMBLY AND OIL-PUMP-DRIVE SPUR GEAR			CATEGORY 7			A/R			
	MOC :									
SB PW500-72-30376 R2 E1	REPLACEMENT/MODIFICATION OF OIL PUMP ASSEMBLY AND OIL-PUMP-DRIVE SPUR GEAR			CATEGORY 7			-			
	MOC :									
SB PW500-72-30376 R2 E2	REPLACEMENT/MODIFICATION OF OIL PUMP ASSEMBLY AND OIL-PUMP-DRIVE SPUR GEAR			CATEGORY 7			-			
	MOC :									
SB PW500-72-30378 E1	REPLACEMENT/MODIFICATION OF LOW PRESSURE TURBINE (LPT) DISC ASSEMBLY	UNK		CATEGORY 7	MTH 14-Jul-2017 HRS 4930.9 LDG 4107		-			Complete
	MOC : COMPLIED WITH									
SB PW500-72-30378 E2	REPLACEMENT/MODIFICATION OF LOW PRESSURE TURBINE (LPT) DISC ASSEMBLY	UNK		CATEGORY 7	MTH 12-Jul-2017 HRS 4930.9 LDG 4107		-			Complete
	MOC : COMPLIED WITH									
SB PW500-72-30382 R2 E1	TURBINE EXHAUST CONE, INNER BY-PASS DUCT ASSEMBLY, FUEL MANIFOLD, FUEL SHUT-OFF CABLE GROMMETS AND COVER PLATE FAIRING - REPLACEMENT / MODIFICATION OF	BOI		CATEGORY 3	MTH 29-Apr-2011 HRS 3153.9 LDG 2622		A/R			Complete
	MOC : COMPLIED WITH									
SB PW500-72-30382 R2 E2	TURBINE EXHAUST CONE, INNER BY-PASS DUCT ASSEMBLY, FUEL MANIFOLD, FUEL SHUT-OFF CABLE GROMMETS AND COVER PLATE FAIRING - REPLACEMENT / MODIFICATION OF	BOI		CATEGORY 3	MTH 29-Apr-2011 HRS 3153.9 LDG 2622		A/R			Complete
	MOC : COMPLIED WITH - INSTALLED OVERHAULED INNER BYPASS DUCT, P/N3073555-01 S/N FN61508. REF. VTVR906K 8130 DATED02/16/2011, FTN 15249 FOR DETAILS. INSTALLED NEW TURBINE EXHAUST CONE P/N3074162-01. INSTALLED NEW FUEL MANIFOLD GROMMETS AND COVER PLATES.ALL WORK PERFORMED IAW P&W SB30382R2 AND THE P&P 535A MAINT. MANUAL									
SB PW500-72-30382 R3 E1	REPLACEMENT / MODIFICATION OF TURBINE EXHAUST CONE, INNER BY-PASS DUCT ASSEMBLY, FUEL MANIFOLD, FUEL SHUT-OFF CABLE GROMMETS AND COVER PLATE FAIRING			CATEGORY 7	MTH		-			
	MOC :									
SB PW500-72-30382 R3 E2	REPLACEMENT / MODIFICATION OF TURBINE EXHAUST CONE, INNER BY-PASS DUCT ASSEMBLY, FUEL MANIFOLD, FUEL SHUT-OFF CABLE GROMMETS AND COVER PLATE FAIRING			CATEGORY 7	MTH		-			
	MOC :									
SB PW500-72-30382 R4 E1	REPLACEMENT / MODIFICATION OF TURBINE EXHAUST CONE, INNER BY-PASS DUCT ASSEMBLY, FUEL MANIFOLD, FUEL SHUT-OFF CABLE GROMMETS AND COVER PLATE FAIRING			CATEGORY 3	MTH		-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30382 R4 E2	REPLACEMENT / MODIFICATION OF TURBINE EXHAUST CONE, INNER BY-PASS DUCT ASSEMBLY, FUEL MANIFOLD, FUEL SHUT-OFF CABLE GROMMETS AND COVER PLATE FAIRING			CATEGORY 3	MTH		-			
MOC :										
SB PW500-72-30386 R1 E1	FLIGHT COUNT FACTOR CRITICAL ROTATING COMPONENTS			CATEGORY 6			A/R			
MOC :										
SB PW500-72-30386 R1 E2	FLIGHT COUNT FACTOR CRITICAL ROTATING COMPONENTS			CATEGORY 6			A/R			
MOC :										
SB PW500-72-30387 R06 E1	REPLACEMENT / MODIFICATION REAR BY-PASS DUCT ASSEMBLY			CATEGORY 6			-			
MOC :										
SB PW500-72-30387 R06 E2	REPLACEMENT / MODIFICATION REAR BY-PASS DUCT ASSEMBLY			CATEGORY 6			-			
MOC :										
SB PW500-72-30387 R1 E1	REPLACEMENT/MODIFICATION REAR BY-PASS DUCT ASSEMBLY	BOI		CATEGORY 6	MTH 29-Apr-2011 HRS 3153.9 LDG 2622		A/R			Complete
MOC : COMPLIED WITH										
SB PW500-72-30387 R1 E2	REPLACEMENT/MODIFICATION REAR BY-PASS DUCT ASSEMBLY	BOI		CATEGORY 6	MTH 29-Apr-2011 HRS 3153.9 LDG 2622		A/R			Complete
MOC : COMPLIED WITH										
SB PW500-72-30387 R2 E1	REPLACEMENT / MODIFICATION REAR BY-PASS DUCT ASSEMBLY			CATEGORY 6			-			
MOC :										
SB PW500-72-30387 R2 E2	REPLACEMENT / MODIFICATION REAR BY-PASS DUCT ASSEMBLY			CATEGORY 6			-			
MOC :										
SB PW500-72-30387 R3 E1	REPLACEMENT / MODIFICATION REAR BY-PASS DUCT ASSEMBLY			CATEGORY 6			-			
MOC :										
SB PW500-72-30387 R3 E2	REPLACEMENT / MODIFICATION REAR BY-PASS DUCT ASSEMBLY			CATEGORY 6			-			
MOC :										
SB PW500-72-30387 R4 E1	REPLACEMENT / MODIFICATION OF REAR BY-PASS DUCT ASSEMBLY			CATEGORY 6			-			
MOC :										
SB PW500-72-30387 R4 E2	REPLACEMENT / MODIFICATION OF REAR BY-PASS DUCT ASSEMBLY			CATEGORY 6			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30387 R5 E1	REPLACEMENT / MODIFICATION REAR BY-PASS DUCT ASSEMBLY			CATEGORY 6			-			
	MOC :									
SB PW500-72-30387 R5 E2	REPLACEMENT / MODIFICATION REAR BY-PASS DUCT ASSEMBLY			CATEGORY 6			-			
	MOC :									
SB PW500-72-30390 R5 E1	CAVITATION REPAIR HYDROMECHANICAL FUEL CONTROL UNIT (SUPERSEDED BY SB PW500-72-30409 R8, DATED JUNE 20, 2012)			CATEGORY 10			-			
	MOC :									
SB PW500-72-30390 R5 E2	CAVITATION REPAIR HYDROMECHANICAL FUEL CONTROL UNIT (SUPERSEDED BY SB PW500-72-30409 R8, DATED JUNE 20, 2012)			CATEGORY 10			-			
	MOC :									
SB PW500-72-30396 R1 E1	REPLACEMENT OF BOLTS			CATEGORY 7			-			
	MOC :									
SB PW500-72-30396 R1 E2	REPLACEMENT OF BOLTS			CATEGORY 7			-			
	MOC :									
SB PW500-72-30396 E1	REPLACEMENT OF BOLTS						A/R			
	MOC :									
SB PW500-72-30396 E2	REPLACEMENT OF BOLTS						A/R			
	MOC :									
SB PW500-72-30400 R1 E1	REPLACEMENT OF INTERMEDIATE CASE ASSEMBLY AND INTERSHAFT SEAL CARRIER			CATEGORY 6			A/R			
	MOC :									
SB PW500-72-30400 R1 E2	REPLACEMENT OF INTERMEDIATE CASE ASSEMBLY AND INTERSHAFT SEAL CARRIER			CATEGORY 6			A/R			
	MOC :									
SB PW500-72-30400 R2 E1	REPLACEMENT OF INTERMEDIATE CASE ASSEMBLY AND INTERSHAFT SEAL CARRIER			CATEGORY 6			A/R			
	MOC :									
SB PW500-72-30400 R2 E2	REPLACEMENT OF INTERMEDIATE CASE ASSEMBLY AND INTERSHAFT SEAL CARRIER			CATEGORY 6			A/R			
	MOC :									
SB PW500-72-30400 R3 E1	REPLACEMENT OF INTERMEDIATE CASE ASSEMBLY AND INTERSHAFT SEAL CARRIER			CATEGORY 6			-			
	MOC :									
SB PW500-72-30400 R3 E2	REPLACEMENT OF INTERMEDIATE CASE ASSEMBLY AND INTERSHAFT SEAL CARRIER			CATEGORY 6			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30400 R4 E1	REPLACEMENT OF INTERMEDIATE CASE ASSEMBLY AND INTERSHAFT SEAL CARRIER	UNK		CATEGORY 6	MTH 14-Jul-2017 HRS 4930.9 LDG 4107		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30400 R4 E2	REPLACEMENT OF INTERMEDIATE CASE ASSEMBLY AND INTERSHAFT SEAL CARRIER	UNK		CATEGORY 6	MTH 12-Jul-2017 HRS 4930.9 LDG 4107		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30400 E1	REPLACEMENT OF INTERMEDIATE CASE ASSEMBLY AND INTERSHAFT SEAL CARRIER			CATEGORY 6			A/R			
MOC :										
SB PW500-72-30400 E2	REPLACEMENT OF INTERMEDIATE CASE ASSEMBLY AND INTERSHAFT SEAL CARRIER			CATEGORY 6			A/R			
MOC :										
SB PW500-72-30403 R02 E1	REPLACEMENT OF TEE HEAD BOLT/1ST.- 2ND. STAGE HP COMPRESSOR ASSEMBLIES	UNK		CATEGORY 6	MTH 14-Jul-2017 HRS 4930.9 LDG 4107		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30403 R02 E2	REPLACEMENT OF TEE HEAD BOLT/1ST.- 2ND. STAGE HP COMPRESSOR ASSEMBLIES	UNK		CATEGORY 6	MTH 12-Jul-2017 HRS 4930.9 LDG 4107		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30403 R03 E1	REPLACEMENT OF TEE HEAD BOLT/1ST.- 2ND. STAGE HP COMPRESSOR ASSEMBLIES			CATEGORY 6			-			
MOC :										
SB PW500-72-30403 R03 E2	REPLACEMENT OF TEE HEAD BOLT/1ST.- 2ND. STAGE HP COMPRESSOR ASSEMBLIES			CATEGORY 6			-			
MOC :										
SB PW500-72-30403 R04 E1	REPLACEMENT OF TEE HEAD BOLT/1ST.- 2ND. STAGE HP COMPRESSOR ASSEMBLIES			CATEGORY 6			-			
MOC :										
SB PW500-72-30403 R04 E2	REPLACEMENT OF TEE HEAD BOLT/1ST.- 2ND. STAGE HP COMPRESSOR ASSEMBLIES			CATEGORY 6			-			
MOC :										
SB PW500-72-30405 R2 E1	REPLACEMENT OF FUEL NOZZLE MANIFOLD			CATEGORY 6			-			
MOC :										
SB PW500-72-30405 R2 E2	REPLACEMENT OF FUEL NOZZLE MANIFOLD			CATEGORY 6			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30405 R3 E1	REPLACEMENT OF - FUEL NOZZLE MANIFOLD UNK			CATEGORY 6	MTH 14-Jul-2017 HRS 4930.9 LDG 4107		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30405 R3 E2	REPLACEMENT OF - FUEL NOZZLE MANIFOLD UNK			CATEGORY 6	MTH 12-Jul-2017 HRS 4930.9 LDG 4107		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30408 E1	REPLACEMENT OF ENGINE GASKET UNK			CATEGORY 6	MTH 14-Jul-2017 HRS 4930.9 LDG 4107		A/R			Complete
MOC : COMPLIED WITH										
SB PW500-72-30408 E2	REPLACEMENT OF ENGINE GASKET UNK			CATEGORY 6	MTH 12-Jul-2017 HRS 4930.9 LDG 4107		A/R			Complete
MOC : COMPLIED WITH										
SB PW500-72-30409 R10 E1	REPLACEMENT / MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT UNK			CATEGORY 3	MTH		-			
MOC :										
SB PW500-72-30409 R10 E2	REPLACEMENT / MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT UNK			CATEGORY 3	MTH		-			
MOC :										
SB PW500-72-30409 R6 E2	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT BOI			CATEGORY 3	MTH 02-Nov-2011 HRS 3259.9 LDG 2719		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30415 R04 E1	REPLACEMENT OF NO. 4 ROLLER BEARING UNK			CATEGORY 6			-			
MOC :										
SB PW500-72-30415 R04 E2	REPLACEMENT OF NO. 4 ROLLER BEARING UNK			CATEGORY 6			-			
MOC :										
SB PW500-72-30415 R1 E1	REPLACEMENT OF NO. 4 ROLLER BEARING UNK			CATEGORY 6			-			
MOC :										
SB PW500-72-30415 R1 E2	REPLACEMENT OF NO. 4 ROLLER BEARING UNK			CATEGORY 6			-			
MOC :										
SB PW500-72-30415 R3 E1	REPLACEMENT OF NO. 4 ROLLER BEARING UNK			CATEGORY 6	MTH 14-Jul-2017 HRS 4930.9 LDG 4107		-			Complete
MOC : COMPLIED WITH										



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30415 R3 E2	REPLACEMENT OF NO. 4 ROLLER BEARING	UNK		CATEGORY 6	MTH 12-Jul-2017 HRS 4930.9 LDG 4107		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30420 R01 E1	REPLACEMENT/MODIFICATION OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE (SUPERSEDED BY PW500-72-30420 R02)	BOI		CATEGORY 3	MTH 07-Mar-2011 HRS 3136 LDG 2606		-			Complete
MOC : COMPLIED WITH - SERVICE BULLETIN C/W 03/07/2011 @ 3113 HRS										
SB PW500-72-30420 R01 E2	REPLACEMENT/MODIFICATION OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE (SUPERSEDED BY PW500-72-30420 R02)	BOI		CATEGORY 3	MTH 07-Mar-2011 HRS 3136 LDG 2606		-			Complete
MOC : COMPLIED WITH - SERVICE BULLETIN C/W 03/07/2011 @ 3113 HRS.										
SB PW500-72-30420 R02 E1	REPLACEMENT/MODIFICATION OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE (SUPERSEDED BY PW500-72-30420 R03)			CATEGORY 3	MTH 07-Mar-2011 HRS 3136 LDG 2606		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30420 R02 E2	REPLACEMENT/MODIFICATION OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE (SUPERSEDED BY PW500-72-30420 R03)			CATEGORY 3	MTH 07-Mar-2011 HRS 3136 LDG 2606		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30420 R03 E1	REPLACEMENT/MODIFICATION OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE (SUPERSEDED BY PW500-72-30420 R04)			CATEGORY 3	MTH 07-Mar-2011 HRS 3136 LDG 2606		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30420 R03 E2	REPLACEMENT/MODIFICATION OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE (SUPERSEDED BY PW500-72-30420 R04)	UNK		CATEGORY 3	MTH 12-Jul-2017 HRS 4930.9 LDG 4107		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30420 R04 E1	REPLACEMENT OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE (SUPERSEDED BY PW500-72-30420 R05)	UNK		CATEGORY 6	MTH 14-Jul-2017 HRS 4930.9 LDG 4107		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30420 R04 E2	REPLACEMENT OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE (SUPERSEDED BY PW500-72-30420 R05)	UNK		CATEGORY 6	MTH 12-Jul-2017 HRS 4930.9 LDG 4107		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30420 R05 E1	REPLACEMENT OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE			CATEGORY 3			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30420 R05 E2	REPLACEMENT OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE			CATEGORY 3			-			
	MOC :									
SB PW500-72-30420 R06 E1	REPLACEMENT OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE			CATEGORY 3 MTH			-			
	MOC :									
SB PW500-72-30420 R06 E2	REPLACEMENT OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE			CATEGORY 3 MTH			-			
	MOC :									
SB PW500-72-30423 R1 E1	REPLACEMENT/MODIFICATION INTERMEDIATE CASE ASSEMBLY	UNK		CATEGORY 6	MTH 14-Jul-2017 HRS 4930.9 LDG 4107		-			Complete
	MOC :	COMPLIED WITH								
SB PW500-72-30423 R1 E2	REPLACEMENT/MODIFICATION INTERMEDIATE CASE ASSEMBLY	UNK		CATEGORY 6	MTH 12-Jul-2017 HRS 4930.9 LDG 4107		-			Complete
	MOC :	COMPLIED WITH								
SB PW500-72-30423 E1	REPLACEMENT/MODIFICATION INTERMEDIATE CASE ASSEMBLY			CATEGORY 6			A/R			
	MOC :									
SB PW500-72-30423 E2	REPLACEMENT/MODIFICATION INTERMEDIATE CASE ASSEMBLY			CATEGORY 6			A/R			
	MOC :									
SB PW500-72-30428 R05 E1	REPLACEMENT OF FUEL MANIFOLD SYSTEM INTERFACE	UNK		CATEGORY 6	MTH 14-Jul-2017 HRS 4930.9 LDG 4107		-			Complete
	MOC :	COMPLIED WITH								
SB PW500-72-30428 R05 E2	REPLACEMENT OF FUEL MANIFOLD SYSTEM INTERFACE	UNK		CATEGORY 6	MTH 12-Jul-2017 HRS 4930.9 LDG 4107		-			Complete
	MOC :	COMPLIED WITH								
SB PW500-72-30428 R06 E1	REPLACEMENT OF FUEL MANIFOLD SYSTEM INTERFACE			CATEGORY 6			-			
	MOC :									
SB PW500-72-30428 R06 E2	REPLACEMENT OF FUEL MANIFOLD SYSTEM INTERFACE			CATEGORY 6			-			
	MOC :									
SB PW500-72-30428 R2 E1	REPLACEMENT OF FUEL MANIFOLD SYSTEM INTERFACE			CATEGORY 6			-			
	MOC :									
SB PW500-72-30428 R2 E2	REPLACEMENT OF FUEL MANIFOLD SYSTEM INTERFACE			CATEGORY 6			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30428 R3 E1	REPLACEMENT OF - FUEL MANIFOLD SYSTEM INTERFACE			CATEGORY 6			-			
	MOC :									
SB PW500-72-30428 R3 E2	REPLACEMENT OF - FUEL MANIFOLD SYSTEM INTERFACE			CATEGORY 6			-			
	MOC :									
SB PW500-72-30428 R4 E1	REPLACEMENT OF FUEL MANIFOLD SYSTEM INTERFACE			CATEGORY 6			-			
	MOC :									
SB PW500-72-30428 R4 E2	REPLACEMENT OF FUEL MANIFOLD SYSTEM INTERFACE			CATEGORY 6			-			
	MOC :									
SB PW500-72-30430 R1 E1	REPLACEMENT OF HIGH PRESSURE TURBINE BLADE	UNK		CATEGORY 7	MTH 14-Jul-2017 HRS 4930.9 LDG 4107		A/R			Complete
	MOC :	COMPLIED WITH								
SB PW500-72-30430 R1 E2	REPLACEMENT OF HIGH PRESSURE TURBINE BLADE			CATEGORY 7			A/R			
	MOC :									
SB PW500-72-30430 E1	REPLACEMENT OF HIGH PRESSURE TURBINE BLADE			CATEGORY 7			-			
	MOC :									
SB PW500-72-30430 E2	REPLACEMENT OF HIGH PRESSURE TURBINE BLADE			CATEGORY 7			-			
	MOC :									
SB PW500-72-30431 E1	CARBON SEAL NO. 4 BEARING - REPLACEMENT OF			CATEGORY 7			A/R			
	MOC :									
SB PW500-72-30431 E2	CARBON SEAL NO. 4 BEARING - REPLACEMENT OF			CATEGORY 7			A/R			
	MOC :									
SB PW500-72-30432 R1 E1	PLAIN SEAL ACCESSORY GEARBOX - REPLACEMENT OF			CATEGORY 7			A/R			
	MOC :									
SB PW500-72-30432 R1 E2	PLAIN SEAL ACCESSORY GEARBOX - REPLACEMENT OF			CATEGORY 7			A/R			
	MOC :									
SB PW500-72-30432 E1	PLAIN SEAL ACCESSORY GEARBOX - REPLACEMENT OF			CATEGORY 7			A/R			
	MOC :									
SB PW500-72-30432 E2	PLAIN SEAL ACCESSORY GEARBOX - REPLACEMENT OF			CATEGORY 7			A/R			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30442 R04 E1	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT CATEGORY 7						-			
	MOC :									
SB PW500-72-30442 R04 E2	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT CATEGORY 7						-			
	MOC :									
SB PW500-72-30442 R1 E1	TURBOFAN ENGINE HYDROMECHANICAL FUEL CONTROL UNIT- REPLACEMENT/MODIFICATION OF CATEGORY 7						A/R			
	MOC :									
SB PW500-72-30442 R1 E2	TURBOFAN ENGINE HYDROMECHANICAL FUEL CONTROL UNIT- REPLACEMENT/MODIFICATION OF CATEGORY 7						A/R			
	MOC :									
SB PW500-72-30442 R2 E1	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT CATEGORY 7						-			
	MOC :									
SB PW500-72-30442 R2 E2	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT CATEGORY 7						-			
	MOC :									
SB PW500-72-30442 R3 E1	REPLACEMENT / MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT CATEGORY 7						-			
	MOC :									
SB PW500-72-30442 R3 E2	REPLACEMENT / MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT CATEGORY 7						-			
	MOC :									
SB PW500-72-30442 E1	HYDROMECHANICAL FUEL CONTROL UNIT- REPLACEMENT/MODIFICATION OF CATEGORY 6						A/R			
	MOC :									
SB PW500-72-30442 E2	HYDROMECHANICAL FUEL CONTROL UNIT- REPLACEMENT/MODIFICATION OF CATEGORY 6						A/R			
	MOC :									
SB PW500-72-30444 R1 E1	REPLACEMENT OF COMBUSTION CHAMBER LINER CATEGORY 7						A/R			
	MOC :									
SB PW500-72-30444 R1 E2	REPLACEMENT OF COMBUSTION CHAMBER LINER CATEGORY 7						A/R			
	MOC :									
SB PW500-72-30444 E1	REPLACEMENT OF COMBUSTION CHAMBER LINER CATEGORY 7						A/R			
	MOC :									
SB PW500-72-30444 E2	REPLACEMENT OF COMBUSTION CHAMBER LINER CATEGORY 7						A/R			
	MOC :									
SB PW500-72-30446 R1 E1	REPLACEMENT OF LOW PRESSURE COMPRESSOR SHAFT BALANCING ASSEMBLY CATEGORY 7						A/R			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30446 R1 E2	REPLACEMENT OF LOW PRESSURE COMPRESSOR SHAFT BALANCING ASSEMBLY			CATEGORY 7			A/R			
	MOC :									
SB PW500-72-30446 R2 E1	REPLACEMENT OF LOW PRESSURE COMPRESSOR SHAFT BALANCING ASSEMBLY			CATEGORY 7			-			
	MOC :									
SB PW500-72-30446 R2 E2	REPLACEMENT OF LOW PRESSURE COMPRESSOR SHAFT BALANCING ASSEMBLY			CATEGORY 7			-			
	MOC :									
SB PW500-72-30446 E1	REPLACEMENT OF LOW PRESSURE COMPRESSOR SHAFT BALANCING ASSEMBLY			CATEGORY 7			A/R			
	MOC :									
SB PW500-72-30446 E2	REPLACEMENT OF LOW PRESSURE COMPRESSOR SHAFT BALANCING ASSEMBLY			CATEGORY 7			A/R			
	MOC :									
SB PW500-72-30447 R1 E1	NEW COATING MODIFICATION OF GAS GENERATOR CASE	UNK		CATEGORY 6	MTH 14-Jul-2017 HRS 4930.9 LDG 4107		-			Complete
	MOC : COMPLIED WITH									
SB PW500-72-30447 R1 E2	NEW COATING MODIFICATION OF GAS GENERATOR CASE	UNK		CATEGORY 6	MTH 12-Jul-2017 HRS 4930.9 LDG 4107		-			Complete
	MOC : COMPLIED WITH									
SB PW500-72-30447 E1	NEW COATING MODIFICATION OF GAS GENERATOR CASE			CATEGORY 6			-			
	MOC :									
SB PW500-72-30447 E2	NEW COATING MODIFICATION OF GAS GENERATOR CASE			CATEGORY 6			-			
	MOC :									
SB PW500-72-30453 R03 E1	REPLACEMENT OF NO. 4 CARBON SEAL			CATEGORY 7			-			
	MOC :									
SB PW500-72-30453 R03 E2	REPLACEMENT OF NO. 4 CARBON SEAL			CATEGORY 7			-			
	MOC :									
SB PW500-72-30453 R1 E1	REPLACEMENT OF NO. 4 CARBON SEAL			CATEGORY 7			-			
	MOC :									
SB PW500-72-30453 R1 E2	REPLACEMENT OF NO. 4 CARBON SEAL			CATEGORY 7			-			
	MOC :									
SB PW500-72-30453 R2 E1	REPLACEMENT OF NO. 4 CARBON SEAL			CATEGORY 7			-			
	MOC :									

NOTE: Item Codes in *italics* show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30453 R2 E2	REPLACEMENT OF NO. 4 CARBON SEAL			CATEGORY 7			-			
MOC :										
SB PW500-72-30453 E1	REPLACEMENT OF NO. 4 CARBON SEAL	UNK		CATEGORY 7	MTH 14-Jul-2017 HRS 4930.9 LDG 4107		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30453 E2	REPLACEMENT OF NO. 4 CARBON SEAL	UNK		CATEGORY 7	MTH 12-Jul-2017 HRS 4930.9 LDG 4107		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30455 R05 E1	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT			CATEGORY 7			-			
MOC :										
SB PW500-72-30455 R05 E2	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT			CATEGORY 7			-			
MOC :										
SB PW500-72-30455 R1 E1	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT			CATEGORY 7			-			
MOC :										
SB PW500-72-30455 R1 E2	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT			CATEGORY 7			-			
MOC :										
SB PW500-72-30455 R2 E1	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT			CATEGORY 7			-			
MOC :										
SB PW500-72-30455 R2 E2	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT			CATEGORY 7			-			
MOC :										
SB PW500-72-30455 R3 E1	REPLACEMENT / MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT			CATEGORY 7			-			
MOC :										
SB PW500-72-30455 R3 E2	REPLACEMENT / MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT			CATEGORY 7			-			
MOC :										
SB PW500-72-30455 R4 E1	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT	UNK		CATEGORY 7	MTH 14-Jul-2017 HRS 4930.9 LDG 4107		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30455 R4 E2	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT	UNK		CATEGORY 7	MTH 12-Jul-2017 HRS 4930.9 LDG 4107		-			Complete
MOC : COMPLIED WITH										



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30455 E1	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT			CATEGORY 6			-			
	MOC :									
SB PW500-72-30455 E2	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT			CATEGORY 6			-			
	MOC :									
SB PW500-72-30459 R1 E1	REPLACEMENT OF NUT OPTION (IC)	UNK		CATEGORY 6	MTH 14-Jul-2017 HRS 4930.9 LDG 4107		-			Complete
	MOC :	COMPLIED WITH								
SB PW500-72-30459 R1 E2	REPLACEMENT OF NUT OPTION (IC)	UNK		CATEGORY 6	MTH 12-Jul-2017 HRS 4930.9 LDG 4107		-			Complete
	MOC :	COMPLIED WITH								
SB PW500-72-30459 E1	REPLACEMENT OF NUT OPTION (IC)			CATEGORY 6			-			
	MOC :									
SB PW500-72-30459 E2	REPLACEMENT OF NUT OPTION (IC)			CATEGORY 6			-			
	MOC :									
SB PW500-72-30461 R01 E1	CONVERSION OF PW535A BUILD SPECIFICATION 1155 TO 909 AND CONVERSION OF PW535B BUILD SPECIFICATION 1262 TO 1208			CATEGORY 8			-			
	MOC :									
SB PW500-72-30461 R01 E2	CONVERSION OF PW535A BUILD SPECIFICATION 1155 TO 909 AND CONVERSION OF PW535B BUILD SPECIFICATION 1262 TO 1208			CATEGORY 8			-			
	MOC :									
SB PW500-72-30461 E1	CONVERSION OF PW535A BUILD SPECIFICATION 1155 TO 909 CONVERSION OF PW535B BUILD SPECIFICATION 1262 TO 1208			CATEGORY 8			-			
	MOC :									
SB PW500-72-30461 E2	CONVERSION OF PW535A BUILD SPECIFICATION 1155 TO 909 CONVERSION OF PW535B BUILD SPECIFICATION 1262 TO 1208			CATEGORY 8			-			
	MOC :									
SB PW500-72-30463 R1 E1	REPLACEMENT OF ACCESSORY DRIVE LIP SEAL			CATEGORY 7			-			
	MOC :									
SB PW500-72-30463 R1 E2	REPLACEMENT OF ACCESSORY DRIVE LIP SEAL			CATEGORY 7			-			
	MOC :									
SB PW500-72-30463 R2 E1	REPLACEMENT OF ACCESSORY DRIVE LIP SEAL			CATEGORY 7			-			
	MOC :									
SB PW500-72-30463 R2 E2	REPLACEMENT OF ACCESSORY DRIVE LIP SEAL			CATEGORY 7			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30463 E1	REPLACEMENT OF ACCESSORY DRIVE LIP SEAL			CATEGORY 7			-			
	MOC :									
SB PW500-72-30463 E2	REPLACEMENT OF ACCESSORY DRIVE LIP SEAL			CATEGORY 7			-			
	MOC :									
SB PW500-72-30465 R1 E1	REPLACEMENT OF FUEL MANIFOLD TUBES			CATEGORY 7			-			
	MOC :									
SB PW500-72-30465 R1 E2	REPLACEMENT OF FUEL MANIFOLD TUBES			CATEGORY 7			-			
	MOC :									
SB PW500-72-30465 R2 E1	REPLACEMENT OF FUEL MANIFOLD TUBES	UNK		CATEGORY 7	MTH 14-Jul-2017 HRS 4930.9 LDG 4107		-			Complete
	MOC : COMPLIED WITH									
SB PW500-72-30465 R2 E2	REPLACEMENT OF FUEL MANIFOLD TUBES	UNK		CATEGORY 7	MTH 12-Jul-2017 HRS 4930.9 LDG 4107		-			Complete
	MOC : COMPLIED WITH									
SB PW500-72-30465 E1	REPLACEMENT OF FUEL MANIFOLD TUBES			CATEGORY 7			-			
	MOC :									
SB PW500-72-30465 E2	REPLACEMENT OF FUEL MANIFOLD TUBES			CATEGORY 7			-			
	MOC :									
SB PW500-72-30472 R02 E1	REPLACEMENT OF N1 AND N2 SPEED SENSORS			CATEGORY 7			-			
	MOC :									
SB PW500-72-30472 R02 E2	REPLACEMENT OF N1 AND N2 SPEED SENSORS			CATEGORY 7			-			
	MOC :									
SB PW500-72-30472 R1 E1	REPLACEMENT OF - N1 AND N2 SPEED SENSORS			CATEGORY 7			-			
	MOC :									
SB PW500-72-30472 R1 E2	REPLACEMENT OF - N1 AND N2 SPEED SENSORS			CATEGORY 7			-			
	MOC :									
SB PW500-72-30472 E1	REPLACEMENT OF N1 AND N2 SPEED SENSORS			CATEGORY 7			-			
	MOC :									
SB PW500-72-30472 E2	REPLACEMENT OF N1 AND N2 SPEED SENSORS			CATEGORY 7			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30475 PART A E1	ACCOMPLISH REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT ASSEMBLY AND FUEL CONTROL DRIVE SPUR GEARSHAFT ASSEMBLY. REMOVE/INSTALL FUEL CONTROL DRIVE GEARSHAFT			CATEGORY 7			-			
	MOC :									
SB PW500-72-30475 PART A E2	ACCOMPLISH REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT ASSEMBLY AND FUEL CONTROL DRIVE SPUR GEARSHAFT ASSEMBLY. REMOVE/INSTALL FUEL CONTROL DRIVE GEARSHAFT			CATEGORY 7			-			
	MOC :									
SB PW500-72-30475 PART B E1	ACCOMPLISH REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT ASSEMBLY AND FUEL CONTROL DRIVE SPUR GEARSHAFT ASSEMBLY. REMOVE/INSTALL ACCESSORY DRIVE GEARSHAFT			CATEGORY 7			-			
	MOC :									
SB PW500-72-30475 PART B E2	ACCOMPLISH REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT ASSEMBLY AND FUEL CONTROL DRIVE SPUR GEARSHAFT ASSEMBLY. REMOVE/INSTALL ACCESSORY DRIVE GEARSHAFT			CATEGORY 7			-			
	MOC :									
SB PW500-72-30475 R1 PART A E1	REMOVE REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT ASSEMBLY AND FUEL CONTROL DRIVE SPUR GEARSHAFT ASSEMBLY //INSTALL THE FUEL CONTROL DRIVE GEARSHAFT			CATEGORY 7			-			
	MOC :									
SB PW500-72-30475 R1 PART A E2	REMOVE REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT ASSEMBLY AND FUEL CONTROL DRIVE SPUR GEARSHAFT ASSEMBLY //INSTALL THE FUEL CONTROL DRIVE GEARSHAFT			CATEGORY 7			-			
	MOC :									
SB PW500-72-30475 R1 PART B E1	REMOVE REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT ASSEMBLY AND FUEL CONTROL DRIVE SPUR GEARSHAFT ASSEMBLY //INSTALL THE ACCESSORY DRIVE GEARSHAFT			CATEGORY 7			-			
	MOC :									
SB PW500-72-30475 R1 PART B E2	REMOVE REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT ASSEMBLY AND FUEL CONTROL DRIVE SPUR GEARSHAFT ASSEMBLY //INSTALL THE ACCESSORY DRIVE GEARSHAFT			CATEGORY 7			-			
	MOC :									
SB PW500-72-30475 R1 E1	REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT ASSEMBLY AND FUEL CONTROL DRIVE SPUR GEARSHAFT ASSEMBLY			CATEGORY 7			-			
	MOC :									
SB PW500-72-30475 R1 E2	REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT ASSEMBLY AND FUEL CONTROL DRIVE SPUR GEARSHAFT ASSEMBLY			CATEGORY 7			-			
	MOC :									
SB PW500-72-30475 R2 PART A E1	REMOVE REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT ASSEMBLY AND FUEL CONTROL DRIVE SPUR GEARSHAFT ASSEMBLY //INSTALL THE FUEL CONTROL DRIVE GEARSHAFT			CATEGORY 7			-			
	MOC :									
SB PW500-72-30475 R2 PART A E2	REMOVE REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT ASSEMBLY AND FUEL CONTROL DRIVE SPUR GEARSHAFT ASSEMBLY //INSTALL THE FUEL CONTROL DRIVE GEARSHAFT			CATEGORY 7			-			
	MOC :									
SB PW500-72-30475 R2 PART B E1	REMOVE REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT ASSEMBLY AND FUEL CONTROL DRIVE SPUR GEARSHAFT ASSEMBLY //INSTALL THE ACCESSORY DRIVE GEARSHAFT			CATEGORY 7			-			
	MOC :									
SB PW500-72-30475 R2 PART B E2	REMOVE REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT ASSEMBLY AND FUEL CONTROL DRIVE SPUR GEARSHAFT ASSEMBLY //INSTALL THE ACCESSORY DRIVE GEARSHAFT			CATEGORY 7			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30475 R2 E1	REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT ASSEMBLY AND FUEL CONTROL DRIVE SPUR GEARSHAFT ASSEMBLY			CATEGORY 7			-			
	MOC :									
SB PW500-72-30475 R2 E2	REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT ASSEMBLY AND FUEL CONTROL DRIVE SPUR GEARSHAFT ASSEMBLY			CATEGORY 7			-			
	MOC :									
SB PW500-72-30475 R3 PART A E1	ACCOMPLISH REMOVE AND INSTALL FUEL CONTROL DRIVE GEARSHAFT			CATEGORY 7			-			
	MOC :									
SB PW500-72-30475 R3 PART A E2	ACCOMPLISH REMOVE AND INSTALL FUEL CONTROL DRIVE GEARSHAFT			CATEGORY 7			-			
	MOC :									
SB PW500-72-30475 R3 PART B E1	ACCOMPLISH REMOVE AND INSTALL THE ACCESSORY DRIVE GEARSHAFT			CATEGORY 7			-			
	MOC :									
SB PW500-72-30475 R3 PART B E2	ACCOMPLISH REMOVE AND INSTALL THE ACCESSORY DRIVE GEARSHAFT			CATEGORY 7			-			
	MOC :									
SB PW500-72-30475 R3 E1	REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT ASSEMBLY AND FUEL CONTROL DRIVE SPUR GEARSHAFT ASSEMBLY			CATEGORY 7			-			
	MOC :									
SB PW500-72-30475 R3 E2	REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT ASSEMBLY AND FUEL CONTROL DRIVE SPUR GEARSHAFT ASSEMBLY			CATEGORY 7			-			
	MOC :									
SB PW500-72-30475 E1	REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT ASSEMBLY AND FUEL CONTROL DRIVE SPUR GEARSHAFT ASSEMBLY.			CATEGORY 7			-			
	MOC :									
SB PW500-72-30475 E2	REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT ASSEMBLY AND FUEL CONTROL DRIVE SPUR GEARSHAFT ASSEMBLY.			CATEGORY 7			-			
	MOC :									
SB PW500-72-30482 R1 E1	INSPECTION OF COMBUSTION CHAMBER LINER COOLING RING SEGMENTS SELF-LOCKING NUT			CATEGORY 3			-			
	MOC :									
SB PW500-72-30482 R1 E2	INSPECTION OF COMBUSTION CHAMBER LINER COOLING RING SEGMENTS SELF-LOCKING NUT			CATEGORY 3			-			
	MOC :									
SB PW500-72-30482 R2 E1	INSPECTION OF COMBUSTION CHAMBER LINER COOLING RING SEGMENTS SELF-LOCKING NUT			CATEGORY 3			-			
	MOC :									
SB PW500-72-30482 R2 E2	INSPECTION OF COMBUSTION CHAMBER LINER COOLING RING SEGMENTS SELF-LOCKING NUT			CATEGORY 3			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30482 R3 E1	INSPECTION OF COMBUSTION CHAMBER LINER COOLING RING SEGMENTS SELF-LOCKING NUT (SUPERSEDED BY SB PW500-72-30492 R2)			CATEGORY 10			-			
	MOC :									
SB PW500-72-30482 R3 E2	INSPECTION OF COMBUSTION CHAMBER LINER COOLING RING SEGMENTS SELF-LOCKING NUT (SUPERSEDED BY SB PW500-72-30492 R2)			CATEGORY 10			-			
	MOC :									
SB PW500-72-30482 E1	INSPECTION OF COMBUSTION CHAMBER LINER COOLING RING SEGMENTS SELF-LOCKING NUT			CATEGORY 3			-			N/A
	MOC :									
SB PW500-72-30482 E2	INSPECTION OF COMBUSTION CHAMBER LINER COOLING RING SEGMENTS SELF-LOCKING NUT			CATEGORY 3			-			N/A
	MOC :									
SB PW500-72-30483 R1 E1	REPLACEMENT/MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY			CATEGORY 7			-			
	MOC :									
SB PW500-72-30483 R1 E2	REPLACEMENT/MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY			CATEGORY 7			-			
	MOC :									
SB PW500-72-30483 R2 E1	REPLACEMENT/MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY			CATEGORY 7			-			
	MOC :									
SB PW500-72-30483 R2 E2	REPLACEMENT/MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY			CATEGORY 7			-			
	MOC :									
SB PW500-72-30483 R3 E1	REPLACEMENT/MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY (SUPERSEDED BY SB PW500-72-30492 R2)			CATEGORY 10			-			
	MOC :									
SB PW500-72-30483 R3 E2	REPLACEMENT/MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY (SUPERSEDED BY SB PW500-72-30492 R2)			CATEGORY 10			-			
	MOC :									
SB PW500-72-30483 E1	REPLACEMENT/MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY			CATEGORY 7			-			
	MOC :									
SB PW500-72-30483 E2	REPLACEMENT/MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY			CATEGORY 7			-			
	MOC :									
SB PW500-72-30485 R02 E1	REPLACEMENT OF REAR OUTER BY-PASS DUCT HARDWARE			CATEGORY 7			-			
	MOC :									
SB PW500-72-30485 R02 E2	REPLACEMENT OF REAR OUTER BY-PASS DUCT HARDWARE			CATEGORY 7			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30485 R1 E1	REPLACEMENT OF REAR OUTER BY-PASS DUCT HARDWARE CATEGORY 7						-			
MOC :										
SB PW500-72-30485 R1 E2	REPLACEMENT OF REAR OUTER BY-PASS DUCT HARDWARE CATEGORY 7						-			
MOC :										
SB PW500-72-30486 R1 E1	REPLACEMENT OF BREATHER ADAPTER PREFORMED PACKING CATEGORY 7						-			
MOC :										
SB PW500-72-30486 R1 E2	REPLACEMENT OF BREATHER ADAPTER PREFORMED PACKING CATEGORY 7						-			
MOC :										
SB PW500-72-30486 R2 E1	REPLACEMENT OF BREATHER ADAPTER PREFORMED PACKING. CATEGORY 7						-			
MOC :										
SB PW500-72-30486 R2 E2	REPLACEMENT OF BREATHER ADAPTER PREFORMED PACKING. CATEGORY 7						-			
MOC :										
SB PW500-72-30486 E1	REPLACEMENT OF BREATHER ADAPTER PREFORMED PACKING CATEGORY 7						-			
MOC :										
SB PW500-72-30486 E2	REPLACEMENT OF BREATHER ADAPTER PREFORMED PACKING CATEGORY 7						-			
MOC :										
SB PW500-72-30487 R3 E1	REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE LIP SEAL (SUPERSEDED BY SB PW500-72-30502)						-			
MOC :										
SB PW500-72-30487 R3 E2	REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE LIP SEAL (SUPERSEDED BY SB PW500-72-30502)						-			
MOC :										
SB PW500-72-30489 E1	INSPECTION/REPLACEMENT OF TURBINE EXHAUST CASE OIL PRESSURE TUBE BRACKET CONFIGURATION UNK CATEGORY 6				MTH 14-Jul-2017 HRS 4930.9 LDG 4107		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30489 E2	INSPECTION/REPLACEMENT OF TURBINE EXHAUST CASE OIL PRESSURE TUBE BRACKET CONFIGURATION UNK CATEGORY 6				MTH 12-Jul-2017 HRS 4930.9 LDG 4107		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30491 R1 E1	REPLACEMENT/MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY CATEGORY 7						-			
MOC :										
SB PW500-72-30491 R1 E2	REPLACEMENT/MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY CATEGORY 7						-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30491 R2 E1	REPLACEMENT / MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY			CATEGORY 7			-			
	MOC :									
SB PW500-72-30491 R2 E2	REPLACEMENT / MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY			CATEGORY 7			-			
	MOC :									
SB PW500-72-30491 E1	REPLACEMENT/MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY			CATEGORY 7			-			
	MOC :									
SB PW500-72-30491 E2	REPLACEMENT/MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY			CATEGORY 7			-			
	MOC :									
SB PW500-72-30492 R01 E1	REPLACEMENT / MODIFICATION OF COMBUSTION CHAMBER LINER (SUPERSEDED BY PW500-72-30492 R02)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30492 R01 E2	REPLACEMENT / MODIFICATION OF COMBUSTION CHAMBER LINER (SUPERSEDED BY PW500-72-30492 R02)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30492 R02 E1	REPLACEMENT / MODIFICATION OF COMBUSTION CHAMBER LINER (SUPERSEDED BY PW500-72-30492 R03)			CATEGORY 6			-			
	MOC :									
SB PW500-72-30492 R02 E2	REPLACEMENT / MODIFICATION OF COMBUSTION CHAMBER LINER (SUPERSEDED BY PW500-72-30492 R03)			CATEGORY 6			-			
	MOC :									
SB PW500-72-30492 R03 E1	REPLACEMENT / MODIFICATION OF COMBUSTION CHAMBER LINER (SUPERSEDED BY PW500-72-30492 R04)			CATEGORY 6			-			
	MOC :									
SB PW500-72-30492 R03 E2	REPLACEMENT / MODIFICATION OF COMBUSTION CHAMBER LINER (SUPERSEDED BY PW500-72-30492 R04)			CATEGORY 6			-			
	MOC :									
SB PW500-72-30492 R04 E1	REPLACEMENT / MODIFICATION OF COMBUSTION CHAMBER LINER			CATEGORY 6			-			
	MOC :									
SB PW500-72-30492 R04 E2	REPLACEMENT / MODIFICATION OF COMBUSTION CHAMBER LINER			CATEGORY 6			-			
	MOC :									
SB PW500-72-30492 E1	REPLACEMENT / MODIFICATION OF COMBUSTION CHAMBER LINER (SUPERSEDED BY PW500-72-30492 R01)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30492 E2	REPLACEMENT / MODIFICATION OF COMBUSTION CHAMBER LINER (SUPERSEDED BY PW500-72-30492 R01)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30493 E1	REPLACEMENT OF TEMPERATURE SENSORS			CATEGORY 7			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30493 E2	REPLACEMENT OF TEMPERATURE SENSORS			CATEGORY 7			-			
MOC :										
SB PW500-72-30495 R01 E1	MODIFICATION OF ACCESSORY GEARBOX COVER BOLT TORQUING PROCEDURE (SUPERSEDED BY PW500-72-30498)			CATEGORY 10			-			
MOC :										
SB PW500-72-30495 R01 E2	MODIFICATION OF ACCESSORY GEARBOX COVER BOLT TORQUING PROCEDURE (SUPERSEDED BY PW500-72-30498)			CATEGORY 10			-			
MOC :										
SB PW500-72-30495 E1	MODIFICATION OF ACCESSORY GEARBOX COVER BOLT TORQUING PROCEDURE (SUPERSEDED BY SB PW500-72-30495 R01)			CATEGORY 10			-			
MOC :										
SB PW500-72-30495 E2	MODIFICATION OF ACCESSORY GEARBOX COVER BOLT TORQUING PROCEDURE (SUPERSEDED BY SB PW500-72-30495 R01)			CATEGORY 10			-			
MOC :										
SB PW500-72-30498 R01 E1	REPLACEMENT / MODIFICATION OF INTERMEDIATE CASE ASSEMBLY (SUPERSEDED BY PW500-72-30498 R02)			CATEGORY 7			-			
MOC :										
SB PW500-72-30498 R01 E2	REPLACEMENT / MODIFICATION OF INTERMEDIATE CASE ASSEMBLY (SUPERSEDED BY PW500-72-30498 R02)			CATEGORY 7			-			
MOC :										
SB PW500-72-30498 R02 E1	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY (SUPERSEDED BY PW500-72-30498 R03)			CATEGORY 7			-			
MOC :										
SB PW500-72-30498 R02 E2	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY (SUPERSEDED BY PW500-72-30498 R03)			CATEGORY 7			-			
MOC :										
SB PW500-72-30498 R03 E1	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY			CATEGORY 7			-			
MOC :										
SB PW500-72-30498 R03 E2	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY			CATEGORY 7			-			
MOC :										
SB PW500-72-30498 E1	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY (SUPERSEDED BY PW500-72-30498 R01)			CATEGORY 7			-			
MOC :										
SB PW500-72-30498 E2	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY (SUPERSEDED BY PW500-72-30498 R01)			CATEGORY 7			-			
MOC :										
SB PW500-72-30500 E1	REPLACEMENT OF PREFORMED PACKING	UNK		CATEGORY 7	MTH 14-Jul-2017 HRS 4930.9 LDG 4107		-			Complete
MOC : COMPLIED WITH										



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30500 E2	REPLACEMENT OF PREFORMED PACKING	UNK		CATEGORY 7	MTH 12-Jul-2017 HRS 4930.9 LDG 4107		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30501 E1	REPLACEMENT OF SHIPPING CAPS FOR SHIPPING CONTAINERS	UNK		CATEGORY 3	MTH 14-Jul-2017 HRS 4930.9 LDG 4107		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30501 E2	REPLACEMENT OF SHIPPING CAPS FOR SHIPPING CONTAINERS	UNK		CATEGORY 3	MTH 12-Jul-2017 HRS 4930.9 LDG 4107		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30502 R01 E1	REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL (SUPERSEDED BY PW500-72-30502 R02)			CATEGORY 7			-			
MOC :										
SB PW500-72-30502 R01 E2	REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL (SUPERSEDED BY PW500-72-30502 R02)			CATEGORY 7			-			
MOC :										
SB PW500-72-30502 R02 PART (A) E1	ACCOMPLISH REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL (SUPERSEDED BY PW500-72-30502 R03) FUEL CONTROL GEARSHAFT SEAL			CATEGORY 7			-			
MOC :										
SB PW500-72-30502 R02 PART (A) E2	ACCOMPLISH REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL (SUPERSEDED BY PW500-72-30502 R03) FUEL CONTROL GEARSHAFT SEAL			CATEGORY 7			-			
MOC :										
SB PW500-72-30502 R02 PART (B) E1	ACCOMPLISH REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL (SUPERSEDED BY PW500-72-30502 R03) ACCESSORY GEARSHAFT SEAL			CATEGORY 7			-			
MOC :										
SB PW500-72-30502 R02 PART (B) E2	ACCOMPLISH REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL (SUPERSEDED BY PW500-72-30502 R03) ACCESSORY GEARSHAFT SEAL			CATEGORY 7			-			
MOC :										
SB PW500-72-30502 R02 E1	REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL (SUPERSEDED BY PW500-72-30502 R03)			CATEGORY 7			-			
MOC :										
SB PW500-72-30502 R02 E2	REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL (SUPERSEDED BY PW500-72-30502 R03)			CATEGORY 7			-			
MOC :										
SB PW500-72-30502 R03 PART (A) E1	ACCOMPLISH REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL (SUPERSEDED BY PW500-72-30502 R04) REPLACE FUEL CONTROL GEARSHAFT SEAL			CATEGORY 7			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Service Bulletins

Item Code Position	Description Drawing # / Task # City	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30502 R03 PART (A) E2	ACCOMPLISH REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL (SUPERSEDED BY PW500-72-30502 R04) REPLACE FUEL CONTROL GEARSHAFT SEAL	CATEGORY 7			-			
	MOC :							
SB PW500-72-30502 R03 PART (B) E1	ACCOMPLISH REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL (SUPERSEDED BY PW500-72-30502 R04) REPLACE ACCESSORY GEARSHAFT SEAL	CATEGORY 7			-			
	MOC :							
SB PW500-72-30502 R03 PART (B) E2	ACCOMPLISH REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL (SUPERSEDED BY PW500-72-30502 R04) REPLACE ACCESSORY GEARSHAFT SEAL	CATEGORY 7			-			
	MOC :							
SB PW500-72-30502 R03 E1	REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL (SUPERSEDED BY PW500-72-30502 R04)	CATEGORY 7			-			
	MOC :							
SB PW500-72-30502 R03 E2	REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL (SUPERSEDED BY PW500-72-30502 R04)	CATEGORY 7			-			
	MOC :							
SB PW500-72-30502 R04 PART (A) E1	ACCOMPLISH REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL FUEL CONTROL GEARSHAFT SEAL	CATEGORY 7			-			
	MOC :							
SB PW500-72-30502 R04 PART (A) E2	ACCOMPLISH REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL FUEL CONTROL GEARSHAFT SEAL	CATEGORY 7			-			
	MOC :							
SB PW500-72-30502 R04 PART (B) E1	ACCOMPLISH REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL ACCESSORY GEARSHAFT SEAL	CATEGORY 7			-			
	MOC :							
SB PW500-72-30502 R04 PART (B) E2	ACCOMPLISH REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL ACCESSORY GEARSHAFT SEAL	CATEGORY 7			-			
	MOC :							
SB PW500-72-30502 R04 E1	REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL	CATEGORY 7			-			
	MOC :							
SB PW500-72-30502 R04 E2	REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL	CATEGORY 7			-			
	MOC :							
SB PW500-72-30502 E1	REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL (SUPERSEDED BY PW500-72-30502 R01)	CATEGORY 7			-			
	MOC :							
SB PW500-72-30502 E2	REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL (SUPERSEDED BY PW500-72-30502 R01)	CATEGORY 7			-			
	MOC :							



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30504 R01 E1	REPLACEMENT OF FUEL/OIL HEAT EXCHANGER (SUPERSEDED BY PW500-72-30504 R02)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30504 R01 E2	REPLACEMENT OF FUEL/OIL HEAT EXCHANGER (SUPERSEDED BY PW500-72-30504 R02)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30504 R02 E1	REPLACEMENT OF FUEL/OIL HEAT EXCHANGER			CATEGORY 7			-			
	MOC :									
SB PW500-72-30504 R02 E2	REPLACEMENT OF FUEL/OIL HEAT EXCHANGER	UNK		CATEGORY 7	MTH 12-Jul-2017 HRS 4930.9 LDG 4107		-			Complete
	MOC :	COMPLIED WITH								
SB PW500-72-30504 R03 E1	REPLACEMENT OF FUEL/OIL HEAT EXCHANGER			CATEGORY 7			-			
	MOC :									
SB PW500-72-30504 R03 E2	REPLACEMENT OF FUEL/OIL HEAT EXCHANGER			CATEGORY 7			-			
	MOC :									
SB PW500-72-30504 E1	REPLACEMENT OF FUEL/OIL HEAT EXCHANGER (SUPERSEDED BY PW500-72-30504 R01)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30504 E2	REPLACEMENT OF FUEL/OIL HEAT EXCHANGER (SUPERSEDED BY PW500-72-30504 R01)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30505 R01 E1	REPLACEMENT OF BLEED OFF VALVE (BOV) GASKETS (SUPERSEDED BY PW500-72-30505 R02)	BOI		CATEGORY 3	MTH 22-Jan-2015 HRS 4198.9 LDG 3514		-			Complete
	MOC :	COMPLIED WITH - COMPLIED WITH PRATT & WHITNEY SERVICE BULLETIN NO. 30505R1 BY REPLACING AFFECTED GASKETS AND NUTS REFERENCING THE INSTRUCTIONS IN THE BULLETIN . GROUND RUN UP AND OPERATIONAL AND LEAKEDCHECKED GOOD.								
SB PW500-72-30505 R01 E2	REPLACEMENT OF BLEED OFF VALVE (BOV) GASKETS (SUPERSEDED BY PW500-72-30505 R02)	BOI		CATEGORY 3	MTH 22-Jan-2015 HRS 4198.9 LDG 3514		-			Complete
	MOC :	COMPLIED WITH - COMPLIED WITH PRATT & WHITNEY SERVICE BULLETIN NO. 30505R1 BY REPLACING THE AFFECTED GASKETS AND NUTS REFERENCING THE INSTRUCTIONS IN THE BULLETIN . GROUND RUN UP AND CHECKED FOR LEAKSAND PROPER OPERATION.								
SB PW500-72-30505 R02 E1	REPLACEMENT OF BLEED OFF VALVE (BOV) GASKETS	UNK		CATEGORY 3	MTH 14-Jul-2017 HRS 4930.9 LDG 4107		-			Complete
	MOC :	COMPLIED WITH								
SB PW500-72-30505 R02 E2	REPLACEMENT OF BLEED OFF VALVE (BOV) GASKETS	UNK		CATEGORY 3	MTH 12-Jul-2017 HRS 4930.9 LDG 4107		-			Complete
	MOC :	COMPLIED WITH								



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30505 R03 E1	REPLACEMENT OF BLEED OFF VALVE (BOV) GASKETS			CATEGORY 3			-			
	MOC :									
SB PW500-72-30505 R03 E2	REPLACEMENT OF BLEED OFF VALVE (BOV) GASKETS			CATEGORY 3			-			
	MOC :									
SB PW500-72-30505 R04 E1	REPLACEMENT OF BLEED OFF VALVE (BOV) GASKETS			CATEGORY 3			-			
	MOC :									
SB PW500-72-30505 R04 E2	REPLACEMENT OF BLEED OFF VALVE (BOV) GASKETS			CATEGORY 3			-			
	MOC :									
SB PW500-72-30505 E1	REPLACEMENT OF BLEED OFF VALVE (BOV) GASKETS (SUPERSEDED BY PW500-72-30505 R01)			CATEGORY 3			-			
	MOC :									
SB PW500-72-30505 E2	REPLACEMENT OF BLEED OFF VALVE (BOV) GASKETS (SUPERSEDED BY PW500-72-30505 R01)			CATEGORY 3			-			
	MOC :									
SB PW500-72-30506 R01 E1	REPLACEMENT OF FUEL MANIFOLD ADAPTERS (SUPERSEDED BY PW500-72-30506 R02)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30506 R01 E2	REPLACEMENT OF FUEL MANIFOLD ADAPTERS (SUPERSEDED BY PW500-72-30506 R02)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30506 R02 E1	REPLACEMENT OF FUEL MANIFOLD ADAPTERS	UNK		CATEGORY 7	MTH 14-Jul-2017 HRS 4930.9 LDG 4107		-			Complete
	MOC :									
SB PW500-72-30506 R02 E2	REPLACEMENT OF FUEL MANIFOLD ADAPTERS			CATEGORY 7			-			
	MOC :									
SB PW500-72-30506 E1	REPLACEMENT OF FUEL MANIFOLD ADAPTERS (SUPERSEDED BY PW500-72-30506 R01)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30506 E2	REPLACEMENT OF FUEL MANIFOLD ADAPTERS (SUPERSEDED BY PW500-72-30506 R01)	UNK		CATEGORY 7	MTH 12-Jul-2017 HRS 4930.9 LDG 4107		-			Complete
	MOC :									
SB PW500-72-30511 R01 E1	RE-TORQUEING OF AGB COVER BOLTS OR NUTS	UNK		CATEGORY 6	MTH 14-Jul-2017 HRS 4930.9 LDG 4107		-			Complete
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30511 R01 E2	RE-TORQUEING OF AGB COVER BOLTS OR NUTS	UNK		CATEGORY 6	MTH 12-Jul-2017 HRS 4930.9 LDG 4107		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30511 R02 E1	RE-TORQUEING OF AGB COVER BOLTS OR NUTS			CATEGORY 6			-			
MOC :										
SB PW500-72-30511 R02 E2	RE-TORQUEING OF AGB COVER BOLTS OR NUTS			CATEGORY 6			-			
MOC :										
SB PW500-72-30511 E1	RE-TORQUEING OF AGB COVER BOLTS OR NUTS (SUPERSEDED BY PW500-72-30511 R01)			CATEGORY 6			-			
MOC :										
SB PW500-72-30511 E2	RE-TORQUEING OF AGB COVER BOLTS OR NUTS (SUPERSEDED BY PW500-72-30511 R01)			CATEGORY 6			-			
MOC :										
SB PW500-72-30512 R01 E1	INSPECTION/REPLACEMENT OF HYDROMECHANICAL FUEL CONTROL (SUPERSEDED BY PW500-72-30512 R02)			CATEGORY 3			-			
MOC :										
SB PW500-72-30512 R01 E2	INSPECTION/REPLACEMENT OF HYDROMECHANICAL FUEL CONTROL (SUPERSEDED BY PW500-72-30512 R02)			CATEGORY 3			-			
MOC :										
SB PW500-72-30512 R02 E1	INSPECTION/ REPLACEMENT OF HYDROMECHANICAL FUEL CONTROL (SUPERSEDED BY PW500-72-30512 R03)	BOI		CATEGORY 3	MTH 26-May-2015 HRS 4298.4 LDG 3593		-			N/A
MOC : NOT APPLICABLE - THIS SERVICE BULLETIN IS N/A TO THIS FUEL CONTROL.										
SB PW500-72-30512 R02 E2	INSPECTION/ REPLACEMENT OF HYDROMECHANICAL FUEL CONTROL (SUPERSEDED BY PW500-72-30512 R03)	BOI		CATEGORY 3	MTH 26-May-2015 HRS 4298.4 LDG 3593		-			N/A
MOC : NOT APPLICABLE - THIS SERVICE BULLETIN IS N/A TO THIS FUEL CONTROL.										
SB PW500-72-30512 R03 E1	INSPECTION/REPLACEMENT OF HYDROMECHANICAL FUEL CONTROL (SUPERSEDED BY PW500-72-30512 R04)			CATEGORY 3	MTH		-			
MOC :										
SB PW500-72-30512 R03 E2	INSPECTION/REPLACEMENT OF HYDROMECHANICAL FUEL CONTROL (SUPERSEDED BY PW500-72-30512 R04)			CATEGORY 3	MTH		-			
MOC :										
SB PW500-72-30512 E1	INSPECTION/REPLACEMENT OF HYDROMECHANICAL FUEL CONTROL (SUPERSEDED BY PW500-72-30512 R01)			CATEGORY 3	MTH		-			
MOC :										
SB PW500-72-30512 E2	INSPECTION/REPLACEMENT OF HYDROMECHANICAL FUEL CONTROL (SUPERSEDED BY PW500-72-30512 R01)			CATEGORY 3	MTH		-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30513 R01 E1	REPLACEMENT / MODIFICATION OF OIL LEVEL INDICATOR			CATEGORY 7			-			
	MOC :									
SB PW500-72-30513 R01 E2	REPLACEMENT / MODIFICATION OF OIL LEVEL INDICATOR			CATEGORY 7			-			
	MOC :									
SB PW500-72-30513 E1	REPLACEMENT OF OIL LEVEL INDICATOR (SUPERSEDED BY PW500-72-30513 R01)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30513 E2	REPLACEMENT OF OIL LEVEL INDICATOR (SUPERSEDED BY PW500-72-30513 R01)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30514 R01 E1	REPLACEMENT / MODIFICATION OF INTERMEDIATE CASE ASSEMBLY	UNK		CATEGORY 7	MTH 14-Jul-2017 HRS 4930.9 LDG 4107		-			Complete
	MOC : COMPLIED WITH									
SB PW500-72-30514 R01 E2	REPLACEMENT / MODIFICATION OF INTERMEDIATE CASE ASSEMBLY	UNK		CATEGORY 7	MTH 12-Jul-2017 HRS 4930.9 LDG 4107		-			Complete
	MOC : COMPLIED WITH									
SB PW500-72-30514 R02 E1	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY			CATEGORY 7			-			
	MOC :									
SB PW500-72-30514 R02 E2	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY			CATEGORY 7			-			
	MOC :									
SB PW500-72-30514 E1	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY (SUPERSEDED BY PW500-72-30514 R01)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30514 E2	REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY (SUPERSEDED BY PW500-72-30514 R01)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30515 R01 E1	REPLACEMENT OF TURBINE SUPPORT CASE			CATEGORY 7			-			
	MOC :									
SB PW500-72-30515 R01 E2	REPLACEMENT OF TURBINE SUPPORT CASE			CATEGORY 7			-			
	MOC :									
SB PW500-72-30515 R02 E1	REPLACEMENT OF TURBINE SUPPORT CASE			CATEGORY 7			-			
	MOC :									
SB PW500-72-30515 R02 E2	REPLACEMENT OF TURBINE SUPPORT CASE			CATEGORY 7			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30515 E1	REPLACEMENT OF TURBINE SUPPORT CASE (SUPERSEDED BY PW500-72-30515 R01)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30515 E2	REPLACEMENT OF TURBINE SUPPORT CASE (SUPERSEDED BY PW500-72-30515 R01)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30516 R01 E1	REPLACEMENT OF HP TURBINE SEAL RINGS (SUPERSEDED BY PW500-72-30516 R02)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30516 R01 E2	REPLACEMENT OF HP TURBINE SEAL RINGS (SUPERSEDED BY PW500-72-30516 R02)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30516 R02 E1	REPLACEMENT OF HP TURBINE SEAL RINGS	UNK		CATEGORY 7	MTH 14-Jul-2017 HRS 4930.9 LDG 4107		-			Complete
	MOC :									
SB PW500-72-30516 R02 E2	REPLACEMENT OF HP TURBINE SEAL RINGS	UNK		CATEGORY 7	MTH 12-Jul-2017 HRS 4930.9 LDG 4107		-			Complete
	MOC :									
SB PW500-72-30516 E1	REPLACEMENT OF HP TURBINE SEAL RINGS (SUPERSEDED BY PW500-72-30516 R01)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30516 E2	REPLACEMENT OF HP TURBINE SEAL RINGS (SUPERSEDED BY PW500-72-30516 R01)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30517 R01 E1	DELETION OF IGNITER FLANGE GASKETS	UNK		CATEGORY 6	MTH 14-Jul-2017 HRS 4930.9 LDG 4107		-			Complete
	MOC :									
SB PW500-72-30517 R01 E2	DELETION OF IGNITER FLANGE GASKETS	UNK		CATEGORY 6	MTH 12-Jul-2017 HRS 4930.9 LDG 4107		-			Complete
	MOC :									
SB PW500-72-30517 E1	DELETION OF IGNITER FLANGE GASKETS (SUPERSEDED BY PW500-72-30517 R01)			CATEGORY 6			-			
	MOC :									
SB PW500-72-30517 E2	DELETION OF IGNITER FLANGE GASKETS (SUPERSEDED BY PW500-72-30517 R01)			CATEGORY 6			-			
	MOC :									
SB PW500-72-30519 R01 E1	INSPECTION OF IGNITION LEAD			CATEGORY 3			-			
	MOC :									
SB PW500-72-30519 R01 E2	INSPECTION OF IGNITION LEAD			CATEGORY 3			-			
	MOC :									

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30519 E1	INSPECTION OF IGNITION LEAD (SUPERSEDED BY PW500-72-30519 R01)	BOI		CATEGORY 3	MTH 23-Apr-2015 HRS 4268.3 LDG 3572		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH SB PW500-72-30519 BY INSPECTION OF IGNITER LEAD, BOTH IGNITER LEADS ARE COMPLIANT WITH PRATT AND WHITNEY REQUIREMENTS.7864										
SB PW500-72-30519 E2	INSPECTION OF IGNITION LEAD (SUPERSEDED BY PW500-72-30519 R01)	BOI		CATEGORY 3	MTH 23-Apr-2015 HRS 4268.3 LDG 3572		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH SB PW500-72-30519 BY INSPECTION OF IGNITER LEAD, BOTH IGNITER LEADS ARE COMPLIANT WITH PRATT AND WHITNEY REQUIREMENTS.										
SB PW500-72-30521 R01 E1	REPLACEMENT OF COMBUSTION CHAMBER LINER			CATEGORY 7			-			
MOC :										
SB PW500-72-30521 R01 E2	REPLACEMENT OF COMBUSTION CHAMBER LINER			CATEGORY 7			-			
MOC :										
SB PW500-72-30521 R02 E1	REPLACEMENT OF COMBUSTION CHAMBER LINER			CATEGORY 7	MTH		-			
MOC :										
SB PW500-72-30521 R02 E2	REPLACEMENT OF COMBUSTION CHAMBER LINER			CATEGORY 7	MTH		-			
MOC :										
SB PW500-72-30521 E1	REPLACEMENT OF COMBUSTION CHAMBER LINER (SUPERSEDED BY PW500-72-30521 R01)			CATEGORY 7			-			
MOC :										
SB PW500-72-30521 E2	REPLACEMENT OF COMBUSTION CHAMBER LINER (SUPERSEDED BY PW500-72-30521 R01)			CATEGORY 7			-			
MOC :										
SB PW500-72-30522 R01 E1	REPLACEMENT OF IGNITER CABLES (SUPERSEDED BY PW500-72-30522 R02)			CATEGORY 7			-			
MOC :										
SB PW500-72-30522 R01 E2	REPLACEMENT OF IGNITER CABLES (SUPERSEDED BY PW500-72-30522 R02)			CATEGORY 7			-			
MOC :										
SB PW500-72-30522 R02 E1	REPLACEMENT OF IGNITER CABLES (SUPERSEDED BY SB PW500-72-30529 R01)			CATEGORY 10			-			
MOC :										
SB PW500-72-30522 R02 E2	REPLACEMENT OF IGNITER CABLES (SUPERSEDED BY SB PW500-72-30529 R01)			CATEGORY 10			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30522 E1	REPLACEMENT OF IGNITER CABLES (SUPERSEDED BY PW500-72-30522 R01)	KBOI		CATEGORY 3	MTH 16-Oct-2015 HRS 4426.7 LDG 3696		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH PRATT & WHITNEY SERVICE BULLETIN PW500-72-30522 BY REPLACING IGNITOR LEADS WITH IMPROVED ITEMS REFERENCING THE PRATT & WHITNEY PW535 A MAINT. MANUAL. OPERATIONALCHECKS GOOD.										
SB PW500-72-30522 E2	REPLACEMENT OF IGNITER CABLES (SUPERSEDED BY PW500-72-30522 R01)	KBOI		CATEGORY 3	MTH 16-Oct-2015 HRS 4426.7 LDG 3696		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH PRATT & WHITNEY SERVICE BULLETIN PW500-72-30522 BY REPLACING IGNITOR LEADS WITH IMPROVED ITEMS REFERENCING THE PRATT & WHITNEY PW535 A MAINT. MANUAL. OPERATIONALCHECKS GOOD.										
SB PW500-72-30523 R01 E1	REPLACEMENT OF ACCESSORY GEARBOX COVER GASKET			CATEGORY 7			-			
MOC :										
SB PW500-72-30523 R01 E2	REPLACEMENT OF ACCESSORY GEARBOX COVER GASKET	UNK		CATEGORY 7	MTH 12-Jul-2017 HRS 4930.9 LDG 4107		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30523 E1	REPLACEMENT OF ACCESSORY GEARBOX COVER GASKET (SUPERSEDED BY PW500-72-30523 R01)	UNK		CATEGORY 7	MTH 14-Jul-2017 HRS 4930.9 LDG 4107		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30523 E2	REPLACEMENT OF ACCESSORY GEARBOX COVER GASKET (SUPERSEDED BY PW500-72-30523 R01)			CATEGORY 7			-			
MOC :										
SB PW500-72-30527 E1	REPLACEMENT OF NO. 4 ROLLER BEARING			CATEGORY 9			-			
MOC :										
SB PW500-72-30527 E2	REPLACEMENT OF NO. 4 ROLLER BEARING			CATEGORY 9			-			
MOC :										
SB PW500-72-30529 R01 E1	REPLACEMENT OF IGNITER CABLES (SUPERSEDED BY PW500-72-30529 R02)	BOI		CATEGORY 3	MTH 25-Jan-2017 HRS 4845.9 LDG 4043		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH PRATT & WHITNEY SERVICE BULLETIN PW500-72-30529R1 BY REPLACING IGNITOR LEADS WITH IMPROVED LEADS REFERENCING THE PRATT & WHITNEY PW535A MAINT. MANUAL. OPERATIONAL CHECKS GOOD. P/N OFF: 3123755-01. S/N OFF: NNA15300039. P/N ON: 3127408-01. S/N ON: NNA16280086. P/N OFF: 3123755-02. S/N OFF: NNA15350050. P/N ON: 3127408-02. S/N ON: NNA16140248.										
SB PW500-72-30529 R01 E2	REPLACEMENT OF IGNITER CABLES (SUPERSEDED BY PW500-72-30529 R02)	BOI		CATEGORY 3	MTH 25-Jan-2017 HRS 4845.9 LDG 4043		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH PRATT & WHITNEY SERVICE BULLETIN PW500-72-30529R1 BY REPLACING IGNITOR LEADS WITH IMPROVED LEADS REFERENCING THE PRATT & WHITNEY PW535A MAINT. MANUAL. OPERATIONAL CHECKS GOOD. P/N OFF: 3123755-01. S/N OFF: NNA15300024. P/N ON: 3127408-01. S/N ON: NNA16280059. P/N OFF: 3123755-02. S/N OFF: NNA15340023. P/N ON: NNA3127408-02. S/N ON: NNA16100275.										



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30529 R02 E1	REPLACEMENT OF IGNITER CABLES			CATEGORY 3	MTH		-			
	MOC :									
SB PW500-72-30529 R02 E2	REPLACEMENT OF IGNITER CABLES			CATEGORY 3	MTH		-			
	MOC :									
SB PW500-72-30529 E1	REPLACEMENT OF IGNITER CABLES (SUPERSEDED BY PW500-72-30529 R01)			CATEGORY 3	MTH		-			
	MOC :									
SB PW500-72-30529 E2	REPLACEMENT OF IGNITER CABLES (SUPERSEDED BY PW500-72-30529 R01)			CATEGORY 3	MTH		-			
	MOC :									
SB PW500-72-30532 E1	REPLACEMENT OF RETAINING RINGS			CATEGORY 9			-			
	MOC :									
SB PW500-72-30532 E2	REPLACEMENT OF RETAINING RINGS			CATEGORY 9			-			
	MOC :									
SB PW500-72-30533 R01 E1	REPLACEMENT OF P3 AIR SEPARATOR TUBE CLAMP			CATEGORY 6			-			
	MOC :									
SB PW500-72-30533 R01 E2	REPLACEMENT OF P3 AIR SEPARATOR TUBE CLAMP			CATEGORY 6			-			
	MOC :									
SB PW500-72-30533 E1	REPLACEMENT OF P3 AIR SEPARATOR TUBE CLAMP			CATEGORY 6			-			
	MOC :									
SB PW500-72-30533 E2	REPLACEMENT OF P3 AIR SEPARATOR TUBE CLAMP			CATEGORY 6			-			
	MOC :									
SB PW500-72-30535 R01 E1	REPLACEMENT OF ENGINE SHIPPING CONTAINER			CATEGORY 7			-			
	MOC :									
SB PW500-72-30535 R01 E2	REPLACEMENT OF ENGINE SHIPPING CONTAINER			CATEGORY 7			-			
	MOC :									
SB PW500-72-30535 R02 E1	REPLACEMENT OF ENGINE SHIPPING CONTAINER			CATEGORY 7			-			
	MOC :									
SB PW500-72-30535 R02 E2	REPLACEMENT OF ENGINE SHIPPING CONTAINER			CATEGORY 7			-			
	MOC :									
SB PW500-72-30535 E1	REPLACEMENT OF ENGINE SHIPPING CONTAINER (SUPERSEDED BY PW500-72-30535 R01)			CATEGORY 7			-			
	MOC :									

NOTE: Item Codes in *italics* show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30535 E2	REPLACEMENT OF ENGINE SHIPPING CONTAINER (SUPERSEDED BY PW500-72-30535 R01)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30541 PART A E1	ACCOMPLISH FUEL CONTROL GEARSHAFT SEAL			CATEGORY 7			-			
	MOC :									
SB PW500-72-30541 PART A E2	ACCOMPLISH FUEL CONTROL GEARSHAFT SEAL			CATEGORY 7			-			
	MOC :									
SB PW500-72-30541 PART B E1	ACCOMPLISH ACCESSORY GEARSHAFT SEAL			CATEGORY 7			-			
	MOC :									
SB PW500-72-30541 PART B E2	ACCOMPLISH ACCESSORY GEARSHAFT SEAL			CATEGORY 7			-			
	MOC :									
SB PW500-72-30541 R01 PART A E1	ACCOMPLISH FUEL CONTROL GEARSHAFT SEAL			CATEGORY 7			-			
	MOC :									
SB PW500-72-30541 R01 PART A E2	ACCOMPLISH FUEL CONTROL GEARSHAFT SEAL			CATEGORY 7			-			
	MOC :									
SB PW500-72-30541 R01 PART B E1	ACCOMPLISH ACCESSORY GEARSHAFT SEAL			CATEGORY 7			-			
	MOC :									
SB PW500-72-30541 R01 PART B E2	ACCOMPLISH ACCESSORY GEARSHAFT SEAL			CATEGORY 7			-			
	MOC :									
SB PW500-72-30541 R01 E1	REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL			CATEGORY 7			-			
	MOC :									
SB PW500-72-30541 R01 E2	REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL			CATEGORY 7			-			
	MOC :									
SB PW500-72-30541 E1	REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL			CATEGORY 7			-			
	MOC :									
SB PW500-72-30541 E2	REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL			CATEGORY 7			-			
	MOC :									
SB PW500-72-30543 R01 E1	REPLACEMENT OF T1 THERMOCOUPLE HARNESS			CATEGORY 7			-			
	MOC :									
SB PW500-72-30543 R01 E2	REPLACEMENT OF T1 THERMOCOUPLE HARNESS			CATEGORY 7			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30543 E1	REPLACEMENT OF T1 THERMOCOUPLE HARNESS			CATEGORY 7			-			
	MOC :									
SB PW500-72-30543 E2	REPLACEMENT OF T1 THERMOCOUPLE HARNESS			CATEGORY 7			-			
	MOC :									
SB PW500-72-30545 R04 E1	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT	KBOI		CATEGORY 6	MTH 12-Aug-2021 HRS 6024.5 LDG 4981		-			Complete
	MOC :									
	COMPLIED WITH - COMPLIED WITH PW500-72-30545R4 BY REPLACEMENT OF LEFT FUEL CONTROL IN REFERENCE TO APPLICABLE SB, P&WC PW535A AND TEXTRON 560 MAINTENANCE MANUALS.									
SB PW500-72-30545 R04 E2	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT	KBOI		CATEGORY 6	MTH 12-Aug-2021 HRS 6024.5 LDG 4981		-			Complete
	MOC :									
	COMPLIED WITH - COMPLIED WITH PW500-72-30545R4 BY REPLACEMENT OF RIGHT FUEL CONTROL IN REFERENCE TO APPLICABLE SB, P&WC PW535A AND TEXTRON 560 MAINTENANCE MANUALS.									
SB PW500-72-30545 R05 E1	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT			CATEGORY 3	MTH		-			
	MOC :									
SB PW500-72-30545 R05 E2	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT			CATEGORY 3	MTH		-			
	MOC :									
SB PW500-72-30548 R01 E1	REPLACEMENT/MODIFICATION OF ANTI-ICING VALVE (SUPERSEDED BY PW500-72-30548 R02)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30548 R01 E2	REPLACEMENT/MODIFICATION OF ANTI-ICING VALVE (SUPERSEDED BY PW500-72-30548 R02)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30548 R02 E1	REPLACEMENT/MODIFICATION OF ANTI-ICING VALVE			CATEGORY 7			-			
	MOC :									
SB PW500-72-30548 R02 E2	REPLACEMENT/MODIFICATION OF ANTI-ICING VALVE			CATEGORY 7			-			
	MOC :									
SB PW500-72-30548 E1	REPLACEMENT/MODIFICATION OF ANTI-ICING VALVE (SUPERSEDED BY PW500-72-30548 R01)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30548 E2	REPLACEMENT/MODIFICATION OF ANTI-ICING VALVE (SUPERSEDED BY PW500-72-30548 R01)			CATEGORY 7			-			
	MOC :									
SB PW500-72-30553 E1	REPLACEMENT OF IC NUMBER INTERMEDIATE CASE			CATEGORY 9			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30553 E2	REPLACEMENT OF IC NUMBER INTERMEDIATE CASE			CATEGORY 9			-			
	MOC :									
SB PW500-72-30554 R01 E1	REPLACEMENT OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE			CATEGORY 7			-			
	MOC :									
SB PW500-72-30554 R01 E2	REPLACEMENT OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE			CATEGORY 7			-			
	MOC :									
SB PW500-72-30554 R02 E1	REPLACEMENT OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE			CATEGORY 7			-			
	MOC :									
SB PW500-72-30554 R02 E2	REPLACEMENT OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE			CATEGORY 7			-			
	MOC :									
SB PW500-72-30565 R01 E1	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT			CATEGORY 6			-			
	MOC :									
SB PW500-72-30565 R01 E2	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT			CATEGORY 6			-			
	MOC :									
SB PW500-72-30565 E1	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT			CATEGORY 7			-			
	MOC :									
SB PW500-72-30565 E2	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT			CATEGORY 7			-			
	MOC :									
SB PW500-72-30568 R01 E1	REPLACEMENT OF NO. 4 BEARING FRONT AND REAR SEAL RUNNERS			CATEGORY 7			-			
	MOC :									
SB PW500-72-30568 R01 E2	REPLACEMENT OF NO. 4 BEARING FRONT AND REAR SEAL RUNNERS			CATEGORY 7			-			
	MOC :									
SB PW500-72-30568 E1	REPLACEMENT OF NO. 4 BEARING FRONT AND REAR SEAL RUNNERS			CATEGORY 7			-			
	MOC :									
SB PW500-72-30568 E2	REPLACEMENT OF NO. 4 BEARING FRONT AND REAR SEAL RUNNERS			CATEGORY 7			-			
	MOC :									
SB PW500-72-30575 R02 E1	CONVERSION OF PW535A (BS909) TO PW535E1 (BS1439)			CATEGORY 8			-			
	MOC :									
SB PW500-72-30575 R02 E2	CONVERSION OF PW535A (BS909) TO PW535E1 (BS1439)			CATEGORY 8			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB PW500-72-30578 R01 E1	INSPECTION OF HIGH-PRESSURE-COMPRESSOR SECOND-STAGE ROTOR			CATEGORY 10			-			
	MOC :									
SB PW500-72-30578 R01 E2	INSPECTION OF HIGH-PRESSURE-COMPRESSOR SECOND-STAGE ROTOR			CATEGORY 10			-			
	MOC :									
SB PW500-72-30578 E1	INSPECTION OF HIGH-PRESSURE COMPRESSOR SECOND-STAGE ROTOR			CATEGORY 3 MTH			-			
	MOC :									
SB PW500-72-30578 E2	INSPECTION OF HIGH-PRESSURE COMPRESSOR SECOND-STAGE ROTOR			CATEGORY 3 MTH			-			
	MOC :									
SB PW500-72-30581 E1	INSPECTION/REPLACEMENT OF FIRST AND SECOND-STAGE LOW-PRESSURE-TURBINE BLADES			CATEGORY 6			-			
	MOC :									
SB PW500-72-30581 E2	INSPECTION/REPLACEMENT OF FIRST AND SECOND-STAGE LOW-PRESSURE-TURBINE BLADES			CATEGORY 6			-			
	MOC :									
SB PW500-72-30586 R01 E1	REPLACEMENT/MODIFICATION OF FAN CASE ASSEMBLY			CATEGORY 7			-			
	MOC :									
SB PW500-72-30586 R01 E2	REPLACEMENT/MODIFICATION OF FAN CASE ASSEMBLY			CATEGORY 7			-			
	MOC :									
ASB PW500-72-A30314 R01 E1	INTRODUCTION OF NEW FUEL MANIFOLD			CATEGORY 10			-			
	MOC :									
ASB PW500-72-A30314 R01 E2	INTRODUCTION OF NEW FUEL MANIFOLD			CATEGORY 10			-			
	MOC :									
ASB PW500-72-A30314 E2	INTRODUCTION OF NEW FUEL MANIFOLD (SUPERSEDED BY PW500-72-A30314 R01)	UNK		CATEGORY 3	DAYS 12-Jul-2017 HRS 4930.9 LDG 4107		-			Complete
	MOC :	COMPLIED WITH								
SB 560-73-03 73SB-03	ENGINE SUPPLY AND MOTIVE FLOW FUEL LINE REPLACEMENT			DISCRETIONARY MTH			-			
	MOC :									
ASL 560-73-13 73ASL-13	ENGINE FUEL AND CONTROL - TRANSMITTAL OF PRATT & WHITNEY CANADA (P&WC) ALERT SERVICE BULLETIN NUMBER A30314 TURBOFAN ENGINE NEW FUEL MANIFOLD - INTRODUCTION OF			MANDATORY	MTH 02-Oct-2007 HRS 1966		A/R			Complete
	MOC :	COMPLIED WITH								



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL 560-73-07 73SL-07	ENGINE FUEL AND CONTROL - TRANSMITTAL OF P&WC SB 30249 TURBOFAN ENGINE FUEL MANIFOLD - INSPECTION/REPLACEMENT OF ANDCOMMERCIAL SUPPORT PROGRAM NOTIFICATION (CSPN) A03008	BOI		RECOMMENDED	MTH 20-Apr-2004 HRS 964		-			Complete
MOC : COMPLIED WITH										
SL 560-73-08 73SL-08	ENGINE FUEL AND CONTROL - TRANSMITTAL OF P&WC ASB 30257 TURBOFAN ENGINE HFC UNIT RATIO SETSCREW ADJUSTMENT AND COMMERCIAL SUPPORT PROGRAM NOTIFICATION (CSPN) A03011	BOI		RECOMMENDED	MTH 13-Jan-2004 HRS 899		A/R			Complete
MOC : COMPLIED WITH										
SL 560-73-10 73SL-10	ENGINE FUEL AND CONTROL - TRANSMITTAL OF P&WC SB 30273: TURBOFAN ENGINE FUEL PRESSURE TUBE REPLACEMENT AND ATTENUATOR INTRODUCTION AND COMMERCIAL SUPPORT PROGRAM NOTIFICATION (CSPN) A03012	BOI		RECOMMENDED	MTH 15-Sep-2004 HRS 1052		-			Complete
MOC : COMPLIED WITH										
SL 560-73-12 73SL-12	ENGINE FUEL AND CONTROL - TRANSMITTAL OF P&W SB 30197R2 TURBOFAN ENGINE NEW FUEL MANIFOLD - INTRODUCTION OF (SUPERSEDED BY SL560-73-12 R01)	BOI		RECOMMENDED	MTH 24-Feb-2006 HRS 1485		-			Complete
MOC : COMPLIED WITH										
SB PW500-72-30405 R04 E1	REPLACEMENT OF FUEL NOZZLE MANIFOLD			CATEGORY 6			-			
MOC :										
SB PW500-72-30405 R04 E2	REPLACEMENT OF FUEL NOZZLE MANIFOLD			CATEGORY 6			-			
MOC :										
SB PW500-72-30405 R05 E1	REPLACEMENT OF FUEL NOZZLE MANIFOLD			CATEGORY 6			-			
MOC :										
SB PW500-72-30405 R05 E2	REPLACEMENT OF FUEL NOZZLE MANIFOLD			CATEGORY 6			-			
MOC :										
SB PW500-72-30565 R02 E1	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT			CATEGORY 6			-			
MOC :										
SB PW500-72-30565 R02 E2	REPLACEMENT/MODIFICATION OF HYDROMECHANICAL FUEL CONTROL UNIT			CATEGORY 6			-			
MOC :										
SB PW500-73-30583 E1	REPLACEMENT OF FUEL PRESSURE HOSE AND TUBE			CATEGORY 7			-			
MOC :										
SB PW500-73-30583 E2	REPLACEMENT OF FUEL PRESSURE HOSE AND TUBE			CATEGORY 7			-			
MOC :										
SB 560-78-04 78SB-04	THRUST REVERSER THROTTLE STOP SOLENOID GROUND IMPROVEMENT	BOI		OPTIONAL	MTH 19-Jun-2003 HRS 765		-			Complete
MOC : COMPLIED WITH										

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SIL GEN-153 R05 E1	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION (SUPERSEDED BY SIL GEN-153 R06)			INFORMATIONAL			-			
	MOC :									
SIL GEN-153 R05 E2	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION (SUPERSEDED BY SIL GEN-153 R06)			INFORMATIONAL			-			
	MOC :									
SIL GEN-153 R06 E1	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION			INFORMATIONAL			-			
	MOC :									
SIL GEN-153 R06 E2	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION			INFORMATIONAL			-			
	MOC :									
SIL GEN-153 R07 E1	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION			INFORMATIONAL			-			
	MOC :									
SIL GEN-153 R07 E2	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION			INFORMATIONAL			-			
	MOC :									
SIL GEN-153 R08 E1	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION						-			
	MOC :									
SIL GEN-153 R08 E2	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION						-			
	MOC :									
SIL GEN-153 R09 E1	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION			INFORMATIONAL			-			
	MOC :									
SIL GEN-153 R09 E2	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION			INFORMATIONAL			-			
	MOC :									
SIL GEN-153 R10 E1	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION			INFORMATIONAL			-			
	MOC :									
SIL GEN-153 R10 E2	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION			INFORMATIONAL			-			
	MOC :									
SB 560-80-05 80SB-05	STARTER GENERATOR POWER-CABLE BOLT REPLACEMENT (SUPERSEDED BY 560-80-05 R01)	BOI		SUPERSEDED	MTH 21-Jan-2004 HRS 902		A/R			Complete
	MOC :	COMPLIED WITH								
SL CIL-99-01 R03	MISCELLANEOUS - USE OF CORROSION INHIBITING COMPOUNDS			CANCELLED			-			
	MOC :									
SL CIL-99-02 R01	MISCELLANEOUS - AVOID OPERATIONS ON RUNWAYS TREATED WITH RUNWAY DE-ICE (RDI) FLUIDS. AIRCRAFT WASHING RECOMMENDED AFTER EXPOSURE TO RDI FLUIDS			CANCELLED			-			
	MOC :									
SL CIL-99-03 R02	MISCELLANEOUS - CORROSION PREVENTION AND CONTROL PROGRAM (CPCP)			CANCELLED			-			
	MOC :									
SL CIL-99-04 R01	MISCELLANEOUS - INCREMENTAL LIBRARY UPDATES FOR CESVIEW			CANCELLED			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL CIL-99-05 REV 1	MISCELLANEOUS - INSTALLATION OF CESSNA VARIANT PART NUMBERS			INFORMATIONAL	MTH		-			

MOC :

SL CIL-99-05	MISCELLANEOUS - INSTALLATION OF CESSNA VARIANT PART NUMBERS			INFORMATIONAL			-			
--------------	---	--	--	---------------	--	--	---	--	--	--

MOC :

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
FAA 1998-04-38 30AD-02	SEVERE ICING PROCEDURES ICT			MANDATORY	MTH HRS 9		-			Complete

MOC : COMPLIED WITH

FAA 2006-04-10 26AD-02	THIS AD REQUIRES INSTALLING IDENTIFICATION SLEEVES ON THE WIRES FOR THE POSITIVE AND NEGATIVE STUDS OF THE ENGINE AND/ OR (APU) FIRE EXTINGUISHING BOTTLES, AS APPICABLE, AND RECONNECTING THE WIRES TO THE CORRECT TERMINAL STUDS.			MANDATORY	MTH HRS 1495		-			Complete
---------------------------	---	--	--	-----------	-----------------	--	---	--	--	----------

MOC : COMPLIED WITH - INTENT ACCOMPLISHED DURING PREVIOUS MAINTENANCE OR THROUGH ALTERNATE METHOD OF COMPLIANCE.

FAA 2006-06-03 28AD-01	PREVENT FUEL VAPOR IGNITION			MANDATORY	MTH HRS 1501		-			Complete
---------------------------	-----------------------------	--	--	-----------	-----------------	--	---	--	--	----------

MOC : COMPLIED WITH - INTENT ACCOMPLISHED DURING PREVIOUS MAINTENANCE OR THROUGH ALTERNATE METHOD OF COMPLIANCE.

FAA 2006-16-18 34AD-16	APPLIANCE AD - SANDEL AVIONICS INCORPORATED MODEL ST3400 TERRAIN AWARENESS WARNING SYSTEM/RADIO MAGNETIC INDICATOR (TAWS/RMI)			MANDATORY	MTH HRS 1966		A/R			N/A
---------------------------	---	--	--	-----------	-----------------	--	-----	--	--	-----

MOC : NOT APPLICABLE - NOT APPLICABLE-EQUIPMENT NOT INSTALLED

FAA 2006-19-04 PARA(F) 34AD-17	REVISE HONEYWELL RCZ-833J/K, -851J/K AND 854J COMMUNICATION (COM) UNITS, EQUIPPED WITH XS-852E/F MODE S TRANSPONDERS; AND HONEYWELL XS-856A/B AND -857A MODE S TRANSPONDERS AIRPLANE FLIGHT MANUAL (AFM)			MANDATORY	MTH HRS 1966		A/R			N/A
--------------------------------------	--	--	--	-----------	-----------------	--	-----	--	--	-----

MOC : NOT APPLICABLE - NOT APPLICABLE-EQUIPMENT NOT INSTALLED

FAA 2013-09-11 PARA (G)	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM INSPECTION FOR PART NUMBER (P/N)	BOI		MANDATORY	DAYS 31-Jul-2013 HRS 3775.3 LDG 3151		-			Complete
----------------------------	---	-----	--	-----------	--	--	---	--	--	----------

MOC : COMPLIED WITH - COMPLIED WITH AD2013-09-11 BY INSPECTING THE A/C COMPRESSOR MOTOR FOR P/N AND TOTAL TIME IN SERVICE. THIS AD APPLIES TO THIS MOTOR, P/N 1134104-5 AND BRUSH REPLACEMENT IS DUE AT500 HRS. ON THE A/C HOUR METER. HOUR METER TIME WILL BE MONITERED BY CESSNA INSPECTION PHASE ML, DUE EVERY 300 HRS. A/F TIME

FAA 2013-09-11 PARA (H)	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM INSPECTION A/C COMPRESSOR HOUR METER AND MAINTENANCE RECORDS	BOI		MANDATORY	DAYS 31-Jul-2013 HRS 3775.3 LDG 3151		-			Complete
----------------------------	---	-----	--	-----------	--	--	---	--	--	----------

MOC : COMPLIED WITH - COMPLIED WITH AD2013-09-11 BY INSPECTING THE A/C COMPRESSOR MOTOR FOR P/N AND TOTAL TIME IN SERVICE. THIS AD APPLIES TO THIS MOTOR, P/N 1134104-5 AND BRUSH REPLACEMENT IS DUE AT500 HRS. ON THE A/C HOUR METER. HOUR METER TIME WILL BE MONITERED BY CESSNA INSPECTION PHASE ML, DUE EVERY 300 HRS. A/F TIME



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
FAA 2013-09-11 PARA (I) & (J)	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM REPLACEMENT OF A/C COMPRESSOR MOTOR BRUSHES AND RELATED MAINTENANCE MANUAL INFORMATION	KBOI		MANDATORY	MTH 13-Sep-2024 HRS 6939.2 LDG 5702 ACH 496.7		500		996.7	Complete 470.7
MOC : COMPLIED WITH										
FAA 2013-09-11 PARA (K)	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM DEACTIVATION OF A/C SYSTEM			MANDATORY			A/R			
MOC :										
FAA 2013-09-11 PARA (L)	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM REACTIVATION OF A/C SYSTEM			MANDATORY			A/R			
MOC :										
FAA 2013-09-11 PARA (M)	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM PARTS RETURN AND REPORTING REQUIREMENTS			MANDATORY	DAYS		30			
MOC :										
FAA 2013-09-11	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM	BOI		MANDATORY	MTH 31-Jul-2013 HRS 3775.3 LDG 3151		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH AD2013-09-11 BY INSPECTING THE A/C COMPRESSOR MOTOR FOR P/N AND TOTAL TIME IN SERVICE. THIS AD APPLIES TO THIS MOTOR, P/N 1134104-5 AND BRUSH REPLACEMENT IS DUE AT500 HRS. ON THE A/C HOUR METER. HOUR METER TIME WILL BE MONITERED BY CESSNA INSPECTION PHASE ML, DUE EVERY 300 HRS. A/F TIME										
FAA 2015-17-12 PARA (G)	INSPECT THE A/C COMPRESSOR MOTOR TO DETERMINE WHETHER P/N FWA1134104-1 OR P/N FWA1134104-5 IS INSTALLED	BOI		MANDATORY	DAYS 31-Aug-2015 HRS 4355.1 LDG 3637		-			N/A
MOC : NOT APPLICABLE - THIS AD IS N/A BY P/N OF THE MOTOR. THIS INSTALLATION IS ADDRESSED BY AD 2013-09-11.										
FAA 2015-17-12 PARA (H)	DETERMINE THE HOUR READING ON THE A/C COMPRESSOR HOUR METER (IF, DURING THE INSPECTION REQUIRED BY PARA (G) OF THIS AD, ANY A/C COMPRESSOR MOTOR HAVING P/N FWA1134104-1 OR P/N FWA1134104-5 IS FOUND	BOI		MANDATORY	DAYS 31-Aug-2015 HRS 4355.1 LDG 3637		-			N/A
MOC : NOT APPLICABLE - THIS AD IS N/A BY P/N OF THE MOTOR. THIS INSTALLATION IS ADDRESSED BY AD 2013-09-11.										
FAA 2015-17-12 PARA (I)	REPLACE THE A/C COMPRESSOR MOTOR BRUSHES WITH NEW BRUSHES (USING THE HOUR READING ON THE A/C COMPRESSOR HOUR METER DETERMINED IN PARA (H) OF THIS AD)	BOI		MANDATORY	MTH 31-Aug-2015 HRS 4355.1 LDG 3637		-			N/A
MOC : NOT APPLICABLE - THIS AD IS N/A BY P/N OF THE MOTOR. THIS INSTALLATION IS ADDRESSED BY AD 2013-09-11.										
FAA 2015-17-12 PARA (K)	DEACTIVATE THE A/C SYSTEM (IN LIEU OF REPLACING THE A/C COMPRESSOR MOTOR BRUSHES AS REQUIRED BY THIS AD)	BOI		MANDATORY	MTH 31-Aug-2015 HRS 4355.1 LDG 3637		-			N/A
MOC : NOT APPLICABLE - THIS AD IS N/A BY P/N OF THE MOTOR. THIS INSTALLATION IS ADDRESSED BY AD 2013-09-11.										



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
FAA 2015-17-12 PARA (L)	IF THE A/C SYSTEM IS DEACTIVATED, AS SPECIFIED IN PARA (K), PRIOR TO THE A/C SYSTEM BEING REACTIVATED: PERFORM THE INSPECTION SPECIFIED IN PARA (H), AND DO THE REPLACEMENTS SPECIFIED IN PARA (I), AT THE TIMES SPECIFIED IN PARA (I). RETURN THE A/C SYSTEM TO SERVICE								
		BOI	MANDATORY	MTH 31-Aug-2015 HRS 4355.1 LDG 3637		-			N/A
MOC : NOT APPLICABLE - THIS AD IS N/A BY P/N OF THE MOTOR. THIS INSTALLATION IS ADDRESSED BY AD 2013-09-11.									
FAA 2015-17-12 PARA (M)	SEND THE REMOVED BRUSHES TO CESSNA AIRCRAFT COMPANY								
		BOI	MANDATORY	DAYS 31-Aug-2015 HRS 4355.1 LDG 3637		-			N/A
MOC : NOT APPLICABLE - THIS AD IS N/A BY P/N OF THE MOTOR. THIS INSTALLATION IS ADDRESSED BY AD 2013-09-11.									
FAA 2015-17-12	AIR CONDITIONING - INSPECTIONS TO DETERMINE IF CERTAIN A/C COMPRESSOR MOTORS ARE INSTALLED AND TO DETERMINE THE ACCUMULATED HOURS ON CERTAIN A/C COMPRESSOR MOTOR ASSEMBLIES; AND REPETITIVE REPLACEMENT OF THE BRUSHES IN THE A/C COMPRESSOR MOTOR ASSEMBLY, OR, AS AN OPTION TO THE BRUSH REPLACEMENT, DEACTIVATION OF THE A/C SYSTEM AND PLACARD INSTALLATION; AND RETURN OF REPLACED BRUSHES TO CESSNA								
		BOI	MANDATORY	MTH 31-Aug-2015 HRS 4355.1 LDG 3637		-			N/A
MOC : NOT APPLICABLE - THIS AD IS N/A BY P/N OF THE MOTOR. THIS INSTALLATION IS ADDRESSED BY AD 2013-09-11.									
FAA 1974-08-09 R02 050809 : 560R2	LAVATORY PAPER OR LINEN WASTE RECEPTACLE FIRE PREVENTION (SUPERSEDED BY FAA AD 1974-08-09 R3)								
		BOI	MANDATORY	MTH 29-Nov-2011 HRS 3250.9 LDG 2704		-			Complete
MOC : COMPLIED WITH									
FAA 1974-08-09 R03	LAVATORY PAPER OR LINEN WASTE RECEPTACLE FIRE PREVENTION								
		KBOI	MANDATORY	MTH 30-Oct-2025 HRS 7185 LDG 5965		1000		8185	Complete 911.3
MOC : COMPLIED WITH - COMPLIED WITH AD1974-08-09 R03 BY INSPECTING FOR NO SMOKING PLACARDS PER PARAGRAPH (G) (1) AND (2) OF THIS AD. NO DEFECTS NOTED. NEXT INSPECTION DUE 8185.0 HRS.									
FAA 2015-10-02 PARA (G)	GENERAL VISUAL INSPECTION FOR CRACKING OF SEAT BACKREST LINKS HAVING PART NUMBER (P/N) 90-000200-104-1, P/N 90-000200-104-2, P/N 90-000202-104-1 AND P/N 90-000202-104-2								
		BOI	MANDATORY	MTH 06-Jul-2015 HRS 4304.9 LDG 3597		-			N/A
MOC : NOT APPLICABLE - THIS AIRWORTHINESS DIRECTIVE IS NOT APPLICABLE, DUE TO MANUFACTURE COMPANY									
FAA 2015-10-02 PARA (H)	CORRECTIVE ACTIONS - CRACKING IS FOUND ON THE LINK								
		BOI	MANDATORY	MTH 06-Jul-2015 HRS 4304.9 LDG 3597		-			N/A
MOC : NOT APPLICABLE - THIS AIRWORTHINESS DIRECTIVE IS NOT APPLICABLE, DUE TO MANUFACTURE COMPANY									
FAA 2015-10-02 PARA (I)	REPLACE ALL SEAT BACKREST LINKS, HAVING P/N 90-000200-104-1, P/N 90-000200-104-2, P/N 90-000202-104-1 AND P/N 90-000202-104-2, WITH NEW LINKS								
		BOI	MANDATORY	MTH 06-Jul-2015 HRS 4304.9 LDG 3597		-			N/A
MOC : NOT APPLICABLE - THIS AIRWORTHINESS DIRECTIVE IS NOT APPLICABLE, DUE TO MANUFACTURE COMPANY									
FAA 2015-10-02	APPLIANCE AD - EQUIPMENT/FURNISHINGS - ZODIAC SEATS FRANCE - INSPECTION/REPLACEMENT								
		BOI	MANDATORY	MTH 06-Jul-2015 HRS 4304.9 LDG 3597		-			N/A
MOC : NOT APPLICABLE - THIS AIRWORTHINESS DIRECTIVE IS NOT APPLICABLE									



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
FAA 2017-16-01 PARA (G)	PERFORM GENERAL VISUAL INSPECTIONS OF THE ELT FOR DISCREPANCIES; CHECKS , TESTS AND VERIFICATIONS AS APPLICABLE, TO ENSURE THE ELT IS FUNCTIONING, AND ALL APPLICABLE CORRECTIVE ACTIONS	KBOI			MTH 20-Oct-2017 HRS 5020.2 LDG 4183 ACH 404.7		-			N/A
MOC : NOT APPLICABLE - DOES NOT APPLY AS AFFECTED PARTS NOT INSTALLED AT THIS TIME.										
FAA 2017-16-01 PARA (J)	OPTIONAL TERMINATING ACTION: REPLACE ELT WITH A SERVICEABLE FAA-APPROVED ELT			MANDATORY			-			
MOC :										
FAA 2017-16-01	APPLIANCE AD - EQUIPMENT / FURNISHINGS - AMERI-KING CORPORATION MODEL AK-450() AND AK-451() SERIES EMERGENCY LOCATOR TRANSMITTERS - REPETATIVE INSPECTIONS, CHECKS, TESTS AND VERIFICATIONS			MANDATORY			-			
MOC :										
FAA 2021-07-13 PARA (E)(1)	INSPECT THE BUCKLE HANDLE FOR A CRACK AND IF CRACKED, BEFORE FURTHER FLIGHT, REPLACE IT WITH AN AIRWORTHY BUCKLE	KBOI		MANDATORY	MTH 08-Apr-2021 HRS 5928.6 LDG 4901		-			N/A
MOC : NOT APPLICABLE - N/A PER APPLICABILITY PARAGRAPH (A). AFFECTED PARTS NOT INSTALLED BY P/N. NO FURTHER ACTION REQUIRED.										
FAA 2021-07-13 PARA (E)(2)	MEASURE THE THICKNESS OF THE BUCKLE HANDLE VANE; IF THICKNESS IS 0.125 INCH OR GREATER, BEFORE FURTHER FLIGHT, REMOVE THE BUCKLE FROM SERVICE AND REPLACE IT WITH AN AIRWORTHY BUCKLE	KBOI		MANDATORY	MTH 08-Apr-2021 HRS 5928.6 LDG 4901		-			N/A
MOC : NOT APPLICABLE - N/A PER APPLICABILITY PARAGRAPH (A). EFFECTED PARTS NOT INSTALLED BY P/N. NO FURTHER ACTION REQUIRED.										
FAA 2021-07-13 PARA (E)(3)	DO NOT INSTALL A BUCKLE OR RESTRAINT SYSTEM WITH A BUCKLE P/N 1111430 OR 1111475, ALL DASH NUMBERS, WITH A HANDLE VANE THICKNESS OF 0.125 INCH OR GREATER			MANDATORY			-			
MOC :										
FAA 2021-07-13	APPLIANCE AD - EQUIPMENT AND FURNISHING - SEAT RESTRAINT SYSTEM PLASTIC ROTARY BUCKLE HANDLE - INSPECTION/REPLACEMENT			MANDATORY			-			
MOC :										
FAA 2024-26-02 PARA (G)(1)	INSPECT THE BUCKLE HANDLE FOR A CRACK AND IF CRACKED, BEFORE FURTHER FLIGHT, REPLACE IT WITH AN AIRWORTHY BUCKLE	KBOI		MANDATORY	MTH 11-Mar-2025 HRS 7039.5 LDG 5798		-			N/A
MOC : NOT APPLICABLE										
FAA 2024-26-02 PARA (G)(2)	MEASURE THE THICKNESS OF THE BUCKLE HANDLE VANE; IF THICKNESS IS 0.125 INCH OR GREATER, BEFORE FURTHER FLIGHT, REMOVE THE BUCKLE FROM SERVICE AND REPLACE IT WITH AN AIRWORTHY BUCKLE	KBOI		MANDATORY	MTH 11-Mar-2025 HRS 7039.5 LDG 5798		-			N/A
MOC : NOT APPLICABLE - AD 2024-26-02 PARAGRAPH (G)(2) DOES NOT APPLY DUE TO MANUFACTURE OF SEAT BELTS INSTALLED. PACIFIC SCIENTIFIC SEAT BELT MANUFACTURE CURRENTLY INSTALLED.										
FAA 2024-26-02 PARA (G)(3)	DO NOT INSTALL A BUCKLE OR RESTRAINT SYSTEM WITH A BUCKLE P/N 1111430 OR 1111475, ALL DASH NUMBERS, WITH A HANDLE VANE THICKNESS OF 0.125 INCH OR GREATER			MANDATORY			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
FAA 2024-26-02	APPLIANCE AD - EQUIPMENT AND FURNISHING - SEAT RESTRAINT SYSTEM PLASTIC ROTARY BUCKLE HANDLE - INSPECTION/REPLACEMENT MANDATORY									
	MOC :									
FAA 2007-11-17 26AD-03	IDENTIFY WIRES FOR FIRE EXTINGUISHING BOTTLES			MANDATORY	MTH 02-Oct-2007 HRS 1966		A/R			Complete
	MOC : COMPLIED WITH - INTENT ACCOMPLISHED DURING PREVIOUS MAINTENANCE OR THROUGH ALTERNATE METHOD OF COMPLIANCE.									
FAA 2010-04-16 PARA (G) 26AD-07	REPLACE TYPE H1-10 AIR HALON 1211 (BCF) PORTABLE FIRE EXTINGUISHERS	BOI		MANDATORY	DAYS 02-Nov-2011 HRS 3236.9 LDG 2696		A/R			N/A
	MOC : NOT APPLICABLE									
FAA 2010-04-16 26AD-07	APPLIANCE AD - TYPE H1-10 AIR HALON 1211 (BCF) PORTABLE FIRE EXTINGUISHERS			MANDATORY	DAYS 02-Nov-2011 HRS 3236.9 LDG 2696		A/R			N/A
	MOC : NOT APPLICABLE									
FAA 2025-11-09 PARA (G)	FIRE BOTTLE WIRE TEST AND INSPECTION	KBOI		MANDATORY	DAYS 04-Sep-2025 HRS 7126.8 LDG 5910		-			Complete
	MOC : COMPLIED WITH - COMPLIED WITH AD2025-11-09 PARA (G) BY COMPLYING WITH TEXTRON SERVICE LETTER SL560-26-02 R1. NO DEFECTS FOUND.									
FAA 2025-11-09 PARA (I)	INSPECTION PROGRAM REVISION			MANDATORY	MTH		24			
	MOC :									
FAA 2025-11-09	FIRE PROTECTION - MIS-WIRED FIRE EXTINGUISHING BOTTLES			MANDATORY			-			
	MOC :									
FAA 2021-23-12	APPLIANCE AD - INDICATING / RECORDING / NAVIGATION - RADIO (RADAR) ALTIMETER - AFM REVISION TO INCORPORATE LIMITATIONS	KBOI		MANDATORY	MTH 04-Jan-2022 HRS 6098.2 LDG 5037		-			Complete
	MOC : COMPLIED WITH - COMPLIED WITH FAA 2021-23-12 PER PARAGRAPH (F) AND (G). INSERTED A COPY OF FAA AD 2021-23-12, AMENDMENT 39-21810 INTO THE LIMITATION SECTION OF THE EXISTING AFM PER INSTRUCTIONS.									
FAA 2023-10-02 PARA (H)	REVISE THE LIMITATIONS SECTION OF THE EXISTING AFM (UNTIL 30-JUNE-2023 - SATISFIED BY FAA 2021-23-12)2)	KBOI		MANDATORY	MTH 20-Jun-2023 HRS 6571.9 LDG 5405		-			Complete
	MOC : COMPLIED WITH									
FAA 2023-10-02 PARA (I)	REVISE THE LIMITATIONS SECTION AND REMOVE THE AFM REVISION REQUIRED BY PARA (H) (AFTER 30 JUN 2023)	KBOI		MANDATORY	MTH 20-Jun-2023 HRS 6571.9 LDG 5405		-			Complete
	MOC : COMPLIED WITH - COMPLIED WITH A.D. 2023-10-02 AMENDMENT 39-22438 PER PARA. (I) INSTRUCTIONS. INSERTED A COPY OF FIGURE 4 TO PARAGRAPH (I) OF THIS AD INTO EXISTING AFM.									
FAA 2023-10-02	APPLIANCE AD - INDICATING/RECORDING SYSTEM/NAVIGATION - RADIO ALTIMETER - AFM REVISION	KBOI		MANDATORY	MTH 20-Jun-2023 HRS 6571.9 LDG 5405		-			Complete
	MOC : COMPLIED WITH									



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
FAA 2001-23-17 <i>34AD-10</i>	APPLIANCE AD - TO PREVENT INACCURATE COURSE DEVIATION DISPLAYS IN THE GNS 430 UNIT			MANDATORY	MTH 30-Dec-2003 HRS 885		A/R			Complete
MOC : COMPLIED WITH - NOT APPLICABLE-EQUIPMENT NOT INSTALLED										
FAA 2003-04-06 <i>34AD-13</i>	APPLIANCE AD - HONEYWELL PRIMUS RNZ-850/851 NM (SUPERSEDED BY FAA 2006-22-05)	BOI		SUPERSEDED	MTH 11-Mar-2003 HRS 691		A/R			Complete
MOC : COMPLIED WITH										
FAA 2006-22-05 <i>34AD-18</i>	APPLIANCE AD - HONEYWELL PRIMUS RNZ-850/851 NM (SUPERSEDED BY FAA 2010-07-02)	BOI		MANDATORY	MTH 14-Oct-2009 HRS 2659		A/R			N/A
MOC : NOT APPLICABLE										
FAA 2010-07-02	APPLIANCE AD - PERFORM A ONE-TIME GENERAL VISUAL INSPECTION OF THE MODIFICATION PLATE FOR THE HONEYWELL PRIMUS II NV-850 NAVIGATION RECEIVER MODULE (NRM)	BOI		MANDATORY	MTH 26-Sep-2012 HRS 3465.3 LDG 2896		A/R			Complete
MOC : COMPLIED WITH - COMPLIED WITH AD2010-07-02 BY COMPLYING WITH HONEYWELL SERVICE BULLETIN 7510100-34-0037 ON THE FORWARD UNIT, SERIAL NO.96011707. WORK PERFORMED BY DUNCAN AVIATION IN LINCOLN NE.UNDER W.O. 1QDDA. THE AFT UNIT, SERIAL NO. 01035253, WAS EXCHANGED FOR A MODIFIED UNIT, SERIAL NO. 98082930										
FAA 2012-02-08	APPLIANCE AD - AVIATION COMMUNICATION AND SURVEILLANCE SYSTEMS (ACSS) TRAFFICALERT AND COLLISION AVOIDANCE SYSTEM (TCAS) UNITS	BOI		MANDATORY	MTH 22-Jan-2015 HRS 4175.9 LDG 3491		-			N/A
MOC : NOT APPLICABLE - THIS AD IS NOT APPLICABLE TO THIS AIRCRAFT, AFFECTED ITEM NOT INSTALLED										
FAA 2014-18-01	APPLIANCE AD - NAVIGATION - ROCKWELL COLLINS, INC. MODE S TRANSPONDERS - INSPECTION / MODIFICATION	BOI		MANDATORY	MTH 13-Oct-2014 HRS 4091.1 LDG 3416		-			N/A
MOC : NOT APPLICABLE - THIS AD DOES NOT APPLY, BECAUSE THIS EQUIPMENT IS NOT INSTALLED ON THIS AIRCRAFT.										
FAA 2015-10-51-E	APPLIANCE AD - AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM OR AFMS.	B01		MANDATORY	MTH 17-Jun-2015 HRS 4294.4 LDG 3586		-			N/A
MOC : NOT APPLICABLE - THIS AIRWORTHINESS DIRECTIVE DOES NOT APPLY, THE AFFECTED EQUIPMENT IS NOT INSTALLED IN THIS AIRCRAFT.										
FAA 2015-10-51	APPLIANCE AD - AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM OR AFMS			MANDATORY			-			
MOC :										
FAA 2015-08-07 PARA (G)	INSPECT THE INFLATABLE HARNESS FITTED TO EACH FLIGHTCREW OXYGEN MASK REGULATOR TO DETERMINE IF THE INFLATABLE HARNESS IS INSTALLED WITH A PART NUMBER AND A BATCH NUMBER IDENTIFIED IN APPENDIX I OF ZODIAC AEROSPACE SERVICE BULLETIN MXH-35-240, REVISION 7, DATED SEPTEMBER 1, 2011	BOI		MANDATORY	MTH 22-May-2015 HRS 4275.4 LDG 3570		-			N/A
MOC : NOT APPLICABLE - AD2015-08-07 COMPLIED WITH BY INSPECTION, DOES NOT APPLY BY DATE OF MANUFACTURE										



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
FAA 2015-08-07 PARA (H)	REPLACE THE INFLATABLE HARNESS IDENTIFIED IN PARAGRAPH G WITH A NEW OR RE-IDENTIFIED HARNESSES	BOI		MANDATORY	MTH 26-May-2015 HRS 4275.4 LDG 3570		-			N/A
MOC : NOT APPLICABLE - THIS AIRWORTHINESS DIRECTIVE IS N/A DOE TO ERECTIVE PARTS NOT INSTALLED.										
FAA 2015-08-07	APPLIANCE AD - OXYGEN - ZODIAC AEROTECHNICS (FORMERLY INTERTECHNIQUE AIRCRAFT SYSTEMS) FLIGHTCREW OXYGEN MASK REGULATORS - INSPECTION / REPLACEMENT OF INFLATABLE HARNESSES			MANDATORY			-			
MOC :										
FAA 2015-23-09 PARA (G)	INSPECT EACH FLIGHTCREW OXYGEN MASK REGULATOR TO IDENTIFY THE PART NUMBER AND SERIAL NUMBER	KBOI		MANDATORY	MTH DAYS 07-Jan-2016 HRS 4479 LDG 3732		-			N/A
MOC : NOT APPLICABLE										
FAA 2015-23-09 PARA (H.1)	REPLACE EACH AFFECTED FLIGHTCREW OXYGEN MASK WITH A PART IDENTIFIED IN PARAGRAPH (H)(1)(I) OR (H)(1)(II).	KBOI		MANDATORY	MTH DAYS 07-Jan-2016 HRS 4479 LDG 3732		-			N/A
MOC : NOT APPLICABLE										
FAA 2015-23-09 PARA (H.2.I)	REVISE THE EMERGENCY PROCEDURES SECTION OF THE AIRPLANE FLIGHT MANUAL (AFM) BY INSERTING THE STATEMENT PROVIDED IN FIGURE 1	KBOI		MANDATORY	MTH DAYS 07-Jan-2016 HRS 4479 LDG 3732		-			N/A
MOC : NOT APPLICABLE										
FAA 2015-23-09 PARA (H.2.II)	FABRICATE AND INSTALL A PLACARD ON THE FLIGHTCREW OXYGEN MASK CONTAINER THAT STATES: "USE SELECTOR ON 100% OR EMERGENCY ONLY."	KBOI		MANDATORY	MTH DAYS 07-Jan-2016 HRS 4479 LDG 3732		-			N/A
MOC : NOT APPLICABLE										
FAA 2015-23-09 PARA (I)	REGULATOR REPLACEMENT	KBOI		MANDATORY	MTH 07-Jan-2016 HRS 4479 LDG 3732		-			N/A
MOC : NOT APPLICABLE										
FAA 2015-23-09	APPLIANCE AD - OXYGEN - ZODIAC AEROTECHNICS (FORMERLY INTERTECHNIQUE AIRCRAFT SYSTEMS) FLIGHT CREW OXYGEN MASK REGULATORS - INSPECTION / REPLACEMENT OF OXYGEN MASK REGULATORS	KBOI		MANDATORY	MTH 07-Jan-2016 HRS 4479 LDG 3732		-			N/A
MOC : NOT APPLICABLE - THIS AD DOES NOT APPLY AS AFFECTED PARTS NOT INSTALLED ON AIRCRAFT AT THIS TIME.										
FAA 2016-11-20 PARA (G)	PHYSICALLY INSPECT THE PBE POUCH TO DETERMINE IF IT HAS AN INTACT VACUUM SEAL IN ACCORDANCE WITH B/E AEROSPACE SERVICE BULLETIN NO. 119003-35-011, REV .000, DATED FEBRUARY 4, 2015, PARA III.A.1 SUPERSEDED BY FAA AD 2017-18-12	KBOI		MANDATORY	MTH 23-Jun-2016 HRS 4639.2 LDG 3877 ACH 365.5		-			N/A
MOC : NOT APPLICABLE										



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
FAA 2016-11-20 PARA (H.1)	REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, THAT DOES NOT HAVE AN INTACT VACUUM SEAL. SUPERSEDED BY FAA AD 2017-18-12	KBOI		MANDATORY	MTH 23-Jun-2016 HRS 4639.2 LDG 3877		-			N/A
MOC : NOT APPLICABLE - N/A BY AFFECTED PARTS NOT INSTALLED ON AIRCRAFT AT THIS TIME.										
FAA 2016-11-20 PARA (H.2)	REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, WHERE THE VACUUM SEAL IS INTACT. SUPERSEDED BY FAA AD 2017-18-12	KBOI		MANDATORY	MTH 23-Jun-2016 HRS 4639.2 LDG 3877 ACH 365.5		-			N/A
MOC : NOT APPLICABLE										
FAA 2016-11-20	APPLIANCE AD - OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003-11 THAT ARE INSTALLED ON AIRPLANES. SUPERSEDED BY FAA AD 2017-18-12	KBOI		MANDATORY	MTH 23-Jun-2016 HRS 4639.2 LDG 3877		-			N/A
MOC : NOT APPLICABLE - N/A BY AFFECTED PARTS NOT INSTALLED ON AIRCRAFT AT THIS TIME.										
FAA 2017-18-12 PARA (G)	INSPECTION RETAINED FROM AD 2016-11-20 FOR AIRPLANES WITH PBE, P/N 119003-11, INSTALLED			MANDATORY			-			
MOC :										
FAA 2017-18-12 PARA (H)	REPLACEMENT RETAINED FROM AD 2016-11-20 FOR AIRPLANES WITH PBE, P/N 119003-11, INSTALLED			MANDATORY			-			
MOC :										
FAA 2017-18-12 PARA (I) & (J)	INSPECT TO DETERMINE IF THE S/N OF THE INSTALLED PBE, P/N 119003-21, IS WITHIN THE RANGE OF 004-14768M THROUGH 004-21093M OR 004-02393M THROUGH 004-03033M AND IF FOUND WITHIN THE S/N RANGE REPLACE IT.	KBOI		MANDATORY	MTH 20-Oct-2017 HRS 5020.2 LDG 4183 ACH 404.7		-			N/A
MOC : NOT APPLICABLE - DOES NOT APPLY AS AFFECTED PARTS NOT INSTALLED AT THIS TIME.										
FAA 2017-18-12	OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003-11 AND 119003-21 THAT ARE INSTALLED ON AIRPLANES			MANDATORY			-			
MOC :										
FAA 2025-25-02	APPLIANCE AD - OXYGEN - PORTABLE BREATHING EQUIPMENT - OPERATIONAL INSTRUCTIONS			MANDATORY	DAYS		-			
MOC :										
FAA 2026-03-09 PARA (G) EASA (1)	REPLACE THE AFFECTED PBE WITH A PBE NOT AFFECTED BY THIS AD	KBOI		MANDATORY	DAYS 27-Mar-2026 HRS 7265.3 LDG 6027		-			N/A
MOC : NOT APPLICABLE - AIRWORTHINESS DIRECTIVE 2026-03-09 EFFECTIVE MARCH 12, 2026 DOES NOT APPLY DUE TO EQUIPMENT NOT INSTALLED.										
FAA 2026-03-09 PARA (G) EASA (2)	ACCOMPLISHMENT OF THE ACTION AS REQUIRED BY PARA (1) OF THIS AD CAN BE DEFERRED IN ACCORDANCE WITH THE APPLICABLE INSTRUCTIONS AND LIMITATIONS OF THE APPLICABLE AIRCRAFT MMEL ITEMS, PROVIDED THAT THOSE MMEL ITEMS ARE INCLUDED IN THE OPERATOR APPROVED MEL, AND THAT THE MINIMUM REQUIRED INSTALLED PBES ARE CONFIRMED NOT AFFECTED BY THIS AD	KBOI		MANDATORY	MTH 27-Mar-2026 HRS 7265.3 LDG 6027		-			N/A
MOC : NOT APPLICABLE										



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
FAA 2026-03-09 PARA (G) EASA (3)	PART INSTALLATION: STARTING FROM THE APPLICABILITY DATE AS IDENTIFIED IN TABLE 1 OF THIS AD, AS APPLICABLE, DEPENDING ON PBE LOCATION, DO NOT INSTALL AN AFFECTED PBE ON ANY AIRCRAFT									
		KBOI		MANDATORY	DAYS 27-Mar-2026 HRS 7265.3 LDG 6027		-			N/A
MOC : NOT APPLICABLE										
FAA 2026-03-09 PARA (G) EASA (4)	LIFE LIMIT: REMOVE FROM SERVICE	KBOI		MANDATORY	MTH 27-Mar-2026 HRS 7265.3 LDG 6027		-			N/A
MOC : NOT APPLICABLE										
FAA 2026-03-09	APPLIANCE AD - OXYGEN - PORTABLE BREATHING EQUIPMENT - REMOVAL FROM SERVICE									
				MANDATORY	MTH 27-Mar-2026 HRS 7265.3 LDG 6027		-			N/A
MOC : NOT APPLICABLE										
FAA 2006-08-13 E1	TO PREVENT LACK OF ENGINE RESPONSE TO POWER LEVER INPUT	UNK		MANDATORY	MTH 14-Jul-2017 HRS 4930.9 LDG 4107		-			Complete
MOC : COMPLIED WITH - PCW										
FAA 2006-08-13 E2	TO PREVENT LACK OF ENGINE RESPONSE TO POWER LEVER INPUT	UNK		MANDATORY	MTH 12-Jul-2017 HRS 4930.9 LDG 4107		-			Complete
MOC : COMPLIED WITH - PCW										
AD 73-04	HFC RATIO UNIT SETSCREW				MTH 05-May-2006 HRS 1539		-			Complete
MOC : COMPLIED WITH										
FAA 2003-03-21 LEFT ENGINE 73AD-03 : E1**L	THIS ACTION REQUIRES A ONE-TIME VISUAL INSPECTION AND RE-MARKING, OR IN LIEU OF INSPECTION, REPLACEMENT OF CERTAIN PART NUMBERS (P/N'S) OF THE FLEXIBLE FUEL TUBE LOCATED BETWEEN THE FUEL/OIL HEAT EXCHANGER AND THE INTEGRAL FUEL CONTROL UNIT-FUEL PUMP									
		BOI		MANDATORY	MTH 27-May-2003 HRS 755		A/R			Complete
MOC : COMPLIED WITH										
FAA 2003-03-21 RIGHT ENGINE 73AD-03 : E2**R	THIS ACTION REQUIRES A ONE-TIME VISUAL INSPECTION AND RE-MARKING, OR IN LIEU OF INSPECTION, REPLACEMENT OF CERTAIN PART NUMBERS (P/N'S) OF THE FLEXIBLE FUEL TUBE LOCATED BETWEEN THE FUEL/OIL HEAT EXCHANGER AND THE INTEGRAL FUEL CONTROL UNIT-FUEL PUMP									
		BOI		MANDATORY	MTH 27-May-2003 HRS 755		A/R			Complete
MOC : COMPLIED WITH										
FAA 2003-03-21 E1	ENGINE FUEL AND CONTROL - ONE-TIME VISUAL INSPECTION AND RE-MARKING, OR IN LIEU OF INSPECTION, REPLACEMENT OF CERTAIN PART NUMBERS (P/N'S) OF THE FLEXIBLE FUEL TUBE LOCATED BETWEEN THE FUEL/OIL HEAT EXCHANGER AND THE INTEGRAL FUEL CONTROL UNIT-FUEL PUMP									
		UNK		MANDATORY	MTH 14-Jul-2017 HRS 4930.9 LDG 4107		-			N/A
MOC : NOT APPLICABLE - SUPERSEDED BY SB 30253										



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
FAA 2003-03-21 E2	ENGINE FUEL AND CONTROL - ONE-TIME VISUAL INSPECTION AND RE-MARKING, OR IN LIEU OF INSPECTION, REPLACEMENT OF CERTAIN PART NUMBERS (P/N'S) OF THE FLEXIBLE FUEL TUBE LOCATED BETWEEN THE FUEL/OIL HEAT EXCHANGER AND THE INTEGRAL FUEL CONTROL UNIT-FUEL PUMP	UNK		MANDATORY	MTH 12-Jul-2017 HRS 4930.9 LDG 4107		-			N/A
MOC : NOT APPLICABLE - SUPERSEDED BY SB 30253										
FAA 2006-24-08 E1 <i>73AD-05 : E1**L</i>	ENGINE FUEL AND CONTROL - REPLACE FUEL MANIFOLD P/N 3052627-01	UNK			MTH 14-Jul-2017 HRS 4930.9 LDG 4107		-			Complete
MOC : COMPLIED WITH - PCW										
FAA 2006-24-08 E2 <i>73AD-05 : E2**R</i>	ENGINE FUEL AND CONTROL - REPLACE FUEL MANIFOLD P/N 3052627-01	UNK			MTH 12-Jul-2017 HRS 4930.9 LDG 4107		-			Complete
MOC : COMPLIED WITH - PCW										
TCCA CF-2002-42 E1	PRATT & WHITNEY CANADA (P&WC) PW530A, PW535A AND PW545A ENGINES - INSPECTION OF FLEXIBLE FUEL TUBES	UNK		MANDATORY	MTH 14-Jul-2017 HRS 4930.9 LDG 4107		-			N/A
MOC : NOT APPLICABLE - SUPERSEDED BY SB 30253										
TCCA CF-2002-42 E2	PRATT & WHITNEY CANADA (P&WC) PW530A, PW535A AND PW545A ENGINES - INSPECTION OF FLEXIBLE FUEL TUBES	UNK		MANDATORY	MTH 12-Jul-2017 HRS 4930.9 LDG 4107		-			N/A
MOC : NOT APPLICABLE - SUPERSEDED BY SB 30253										
TCCA CF-2004-28 E1	PRATT & WHITNEY CANADA PW535A ENGINES - HFC RATIO UNIT SETSCREW ADJUST	UNK		MANDATORY	MTH 14-Jul-2017 HRS 4930.9 LDG 4107		A/R			Complete
MOC : COMPLIED WITH - PCW										
TCCA CF-2004-28 E2	PRATT & WHITNEY CANADA PW535A ENGINES - HFC RATIO UNIT SETSCREW ADJUST	UNK		MANDATORY	MTH 12-Jul-2017 HRS 4930.9 LDG 4107		A/R			Complete
MOC : COMPLIED WITH - PCW										
TCCA CF-2006-22 E1	FUEL MANIFOLD LEAKAGE - REPLACE FUEL MANIFOLD	UNK		MANDATORY	MTH 14-Jul-2017 HRS 4930.9 LDG 4107		-			Complete
MOC : COMPLIED WITH - PCW										
TCCA CF-2006-22 E2	FUEL MANIFOLD LEAKAGE - REPLACE FUEL MANIFOLD	UNK		MANDATORY	MTH 12-Jul-2017 HRS 4930.9 LDG 4107		-			Complete
MOC : COMPLIED WITH - PCW										



CESCOM 10 - Aircraft Status Report

Owner: **J.R.SIMPLLOT COMPANY**
Aircraft Model: **560 - CITATION ENCORE**
Aircraft Serial: **560-0572**
Unit: **0572** Reg No: **N174JS**
Airworthiness: **28-Jun-2001**
Print Date: **08-May-2026 12:28PM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	7273.7	6035	06-May-2026	.43
ENG 1	7250.7	6012	06-May-2026	.43
ENG 2	7250.7	6012	06-May-2026	.43
AIR COND	526		06-May-2026	0

Factory Installed

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
23FO-04 560/G <i>23FO-04 : 560/G</i>	HF COMM-PROVISIONS (HONEYWELL) FACTORY OPTION *CF			631G FO	MTH 28-Jun-2001		-			
23FO-08 560/B <i>23FO-08 : 560/B</i>	COCKPIT SPEAKER MUTE FACTORY OPTION *CF			674B FO	MTH 28-Jun-2001		-			
23FO-08 560/M <i>23FO-08 : 560/M</i>	DITIGAL PHONE-MAGNASTAR FACTORY OPTION *CF			674M FO	MTH 28-Jun-2001		-			
25FO-07 560 <i>25FO-07 : 560</i>	EXTENDED BAGGAGE TUBE FACTORY OPTION *CF			132B FO	MTH 28-Jun-2001		-			
33FO-02 560/D <i>33FO-02 : 560/D</i>	GND OPER PULSELITE FACTORY OPTION *CF			56D FO	MTH 28-Jun-2001		-			
34FO-06 560/F <i>34FO-06 : 560/F</i>	UNS-1CSP PERMANENT DATA LOADER FACTORY OPTION *CF			695F FO	MTH 28-Jun-2001		-			
34FO-06 560/K <i>34FO-06 : 560/K</i>	FMS UNS 1CSP FACTORY OPTION *CF			696K FO	MTH 28-Jun-2001		-			
34FO-08 560/F <i>34FO-08 : 560/F</i>	TCAS II-CAS-67A FACTORY OPTION *CF			635F FO	MTH 28-Jun-2001		-			
34FO-15 560/B <i>34FO-15 : 560/B</i>	EGPWS-WINDSHEAR COMPUTER FACTORY OPTION *CF			691B FO	MTH 28-Jun-2001		-			